

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Site: Dundee Street (7902795)			Locality: Fountainbridge, Edinburgh, City of Edinburgh			Area: South West Locality		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W			Feature Type: Road Asset		Area: South West Locality	
Batch: 41266651 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 06/07/2026		
No actionable defects found								
Batch: 41264325 - Inspection Batch				Route: SfP_SouthWest		Date: 28/05/2026		
No actionable defects found								
Batch: 41264122 - Inspection Batch				Route: SW_CW1_North1		Date: 27/05/2026		
No actionable defects found								
Batch: 41264059 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 26/05/2026		
No actionable defects found								
Batch: 41263859 - Inspection Batch				Route: Ad hoc Route		Date: 22/05/2026		
42206971	Defective Manhole quarters have slipped	22/05/2026	Opposite high school east bound lane	RU: Utility Apparatus	Internal		Uncommitted	50197265
Batch: 41263388 - Inspection Batch				Route: Ad hoc Route		Date: 18/05/2026		
42206604	Triple bt manhole sunken and loose	18/05/2026	At the junction of yeaman place	RU: Utility Apparatus	Internal		Uncommitted	50197013
Batch: 41263320 - Inspection Batch				Route: Ad hoc Route		Date: 15/05/2026		
42206542	Various areas in Need of hra overlay	15/05/2026	Opposite victor Paris	RD: CW Pothole	Internal		Committed	50196965
Batch: 41263319 - Inspection Batch				Route: Ad hoc Route		Date: 15/05/2026		
42206541	Pothole	15/05/2026	Just after fowler terrace junction west bound	RD: CW Pothole	Internal		Committed	50196964
Batch: 41263317 - Inspection Batch				Route: Ad hoc Route		Date: 15/05/2026		
42206539	Pothole	15/05/2026	Outside Edinburgh print makers	RD: CW Pothole	Internal		Committed	50196962
Batch: 41262496 - Inspection Batch				Route: SfP_SouthWest		Date: 06/05/2026		
No actionable defects found								
Batch: 41262165 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205360	Potholes	01/05/2026	Outside Scott Arthur mp	RD: CW Pothole	Internal		Committed	50196194
Batch: 41262164 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205359	Pothole	01/05/2026	Outside library west bound lane	RD: CW Pothole	Internal		Committed	50196193
Batch: 41262162 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205357	Burst coming from patch	01/05/2026	Outside Edinburgh printmakers building	RU: Utility Apparatus	Internal		Uncommitted	50196192
Batch: 41262161 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205356	Reset Sfp bollard back to position	01/05/2026	Opposite Gibson terrace junction east bound lane	RD: SFP Damaged Bollard	Internal		Committed	50196191
Batch: 41262160 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205355	Pothole	01/05/2026	Opposite Sainsbury's next to bus stop	RD: CW Pothole	Internal		Committed	50196190
Batch: 41262159 - Inspection Batch				Route: Ad hoc Route		Date: 01/05/2026		
42205354	2 areas needing hra overlay	01/05/2026	Outside fettle beside cycle lane	RD: CW Pothole	Internal		Committed	50196189

Effective: 17/01/2025 to 16/07/2026
 Service: Roads General
 Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W		Feature Type: Road Asset		Area: South West Locality		
Batch: 41262158 - Inspection Batch		Route: Ad hoc Route			Date: 01/05/2026			
42205352	Pothole	01/05/2026	Just past the Edinburgh print makers building west bound lane	RD: CW Pothole	Internal	Committed	50196187	
Batch: 41261758 - Inspection Batch No actionable defects found		Route: SW_FW1_Dalry1			Date: 27/04/2026			
Batch: 41260278 - Inspection Batch No actionable defects found		Route: SfP_SouthWest			Date: 07/04/2026			
Batch: 41259868 - Inspection Batch No actionable defects found		Route: SW_FW1_Dalry1			Date: 31/03/2026			
Batch: 41259254 - Inspection Batch		Route: Ad hoc Route			Date: 25/03/2026			
42202955	Pothole west bound	25/03/2026	Opposite the new co-op shop	RD: CW Pothole	Internal	Committed	50194522	
Batch: 41257743 - Inspection Batch No actionable defects found		Route: SfP_SouthWest			Date: 11/03/2026			
Batch: 41256737 - Inspection Batch		Route: Ad hoc Route			Date: 04/03/2026			
42201167	Pothole	04/03/2026	Just on corner at entrance to west approach	RD: CW Pothole	Internal	Committed	50193239	
Batch: 41256289 - Inspection Batch No actionable defects found		Route: SW_FW1_Dalry1			Date: 02/03/2026			
Batch: 41253966 - Inspection Batch		Route: SW_CW1_North1			Date: 18/02/2026			
42199769	1no missing Sfp bollard 1no dislodged Sfp base	18/02/2026	Opposite fountain park fry	RD: SFP Damaged Bollard	Internal	Committed	50192135	
Batch: 41253280 - Inspection Batch		Route: Ad hoc Route			Date: 13/02/2026			
42199365	Pothole and manhole	13/02/2026	Outside old school wear shop	RD: CW Pothole	Internal	Committed	50191796	
Batch: 41253276 - Inspection Batch		Route: Ad hoc Route			Date: 13/02/2026			
42199361	Pothole	13/02/2026	Outside fettle bikes	RD: CW Pothole	Internal	Committed	50191792	
Batch: 41251870 - Inspection Batch No actionable defects found		Route: SW_FW1_Dalry1			Date: 04/02/2026			
Batch: 41251761 - Inspection Batch		Route: Ad hoc Route			Date: 04/02/2026			
42198485	4 areas needing hra overlay	04/02/2026	Opposite Victoria Paris	RD: CW Pothole	Internal	Committed	50191099	
Batch: 41251187 - Inspection Batch		Route: Ad hoc Route			Date: 30/01/2026			
42198088	Cover has come away exposing inside of toby on carriageway	30/01/2026	Outside fountain park exit junction	RU: Utility Apparatus	Internal	Uncommitted	50190781	
Batch: 41248405 - Inspection Batch No actionable defects found		Route: SfP_SouthWest			Date: 14/01/2026			
Batch: 41247918 - Inspection Batch		Route: Ad hoc Route			Date: 12/01/2026			
42196400	Cracked broken road surface	12/01/2026	Outside school wear shop	RD: CW Cracked/Broken	Internal	Uncommitted	50189490	

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W			Feature Type: Road Asset		Area: South West Locality	
Batch:	41247188 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 07/01/2026	
No actionable defects found								
Batch:	41244771 - Inspection Batch			Route: SfP_SouthWest			Date: 16/12/2025	
42195340	1no dislodged Sfp base	16/12/2025	Opposite Gibson terrace	RD: SFP Damaged Bollard	Internal		Committed	50188552
Batch:	41244075 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 08/12/2025	
No actionable defects found								
Batch:	41244027 - Inspection Batch			Route: Ad hoc Route			Date: 08/12/2025	
42194863	Scottish water Toby on carriageway cover loose and broken off in middle of carriageway	08/12/2025	On junction leaving fountain park	RU: Utility Apparatus	Internal		Uncommitted	50188207
Batch:	41243126 - Inspection Batch			Route: Ad hoc Route			Date: 28/11/2025	
42194253	Pothole	28/11/2025	Outside fettle bike shop	RD: CW Pothole	Internal		Committed	50187730
Batch:	41242140 - Inspection Batch			Route: SfP_SouthWest			Date: 20/11/2025	
No actionable defects found								
Batch:	41241316 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 12/11/2025	
No actionable defects found								
Batch:	41241230 - Inspection Batch			Route: SW_CW1_North1			Date: 11/11/2025	
No actionable defects found								
Batch:	41238717 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 14/10/2025	
No actionable defects found								
Batch:	41238639 - Inspection Batch			Route: SfP_SouthWest			Date: 14/10/2025	
No actionable defects found								
Batch:	41236820 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 16/09/2025	
42190016	Sunken water Toby on footway	16/09/2025	Outside fettle	RU: Utility Apparatus	Internal		Uncommitted	50184839
Batch:	41236297 - Inspection Batch			Route: Ad hoc Route			Date: 09/09/2025	
42189846	Bt manhole sunken loose and noisy	09/09/2025	Outside 123 on care	RU: Utility Apparatus	Internal		Uncommitted	50184682
Batch:	41236250 - Inspection Batch			Route: SfP_SouthWest			Date: 09/09/2025	
No actionable defects found								
Batch:	41234896 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 18/08/2025	
42188587	1 rocking slab	18/08/2025	Outside the fountain	RD: FW Slabs Rocking	Internal		Committed	50183701
Batch:	41234287 - Inspection Batch			Route: SfP_SouthWest			Date: 07/08/2025	
No actionable defects found								
Batch:	41234020 - Inspection Batch			Route: SW_CW1_North1			Date: 31/07/2025	
No actionable defects found								
Batch:	41233014 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 15/07/2025	
No actionable defects found								

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W			Feature Type: Road Asset		Area: South West Locality	
Batch: 41232575 - Inspection Batch				Route: SfP_SouthWest		Date: 09/07/2025		
No actionable defects found								
Batch: 41231323 - Inspection Batch				Route: Ad hoc Route		Date: 18/06/2025		
42185789	Scottish water Toby sunken	18/06/2025	Inbetween fettle and kwick fit on footway	RU: Utility Apparatus	Internal		Uncommitted	50181664
Batch: 41230980 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 16/06/2025		
No actionable defects found								
Batch: 41229884 - Inspection Batch				Route: Ad hoc Route		Date: 04/06/2025		
42184927	Pothole around manhole on footway	04/06/2025	Beside Edinburgh printers build	RD: FW HRA Pothole	Internal		Committed	50180840
Batch: 41229623 - Inspection Batch				Route: SfP_SouthWest		Date: 29/05/2025		
No actionable defects found								
Batch: 41228625 - Inspection Batch				Route: Ad hoc Route		Date: 19/05/2025		
42183807	Remove signs pole with no sign on it	19/05/2025	On footway at side of victor pairs	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180086
Batch: 41228027 - Inspection Batch				Route: Ad hoc Route		Date: 12/05/2025		
42183283	Reset dislodged Sfp base	12/05/2025	Opposite Gibson terrace	RD: SFP Damaged Bollard	Internal		Committed	50179797
Batch: 41227489 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 05/05/2025		
No actionable defects found								
Batch: 41227397 - Inspection Batch				Route: SW_CW1_North1		Date: 02/05/2025		
No actionable defects found								
Batch: 41227130 - Inspection Batch				Route: SfP_SouthWest		Date: 01/05/2025		
42182578	1no missing bollard	30/04/2025	At lamppost DLE16	RD: SFP Damaged Bollard	Internal		Committed	50179315
Batch: 41225159 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 03/04/2025		
No actionable defects found								
Batch: 41225101 - Inspection Batch				Route: SfP_SouthWest		Date: 03/04/2025		
42180653	Missing bollard	03/04/2025	Opposite building site	RD: SFP Damaged Bollard	Internal		Committed	50178144
Batch: 41221433 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 05/03/2025		
No actionable defects found								
Batch: 41221428 - Inspection Batch				Route: SfP_SouthWest		Date: 05/03/2025		
No actionable defects found								
Batch: 41221167 - Inspection Batch				Route: Ad hoc Route		Date: 03/03/2025		
42177565	Pothole	03/03/2025	Opposite David Phillips car sales	RD: CW Pothole	Internal		Committed	50176219
Batch: 41220871 - Inspection Batch				Route: Ad hoc Route		Date: 27/02/2025		
42177310	3 potholes	27/02/2025	Opposite usave shop	RD: CW Pothole	Internal		Committed	50176040
Batch: 41220870 - Inspection Batch				Route: Ad hoc Route		Date: 27/02/2025		
42177309	Potholes	27/02/2025	Outside fountain news shop	RD: CW Pothole	Internal		Committed	50176039

Effective: 17/01/2025 to 16/07/2026
 Service: Roads General
 Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.:	Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41220869 - Inspection Batch			Route:	Ad hoc Route		Date:	27/02/2025
42177308	Potholes	27/02/2025	Opposite fountain news shop	RD: CW Pothole	Internal		Committed	50176038
Batch:	41219170 - Inspection Batch			Route:	SW_CW1_North1		Date:	14/02/2025
	No actionable defects found							
Batch:	41217425 - Inspection Batch			Route:	SW_FW1_Dalry1		Date:	04/02/2025
42174833	Pothole	04/02/2025	Outside be uniforms	RD: CW Pothole	Internal		Committed	50174184
Batch:	41217218 - Inspection Batch			Route:	SfP_SouthWest		Date:	03/02/2025
42174638	2no missing bollards	03/02/2025	Outside Fountainpark fry	RD: SFP Damaged Bollard	Internal		Committed	50174052
Batch:	41215187 - Inspection Batch			Route:	Ad hoc Route		Date:	17/01/2025
42173352	Potholes	17/01/2025	Just beside cycle lane at Kwick fit	RD: CW Pothole	Internal		Committed	50173084

Customer Services

Enquiry No.: 34010005 **Logged by:** [REDACTED] **on:** 04/06/2025 08:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Hi [REDACTED] please pass this damaged traffic sensor loop cabinet to traffic signals. It has been flattened in accident with vehicle. (cones put out by inspector)
Location: Opposite kwick fit **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 31603827 **Logged by:** [REDACTED] **on:** 03/09/2025 15:49
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: Please log on Confirm database for an inspector to visit site and arrange for the installation of a new no through road sign face, foundation and post thanks
Location: **Contact:**

Enquiry No.: 2174075 **Logged by:** Verint CRM Connector **on:** 04/07/2026 00:28
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Loose and sunken manhole cover. Eastbound cycle lane on Dundee Street as approaching junction with Viewforth. Opposite Boroughmuir High School **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 2172782 **Logged by:** Verint CRM Connector **on:** 01/07/2026 23:08
Service: Roads General **Subject:** RS Pedestrian Crossing Request **Classification:** General Enquiry
Desc.: Problem: This is a known dangerous area where accidents have already occurred and yet there is still not a suitable pedestrian crossing in place. Visibility is limited and it is constantly busy. A zebra crossing or lights which force cars to stop and give way to pedestrians would make it a much safer road to cross..
Location: S T FOOD & WINE, 155, DUNDEE STREET, EDINBURGH, EH11 1BP **Contact:**

Enquiry No.: 2165372 **Logged by:** Verint CRM Connector **on:** 18/06/2026 15:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: more potholes than road. Very difficult and dangerous to drive and cycle on this busy road. Damaged my car twice! **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Customer Services



Enquiry No.: 2142477	Logged by: Verint CRM Connector	on: 05/05/2026 19:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Diagonal to Scotmid Coop	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2141317	Logged by: Verint CRM Connector	on: 04/05/2026 08:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Pothole on westbound carriageway	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2139631	Logged by: Verint CRM Connector	on: 30/04/2026 19:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Pothole in middle of the lane outside Scott Arthur's office @ 139 Dundee St. West direction. Damaged my bike.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Customer Services

Enquiry No.: 2135088	Logged by: Verint CRM Connector	on: 22/04/2026 16:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pothole on the road	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2101224	Logged by: Verint CRM Connector	on: 24/02/2026 11:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The entire length of the road from Fountainbridge to Ardmillan is blighted with potholes	Contact:	
Enquiry No.: 2098750	Logged by: Verint CRM Connector	on: 19/02/2026 19:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole in road, getting bigger daily	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2096515	Logged by: Verint CRM Connector	on: 16/02/2026 20:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole is located on dundee street when you turn left from henderson street towards fountain bridge , It's massive and	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2095371	Logged by: Verint CRM Connector	on: 15/02/2026 09:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road has degraded, becoming a pothole.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2095216	Logged by: Verint CRM Connector	on: 14/02/2026 19:39
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pothole. But it's a square one, so looks like it been dug up for work and never been filled in.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2095190	Logged by: Verint CRM Connector	on: 14/02/2026 18:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The whole Road is an absolute disgrace full of massive potholes - very dangerous	Contact:	

Effective: 17/01/2025 to 16/07/2026
Service: Roads General
Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 2094699 **Logged by:** Verint CRM Connector **on:** 13/02/2026 17:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Westbound cway of Dundee St outside Be Uniform store opp Victor Paris Bathrooms. Road surface has broken up around a manhole cover + there are also 2 large potholes between the failing manhole cover and centre line of road. **Contact:**

Enquiry No.: 2094578 **Logged by:** Verint CRM Connector **on:** 13/02/2026 14:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on the road **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 2094354 **Logged by:** Verint CRM Connector **on:** 13/02/2026 10:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple large potholes across entire westbound carriageway on Dundee St, outside the clothing/workwear shop. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 2092526 **Logged by:** Verint CRM Connector **on:** 11/02/2026 10:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole across the west bound road. Deep pothole need to slow to a newr stop with hazard lights on or wait until oncoming traffic ceases and drive in the other side of the road. Very dangerous **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 2088376 **Logged by:** Verint CRM Connector **on:** 04/02/2026 08:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Giant hole in centre of the road west bound. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Job Number: 50191099 **Defect Number:** 42198485

Enquiry No.: 2082008 **Logged by:** Verint CRM Connector **on:** 23/01/2026 19:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot hole next to bus stop **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Enquiry No.: 2080884 **Logged by:** Verint CRM Connector **on:** 22/01/2026 00:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the whole section of road is covered in potholes **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 9 - From Gilmore Park west & north-west to slip road to W **Feature Type:** Road Asset

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Customer Services

Enquiry No.: 2074009	Logged by: Verint CRM Connector	on: 11/01/2026 12:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large deep pothole across the whole west bound carriageway. Cannot be avoided. Road surface deteriorating day by day. Unsafe for vehicles and cyclists. Very dangerous. Needs urgent repair.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50189490	Defect Number: 42196400	
Enquiry No.: 2054568	Logged by: Verint CRM Connector	on: 08/12/2025 07:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole at crossing island	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50188207	Defect Number: 42194863	
Enquiry No.: 2049734	Logged by: Verint CRM Connector	on: 27/11/2025 11:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Polehole was on the road	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50187730	Defect Number: 42194253	
Enquiry No.: 2048901	Logged by: Verint CRM Connector	on: 26/11/2025 03:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This road needs to be checked its really bad and needs to be re surfaced asap	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 2011931	Logged by:	on: 10/09/2025 11:30
Service: Roads General	Subject: Road Safety: General Enquiry	Classification: General Enquiry
Desc.: speed bumps or reduce speed lights sign or give way sign to cyclists - would be appreciated as vehicle drivers - doing up to 50/60 MPH heading up to flyover		
Location: junction of dundee street and western approach road	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Enquiry No.: 1984005	Logged by:	on: 23/07/2025 15:08
Service: Roads General	Subject: Fence: Damaged / Defective	Classification: Request for service
Desc.: could the metal barriers that used to block off a perilous drop at the Telfer Subway could be put back, Precisely two metal barriers are required. They're actually sitting near the top of Telfer Subway doing nothing.		
Location: next to stairs At the telfer subway going down towards dalry and western approach road	Contact:	
Enquiry No.: 1965044	Logged by:	on: 17/06/2025 18:52
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: can you please remove this cone next to Fettle on Dundee Street?		
Location: cone next to Fettle on Dundee Street	Contact:	

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Customer Services

Enquiry No.: 1965029	Logged by:	on: 17/06/2025 18:21
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: an you please remove this cone next to Sainsbury's on Dundee Street?		
Location: dundee street	Contact:	
Enquiry No.: 1957936	Logged by: Verint CRM Connector	on: 03/06/2025 14:30
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush		
Location: A narrow pavement is almost entirely blocked due to overgrowing plants.	Contact:	
Enquiry No.: 1956135	Logged by: Verint CRM Connector	on: 30/05/2025 14:40
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown. Location:Pavement. Type:Foliage / Bush		
Location: A large foilage/tree has grown next to the existing tree, in the metal tree ring on Viewforth, at the junction with Dundee Street, outside Boroughmuir High School.	Contact:	
It is occupying part of the pavement and causing an obstruction. Can you please arrange to have it removed.		
Thank you		
Enquiry No.: 1949792	Logged by: Verint CRM Connector	on: 18/05/2025 19:42
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit End sign on Lampost bent. This is at the very end of Dundee Street where it meets the exit from approach Road.		
Location: End sign on Lampost bent. This is at the very end of Dundee Street where it meets the exit from approach Road.	Contact:	
Enquiry No.: 1949710	Logged by: Verint CRM Connector	on: 18/05/2025 16:15
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Pole with no sign. This is to the side of victor palace near to their car park entrance.		
Location: Pole with no sign. This is to the side of victor Paris near to car park.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50180086	Defect Number: 42183807	
Enquiry No.: 1916249	Logged by: Verint CRM Connector	on: 11/03/2025 09:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large area or potholes heading towards the traffic lights just outside the BE Uniform shop	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset

Effective: 17/01/2025 to 16/07/2026
Service: Roads General
Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1912028	Logged by: Verint CRM Connector	on: 02/03/2025 22:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Lots of pot holes heading down the hill towards the traffic lights	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50176219	Defect Number: 42177565	
Enquiry No.: 1910255	Logged by: Verint CRM Connector	on: 26/02/2025 20:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot holes heading west bound near the junction at Fowler terrace	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset
Job Number: 50176038	Defect Number: 42177308	
Enquiry No.: 1910254	Logged by: Verint CRM Connector	on: 26/02/2025 19:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 9 - From Gilmore Park west & north-west to slip road to W	Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W		Feature Type: Road Asset		Area: South West Locality	
50172356	Pothole (RD: CW Pothole)	Near western approach on ramp	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2025	17/01/2025	Act. ROAD/82100353
50173084	Potholes (RD: CW Pothole)	Just beside cycle lane at Kwick fit	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2025	21/01/2025	Act. ROAD/82100929
50174052	2no missing bollards (RD: SFP Damaged Bollard)	Outside Fountainpark fry	RD: Cat 3 - 60 Day	Job Complete	03/02/2025	10/02/2025	Act. ROAD/82101638
50174184	Pothole (RD: CW Pothole)	Outside be uniforms	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2025	05/02/2025	Act. ROAD/82101737
50176038	Potholes (RD: CW Pothole)	Opposite fountain news shop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	27/02/2025	28/02/2025	Act. ROAD/82103292

Effective: 17/01/2025 to 16/07/2026
 Service: Roads General
 Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W			Feature Type: Road Asset		Area: South West Locality
50176039	Potholes (RD: CW Pothole)	Outside fountain news shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	28/02/2025	Act. ROAD/82103293
50176040	3 potholes (RD: CW Pothole)	Opposite usave shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	25/03/2025	Act. ROAD/82103294
50176219	Pothole (RD: CW Pothole)	Opposite David Phillips car sales	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2025	08/03/2025	Act. ROAD/82103443
50178144	Missing bollard (RD: SFP Damaged Bollard)	Opposite building site	RD: Cat 3 - 60 Day	Job Complete	03/04/2025	08/04/2025	Act. ROAD/82104832
50179315	1no missing bollard (RD: SFP Damaged Bollard)	At lamppost DLE16	RD: Cat 3 - 60 Day	Job Complete	30/04/2025	30/04/2025	Act. ROAD/82105573
50179797	Reset dislodged Sfp base (RD: SFP Damaged Bollard)	Opposite Gibson terrace	RD: Cat 3 - 60 Day	Job Complete	12/05/2025	14/05/2025	Act. ROAD/82105960
50180086	Remove signs pole with no sign on it (RD: Unlit Sign Damaged/Missing)	On footway at side of victor pairs	RD: Cat 3 - 60 Day	Job Complete	19/05/2025	12/07/2025	Act. ROAD/82106148
50180840	Pothole around manhole on footway (RD: FW HRA Pothole)	Beside Edinburgh printers build	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/06/2025	04/06/2025	Act. ROAD/82106635
50183701	1 rocking slab (RD: FW Slabs Rocking)	Outside the fountain	RD: Cat 3 - 60 Day	Job Complete	18/08/2025	20/08/2025	Act. ROAD/82108425
50187730	Pothole (RD: CW Pothole)	Outside fettle bike shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2025	01/12/2025	Act. ROAD/82111070
50188552	1no dislodged Sfp base (RD: SFP Damaged Bollard)	Opposite Gibson terrace	RD: Cat 3 - 60 Day	Job Complete	16/12/2025	17/12/2025	Act. ROAD/82111700
50191099	4 areas needing hra overlay (RD: CW Pothole)	Opposite Victoria Paris	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2026	08/03/2026	Act. ROAD/82113759
50191792	Pothole (RD: CW Pothole)	Outside fettle bikes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2026	20/02/2026	Act. ROAD/82114339
50191796	Pothole and manhole (RD: CW Pothole)	Outside old school wear shop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/02/2026	17/02/2026	Act. ROAD/82114342
50192135	1no missing Sfp bollard 1no dislodged Sfp base (RD: SFP Damaged Bollard)	Opposite fountain park fry	RD: Cat 3 - 60 Day	Job Complete	18/02/2026	19/02/2026	Act. ROAD/82114643
50193239	Pothole (RD: CW Pothole)	Just on corner at entrance to west approach	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/03/2026	08/03/2026	Act. ROAD/82115577
50194522	Pothole west bound (RD: CW Pothole)	Opposite the new co-op shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/03/2026	27/03/2026	Act. ROAD/82116580
50196187	Pothole (RD: CW Pothole)	Just past the Edinburgh print makers building west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117878
50196189	2 areas needing hra overlay (RD: CW Pothole)	Outside fettle beside cycle lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117880
50196190	Pothole (RD: CW Pothole)	Opposite Sainsbury's next to bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117881
50196191	Reset Sfp bollard back to position (RD: SFP Damaged Bollard)	Opposite Gibson terrace junction east bound lane	RD: Cat 3 - 60 Day	Job Complete	01/05/2026	04/05/2026	Act. ROAD/82117882

Effective: 17/01/2025 to 16/07/2026

Service: Roads General

Site: Dundee Street (7902795)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 9 - From Gilmore Park west & north-west to slip road to W			Feature Type: Road Asset		
					Area: South West Locality		
50196193	Pothole (RD: CW Pothole)	Outside library west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117883
50196194	Potholes (RD: CW Pothole)	Outside Scott Arthur mp	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117884
50196962	Pothole (RD: CW Pothole)	Outside Edinburgh print makers	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2026	18/05/2026	Act. ROAD/82118460
50196964	Pothole (RD: CW Pothole)	Just after fowler terrace junction west bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2026	18/05/2026	Act. ROAD/82118462
50196965	Various areas in Need of hra overlay (RD: CW Pothole)	Opposite victor Paris	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2026	18/05/2026	Act. ROAD/82118463