

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Locality: South Queensferry, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street except cyclepath/footpath		Feature Type: Road Asset		Area: North West Locality		
Batch: 41258715 - Inspection Batch		Route: Ad hoc Route		Date: 20/03/2026				
42202568	1 number pothole	20/03/2026	Before gantry heading north	RD: CW Pothole	Internal	Committed	50194244	
Batch: 41258495 - Inspection Batch		Route: Ad hoc Route		Date: 18/03/2026				
42202393	1 number pothole	18/03/2026	About 50m from entrance to Miller & Carter	RD: CW Pothole	Internal	Committed	50194126	
Batch: 41258490 - Inspection Batch		Route: Ad hoc Route		Date: 18/03/2026				
42202389	1 number pothole	18/03/2026	Bottom of slip road on A90 heading towards Barnton	RD: CW Pothole	Internal	Committed	50194122	
Batch: 41258080 - Inspection Batch		Route: Mobile Inspection Strategic		Date: 15/03/2026				
42202059	1no pothole	15/03/2026	Southbound lane next to bus priority sign	RD: CW Pothole	Internal	Committed	50193890	
42202060	1no pothole	15/03/2026	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: CW Pothole	Internal	Committed	50193891	
Batch: 41257231 - Inspection Batch No actionable defects found		Route: North Mobile Inspection Route		Date: 09/03/2026				
Batch: 41257205 - Inspection Batch		Route: Mobile Inspection Strategic		Date: 08/03/2026				
42201537	1no pothole	08/03/2026	No reference point please use pin location Southbound lane	RD: CW Pothole	Internal	Committed	50193507	
42201536	1no pothole	08/03/2026	Northbound lane 20m before B924 slip road	RD: CW Pothole	Internal	Committed	50193506	
Batch: 41256035 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic		Date: 01/03/2026				
Batch: 41254649 - Inspection Batch		Route: Mobile Inspection Strategic		Date: 22/02/2026				
42200236	1no Cw pothole	22/02/2026	On northbound Lane under information gantry Check pin location	RD: CW Pothole	Internal	Committed	50192541	
42200235	1no Cw pothole	22/02/2026	Check pin location	RD: CW Pothole	Internal	Committed	50192540	
Batch: 41253579 - Inspection Batch		Route: Mobile Inspection Strategic		Date: 15/02/2026				
42199536	1no pothole	15/02/2026	Northbound underneath the large sign gantry	RD: CW Pothole	Internal	Committed	50191943	
42199535	1no pothole	15/02/2026	City bound lane at Bus Priority sign	RD: CW Pothole	Internal	Committed	50191942	
Batch: 41253557 - Inspection Batch		Route: Ad hoc Route		Date: 14/02/2026				
42199519	Pothole left lane	14/02/2026	A90 city bound after the Dalmeny bus stop where the tarmac turns red.	RD: CW Pothole	Internal	Committed	50191926	

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street except cyclepath/footpath			Feature Type: Road Asset		Area: North West Locality	
Batch: 41253556 - Inspection Batch			Route: Ad hoc Route			Date: 14/02/2026		
42199518	Pothole (phoned into emergency line 0131 200 2000 as category 1	14/02/2026	Left lane of a90 just before the slip to b924	RD: CW Pothole	Internal		Committed	50191925

Customer Services

Enquiry No.: 2114787
Service: Roads General
Desc.:
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 17/03/2026 20:36
Classification: Request for service

Location: Hit a massive pothole on the slow lane coming from miller and carter heading to the forth road bridge. Was about half way along the road from miller and carter to the bridge before the corner that goes into the tunnel area. Probably just after the over pass i think its for kirkliston. Im sure the road is orange around the area. It was dark i could not see but there was a massive bang. It happened on sat 14th about 8.30pm. I previously reported it to west lothian council. They sent me here.

Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street except cyclepath/footpath
Feature Type: Road Asset

Enquiry No.: 2114614
Service: Roads General
Desc.:
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 17/03/2026 15:50
Classification: Request for service

Location: From: [REDACTED]
Subject: Report defect form
Message Body:
Email: [REDACTED]
Phone: [REDACTED]
Enquiry type: Pothole
Road: A90 Dalmeny to Scotstoun
Attachment: [your-file]
Precise Location: Near bus stop just above Dalmeny Village on A90 north-west bound carriage way. Inside lane on nearside.

Contact:

Message Body:
Unable to take picture as driving. Pothole is large and sharp-edged. Likely to damage wheels and/or cause punctures.

Enquiry No.: 2114605
Service: Roads General
Desc.:
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 17/03/2026 15:45
Classification: Request for service

Location: Large pothole (would sink a tyre) on the carriageway heading down towards miller and Carter. You will see it once you have left the slip road to join the main carriageway.

Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street except cyclepath/footpath
Feature Type: Road Asset

Job Number: 50194122
Defect Number: 42202389

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2114095

Service: Roads General

Desc.:

Location: Deep pothole between slip road from Dalmeny and A90

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 17/03/2026 07:31

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113753

Service: Roads General

Desc.:

Location: 3 huge pot holes on slow lane near bus lane put to the Queensferry junction joining on the bend

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 16/03/2026 15:38

Classification: Request for service

Contact:

3 huge craters in the inside lane on the a90 after the speed limit drops to 50 mph going into Edinburgh prior to lane joining at the bend from south Queensferry.

Going to cause an accident as cars are taking avoidance action at last minute or risk damage to their vehicles.

I've reported these to Amy & bear and they said they're not responsible for the road but you are.

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113396

Service: Roads General

Desc.:

Location: A90 Southbound

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 16/03/2026 10:35

Classification: Request for service

Contact:

Precise Location: A90 road as you take left exit and carry on towards miller and carter cramond brig, southbound after Queensferry crossing.

Message:

Yesterday, 8-10 cars were on the side of the road due to burst tires from the pot holes caused by the A90 road when you take the left exit to continue on to Queensferry Road / Cramond on the A90. Someone needs to do something! Videos and photos circulating online.

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113226

Service: Roads General

Desc.:

Location: On the right lane on A90 leading into Edinburgh there is a huge pothole. Very dangerous

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 16/03/2026 07:47

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2113150

Service: Roads General

Desc.:

Location: I drove past FIVE cars that had broken down and couldn't drive this evening because of this pothole it's not safe anymore!!!

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 21:21

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113139

Service: Roads General

Desc.:

Location: Massive potholes on this road!

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 20:48

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113127

Service: Roads General

Desc.:

Location: East bound potholes, inside lane appear to have caused punctures / wheel damage to at least 4 cars

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 20:30

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113110

Service: Roads General

Desc.:

Location: Driving tonight- Sunday 15th March at 7pm drove through a huge pot hole on left lane. There was at least 10 other cars that had to stop on hard shoulder with hazard lights on. My cars tyre has been badly damaged

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 19:41

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2113083

Service: Roads General

Desc.:

Location: Two large potholes on A90 towards Edinburgh. Inside lane shortly after split from M90

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 18:54

Classification: Request for service

Contact:

Enquiry No.: 2112980

Service: Roads General

Desc.:

Location: There's a massive pothole on the left lane of the road heading east

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/03/2026 15:35

Classification: Request for service

Contact:

Enquiry No.: 2112749

Service: Roads General

Desc.:

Location: Deep pot hole

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 14/03/2026 20:47

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2112655 **Logged by:** Verint CRM Connector **on:** 14/03/2026 17:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A90 Crammond to the Queensferry Bridge, an absolute disgrace. Full of pot holes. **Contact:**
Threat to life and causing significant damage to property.

Enquiry No.: 2112575 **Logged by:** Verint CRM Connector **on:** 14/03/2026 12:42
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Huge pothole northbound right under the overhead noticeboard gantry **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2111817 **Logged by:** Verint CRM Connector **on:** 13/03/2026 07:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and deep pothole on inside lane. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2108870 **Logged by:** Verint CRM Connector **on:** 09/03/2026 08:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are several wide and deep potholes in Queensferry road towards M90 starting from just before B 924 exit (the widest and deepest) along the way up until the first motorway gantry before entering M90. These have been deteriorating over time and now quite dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2105387 **Logged by:** Verint CRM Connector **on:** 02/03/2026 22:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple pot holes on carriage way older surface in left hand lane along this stretch **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2104726 **Logged by:** Verint CRM Connector **on:** 02/03/2026 07:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2104724 **Logged by:** Verint CRM Connector **on:** 02/03/2026 07:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2101593

Service: Roads General

Desc.:

Location: Huge pothole. Caused tyre blowout.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 24/02/2026 18:55

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2101012

Service: Roads General

Desc.:

Location: A90 from Edinburgh to Dunfermline. Cannot stop to take a photo cars going with high speed

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 24/02/2026 07:51

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100963

Service: Roads General

Desc.:

Location: Huge pothole. In fact this whole road from Barnton to the M9 flyover is a covered in them. It's a disgrace!

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 22:02

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100892

Service: Roads General

Desc.:

Location: There are a few bad potholes on the left hand side of the road just after the dalmeny slip road after you go under the bridge. I hit two today!

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 19:42

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100877

Service: Roads General

Desc.:

Location: There are a number of potholes and sunken dips in the main road left side just after the spur turnoff. It's after you leave the bridge heading into Edinburgh. Please can this be checked and fixed. Impossible to miss a lot of them and at night it's really bad.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 19:26

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100860

Service: Roads General

Desc.:

Location: There is an awful pothole which is causing cars to swerve which is going to cause an accident! I've looked at maps and the most recent photo is two years ago, you can see there was a temporary repair done then in the exact same spot so it's clearly not helped. 2 years is more than enough time to carry out a more permanent repair!!

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 19:03

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2100846

Service: Roads General

Desc.:

Location: I hit a pot hole and got a flat tyre on the A90 somewhere between the Burnshot bridge and the layby opposite dalmeny before slip road on to M90

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 18:22

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100819

Service: Roads General

Desc.:

Location: I hit a pothole on the slow lane of the westbound carriageway heading from Edinburgh to Queensferry Crossing this afternoon. Thankfully I don't appear to have any obvious damage to my car but unfortunately another driver might not be so lucky so this really needs to be addressed as soon as possible. I'd also like to express my shock at the roads in general in and around Edinburgh.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 17:51

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2100484

Service: Roads General

Desc.:

Location: Pot hole in middle of road, straddling both lanes

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 11:37

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2099831

Service: Roads General

Desc.:

Location: There is a big pothole on the motorway just before the turn off towards Craigies Farm, heading north. It's in the left hand lane and immediately after driving over it my tyre warning came on and later I noticed by tyre was deflating and needed a replacement.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 22/02/2026 09:23

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2098123

Service: Roads General

Desc.:

Location: Potholes-lots all along the burnshot road.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 18/02/2026 21:55

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2097316

Service: Roads General

Desc.:

Location: Depression in road near gantry queensferry road northbound

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 17/02/2026 20:42

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2097302

Service: Roads General

Desc.:

Location: There is a sagging tarmac on A90 heading towards Quensferry Bridge. The sagging tarmac is in the left lane where the asphalt change is (end of the grey one and beginning of the red one). Before the overhead bridge. See the photo with the location attached

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 17/02/2026 20:14

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2095537

Service: Roads General

Desc.:

Location: Pothole in lane 1

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/02/2026 14:42

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2095331

Service: Roads General

Desc.:

Location: I can't pinpoint the location and I don't know if the A90 and road into Edinburgh is the responsibility of BEAR or Edin council, but this road and all the way into ferry road is full of large potholes causing cars to swerve to avoid and must be ultra dangerous for those on motorbikes.

Please review the whole route from M90/A90 interchanges into queensferry Road and down as far as Telford Road and even onto ferry Road, at Telford / Ferry Road roundabout there is a massive hole just at roundabout

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/02/2026 08:20

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Enquiry No.: 2092764

Service: Roads General

Desc.:

Location: A90 city bound after the Dalmeny bus stop where the tarmac turns red, the entire red section is littered with massive previously repaired potholes.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 11/02/2026 13:53

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Job Number: 50191926

Defect Number: 42199519

Enquiry No.: 2092576

Service: Roads General

Desc.:

Location: Huge pothole in the middle of the dual carriageway. Car suffered damage to suspension as a result.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 11/02/2026 11:04

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street except cyclepath/footpath

Feature Type: Road Asset

Job Number: 50191925

Defect Number: 42199518

Site History Report

Effective: 10/02/2026 to 20/03/2026

Service: Roads General

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street except cyclepath/footpath		Feature Type: Road Asset		Area: North West Locality	
50176954	Replace missing and damaged anti glare bollards (RD: Bollard Damage/Missing/New)	Central reservation at slip road to Kirkliston	RD: Cat 3 - 60 Day	Job Committed	14/03/2025	06/06/2025	Est. ROAD/82104024
50191925	Pothole (phoned into emergency line 0131 200 2000 as category 1 (RD: CW Pothole)	Left lane of a90 just before the slip to b924	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	14/02/2026	15/02/2026	Act. ROAD/82114457
50191926	Pothole left lane (RD: CW Pothole)	A90 city bound after the Dalmeny bus stop where the tarmac turns red,	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2026	17/02/2026	Act. ROAD/82114458
50191942	1no pothole (RD: CW Pothole)	City bound lane at Bus Priority sign	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/02/2026	17/02/2026	Act. ROAD/82114474
50191943	1no pothole (RD: CW Pothole)	Northbound underneath the large sign gantry	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/02/2026	18/02/2026	Act. ROAD/82114475
50192540	1no Cw pothole (RD: CW Pothole)	Check pin location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2026	23/02/2026	Act. ROAD/82115009
50192541	1no Cw pothole (RD: CW Pothole)	On northbound Lane under information gantry Check pin location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2026	23/02/2026	Act. ROAD/82115010
50193506	1no pothole (RD: CW Pothole)	Northbound lane 20m before B924 slip road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2026	10/03/2026	Act. ROAD/82115784
50193507	1no pothole (RD: CW Pothole)	No reference point please use pin location Southbound lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2026	10/03/2026	Act. ROAD/82115785
50193890	1no pothole (RD: CW Pothole)	Southbound lane next to bus priority sign	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	15/03/2026	Act. ROAD/82116090
50193891	1no pothole (RD: CW Pothole)	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	18/03/2026	Act. ROAD/82116091
50194122	1 number pothole (RD: CW Pothole)	Bottom of slip road on A90 heading towards Barnton	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2026	31/03/2026	Act. ROAD/82116275
50194126	1 number pothole (RD: CW Pothole)	About 50m from entrance to Miller & Carter	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/03/2026	21/03/2026	Act. ROAD/82116279
50194244	1 number pothole (RD: CW Pothole)	Before gantry heading north	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/03/2026	21/03/2026	Act. ROAD/82116365