

Defect Number	42033891	Date	04/07/2019 08:47:21	Target Date	00/00/0000
Site	Dundas Street		7901760		
	New Town, Edinburgh, City of Edinburgh				
Asset Id		Location	Ward 11 - From Heriot Row to Fettes Row		
Asset Number	2.00	Road Asset			
Description	Cracked and broken asphalt surface approx 2m x 3m		Work Location	At junction with heriot row in northbound lane at pedestrian crossing	
Cust. Ref.			Estimated Cost	0.00	
Raised by Officer					
Observe Type			Defect Status	Superseded by 42070964	
Defect Type	RD02	RD: CW Cracked/Broken	Rating	.0000	
Organisation					
Priority	RD: Cat 4 - Programmed				
Defect Notes	Imported Defect via Connector		From	.00	To .00
			From and To Distance Supplied	☐	
			XSP		
Raise Job	☐				
Job Number		Contract			
Cost Code					
Officer					
Inspection Batch No	41035778	Inspection Batch			