

Defect Number	42070964	Date	10/06/2021 15:02:40	Target Date	00/00/0000
Site	Dundas Street			7901760	
New Town, Edinburgh, City of Edinburgh					
Asset Id				Location	Ward 11 - From Heriot Row to Fettes Row
Asset Number	2.00 Road Asset				
Description	Cracked and broken asphalt surface approx 2m x 3m			Work Location	At junction with heriot row in northbound lane at pedestrian crossing
Cust. Ref.				Estimated Cost	0.00
Raised by Officer				Supersedes Defect	42033891
Observe Type				Defect Status	Superseded by 42103451
Defect Type	RD02 RD: CW Cracked/Broken			Rating	.0000
Organisation					
Priority	RD: Cat 4 - Programmed				
Defect Notes	Imported Defect via Connector			From	.00
				To	.00
				From and To Distance Supplied	☐
				XSP	
Raise Job	☐				
Job Number	Contract				
Cost Code					
Officer					
Inspection Batch No	41094080 Inspection Batch				