

Defect Number	42103451	Date	15/06/2022 14:31:36	Target Date	00/00/0000
Site	Dundas Street			7901760	
	New Town, Edinburgh, City of Edinburgh				
Asset Id		Location	Ward 11 - From Heriot Row to Fettes Row		
Asset Number	2.00 Road Asset				
Description	Cracked and broken asphalt surface approx 2m x 3m		Work Location	At junction with heriot row in northbound lane at pedestrian crossing	
Cust. Ref.			Estimated Cost	0.00	
Raised by Officer			Supersedes Defect	42070964	
Observe Type			Defect Status	Superseded by 42135498	
Defect Type	RD02 RD: CW Cracked/Broken		Rating	.0000	
Organisation					
Priority	RD: Cat 4 - Programmed				
Defect Notes	Imported Defect via Connector		From	.00	To .00
			From and To Distance Supplied ☐		
			XSP		
Raise Job	☐				
Job Number		Contract			
Cost Code					
Officer					
Inspection Batch No	41125934	Inspection Batch			