

Site History Report

Effective: 10/03/2026 to 15/03/2026

Display Action Officer: No

Asset Number: 1.00 to 1.00

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Locality: South Queensferry, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street except cyclepath/footpath			Feature Type: Road Asset		Area: North West Locality	
Batch: 41258080 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 15/03/2026	
42202059	1no pothole	15/03/2026	Southbound lane next to bus priority sign	RD: CW Pothole	Internal		Committed	50193890
42202060	1no pothole	15/03/2026	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: CW Pothole	Internal		Committed	50193891

Customer Services

Enquiry No.: 2113180 **Logged by:** Verint CRM Connector **on:** 15/03/2026 22:43
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.:
Location: Heading into Edinburgh on the Queensferry Road, farm on the left. Just outside Dalmany estate. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2113150 **Logged by:** Verint CRM Connector **on:** 15/03/2026 21:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: I drove past FIVE cars that had broken down and couldn't drive this evening because of this pothole it's not safe anymore!!! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2113139 **Logged by:** Verint CRM Connector **on:** 15/03/2026 20:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive potholes on this road! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2113127 **Logged by:** Verint CRM Connector **on:** 15/03/2026 20:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: East bound potholes, inside lane appear to have caused punctures / wheel damage to at least 4 cars **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2113110 **Logged by:** Verint CRM Connector **on:** 15/03/2026 19:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Driving tonight- Sunday 15th March at 7pm drove through a huge pot hole on left lane. There was at least 10 other cars that had to stop on hard shoulder with hazard lights on. My cars tyre has been badly damaged **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Site History Report

Effective: 10/03/2026 to 15/03/2026

Display Action Officer: No

Asset Number: 1.00 to 1.00

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Customer Services

Enquiry No.: 2113083 **Logged by:** Verint CRM Connector **on:** 15/03/2026 18:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two large potholes on A90 towards Edinburgh. Inside lane shortly after split from M90 **Contact:**

Enquiry No.: 2112980 **Logged by:** Verint CRM Connector **on:** 15/03/2026 15:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There's a massive pothole on the left lane of the road heading east **Contact:**

Enquiry No.: 2112965 **Logged by:** Verint CRM Connector **on:** 15/03/2026 14:43
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.:
Location: I was driving from s queensferry to cramond. Along the a90 after the section where the road was resurfaced and maybe a mile before the turn off to kirkliston i went over a pothole which immediately resulted in a flat tyre. I came off the a90 to assess the damage and drove slowly to my destination of cramond [REDACTED]. After [REDACTED] i tried calling the manufacturers car garage who noted their service department is closed on a Sunday. I used a local mobile tyre fitting service **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2112749 **Logged by:** Verint CRM Connector **on:** 14/03/2026 20:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pot hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2112655 **Logged by:** Verint CRM Connector **on:** 14/03/2026 17:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A90 Crammond to the Queensferry Bridge, an absolute disgrace. Full of pot holes. Threat to life and causing significant damage to property. **Contact:**

Enquiry No.: 2112575 **Logged by:** Verint CRM Connector **on:** 14/03/2026 12:42
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Huge pothole northbound right under the overhead noticeboard gantry **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Enquiry No.: 2111817 **Logged by:** Verint CRM Connector **on:** 13/03/2026 07:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and deep pothole on inside lane. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street except cyclepath/footpath **Feature Type:** Road Asset

Site History Report

Effective: 10/03/2026 to 15/03/2026

Display Action Officer: No

Asset Number: 1.00 to 1.00

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street except cyclepath/footpath		Feature Type: Road Asset		Area: North West Locality	
50176954	Replace missing and damaged anti glare bollards (RD: Bollard Damage/Missing/New)	Central reservation at slip road to Kirkliston	RD: Cat 3 - 60 Day	Job Committed	14/03/2025	06/06/2025	Est. ROAD/82104024
50181930	Approximately 1x8m patch (RD: CW Cracked/Broken)	At bus priority measures sign south lane	RD: Cat 4 - Programmed	Job Complete	24/06/2025	30/04/2026	Act.
50193506	1no pothole (RD: CW Pothole)	Northbound lane 20m before B924 slip road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2026	10/03/2026	Act. ROAD/82115784
50193507	1no pothole (RD: CW Pothole)	No reference point please use pin location Southbound lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2026	10/03/2026	Act. ROAD/82115785
50193890	1no pothole (RD: CW Pothole)	Southbound lane next to bus priority sign	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	15/03/2026	Act. ROAD/82116090
50193891	1no pothole (RD: CW Pothole)	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	18/03/2026	Act. ROAD/82116091