

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Site: Princes Street (7903151)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place		Feature Type: Road Asset		Area: South East Locality		
Batch:	41267658 - Inspection Batch No actionable defects found		Route: SfP_CityCentre				Date:	17/07/2026
Batch:	41267313 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route				Date:	15/07/2026
Batch:	41267184 - Inspection Batch		Route: Ad hoc Route				Date:	14/07/2026
42211070	4 x rocking flags	14/07/2026	Opposite Hotter	RD: FW Slabs Rocking	Internal		Committed	50199901
Batch:	41267183 - Inspection Batch		Route: Ad hoc Route				Date:	14/07/2026
42211068	3 x rocking flags	14/07/2026	Opposite Lush	RD: FW Slabs Rocking	Internal		Committed	50199899
Batch:	41267177 - Inspection Batch		Route: Ad hoc Route				Date:	14/07/2026
42211061	2 x rocking flags 2 x rocking off cuts	14/07/2026	Opposite Vodafone	RD: FW Slabs Rocking	Internal		Committed	50199897
Batch:	41267172 - Inspection Batch		Route: Ad hoc Route				Date:	14/07/2026
42211060	Cw cracked and broken permanent patch required 2 x 1.5	14/07/2026	Outside Edinburgh bus tours	RD: CW Cracked/Broken	Internal		Committed	50199896
Batch:	41267170 - Inspection Batch		Route: Ad hoc Route				Date:	14/07/2026
42211059	3 x rocking tactile Rest 1 x raised tackle	14/07/2026	Outside 3 store	RD: FW Slabs Rocking	Internal		Committed	50199895
Batch:	41267117 - Inspection Batch		Route: Ad hoc Route				Date:	13/07/2026
42211053	1 x rocking 1 x broken off cut	13/07/2026	Outside 3 store	RD: FW Slabs Rocking	Internal		Committed	50199888
Batch:	41267115 - Inspection Batch		Route: Ad hoc Route				Date:	13/07/2026
42211051	2 x rocking 1 x broken	13/07/2026	Outside Day-today	RD: FW Slabs Rocking	Internal		Committed	50199886
Batch:	41267114 - Inspection Batch		Route: Ad hoc Route				Date:	13/07/2026
42211050	2 x rocking flags 1 x broken	13/07/2026	Outside Waterstone	RD: FW Slabs Rocking	Internal		Committed	50199885
Batch:	41267113 - Inspection Batch		Route: Ad hoc Route				Date:	13/07/2026
42211049	4 x rocking perfect flags	13/07/2026	Outside Mountain warehouse	RD: FW Slabs Rocking	Internal		Committed	50199884
Batch:	41266731 - Inspection Batch		Route: Ad hoc Route				Date:	07/07/2026
42210683	Defective Scottish water cover on cw photos attached	07/07/2026	Princess Street at south st David's street east bound inside lane on edge of box junction previous repairs by Scottish water	RU: Utility Apparatus	Internal		Uncommitted	50199661
Batch:	41266564 - Inspection Batch		Route: Ad hoc Route				Date:	03/07/2026
42210381	Relay 4 x rocking slabs at bus stop	03/07/2026	Outside Mount Royal Hotel	RD: FW Slabs Rocking	Internal		Committed	50199472

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41266563 - Inspection Batch		Route: SE_FW1_Princes1			Date: 03/07/2026			
42210417	2no broken pefecta slabs 4no rocking perfecta slabs	03/07/2026	Outside H&M shop	RD: FW Slabs Broken/Missing	Internal		Committed	50199500
42210402	1no rocking perfecta slab	03/07/2026	Next to boots	RD: FW Slabs Rocking	Internal		Committed	50199492
42210384	2no broken pefecta slabs 4no rocking perfecta slabs	03/07/2026	At pedestrian crossing outside H&M	RD: FW Slabs Broken/Missing	Internal		Committed	50199475
42210383	1no rocking perfecta slab	03/07/2026	Outside old Top shop - Top man shop	RD: FW Slabs Rocking	Internal		Committed	50199474
42210379	4no rocking perfecta slabs	03/07/2026	Outside Sainsbury's local	RD: FW Slabs Rocking	Internal		Committed	50199470
42210404	7no broken perfecta slabs 11no rocking perfecta slabs	03/07/2026	At junction with castle street	RD: FW Slabs Broken/Missing	Internal		Committed	50197574
42210385	Approx 12m x 2.5m broken and rocking pefecta slabs	03/07/2026	Outside H&M	RD: FW Slabs Broken/Missing	Internal		Committed	50199476
42210401	2no broken perfecta slab 1no rocking perfecta slab	03/07/2026	Outside boots	RD: FW Slabs Broken/Missing	Internal		Committed	50199491
42210394	1no rocking perfecta slab	03/07/2026	Outside Great Scot	RD: FW Slabs Rocking	Internal		Committed	50199484
42210399	2no broken perfecta slab 1no rocking perfecta slab	03/07/2026	Outside IWC	RD: FW Slabs Broken/Missing	Internal		Committed	50199489
42210390	Remove bike rack plates and sockets and renew 14 number perfecta flags	03/07/2026	At bus stop PK	RD:BikeRack Damage/Missing/N	Internal		Committed	50197367
42210400	4no broken perfecta slab	03/07/2026	Outside swatch	RD: FW Slabs Broken/Missing	Internal		Committed	50199490
42210416	1no dislodged kerb	03/07/2026	At junction with North bridge at island	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50197457
42210386	1no rocking perfecta slab	03/07/2026	Outside H&M	RD: FW Slabs Rocking	Internal		Committed	50199477
42210387	1no rocking perfecta slab	03/07/2026	Outside smiggle shop	RD: FW Slabs Rocking	Internal		Committed	50199478
42210406	12no rocking perfecta slabs	03/07/2026	Outside premier Inn	RD: FW Slabs Rocking	Internal		Committed	50197564
42210405	6no broken perfecta slabs 7no rocking perfecta slabs	03/07/2026	Outside Starbucks	RD: FW Slabs Broken/Missing	Internal		Committed	50197570
42210397	1no rocking perfecta slab	03/07/2026	Outside primark	RD: FW Slabs Rocking	Internal		Committed	50199487
42210392	3no rocking perfecta slabs	03/07/2026	At bus stop PK	RD: FW Slabs Rocking	Internal		Committed	50199482
42210403	1no broken perfecta slab	03/07/2026	Outside old Levi's shop	RD: FW Slabs Broken/Missing	Internal		Committed	50199493
42210388	3no broken pefecta slabs 7no rocking perfecta slabs	03/07/2026	Outside Balmoral country wear	RD: FW Slabs Broken/Missing	Internal		Committed	50199479
42210382	5no broken pefecta slabs 9no rocking perfecta slabs	03/07/2026	Outside Black sheep coffee	RD: FW Slabs Broken/Missing	Internal		Committed	50199473
42210395	1no rocking perfecta slab	03/07/2026	Outside Fraser hart	RD: FW Slabs Rocking	Internal		Committed	50199485
42210398	2nno rocking perfecta slabs	03/07/2026	Outside Blackford sheep coffee	RD: FW Slabs Rocking	Internal		Committed	50199488
42210389	2no broken / missing charcoal tactile slabs	03/07/2026	Pedestrian crossing at junction with south St David's street	RD: FW Slabs Broken/Missing	Internal		Committed	50199480
42210380	5no rocking perfecta slabs	03/07/2026	Outside EE shop	RD: FW Slabs Rocking	Internal		Committed	50199471
42210393	5no rocking perfecta slabs	03/07/2026	Outside Marks & Spencer	RD: FW Slabs Rocking	Internal		Committed	50199483
42210396	1no rocking perfecta slab	03/07/2026	Outside accesorize	RD: FW Slabs Rocking	Internal		Committed	50199486
42210415	2no rocking courtstone slabs	03/07/2026	Outside Balmoral hotel	RD: FW Slabs Rocking	Internal		Committed	50199499
42210407	1no broken perfecta slab 1no rocking perfecta slab	03/07/2026	Outside urban outfitters	RD: FW Slabs Broken/Missing	Internal		Committed	50199494

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41266562 - Inspection Batch		Route: Ad hoc Route			Date: 03/07/2026			
42210378	Replace 1 x missing perfecta slab 1 x broken	03/07/2026	Outside H&M	RD: FW Slabs Broken/Missing	Internal		Committed	50199469
Batch: 41266561 - Inspection Batch		Route: Ad hoc Route			Date: 03/07/2026			
42210377	Really rocking slab	03/07/2026	Outside number 42a	RD: FW Slabs Rocking	Internal		Committed	50199468
Batch: 41266021 - Inspection Batch		Route: Ad hoc Route			Date: 24/06/2026			
42209752	Sunken fire hydrant at bus stop	24/06/2026	Outside 120 the works shop east bound	RU: Utility Apparatus	Internal		Uncommitted	50199046
Batch: 41265853 - Inspection Batch		Route: Ad hoc Route			Date: 22/06/2026			
42209464	Defective Scottish water cover on cw photos attached	22/06/2026	Princess st east bound inside lane os 135 pret	RU: Utility Apparatus	Internal		Uncommitted	50198861
Batch: 41265074 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 08/06/2026			
Batch: 41264835 - Inspection Batch		Route: Ad hoc Route			Date: 04/06/2026			
42208139	Parking: Other - Plate required to cover hole as there is not one inside the socket (Enquiry 34010976)	04/06/2026	Outside the Apple Store	NSL: Pole Sign Remove Defect	Internal		Committed	50198012
Batch: 41264793 - Inspection Batch No actionable defects found		Route: SfP_CityCentre			Date: 04/06/2026			
Batch: 41264346 - Inspection Batch		Route: Ad hoc Route			Date: 29/05/2026			
42207578	3no rocking perfecta slabs	29/05/2026	At junction with Hanover street outside Fraser hart	RD: FW Slabs Rocking	Internal		Committed	50197670
Batch: 41264171 - Inspection Batch		Route: Ad hoc Route			Date: 27/05/2026			
42207344	2 x sunken Scottish water covers on footpath photos attached	27/05/2026	Outside 140	RU: Utility Apparatus	Internal		Uncommitted	50197516
Batch: 41264150 - Inspection Batch		Route: Ad hoc Route			Date: 27/05/2026			
42207339	Sunken manhole cover on carriageway photos attached	27/05/2026	Opposite McDonald	RU: Utility Apparatus	Internal		Uncommitted	50197511
Batch: 41264145 - Inspection Batch		Route: Ad hoc Route			Date: 27/05/2026			
42207320	Sunken manhole cover on carriageway photos attached	27/05/2026	Opposite junction of South St David Street	RU: Utility Apparatus	Internal		Uncommitted	50197499
Batch: 41264144 - Inspection Batch		Route: Ad hoc Route			Date: 27/05/2026			
42207318	Sunken Scottish water manhole cover on carriageway photos attached	27/05/2026	At junction of South St David Street	RU: Utility Apparatus	Internal		Uncommitted	50197497
Batch: 41264101 - Inspection Batch		Route: Ad hoc Route			Date: 27/05/2026			
42207293	Potholes at manhole on pedestrian crossing overlay as required	27/05/2026	Opposite Black Sheep Coffee	RD: CW Pothole	Internal		Committed	50197477
Batch: 41264042 - Inspection Batch		Route: Ad hoc Route			Date: 26/05/2026			
42207237	Sunken loose and noisy Scottish water fire hydrant on carriageway photos attached	26/05/2026	Outside number 109	RU: Utility Apparatus	Internal		Uncommitted	50197424

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place		Feature Type: Road Asset		Area: South East Locality		
Batch: 41264040 - Inspection Batch		Route: Ad hoc Route		Date: 26/05/2026				
42207231	1 number pothole at fire hydrant	26/05/2026	At bus stop PD	RD: CW Pothole	Internal		Committed	50197419
Batch: 41264011 - Inspection Batch		Route: Ad hoc Route		Date: 26/05/2026				
42207169	Remove bike rack plates and sockets and renew 14 number perfecta flags	26/05/2026	At bus stop PK	RD:BikeRack Damage/Missing/N	Internal		No Action Required	
Batch: 41263996 - Inspection Batch		Route: Ad hoc Route		Date: 26/05/2026				
42207155	Failed Scottish power reinstatement on footpath photos attached	26/05/2026	At junction of South St David Street	RU: Utility Reinstatement	Internal		Uncommitted	50197362
Batch: 41263982 - Inspection Batch		Route: Ad hoc Route		Date: 26/05/2026				
42207132	Sunken Virgin Media manhole cover on footpath photos attached	26/05/2026	Outside Black Sheep Coffee	RU: Utility Apparatus	Internal		Uncommitted	50197350
Batch: 41263981 - Inspection Batch		Route: Ad hoc Route		Date: 26/05/2026				
42207131	Sunken Double Vodafone manhole cover on footpath photos attached	26/05/2026	Outside Black Sheep Coffee	RU: Utility Apparatus	Internal		Uncommitted	50197349
Batch: 41263959 - Inspection Batch		Route: SE_FW1_Princes1		Date: 28/05/2026				
42207285	1no broken 900 x 600 pcc slab	27/05/2026	Opposite Sainsbury's local at waverly mall	RD: FW Slabs Broken/Missing	Internal		Committed	50197470
42207216	1no broken perfecta slab	26/05/2026	Outside swatch	RD: FW Slabs Broken/Missing	Internal		Committed	50197408
42207278	1no broken 750 x 600 courtstone slab	27/05/2026	At junction with North bridge outside Balmoral hotel	RD: FW Slabs Broken/Missing	Internal		Committed	50197463
42207187	8no broken perfecta slabs	26/05/2026	At junction with Hanover street outside Fraser hart	RD: FW Slabs Broken/Missing	Internal		Committed	50197379
42207401	3no rocking perfecta slabs	28/05/2026	Outside card factory	RD: FW Slabs Rocking	Internal		Committed	50197568
42207354	5no broken 450 x 450 perfecta slabs	27/05/2026	Outside 132 princes st	RD: FW Slabs Broken/Missing	Internal		Committed	50197526
42207200	1no broken perfecta soap	26/05/2026	Outside mini so shop	RD: FW Slabs Broken/Missing	Internal		Committed	50197392
42207349	1no sunken cut pcc slab slab	27/05/2026	Pedestrian crossing outside Pret A Manger	RD: FW Slabs Rocking	Internal		Committed	50197521
42207322	2no sunken pcc slabs at box	27/05/2026	At bus stop PR	RD: FW Slabs Rocking	Internal		Committed	50197501
42207279	2no broken 750 x 600 courtstone slabs	27/05/2026	Outside Balmoral hotel prince bar	RD: FW Slabs Broken/Missing	Internal		Committed	50197464
42207186	4no rocking perfecta slabs	26/05/2026	At pedestrian crossing outside Dr martens shop	RD: FW Slabs Rocking	Internal		Committed	50197378
42207411	3no rocking perfecta slabs	28/05/2026	Outside Vodafone shop	RD: FW Slabs Rocking	Internal		Committed	50197575
42207271	1no dislodged kerb	27/05/2026	At junction with North bridge at island	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42207152	1no rocking perfecta slab	26/05/2026	Outside pride of Edinburgh shop	RD: FW Slabs Rocking	Internal		Committed	50197360
42207414	5no rocking perfecta slabs	28/05/2026	Outside Hotter	RD: FW Slabs Rocking	Internal		Committed	50197578
42207208	2no rocking perfecta slab	26/05/2026	Outside black sheep coffee	RD: FW Slabs Rocking	Internal		Committed	50197400
42207136	8no rocking perfecta slabs	26/05/2026	Next to pedestrian crossing Opposite waverly market / waverly bridge	RD: FW Slabs Rocking	Internal		Committed	50197354
42207346	1no rocking pcc slab	27/05/2026	Outside McDonald's	RD: FW Slabs Rocking	Internal		Committed	50197518

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place		Feature Type: Road Asset		Area: South East Locality		
Batch: 41263959 - Inspection Batch		Route: SE_FW1_Princes1				Date: 28/05/2026		
42207334	2no rocking pcc slabs	27/05/2026	At bus stop Pv	RD: FW Slabs Rocking	Internal		Committed	50197506
42207194	1no rocking perfecta slab	26/05/2026	Outside Clark's shop	RD: FW Slabs Rocking	Internal		Committed	50197386
42207275	4no dislodged kerb Replace cold tar with 3no cut courtstone slabs	27/05/2026	At junction with North bridge outside Balmoral hotel	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50197461
42207205	3no rocking perfecta slabs	26/05/2026	Outside Claire's	RD: FW Slabs Rocking	Internal		Committed	50197397
42207267	1no broken tactile at kerb edge	27/05/2026	At junction with North bridge at pedestrian crossing	RD: FW Slabs Broken/Missing	Internal		Committed	50197453
42207295	1no broken cut 300 x 600 pcc slab 1no sunken 450 x 600 pcc slab	27/05/2026	At bus stop PQ	RD: FW Slabs Broken/Missing	Internal		Committed	50197478
42207270	1no rocking pcc slab	27/05/2026	Outside Waverley gate	RD: FW Slabs Rocking	Internal		Committed	50197456
42207234	1no rocking perfecta slab	26/05/2026	Outside Edinburgh gift vault	RD: FW Slabs Rocking	Internal		Committed	50197422
42207180	2no broken perfecta slabs 9no rocking perfecta slabs	26/05/2026	Outside Marks & Spencer	RD: FW Slabs Broken/Missing	Internal		Committed	50197372
42207146	3no broken perfecta slabs 4no rocking perfecta slabs	26/05/2026	Outside H&M shop	RD: FW Slabs Rocking	Internal		Committed	50197359
42207347	4no rocking pcc slab	27/05/2026	Outside jollibee	RD: FW Slabs Rocking	Internal		Committed	50197519
42207319	1no Fw Grano pothole	27/05/2026	At Scott's monument	RD: FW Grano Pothole	Internal		Committed	50197498
42207214	2no rocking perfecta slab 2no broken perfecta slabs	26/05/2026	Outside IWC	RD: FW Slabs Rocking	Internal		Committed	50197406
42207188	2no fw potholes at channel	26/05/2026	Outside Fraser hart	RD: FW HRA Pothole	Internal		Committed	50197380
42207298	3no broken 900 x 600 pcc slabs 4no rocking pcc slabs 2no areas of missing grano at 2 boxes	27/05/2026	Outside Costa coffee opposite old Top man shop	RD: FW Slabs Broken/Missing	Internal		Committed	50197482
42207176	3no rocking perfecta slabs	26/05/2026	Outside mount royal hotel	RD: FW Slabs Rocking	Internal		Committed	50197369
42207232	Remove broken grano at box and replace with 2no 450 x 450 perfecta slabs 1no broken perfecta slab 10no rocking perfecta slabs	26/05/2026	Next to Levi's shop	RD: FW Slabs Broken/Missing	Internal		Committed	50197420
42207292	1no broken 750 x 600 pcc slab 1no broken 600 x 600 pcc slab	27/05/2026	Opposite EE near bus stop PQ	RD: FW Slabs Broken/Missing	Internal		Committed	50197476
42207154	3no rocking perfecta slabs	26/05/2026	outside Balmoral countrywear shop	RD: FW Slabs Rocking	Internal		Committed	50197361
42207338	1no broken 900 x 600 pcc slab 1no rocking cut pcc slab	27/05/2026	Opposite jollibee	RD: FW Slabs Broken/Missing	Internal		Committed	50197510
42207403	6no broken perfecta slabs 7no rocking perfecta slabs	28/05/2026	Outside Starbucks	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42207198	1no rocking perfecta slab	26/05/2026	Outside Skechers	RD: FW Slabs Rocking	Internal		Committed	50197390
42207196	1no rocking perfecta slab	26/05/2026	Outside Regus	RD: FW Slabs Rocking	Internal		Committed	50197388
42207128	2no rocking perfecta slabs	26/05/2026	At bus stop PM outside Holland and Barrett shop	RD: FW Slabs Rocking	Internal		Committed	50197346
42207139	Approx 12m x 2m replace all broken perfecta slabs	26/05/2026	Outside H&M shop	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50197357
42207412	5no rocking perfecta slabs	28/05/2026	Outside Lush	RD: FW Slabs Rocking	Internal		Committed	50197576

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41263959 - Inspection Batch			Route: SE_FW1_Princes1			Date: 28/05/2026		
42207332	1no Fw Grano strip at rear of Fw	27/05/2026	At bus stop PU	RD: FW Grano Pothole	Internal		Committed	50197504
42207397	12no rocking perfecta slabs	28/05/2026	Outside premier Inn	RD: FW Slabs Rocking	Internal		No Action Required	
42207239	5no broken perfecta slabs	26/05/2026	At junction with castle street	RD: FW Slabs Broken/Missing	Internal		Committed	50197426
	4no rocking perfecta slabs							
	1no rocking tactile							
42207399	2no broken perfecta slabs	28/05/2026	Outside The works	RD: FW Slabs Broken/Missing	Internal		Committed	50197566
	2no rocking perfecta slabs							
42207121	2no perfecta slabs	26/05/2026	Next to pedestrian crossing opposite Balmoral hotel	RD: FW Slabs Rocking	Internal		Committed	50197343
42207345	1no Fw Grano pothole	27/05/2026	Outside thistle and co	RD: FW Grano Pothole	Internal		Committed	50197517
42207336	Broken grano on Fw surrounding Nal box	27/05/2026	Opposite popeyes	RD: FW Grano Cracked/Broken	Internal		Committed	50197508
42207360	1no broken perfecta slab	27/05/2026	Outside 125	RD: FW Slabs Broken/Missing	Internal		Committed	50197532
	6no rocking perfecta slabs							
42207351	4no broken 450 x 450 perfecta slabs	27/05/2026	Outside 3 shop	RD: FW Slabs Broken/Missing	Internal		Committed	50197523
	11no rocking perfecta slabs							
42207348	1no. Broken 900 x 600 pcc slab	27/05/2026	Outside Pret a manger	RD: FW Slabs Broken/Missing	Internal		Committed	50197520
42207184	1no rocking perfecta slab	26/05/2026	Outside isle of tweed shop	RD: FW Slabs Rocking	Internal		Committed	50197376
42207398	1no rocking perfecta slab	28/05/2026	Outside no120b	RD: FW Slabs Rocking	Internal		Committed	50197565
42207317	1no rocking scoutmoor slab	27/05/2026	Opposite H&M	RD: FW Slabs Rocking	Internal		Committed	50197496
42207125	7no rocking perfecta slabs	26/05/2026	At junction with west register street	RD: FW Slabs Rocking	Internal		Committed	50197345
42207207	1no rocking perfecta slabs	26/05/2026	Outside primark	RD: FW Slabs Rocking	Internal		Committed	50197399
42207195	3no rocking perfecta slabs	26/05/2026	Outside Superdrug	RD: FW Slabs Rocking	Internal		Committed	50197387
42207130	3no rocking perfecta slabs	26/05/2026	Outside Black sheep coffee shop at pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50197348
42207193	1no rocking perfecta slab	26/05/2026	Outside office shop	RD: FW Slabs Rocking	Internal		Committed	50197385
42207225	1no broken perfecta slab	26/05/2026	West of bus stop PE	RD: FW Slabs Broken/Missing	Internal		Committed	50197415
	2no rocking perfecta slabs							
42207350	2no rocking tactile slabs box insert	27/05/2026	At traffic island at junction of Charlotte street	RD: FW Slabs Rocking	Internal		Committed	50197522
42207301	1no rocking scoutmoor slab	27/05/2026	Outside Waverley market	RD: FW Slabs Rocking	Internal		Committed	50197484
42207341	1no. Broken cut Caithness slab	27/05/2026	Outside johnnie walker	RD: FW Slabs Broken/Missing	Internal		Committed	50197513
	8no sunken / rocking Caithness slabs							
42207321	2no sunken pcc slabs at box	27/05/2026	At Scott's monument	RD: FW Slabs Rocking	Internal		Committed	50197500
42207282	1no rocking pcc slab	27/05/2026	Next to entrance into Waverley train station	RD: FW Slabs Rocking	Internal		Committed	50197467
42207280	2no rocking courtstone slabs	27/05/2026	Outside Balmoral hotel	RD: FW Slabs Rocking	Internal		Committed	50197465
42207135	1no rocking perfecta slab	26/05/2026	At south St Andrews street outside old Top man shop	RD: FW Slabs Rocking	Internal		Committed	50197353
	5no sunken / uneven tactile slabs							
42207283	2no broken cut pcc slabs	27/05/2026	At bus stop PP	RD: FW Slabs Broken/Missing	Internal		Committed	50197468
	2no rocking cut pcc slabs							
42207409	7no broken perfecta slabs	28/05/2026	At junction with castle street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
	11no rocking perfecta slabs							

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 3.00		Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41263959 - Inspection Batch			Route: SE_FW1_Princes1			Date: 28/05/2026		
42207343	Remove cold tar and replace with 1no cut 900 x 600 pcc slab And Renew grano at box	27/05/2026	Outside Tesco express	RD: FW Slabs Broken/Missing	Internal		Committed	50197515
42207223	2no broken perfecta slabs 2no rocking perfecta slabs	26/05/2026	From bus stop PE to boots	RD: FW Slabs Broken/Missing	Internal		Committed	50197413
42207391	2no broken perfecta slabs	28/05/2026	Outside mountain warehouse	RD: FW Slabs Broken/Missing	Internal		Committed	50197531
42207287	2no broken 900 x 600 pcc slabs	27/05/2026	Opposite hotel indigo	RD: FW Slabs Broken/Missing	Internal		Committed	50197472
42207165	2no rocking perfecta slab	26/05/2026	Opposite Scott's monument outside old Jenners building either side of pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50197365
42207337	1no rocking pcc slab	27/05/2026	Next to information box at entrance into public toilets	RD: FW Slabs Rocking	Internal		Committed	50197509
42207266	1no rocking pcc slab	27/05/2026	Outside Waverley gate	RD: FW Slabs Rocking	Internal		Committed	50197452
42207402	1no rocking perfecta slab	28/05/2026	At bus stop PC	RD: FW Slabs Rocking	Internal		Committed	50197569
42207182	3no broken perfecta slabs 5no rocking perfecta slabs	26/05/2026	Outside uni Qlo shop	RD: FW Slabs Broken/Missing	Internal		Committed	50197374
42207358	7no rocking perfecta slabs	27/05/2026	At bus stop PA	RD: FW Slabs Rocking	Internal		Committed	50197530
42207355	3no broken 450 x 450 perfecta slabs 5 rocking perfecta slabs	27/05/2026	Outside popeyes	RD: FW Slabs Broken/Missing	Internal		Committed	50197527
42207174	2no broken perfecta slabs 3no rocking perfecta slabs	26/05/2026	From bus stop PK to old Jenners building	RD: FW Slabs Broken/Missing	Internal		Committed	50197368
42207356	13 broken 450 x 450 perfecta slabs 6no rocking perfecta slabs	27/05/2026	Outside sports direct	RD: FW Slabs Broken/Missing	Internal		Committed	50197528
42207359	13 2no broken perfecta slabs	27/05/2026	Outside mountain warehouse	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42207185	1no rocking perfecta slab	26/05/2026	Outside three shop	RD: FW Slabs Rocking	Internal		Committed	50197377
42207364	5no broken perfecta slabs 4no rocking perfecta slabs	27/05/2026	Outside urban outfitters	RD: FW Slabs Broken/Missing	Internal		Committed	50197534
42207323	1no Fw Grano pothole	27/05/2026	Outside Royal Scottish academy opposite Hanover street	RD: FW Grano Pothole	Internal		Committed	50197502
42207211	7no rocking perfecta slabs	26/05/2026	Outside chisholm Hunter	RD: FW Slabs Rocking	Internal		Committed	50197403
42207352	1no broken 459 x 450 perfecta slab 2no rocking perfecta slabs	27/05/2026	Outside Day - today	RD: FW Slabs Broken/Missing	Internal		Committed	50197524
42207161	1no broken cut charcoal tactile 1no pothole infill with cold tar	26/05/2026	At pedestrian crossing at junction with south St David's street	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50197363
42207134	1no broken cut perfecta slab 3no rocking perfecta slabs 2no rocking tactile slabs	26/05/2026	At junction with south St Andrews street	RD: FW Slabs Rocking	Internal		Committed	50197352
42207217	1no broken perfecta slab	26/05/2026	Outside tweed & moor	RD: FW Slabs Broken/Missing	Internal		Committed	50197409
42207342	1no rocking pcc slab 1no grano pothole	27/05/2026	Outside Royal bank of Scotland	RD: FW Slabs Rocking	Internal		Committed	50197514
42207191	1no broken cut tactile slab 3no rocking tactile slabs 1no rocking perfecta slab	26/05/2026	Outside Blank street	RD: FW Slabs Broken/Missing	Internal		Committed	50197383

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41263959 - Inspection Batch				Route: SE_FW1_Princes1			Date: 28/05/2026	
42207203	2no rocking perfecta slab	26/05/2026	Outside burger king	RD: FW Slabs Rocking	Internal		Committed	50197395
Batch: 41263697 - Inspection Batch				Route: Ad hoc Route			Date: 21/05/2026	
42206887	2 x sunken Scottish water SV valves on carriageway photos attached	21/05/2026	Outside Costa Coffee	RU: Utility Apparatus	Internal		Uncommitted	50197195
Batch: 41263696 - Inspection Batch				Route: Ad hoc Route			Date: 21/05/2026	
42206886	2 number potholes at SV covers to make safe	21/05/2026	Outside Costa Coffee	RD: CW Pothole	Internal		Committed	50197194
Batch: 41263676 - Inspection Batch				Route: Ad hoc Route			Date: 21/05/2026	
42206845	Rest rocking flag	21/05/2026	Opposite Hotel Indigo	RD: FW Slabs Rocking	Internal		Committed	50197174
Batch: 41263580 - Inspection Batch				Route: Ad hoc Route			Date: 20/05/2026	
42206803	3no rocking perfecta slabs	20/05/2026	Outside Costa Coffee	RD: FW Slabs Rocking	Internal		Committed	50197149
Batch: 41263427 - Inspection Batch				Route: Ad hoc Route			Date: 19/05/2026	
42206635	1 number pothole in pedestrian crossing	19/05/2026	Opposite H&M	RD: CW Pothole	Internal		Committed	50197042
Batch: 41263391 - Inspection Batch				Route: Ad hoc Route			Date: 18/05/2026	
42206607	Defective Scottish water cover on cw photos attached Check la2241934	18/05/2026	Princess street east bound inside lane os 135	RU: Utility Apparatus	Internal		Uncommitted	50197016
Batch: 41263328 - Inspection Batch No actionable defects found				Route: SfP_CityCentre			Date: 15/05/2026	
Batch: 41263056 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206175	1 grano infill	12/05/2026	OPP Three Store	RD: FW Grano Open Joint	Internal		Committed	50196740
Batch: 41263055 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206174	1 rocking flag	12/05/2026	OPP Phone Spot	RD: FW Slabs Rocking	Internal		Committed	50196739
Batch: 41263054 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206173	1 rocking flag	12/05/2026	OPP Phone Spot	RD: FW Slabs Rocking	Internal		Committed	50196738
Batch: 41263053 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206172	2 rocking flags	12/05/2026	OPP Phone Spot	RD: FW Slabs Rocking	Internal		Committed	50196737
Batch: 41263052 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206171	1 rocking flag	12/05/2026	OPP Day Today	RD: FW Slabs Rocking	Internal		Committed	50196736
Batch: 41263051 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206170	1 rocking flag	12/05/2026	OPP Popeyes	RD: FW Slabs Rocking	Internal		Committed	50196735
Batch: 41263050 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206169	1 grano infill around bt chamber, frame adjustment, if possible	12/05/2026	OPP Sports Direct	RD: FW Grano Depression/Sunk	Internal		Committed	50196734
Batch: 41263049 - Inspection Batch				Route: Ad hoc Route			Date: 12/05/2026	
42206168	1 rocking flag, 1 grano infill	12/05/2026	OPP Scribbler	RD: FW Slabs Rocking	Internal		Committed	50196733

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41263048 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206167	17 rocking flags (at least a few broken 900x600s with cuts)	12/05/2026	OPP Superdrug	RD: FW Slabs Rocking	Internal		Committed	50196732
Batch: 41263047 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206166	2 rocking flags (broken cut, broken 900x600 cut)	12/05/2026	OPP Superdrug	RD: FW Slabs Rocking	Internal		Committed	50196731
Batch: 41263046 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206165	1 rocking flag (broken 900x600)	12/05/2026	OPP HMV	RD: FW Slabs Rocking	Internal		Committed	50196730
Batch: 41263045 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206164	4 rocking flags 1 grano infill (4 broken 900x600, 2 need cut)	12/05/2026	OPP HMV	RD: FW Slabs Rocking	Internal		Committed	50196729
Batch: 41263044 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206163	1 grano infill	12/05/2026	OPP Ann Summers	RD: FW Grano Depression/Sunk	Internal		Committed	50196728
Batch: 41263043 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206162	1 grano infill	12/05/2026	OPP Burger King	RD: FW Grano Depression/Sunk	Internal		Committed	50196727
Batch: 41263042 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206161	1 rocking flag (broken 900x600)	12/05/2026	OPP Claires	RD: FW Slabs Rocking	Internal		Committed	50196726
Batch: 41263013 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206159	1 rocking flag 1 grano infill (broken cut)	12/05/2026	OPP Primark	RD: FW Slabs Rocking	Internal		Committed	50196724
Batch: 41263012 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206158	1 rocking flag	12/05/2026	OPP Primark	RD: FW Slabs Rocking	Internal		Committed	50196723
Batch: 41263011 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206157	1 grano infill	12/05/2026	OPP Chisholm Hunter	RD: FW Grano Open Joint	Internal		Committed	50196722
Batch: 41263010 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206156	1 rocking flag	12/05/2026	OPP Chisholm Hunter	RD: FW Slabs Rocking	Internal		Committed	50196721
Batch: 41263009 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206155	2 grano infills	12/05/2026	OPP Frederick Street	RD: FW Grano Open Joint	Internal		Committed	50196720
Batch: 41263007 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206153	3 rocking slabs	12/05/2026	OPP Frederick Street	RD: FW Slabs Rocking	Internal		Committed	50196718
Batch: 41263006 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206152	2 rocking flags	12/05/2026	OPP IWC	RD: FW Slabs Rocking	Internal		Committed	50196717
Batch: 41263005 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206151	2 rocking flags	12/05/2026	OPP IWC	RD: FW Slabs Rocking	Internal		Committed	50196716
Batch: 41263004 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206150	1 rocking flag	12/05/2026	OPP Swatch	RD: FW Slabs Rocking	Internal		Committed	50196715

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41263003 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206149	3 rocking flags	12/05/2026	OPP Tweed and Moor	RD: FW Slabs Rocking	Internal		Committed	50196714
Batch: 41263000 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206146	3 rocking flags (2 broken 900x600)	12/05/2026	OPP Boots	RD: FW Slabs Rocking	Internal		Committed	50196711
Batch: 41262999 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206145	1 rocking flag	12/05/2026	OPP Boots	RD: FW Slabs Rocking	Internal		Committed	50196710
Batch: 41262997 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206143	3 rocking flags	12/05/2026	OPP Boots	RD: FW Slabs Rocking	Internal		Committed	50196708
Batch: 41262995 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206141	1 rocking flag	12/05/2026	OPP Construction Site	RD: FW Slabs Rocking	Internal		Committed	50196706
Batch: 41262993 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206139	1 rocking flag	12/05/2026	OPP Construction Site	RD: FW Slabs Rocking	Internal		Committed	50196704
Batch: 41262991 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206137	5 rocking flags 2 rocking kerb	12/05/2026	OPP Construction Site	RD: FW Slabs Rocking	Internal		Committed	50196702
Batch: 41262987 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206133	1 rocking flag	12/05/2026	OPP Levis	RD: FW Slabs Rocking	Internal		Committed	50196698
Batch: 41262985 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206131	19 rocking flags	12/05/2026	OPP 7 DaySmart	RD: FW Slabs Rocking	Internal		Committed	50196696
Batch: 41262984 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206130	5 rocking flags (1 broken 900x600)	12/05/2026	OPP 7 DaySmart	RD: FW Slabs Rocking	Internal		Committed	50196695
Batch: 41262983 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206129	2 rocking flags	12/05/2026	OPP House of Treasure	RD: FW Slabs Rocking	Internal		Committed	50196694
Batch: 41262982 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206128	3 rocking flags	12/05/2026	OPP Hotter Shoes	RD: FW Slabs Rocking	Internal		Committed	50196693
Batch: 41262979 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206125	2 rocking flags	12/05/2026	OPP Lush	RD: FW Slabs Rocking	Internal		Committed	50196690
Batch: 41262978 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206124	Rocking flag	12/05/2026	OPP Castle Street	RD: FW Slabs Rocking	Internal		Committed	50196689
Batch: 41262977 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206118	4 rocking flags	12/05/2026	OPP Castle Street	RD: FW Slabs Rocking	Internal		Committed	50196686
Batch: 41262975 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206109	7 rocking flags (1 broken cut)	12/05/2026	OPP Castle Street	RD: FW Slabs Rocking	Internal		Committed	50196682
Batch: 41262969 - Inspection Batch		Route: Ad hoc Route			Date: 12/05/2026			
42206094	2 rocking flags (1 broken cut)	12/05/2026	OPP Castle Street	RD: FW Slabs Rocking	Internal		Committed	50196676

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
	Asset: 3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
	Batch: 41262963 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206078	Joint pointed at bin should make good	12/05/2026	OPP Starbucks	RD: FW Grano Open Joint	Internal		Committed	50196671
	Batch: 41262960 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206074	1 rocking flag (damaged edge, possibly just point)	12/05/2026	OPP Samuels	RD: FW Slabs Rocking	Internal		Committed	50196667
	Batch: 41262959 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206073	1 rocking flag (broken 900x600)	12/05/2026	OPP Samuels	RD: FW Slabs Rocking	Internal		Committed	50196666
	Batch: 41262955 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206068	3 rocking flags	12/05/2026	OPP The Works	RD: FW Slabs Rocking	Internal		Committed	50196661
	Batch: 41262953 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206066	1 rocking flag	12/05/2026	OPP The Works	RD: FW Slabs Rocking	Internal		Committed	50196659
	Batch: 41262951 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206064	6 rocking flags (1 broken 900x600)	12/05/2026	OPP The Works	RD: FW Slabs Rocking	Internal		Committed	50196657
	Batch: 41262950 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206063	1 rocking flag (broken 900x600)	12/05/2026	OPP Premier Inn	RD: FW Slabs Rocking	Internal		Committed	50196656
	Batch: 41262949 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206061	3 rocking flags (1 broken 900x600)	12/05/2026	OPP Premier Inn	RD: FW Slabs Rocking	Internal		Committed	50196654
	Batch: 41262948 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206060	2 rocking flags	12/05/2026	OPP Bar + Block	RD: FW Slabs Rocking	Internal		Committed	50196653
	Batch: 41262947 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206059	2 rocking flags	12/05/2026	OPP Bar + Block	RD: FW Slabs Rocking	Internal		Committed	50196652
	Batch: 41262946 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206058	1 rocking flag (broken 900x600)	12/05/2026	OPP Bar + Block	RD: FW Slabs Rocking	Internal		Committed	50196651
	Batch: 41262941 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206050	2 rocking flags	12/05/2026	OPP Bar + Block	RD: FW Slabs Rocking	Internal		Committed	50196646
	Batch: 41262936 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206045	4 rocking flags (2 broken 900x600)	12/05/2026	OPP Urban Outfitters	RD: FW Slabs Rocking	Internal		Committed	50196641
	Batch: 41262933 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206042	1 rocking flag (broken 900x600)	12/05/2026	OPP Urban Outfitters	RD: FW Slabs Rocking	Internal		Committed	50196638
	Batch: 41262931 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206037	1 rocking flag	12/05/2026	OPP Urban Outfitters	RD: FW Slabs Rocking	Internal		Committed	50196633
	Batch: 41262929 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206031	3 rocking flags	12/05/2026	OPP Easy Hotel	RD: FW Slabs Rocking	Internal		Committed	50196629
	Batch: 41262928 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2026	
42206029	1 rocking flag	12/05/2026	OPP Waterstones	RD: FW Slabs Rocking	Internal		Committed	50196627

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41262927 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206026	6 rocking flags (including 1 broken 900x600)	12/05/2026	OPP Sports Direct	RD: FW Slabs Rocking	Internal		Committed	50196624
Batch: 41262926 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206025	2 rocking flags, grano infill	12/05/2026	OPP Sports Direct	RD: FW Slabs Rocking	Internal		Committed	50196623
Batch: 41262925 - Inspection Batch					Route: Ad hoc Route		Date: 12/05/2026	
42206021	1 flag	12/05/2026	OPP Popeyes	RD: FW Slabs Rocking	Internal		Committed	50196619
Batch: 41262760 - Inspection Batch No actionable defects found					Route: South Mobile Inspection Route		Date: 08/05/2026	
Batch: 41262156 - Inspection Batch					Route: SE_FW1_Princes1		Date: 01/05/2026	
42205350	1no broken perfecta slab 1no rocking perfecta slab	01/05/2026	Outside Costa coffee	RD: FW Slabs Broken/Missing	Internal		Committed	50196185
42205348	1no rocking perfecta slab	01/05/2026	Outside Balmoral shop	RD: FW Slabs Rocking	Internal		Committed	50196183
42205364	1no broken 900 x 600 pcc slab 3no rocking pcc slabs	01/05/2026	Opposite boots	RD: FW Slabs Broken/Missing	Internal		Committed	50196198
42205351	1no rocking perfecta slab	01/05/2026	Outside swatch shop	RD: FW Slabs Rocking	Internal		Committed	50196186
42205353	1no rocking perfecta slab	01/05/2026	Outside urban outfitters shop	RD: FW Slabs Rocking	Internal		Committed	50196188
42205363	1no broken cross cut 900 x 600 pcc slab	01/05/2026	At pedestrian crossing opposite castle street	RD: FW Slabs Broken/Missing	Internal		Committed	50196197
Batch: 41261704 - Inspection Batch					Route: Ad hoc Route		Date: 24/04/2026	
42204880	1 number pothole	24/04/2026	Outside Mountain Warehouse	RD: CW Pothole	Internal		Committed	50195897
Batch: 41261702 - Inspection Batch					Route: Ad hoc Route		Date: 24/04/2026	
42204878	Sunken loose and noisy Scottish water fire hydrant cover on carriageway photos attached	24/04/2026	Outside Mountain Warehouse	RU: Utility Apparatus	Internal		Uncommitted	50195895
Batch: 41261222 - Inspection Batch					Route: Ad hoc Route		Date: 20/04/2026	
42204381	Broken Scottish water SV cover on carriageway photos attached	20/04/2026	At bus stop PS	RU: Utility Apparatus	Internal		Uncommitted	50195559
Batch: 41261217 - Inspection Batch					Route: Ad hoc Route		Date: 20/04/2026	
42204372	Reset 8 x dislodged kerbs	20/04/2026	At junction of the Mound	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50195556
Batch: 41260580 - Inspection Batch					Route: Ad hoc Route		Date: 10/04/2026	
42203932	1 number pothole at crossing overlay as re	10/04/2026	Opposite Black Sheep Coffee	RD: CW Pothole	Internal		Committed	50195190
Batch: 41260553 - Inspection Batch					Route: Ad hoc Route		Date: 09/04/2026	
42203916	1no sunken manhole between studded area of pedestrian crossing. Been raised several times over the last few years but no action has been taken. Last ref number recorded 3944970	09/04/2026	On westbound cw outside waverly market opposite no 24 / 25 Black sheep coffee shop	RU: Utility Apparatus	Internal		Uncommitted	50195174

Site History Report

Effective: 01/02/2026 to 01/08/2026

Service: Roads General

Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41260505 - Inspection Batch			Route: SfP_CityCentre				Date: 09/04/2026	
No actionable defects found								
Batch: 41260315 - Inspection Batch			Route: SE_FW1_Princes1				Date: 08/04/2026	
42203732	2no rocking perfecta slabs	08/04/2026	Outside boots shop	RD: FW Slabs Rocking	Internal		Committed	50195010
42203713	4no rocking perfecta slabs	08/04/2026	Outside old Jenners opposite Scott's monument	RD: FW Slabs Rocking	Internal		Committed	50194991
42203739	1no broken perfecta slab	08/04/2026	Outside 3 shop	RD: FW Slabs Broken/Missing	Internal		Committed	50195017
42203729	3no rocking perfecta slabs	08/04/2026	At pedestrian crossing at junction with Frederick st	RD: FW Slabs Rocking	Internal		Committed	50195007
42203721	1no rocking tactile slab	08/04/2026	Outside Chisholm Hunter shop	RD: FW Slabs Rocking	Internal		Committed	50194999
42203720	3no broken perfecta slabs	08/04/2026	Outside Ann summers shop	RD: FW Slabs Broken/Missing	Internal		Committed	50194998
42203751	1no Fw pothole	08/04/2026	On corner At junction with North bridge	RD: FW HRA Pothole	Internal		Committed	50195029
	Remove small loose slab / make safe							
42203714	7no rocking perfecta slabs	08/04/2026	Outside old Jenners building approx 20m from bus stop PK	RD: FW Slabs Rocking	Internal		Committed	50194992
42203727	2no rocking perfecta slab	08/04/2026	Outside IWC	RD: FW Slabs Rocking	Internal		Committed	50195005
42203716	1no broken perfecta slab	08/04/2026	Outside Marks & Spencer at bus stop PJ	RD: FW Slabs Broken/Missing	Internal		Committed	50194994
42203743	1no rocking 900 x 600 pcc slab	08/04/2026	At pedestrian crossing opposite Claire's	RD: FW Slabs Rocking	Internal		Committed	50195021
42203715	5no rocking perfecta slabs	08/04/2026	At bus stop PK	RD: FW Slabs Rocking	Internal		Committed	50194993
42203736	1no broken cut perfecta slab	08/04/2026	At double catv box junction of castle street	RD: FW Slabs Broken/Missing	Internal		Committed	50195014
42203738	3no broken perfecta slabs	08/04/2026	Outside sports direct	RD: FW Slabs Broken/Missing	Internal		Committed	50195016
42203747	Broken grano at box surround	08/04/2026	Opposite Skechers shop / tram stop	RD: FW Grano Cracked/Broken	Internal		Committed	50195025
42203712	1no broken perfecta slab	08/04/2026	Outside Balmoral country wear shop	RD: FW Slabs Broken/Missing	Internal		Committed	50194990
42203709	2no broken perfecta slabs	08/04/2026	Outside black sheep coffee	RD: FW Slabs Broken/Missing	Internal		Committed	50194987
	1no rocking perfecta slab							
42203731	4no broken perfecta slabs	08/04/2026	Outside 100 princes st at bus stop PF	RD: FW Slabs Broken/Missing	Internal		Committed	50195009
	7no rocking perfecta slabs							
42203717	2no rocking perfecta slabs	08/04/2026	Outside Romanes & Paterson	RD: FW Slabs Rocking	Internal		Committed	50194995
42203708	1no broken perfecta slab	08/04/2026	Outside Sainsbury's local	RD: FW Slabs Broken/Missing	Internal		Committed	50194986
42203735	1no rocking perfecta slab	08/04/2026	At bus stop PE	RD: FW Slabs Rocking	Internal		Committed	50195013
42203711	3no broken perfecta slabs	08/04/2026	Outside smiggle shop	RD: FW Slabs Broken/Missing	Internal		Committed	50194989
42203710	2no rocking perfecta slabs	08/04/2026	Opposite waverly market outside old top shop	RD: FW Slabs Rocking	Internal		Committed	50194988
Batch: 41260244 - Inspection Batch			Route: Ad hoc Route				Date: 07/04/2026	
42203668	2 number potholes	07/04/2026	Outside number 90	RD: CW Pothole	Internal		Committed	50194950
Batch: 41260104 - Inspection Batch			Route: South Mobile Inspection Route				Date: 01/04/2026	
No actionable defects found								
Batch: 41259777 - Inspection Batch			Route: Ad hoc Route				Date: 31/03/2026	
42203333	1 number pothole beside SV Valves	31/03/2026	Outside the Office	RD: CW Pothole	Internal		Committed	50194726

Site History Report

Effective: 01/02/2026 to 01/08/2026

Service: Roads General

Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset:	3.00	Asset - Locn.:	Ward 11 - From Waterloo Place to Shandwick Place	Feature Type:	Road Asset		Area:	South East Locality	
Batch:	41259719 - Inspection Batch			Route:	Mobile Inspection Strategic			Date:	30/03/2026
	No actionable defects found								
Batch:	41259328 - Inspection Batch			Route:	Ad hoc Route			Date:	26/03/2026
42202970	Reset off cut of tactile at pedestrian crossing	26/03/2026	At corner of South St David Street	RD: FW Slabs Broken/Missing	Internal		Committed		50194537
Batch:	41258985 - Inspection Batch			Route:	Mobile Inspection Strategic			Date:	23/03/2026
	No actionable defects found								
Batch:	41258625 - Inspection Batch			Route:	Ad hoc Route			Date:	19/03/2026
42202467	Rest rocking flag	19/03/2026	Outside Johnnie Walker	RD: FW Slabs Broken/Missing	Internal		Committed		50194184
Batch:	41258196 - Inspection Batch			Route:	Mobile Inspection Strategic			Date:	16/03/2026
42202127	1no pothole	16/03/2026	At the junction with South St Andrew Street	RD: CW Pothole	Internal		Committed		50193938
Batch:	41257901 - Inspection Batch			Route:	Ad hoc Route			Date:	13/03/2026
42201948	Patch 8	13/03/2026	After Scott,s Monument	RO: Permanent Patching	Internal		Committed		50193828
Batch:	41257900 - Inspection Batch			Route:	Ad hoc Route			Date:	13/03/2026
42201947	Patch 7	13/03/2026	After Scott,s Monument	RO: Permanent Patching	Internal		Committed		50193827
Batch:	41257899 - Inspection Batch			Route:	Ad hoc Route			Date:	13/03/2026
42201946	Patch 6	13/03/2026	Pedestrian crossing after Scott,s Monument	RO: Permanent Patching	Internal		Committed		50193826
Batch:	41257898 - Inspection Batch			Route:	Ad hoc Route			Date:	13/03/2026
42201945	Patch 5	13/03/2026	Pedestrian after Scott,s Monument	RO: Permanent Patching	Internal		Committed		50193825
Batch:	41257894 - Inspection Batch			Route:	Ad hoc Route			Date:	13/03/2026
42201944	Patch 4	13/03/2026	Pedestrian crossing at Scott,s monument	RO: Permanent Patching	Internal		Committed		50193824
Batch:	41257891 - Inspection Batch			Route:	SfP_ CityCentre			Date:	13/03/2026
	No actionable defects found								
Batch:	41257391 - Inspection Batch			Route:	Mobile Inspection Strategic			Date:	09/03/2026
42201595	1no pothole	09/03/2026	At the left turn into Leith Street	RD: CW Pothole	Internal		Committed		50193551
Batch:	41256986 - Inspection Batch			Route:	SE_FW1_Princes1			Date:	06/03/2026
42201411	1no rocking sandstone slab	06/03/2026	Outside art gallery Opposite Hanover stree	RD: FW Slabs Rocking	Internal		Committed		50193411
42201399	4no broken perfecta slabs 1no rocking perfecta slab	06/03/2026	Outside sports direct	RD: FW Slabs Broken/Missing	Internal		Committed		50193401
Batch:	41256827 - Inspection Batch			Route:	Ad hoc Route			Date:	05/03/2026
42201234	Renew 1 x broken perfecta slab and relay 1 x rocking perfecta slab	05/03/2026	Outside Sports Direct	RD: FW Slabs Broken/Missing	Internal		Committed		50193291
Batch:	41256313 - Inspection Batch			Route:	South Mobile Inspection Route			Date:	02/03/2026
	No actionable defects found								

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 3.00		Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41255961 - Inspection Batch		Route: Mobile Inspection Strategic Date: 02/03/2026						
42200820	1no pothole	01/03/2026	Westbound lane near the corner of Waverley Bridge	RD: CW Pothole	Internal		Committed	50192977
Batch: 41255758 - Inspection Batch		Route: Ad hoc Route Date: 27/02/2026						
42200700	Please reinstate markings after patching works	27/02/2026	Westbound opposite Frederick Street	RD: Markings Refresh	Internal		Committed	50192879
Batch: 41255522 - Inspection Batch		Route: Ad hoc Route Date: 26/02/2026						
42200581	Please reinstate markings after patching works	26/02/2026	Opposite tram stop westbound	RD: Markings Refresh	Internal		Committed	50192789
Batch: 41254944 - Inspection Batch		Route: Ad hoc Route Date: 23/02/2026						
42200320		23/02/2026	After junction with Frederick Street	RO: Permanent Patching	Internal		Committed	50192608
Batch: 41254943 - Inspection Batch		Route: Ad hoc Route Date: 23/02/2026						
42200319	Patch 2	23/02/2026	After junction with Fredrick Street (Westbound)	RO: Permanent Patching	Internal		Committed	50192607
Batch: 41254766 - Inspection Batch		Route: Ad hoc Route Date: 23/02/2026						
42200259	Sunken loose and noisy manhole cover on carriageway photos attached	23/02/2026	Outside number 135	RU: Utility Apparatus	Internal		Uncommitted	50192554
Batch: 41254668 - Inspection Batch		Route: Mobile Inspection Strategic Date: 22/02/2026						
No actionable defects found								
Batch: 41253865 - Inspection Batch		Route: Ad hoc Route Date: 17/02/2026						
42199709	Patch 1	17/02/2026	Opposite Tram Stop	RO: Permanent Patching	Internal		Committed	50192077
Batch: 41253588 - Inspection Batch		Route: Mobile Inspection Strategic Date: 15/02/2026						
42199543	1no pothole	15/02/2026	At the junction with Waverley Bridge	RD: CW Pothole	Internal		Committed	50191950
42199544	1no pothole	15/02/2026	At manhole opposite Black Sheep Coffee	RD: CW Pothole	Internal		Committed	50191951
42199542	1no pothole	15/02/2026	At the corner of South St David Street	RD: CW Pothole	Internal		Committed	50191949
Batch: 41253586 - Inspection Batch		Route: Ad hoc Route Date: 15/02/2026						
42199540	1no pothole	15/02/2026	Outside Clarks	RD: CW Pothole	Internal		Committed	50191947
Batch: 41252571 - Inspection Batch		Route: Ad hoc Route Date: 09/02/2026						
42198918	1no pothole	09/02/2026	Eastbound lane outside Office	RD: CW Pothole	Internal		Committed	50191417
Batch: 41252570 - Inspection Batch		Route: Ad hoc Route Date: 09/02/2026						
42198917	2no sunken sv boxes	09/02/2026	On the eastbound carriageway outside Office	RU: Utility Apparatus	Internal		Uncommitted	50191416
Batch: 41252455 - Inspection Batch		Route: Mobile Inspection Strategic Date: 08/02/2026						
42198810	1no pothole	08/02/2026	At the left turn on to Leith Street	RD: CW Pothole	Internal		Committed	50191343

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place			Feature Type: Road Asset		Area: South East Locality	
Batch: 41251913 - Inspection Batch			Route: SE_FW1_Princes1				Date: 05/02/2026	
42198618	1no rocking 900 x 600 pcc slab 1no rocking 600 x 600 pcc slab 1no rocking cut pcc slab	05/02/2026	At bus stop PR	RD: FW Slabs Rocking	Internal		Committed	50191204
42198587	1no broken perfecta slab	05/02/2026	Outside old waverley hotel	RD: FW Slabs Broken/Missing	Internal		Committed	50191178
42198600	7no rocking perfecta slabs	05/02/2026	Outside Starbucks	RD: FW Slabs Rocking	Internal		Committed	50191191
42198580	3no rocking cut perfecta slabs	05/02/2026	Outside Hotel indigo	RD: FW Slabs Rocking	Internal		Committed	50191171
42198599	2no rocking perfecta slabs	05/02/2026	Outside IWC	RD: FW Slabs Rocking	Internal		Committed	50191190
42198614	1no rocking 900 x 600 pcc slab	05/02/2026	Outside Royal bank and f Scotland	RD: FW Slabs Rocking	Internal		Committed	50191200
42198615	1no rocking cut Caithness slab	05/02/2026	Outside Johnnie walkers next to pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50191201
42198598	2no broken perfecta slab	05/02/2026	Outside 90 next to Claire's	RD: FW Slabs Broken/Missing	Internal		Committed	50191189
42198634	2no rocking perfecta slabs	05/02/2026	At bus stop PH	RD: FW Slabs Rocking	Internal		Committed	50191220
42198583	11no rocking perfecta slabs 1no rocking tactile slab	05/02/2026	Outside black sheep coffee	RD: FW Slabs Rocking	Internal		Committed	50191174
42198596	5no rocking perfecta slabs	05/02/2026	Outside blank street	RD: FW Slabs Rocking	Internal		Committed	50191187
Batch: 41251251 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 01/02/2026	
42198114	1no pothole	31/01/2026	On the pedestrian crossing opposite Black Sheep Coffee	RD: CW Pothole	Internal		Committed	50190806
42198115	1no pothole	31/01/2026		RD: CW Pothole	Internal		Committed	50190807
42198221	1no pothole Utility defect already raised	01/02/2026	Outside Primark	RD: CW Pothole	Internal		Committed	50190911
42198116	2no potholes	31/01/2026	At the pedestrian crossing opposite Burger King	RD: CW Pothole	Internal		Committed	50190808
42198220	1no pothole	01/02/2026	At the corner of South St David Street	RD: CW Pothole	Internal		Committed	50190910

Customer Services

Enquiry No.: 2187586 **Logged by:** Verint CRM Connector **on:** 29/07/2026 14:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside Pret, Princes St.
 Given trams are not currently running, please can a quality, enduring repair be made to the damaged area per the attached photo. It's currently a hazard for cyclists

Contact:

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2184967 **Logged by:** [REDACTED] **on:** 24/07/2026 08:34
Service: Roads General **Subject:** Public Utilities: General **Classification:** General Enquiry
Desc.: Manhole cover at junction of Prince St and South Charlotte St is broken, can see frame flexing and makes a loud noise. Urgent fix before more traffic chaos at this junction.
Location: **Contact:**

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2181527 **Logged by:** Verint CRM Connector **on:** 17/07/2026 14:24
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Loose and wobbling paving slabs on Princes Street in front of Clarks/Skechers shoe shops. They are a danger to pedestrians. I am currently walking with a crutch due to an existing hip/foot injury and the loose slabs made getting around harder and there is more danger of falling over. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2180774 **Logged by:** Verint CRM Connector **on:** 16/07/2026 13:25
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Manhole cover loose and sinking in road. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2173171 **Logged by:** Verint CRM Connector **on:** 02/07/2026 13:50
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Loose manhole cover and tar breaking away in left turn filter lane for South Charlotte Street traffic **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2173142 **Logged by:** Verint CRM Connector **on:** 02/07/2026 13:22
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Multiple broken slabs on the pavement and two persons have fallen on around 1pm today. I would say this is an urgent issue that needs to be fixed **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2173113 **Logged by:** Verint CRM Connector **on:** 02/07/2026 12:56
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: In front of 42a princes street a shop called smiggle
The paving is extremely wobbly and someone fell over on it at 1250 today 2nd July 2026 **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50199468 **Defect Number:** 42210377

Enquiry No.: 2173065 **Logged by:** Verint CRM Connector **on:** 02/07/2026 12:09
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Loose paving slab rocks when stepped on and not very noticeable
It is outside mount royal hotel about 6 paving stones down from the edge **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50199472 **Defect Number:** 42210381

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2171991 **Logged by:** Verint CRM Connector **on:** 30/06/2026 20:37
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Grid on princes street near Pret is very loose with tarmac around it having come loose. Grid banging loudly as traffic passes over it **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2169729 **Logged by:** Verint CRM Connector **on:** 26/06/2026 13:08
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: On road near McDonalds. 137 princes street **Contact:**

Enquiry No.: 2167213 **Logged by:** Verint CRM Connector **on:** 22/06/2026 15:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are dangerous potholes around sunken metal covers in the road near Mountain Warehouse And The Works further east... Very dangerous for cyclists **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2167153 **Logged by:** Verint CRM Connector **on:** 22/06/2026 14:44
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Tarmac has been paid over a metal cover and now it's breaking up! This sits amongst other surface irregularities so avoiding it is difficult if buses are passing bikes **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50199661 **Defect Number:** 42210683

Enquiry No.: 2167110 **Logged by:** Verint CRM Connector **on:** 22/06/2026 13:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous potholes at sunken metal covers outside mountain warehouse and the works stores. Would not want to hit one of these on a bike! **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50199046 **Defect Number:** 42209752

Enquiry No.: 2166609 **Logged by:** Verint CRM Connector **on:** 21/06/2026 16:10
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement towards kerb side outside of H&M in Princes Street is extremely dangerous with many broken slabs making a very uneven surface resulting a trip hazard.
No photo taken as it was pouring with rain at the time.
The broken tiles allow pooling of water and mud which squelched up as pedestrians try to negotiate this stretch of pavement. On such a wet day it becomes slippery with mud. **Contact:**

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2165963 **Logged by:** Verint CRM Connector **on:** 19/06/2026 16:08
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Faulty manhole cover. Very noisy **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2165543 **Logged by:** Verint CRM Connector **on:** 18/06/2026 22:53
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Outside prêt à manger there is a man hole cover. About 90% of cars drive over it and it makes a very load noise which I hear in my flat. The traffic on this road never stops. It is affecting me more at night as I try to sleep **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50198861 **Defect Number:** 42209464

Enquiry No.: 2162258 **Logged by:** Verint CRM Connector **on:** 12/06/2026 13:20
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: there a number of loose slabs in this area and a lady had fell yestnesday **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2161848 **Logged by:** Verint CRM Connector **on:** 11/06/2026 18:07
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: A 79 years old [redacted] felt on the street, right on front of H&M because of the irregular pavement. I assisted [redacted] and needed to call the ambulante to take [redacted] to the hospital. The pavement is broken and is a risk for the people that walk there daily. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2158745 **Logged by:** Verint CRM Connector **on:** 05/06/2026 14:27
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Drain cover in eastbound lane (just outside 135 Princes Street) making a huge racket when cars drive over it. The road surrounding the cover looks quite broken up. **Contact:**

Enquiry No.: 2157571 **Logged by:** Verint CRM Connector **on:** 03/06/2026 15:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: lothian buses called to report that there are approx. 6 kerbs stones sticking out from the pavement towards the road, outside the art gallery, damaged a few weeks ago by a car apparently. these are now sticking out far enough to cause a severe problem when a bus and tram are travelling at the same time on this section (heading towards haymarket), 3 buses already damaged with this section of kerbs. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2156676 **Logged by:** Verint CRM Connector **on:** 02/06/2026 11:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Kerb stones detached from the pavement, damage caused to a bus wheel. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2155550 **Logged by:** Verint CRM Connector **on:** 30/05/2026 23:00
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: A square drain cover on the road on Princes Street at the Pret A Manger door level is loose. Every time a car drives over it (which is all the time!) it makes a really loud noise. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2153561 **Logged by:** Verint CRM Connector **on:** 27/05/2026 10:15
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Princes street, at Jenners, almost at corner of South St. David Street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2150901 **Logged by:** Verint CRM Connector **on:** 21/05/2026 18:40
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement on Princes St, between Uniqlo and Hanover St **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2149500 **Logged by:** Verint CRM Connector **on:** 19/05/2026 15:29
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Princes St, on and around no. 83 and Superdrug **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2149493 **Logged by:** Verint CRM Connector **on:** 19/05/2026 15:24
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement between busstop PE and Boots **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2149311 **Logged by:** Verint CRM Connector **on:** 19/05/2026 11:38
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Stretch of Princes St pavement between South St David St and the Mount Royal Hotel is broken in many places and presents a trip hazard **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2146258 **Logged by:** Verint CRM Connector **on:** 12/05/2026 19:48
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: On 12/5 my [REDACTED] had a bad fall on the Gardens side of Princes Street, just after the number 4 bus bus stop. [REDACTED] was walking along and tripped over an irregular paving stone. [REDACTED] had a terrible fall, flat on [REDACTED] face and as a result of this has a broken wrist and severe facial bruising. [REDACTED] is a very active, fit and strong [REDACTED] and this was definitely a result of the difference in height of the paving slabs. The area is just before the last footway entrance to the gardens before the gallery. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2146048 **Logged by:** Verint CRM Connector **on:** 12/05/2026 14:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole in the centre of a pedestrian crossing , princes street, Edinburgh **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2145866 **Logged by:** Verint CRM Connector **on:** 12/05/2026 10:55
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Garden side just before the national gallery **Contact:**

Enquiry No.: 2145294 **Logged by:** Verint CRM Connector **on:** 11/05/2026 11:48
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Within Princes street gardens, as you turn right down in the ramp from the castle street entrance towards the fountain. Really challenging and dangerous for prams and wheelchairs! **Contact:**

Enquiry No.: 2145213 **Logged by:** Verint CRM Connector **on:** 11/05/2026 10:33
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: The whole length of the shop side of princes street is a terrible trip hazard. The paving slabs are very uneven and you have to walk looking down or you'll fall! My [REDACTED] who works in town has witnessed countless people falling. This needs fixed as it's a disgrace that our capital city's main street's pavements are in this state. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2144548 **Logged by:** Verint CRM Connector **on:** 09/05/2026 14:13
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Manhole cover and frame and surrounding road surface damaged and causing lots of noise due to movement. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50197016 **Defect Number:** 42206607

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2144472 **Logged by:** Verint CRM Connector **on:** 09/05/2026 11:05
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Other year of reporting the major issue at the crossing. People are constantly falling over splitting heads, legs, face. Breaking arms, wrist it is not acceptable. Nothing has been done and I have reported several times there is going to be a serious accident. Please please listen up **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2143927 **Logged by:** Verint CRM Connector **on:** 08/05/2026 09:24
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: From St James quarter until the Vodafone shop on Princes street the pavement is filled with holes due to cracked paving slabs or missing pieces **Contact:**

Enquiry No.: 2142952 **Logged by:** Verint CRM Connector **on:** 06/05/2026 15:43
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: The whole block from the Scotland shop to where topshop used to be right along the front of H&M has at least 9 areas where there are clusters of paving moving with deep edges, i witnessed 4 people trip 2 actually hurt themselves **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2138783 **Logged by:** Verint CRM Connector **on:** 29/04/2026 14:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dear Sir/Madam, I am writing to raise a serious safety concern regarding the pedestrian crossing and tram platform area on Princes Street at the junction with The Mound (eastbound tram stop, near Clarks shoe shop). On the 18th of April 2026 I sustained a significant injury after tripping on the raised concrete section adjacent to the tram lines while crossing at this location. The design of the area led me to believe I was using a direct pedestrian crossing, particularly due to the alignment of the crossing markings and the flow of foot traffic. In my view, the layout is misleading and presents a hazard to pedestrians. There is no clear signage or visual warning indicating the change in level or directing pedestrians safely around the tram platform. In busy conditions, it is very easy to follow the natural crossing line and encounter the raised section unexpectedly. As a result of this fall, I suffered a serious arm fracture requiring surgical intervention. I would ask that you urgently review the safety of this location, including consideration of:
* Clearer visual markings or warnings at the platform edge
* Improved guidance for pedestrian crossing routes
* Any other measures to reduce the risk of further incidents
I would also be grateful if you could confirm whether this location has been subject to previous incident reports or safety concerns. I look forward to your response. Kind regards [REDACTED] **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2137965 Logged by: Verint CRM Connector on: 28/04/2026 10:41
Service: Roads General Subject: Public Utilities: General Classification: Request for service
Desc.:
Location: Collapsing ironwork making terrible noise from traffic Contact:

Plot Number: 3.00 Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 2134614 Logged by: Verint CRM Connector on: 22/04/2026 06:12
Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service
Desc.:
Location: Collapsed drain cover just before bus stop PB Contact:

Plot Number: 3.00 Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
Job Number: 50195895 Defect Number: 42204878

Enquiry No.: 2134234 Logged by: Verint CRM Connector on: 21/04/2026 12:11
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: [redacted] tripped up on under even pavement and [redacted] hurt [redacted] outside number 69 Contact:
princes street [redacted] whole body is sore and [redacted] hurt her knees and [redacted] trainer's have
been damaged [redacted] has pictures

Plot Number: 3.00 Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 2134210 Logged by: Verint CRM Connector on: 21/04/2026 11:41
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: Hello, Contact:

Im reporting their terrible state of the footpaths on princes street. I feel here last week and narrowly avoided a serious injury. The footpaths are a constant tripping hazard with parts sticking up and the majority of the slabs cracked. This area needs attention to prevent more people falling and seriously injuring themselves.

Thanks,

Plot Number: 3.00 Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 2133430 Logged by: Verint CRM Connector on: 20/04/2026 09:33
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Kerb stones at Princes Street/Mound westbound dislodged Contact:

Plot Number: 3.00 Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
Job Number: 50195556 Defect Number: 42204372

Site History Report

Effective: 01/02/2026 to 01/08/2026

Service: Roads General

Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2133373	Logged by: Verint CRM Connector	on: 20/04/2026 08:38
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Pavement next to the bus shelter opposite Waverley steps north side of prnces street. Paving slab has sunk and my wife fell and injured herself.	Contact:	
Plot Number: 3.00	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place	Feature Type: Road Asset
Enquiry No.: 2133146	Logged by: Verint CRM Connector	on: 19/04/2026 14:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Princes Street Bus Stop PS westbound drain cover missing.	Contact:	
Plot Number: 3.00	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place	Feature Type: Road Asset
Job Number: 50195559	Defect Number: 42204381	
Enquiry No.: 2132327	Logged by: [REDACTED]	on: 17/04/2026 11:54
Service: Roads General	Subject: Pavement: General Enquiry	Classification: General Enquiry
Desc.: First name : [REDACTED] Last name : [REDACTED] email : [REDACTED] telephone number : [REDACTED] Full address : [REDACTED] What area does your complaint relate to ? : Other Other details : Shockingly poor Pavement conditions Short description of complaint : My [REDACTED] and I visited Edinburgh on 16 April 2026. We walked 6 miles around the centre and were appalled at the poor condition of the pavement surfaces Please provide the details of the complaint : On a 6 mile walk I lost count of the number of tripping hazards we encountered on the paved slab surfaces in Edinburgh. As a retired local authority engineer what I observed was abject neglect and complete lack of supervision of the contractors/ cowboys who are disturbing these surfaces. Self-regulation clearly doesn't work. I was ashamed and disgusted at the state of Edinburgh's pavements. How would you like us to deal with this? : This is not rocket science. Get Paul Lawrence and each of his senior management team to go for a 6 mile walk, survey what they find, compare notes and find answers. I kicked ass when I held senior role in local authority wrt to contractors. They shouldn't get to open a surface until they pay for the mess they have left behind previously. And ask Paul Lawrence to respond to me directly.		
Location: Princes Street and city centre	Contact:	
Enquiry No.: 2130489	Logged by: Verint CRM Connector	on: 14/04/2026 13:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Outside Costa Coffee at Waverley Mall on Princes Street at the pedestrian crossing. The manhole is low and moving when traffic goes over it.	Contact:	
Plot Number: 3.00	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place	Feature Type: Road Asset
Enquiry No.: 2127802	Logged by: [REDACTED]	on: 09/04/2026 11:34
Service: Roads General	Subject: RO: Drop Crossing Request	Classification: Request for service
Desc.: There is a ridge on the pavement obstructing wheelchair users from crossing at costa (waverly mall) over to black street coffee. Citizen was catapulted from her wheelchair and has photos of said ridge.#		
Location: 24-25 Princes Street	Contact:	

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2125869 **Logged by:** Verint CRM Connector **on:** 06/04/2026 11:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Where the tram tracks meet the road is in extremely poor condition along the length of princes street but is life threatening for cyclists at certain points. Bus stop area on princes street outside Waverley mall is also very hazardous
Contact: Princes Street, Old Town, City of Edinburgh, Alba / Scotland, EH2 3DW, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH2 4AH (40m away)

Enquiry No.: 2124746 **Logged by:** Verint CRM Connector **on:** 03/04/2026 10:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Road surface is damaged around iron works and needs repaired. Large vehicles & buses are driving over this due to the tram track. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2123376 **Logged by:** Verint CRM Connector **on:** 01/04/2026 09:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The seam on the road next to tram line is opening up creating category one potholes
Contact: .
It is about 10-15m of damaged tarmac

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2121952 **Logged by:** Verint CRM Connector **on:** 30/03/2026 08:51
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: I cannot give specifics to part of the pavement as there are too many to choose. Every couple of steps there is another trip hazard due to loose and broken slabs from Shandwick Place to The apple shop. **Contact:**

Location:
Easting/Northing: 324994/673752 (55.950921, -3.202693)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Princes Street, Old Town, City of Edinburgh, Alba / Scotland, EH2 3DW, United Kingdom
Nearest postcode to the pin placed on the map (automaticall

Enquiry No.: 2120835 **Logged by:** Verint CRM Connector **on:** 27/03/2026 12:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: 2 potholes outside Accessorize... Dangerous for cyclists especially **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50194726 **Defect Number:** 42203333

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2120834 Service: Roads General Desc.: Location: Pothole By The Works on north side of road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/03/2026 12:37 Classification: Request for service Contact:
Enquiry No.: 2119622 Service: Roads General Desc.: Location: Part of slab missing making deep hole. Nearly went over ankle. It is at the pedestrian crossing on the old Jenners side. Thank you.	Logged by: Verint CRM Connector Subject: Pavement: Missing Slab / Kerb	on: 25/03/2026 12:54 Classification: Customer Emergency Contact:
Plot Number: 3.00 Job Number: 50194537	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Defect Number: 42202970	Feature Type: Road Asset
Enquiry No.: 2115482 Service: Roads General Desc.: Location: Outside Johnnie Walker - loose and rocking paving slab - now lethal having almost twisted my ankle in it today!	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 18/03/2026 18:06 Classification: Request for service Contact:
Plot Number: 3.00 Job Number: 50194184	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Defect Number: 42202467	Feature Type: Road Asset
Enquiry No.: 2115176 Service: Roads General Desc.: Location: Large paving slab is loose and is a trip hazard.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 18/03/2026 12:22 Classification: Request for service Contact:
Plot Number: 3.00 Enquiry No.: 2114139 Service: Roads General Desc.: Location: @edinhelp there's a paving stone on the corner of princes street by Johnnie Walker that's sticking up about an inch just waiting for people to trip over it. It's wobbly too.	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	Feature Type: Road Asset on: 17/03/2026 08:34 Classification: Request for service Contact:
Enquiry No.: 2111202 Service: Roads General Desc.: Location: I want to report pothole on princes street outside Burger King near the tram tracks	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/03/2026 11:23 Classification: Request for service Contact:
Enquiry No.: 2109928 Service: Roads General Desc.: Location: The loose slab and sticking up is located outside old Jenners Store. It is quite close to the white boards surrounding the store and about 20 feet approx from the traffic lights at the corner of Princess Street and South St David Street.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 10/03/2026 13:46 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place	Feature Type: Road Asset

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2108939 **Logged by:** [REDACTED] **on:** 09/03/2026 09:59
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Elderly [REDACTED] fell due to Pavement defect, severely hurting [REDACTED] and having to receive first aid from shop security.
Location: UNIQLO 64 Princes Street **Contact:**

Enquiry No.: 2108203 **Logged by:** Verint CRM Connector **on:** 07/03/2026 11:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pedestrian crossing beside train station **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2108128 **Logged by:** Verint CRM Connector **on:** 07/03/2026 08:49
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Collapsed drain cover Princes bus stop PA **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2105734 **Logged by:** Verint CRM Connector **on:** 03/03/2026 13:33
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Many broken and loose paving slabs. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50193291 **Defect Number:** 42201234

Enquiry No.: 2104883 **Logged by:** [REDACTED] **on:** 02/03/2026 10:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: i picked princes street...this is for the new town part of the enquiry only please see attached document
Location: i picked as one of the possible streets princes street...this is for the new town part of the enquiry only please see attached document **Contact:**

Enquiry No.: 2100089 **Logged by:** Verint CRM Connector **on:** 22/02/2026 17:42
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: My 80 year old fit and able [REDACTED] tripped over an uneven paving slab outside Marks & Spencer. [REDACTED] landed heavily on [REDACTED] face and arm, resulting in a lot of blood and swelling and a trip to A&E to check for broken bones [REDACTED] is badly bruised and shaken. Nothing like this has ever happened to [REDACTED] before. Please can you fix the paving slabs on such a high footfall area before anyone else gets hurt. Thank you. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2099775 **Logged by:** Verint CRM Connector **on:** 21/02/2026 21:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Collapsed manhole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50192554 **Defect Number:** 42200259

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2097832 **Logged by:** Verint CRM Connector **on:** 18/02/2026 13:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Tarmac breaking up . Uneven, possible potholes, cycling hazard
Next to pavement, east bound carriage way at Princes's Street tram stop **Contact:**

Enquiry No.: 2096560 **Logged by:** Verint CRM Connector **on:** 16/02/2026 21:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole near edge of road roughly in line with Clarks shoe shop **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2096558 **Logged by:** Verint CRM Connector **on:** 16/02/2026 21:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole near road edge **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2095282 **Logged by:** Verint CRM Connector **on:** 14/02/2026 21:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Princes St eastbound carriageway outside Office at 79A. Fix it properly, third time in less than 6 months this has been reported & 'fixed' **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50191947 **Defect Number:** 42199540

Enquiry No.: 2094107 **Logged by:** Verint CRM Connector **on:** 12/02/2026 22:38
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Multiple broken and sunken paving stones leading to high risk of people tripping, falling and sustaining injuries. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2090339 **Logged by:** Verint CRM Connector **on:** 07/02/2026 11:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Numerous broken and uneven paving slabs outside Ann summers **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 2088187 **Logged by:** Verint CRM Connector **on:** 03/02/2026 17:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken ironwork on approach to junction, just prior to stop line. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50191416 **Defect Number:** 42198917

Site History Report

Effective: 01/02/2026 to 01/08/2026
Service: Roads General
Site: Princes Street (7903151)

Asset Number: 3.00 to 3.00
Display Action Officer: No