

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Saughton Road North (7903234)			Locality: Corstorphine, Edinburgh, City of Edinburgh			Area: North West Locality		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road			Feature Type: Road Asset		Area: North West Locality	
Batch: 41254504 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2026		
42200114	Pothole	20/02/2026	At junction with castle avenue	RD: CW Pothole	Internal		Committed	50192446
Batch: 41254502 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2026		
42200112	Pothole	20/02/2026	beside the island crossing	RD: CW Pothole	Internal		Committed	50192445
Batch: 41254501 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2026		
42200111	Pothole	20/02/2026	After kwick fit entrance	RD: CW Pothole	Internal		Committed	50192444
Batch: 41254500 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2026		
42200110	Pothole around ironwork	20/02/2026	At bus stop	RD: CW Pothole	Internal		Committed	50192443
Batch: 41254498 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2026		
42200108	Potholes	20/02/2026	At bus stop outside time hair	RD: CW Pothole	Internal		Committed	50192441
Batch: 41253614 - Inspection Batch			Route: Ad hoc Route			Date: 15/02/2026		
42199570	1no pothole	15/02/2026	Before the rail bridge after the junction	RD: CW Pothole	Internal		Committed	50191973
Batch: 41253609 - Inspection Batch			Route: Ad hoc Route			Date: 15/02/2026		
42199566	2no potholes	15/02/2026	At bus stop next to time hair	RD: CW Pothole	Internal		Committed	50191970
Batch: 41253608 - Inspection Batch			Route: Ad hoc Route			Date: 15/02/2026		
42199564	1 no pothole	15/02/2026	South bound carriageway outside Kwik Fit.	RD: CW Pothole	Internal		Committed	50191969
Batch: 41252914 - Inspection Batch			Route: Ad hoc Route			Date: 11/02/2026		
42199173	Pothole	11/02/2026	Opposite gas shop	RD: CW Pothole	Internal		Committed	50191645
Batch: 41252913 - Inspection Batch			Route: Ad hoc Route			Date: 11/02/2026		
42199172	Pothole	11/02/2026	At entrance to kwick fit	RD: CW Pothole	Internal		Committed	50191644
Batch: 41252912 - Inspection Batch			Route: Ad hoc Route			Date: 11/02/2026		
42199171	Pothole	11/02/2026	Outside 71	RD: CW Pothole	Internal		Committed	50191643
Batch: 41252911 - Inspection Batch			Route: Ad hoc Route			Date: 11/02/2026		
42199170	Pothole	11/02/2026	At road island	RD: CW Pothole	Internal		Committed	50191642
Batch: 41250691 - Inspection Batch			Route: Ad hoc Route			Date: 27/01/2026		
42197679	Pothole	27/01/2026	In bus stop	RD: CW Pothole	Internal		Committed	50190505
Batch: 41249837 - Inspection Batch			Route: Ad hoc Route			Date: 23/01/2026		
42197408	Pothole	23/01/2026	Opposite church at bus stop	RD: CW Pothole	Internal		Committed	50190252
Batch: 41248487 - Inspection Batch			Route: NW_CW1_East1			Date: 15/01/2026		
42196610	1 cw pothole	15/01/2026	Outside kwik fit	RD: CW Pothole	Internal		Committed	50189633
Batch: 41246380 - Inspection Batch			Route: Ad hoc Route			Date: 29/12/2025		
42195825	1no pothole	29/12/2025	At the junction with Castle Avenue	RD: CW Pothole	Internal		Committed	50188980

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road			Feature Type: Road Asset		Area: North West Locality	
Batch:	41243655 - Inspection Batch		Route:	Ad hoc Route			Date:	03/12/2025
42194636	1 cw pothole	03/12/2025	At junction with roull road	RD: CW Pothole	Internal		Committed	50188017
Batch:	41242411 - Inspection Batch		Route:	NW_CW1_East1			Date:	24/11/2025
42193742	1 cw pothole	24/11/2025	Outside 176	RD: CW Pothole	Internal		Committed	50187342
Batch:	41242080 - Inspection Batch		Route:	Ad hoc Route			Date:	20/11/2025
42193568	1no pothole	20/11/2025	At the corner of Roull Road	RD: CW Pothole	Internal		Committed	50187205
Batch:	41240827 - Inspection Batch		Route:	Ad hoc Route			Date:	06/11/2025
42192802	1 cw pothole	06/11/2025	At junction with castle avenue	RD: CW Pothole	Internal		Committed	50186563
Batch:	41240670 - Inspection Batch		Route:	Ad hoc Route			Date:	04/11/2025
42192659	1 cw pothole	04/11/2025	Outside time hair	RD: CW Pothole	Internal		Committed	50186479
Batch:	41239252 - Inspection Batch		Route:	Ad hoc Route			Date:	20/10/2025
42191495	Carriageway surface heaving	20/10/2025	Outside 176 on carriageway	RD: CW Subsidence/Heaving	Internal		No Action Required	
Batch:	41235002 - Inspection Batch		Route:	Ad hoc Route			Date:	19/08/2025
42188628	Pothole on carriageway	19/08/2025	Outside 78	RD: CW Pothole	Internal		Committed	50183772
Batch:	41234994 - Inspection Batch		Route:	Ad hoc Route			Date:	19/08/2025
42188625	Pothole on carriageway	19/08/2025	Outside Scotmid	RD: CW Pothole	Internal		Committed	50183769
Batch:	41234992 - Inspection Batch		Route:	Ad hoc Route			Date:	19/08/2025
42188623	Pothole on carriageway	19/08/2025	Outside Kwik Fit	RD: CW Pothole	Internal		Committed	50183768
Batch:	41234756 - Inspection Batch		Route:	NW_CW1_East1			Date:	15/08/2025
No actionable defects found								
Batch:	41228295 - Inspection Batch		Route:	Ad hoc Route			Date:	15/05/2025
42183544	Replace damaged bollard	15/05/2025	Outside 135	RD: Bollard Damage/Missing/Nev	Internal		Committed	50179937
Batch:	41228147 - Inspection Batch		Route:	NW_CW1_East1			Date:	13/05/2025
No actionable defects found								
Batch:	41227579 - Inspection Batch		Route:	NW_CF1_BroomhallEast1			Date:	06/05/2025
42182997	Renew granite around both manholes	06/05/2025	Outside Shirley's grooming services	RD: FW Grano Cracked/Broken	Internal		Committed	50179597
42182920	permanent repair required	06/05/2025	Bus stop opposite church	RD: CW Rutting	Internal		No Action Required	
42182940	Patch required	06/05/2025	Outside 76	RD: FW HRA Cracked/Broken	Internal		No Action Required	
	Approx 3m x 1.5m							
42182918	Patch required	06/05/2025	Opposite 112 - 114	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50137041
	Approx 7m x 2m							
42182937	.5x2.5m patch	06/05/2025	Outside 164	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42182928	Replace 3 broken tactiles & relay 3 rocking tactiles	06/05/2025	At junction with carrick knowe parkway	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42182941	permanent repair required to carriageway in hra	06/05/2025	Outside 8 + 5	RD: CW Rutting	Internal		No Action Required	
42182938	Permanent repair required	06/05/2025	Bus stop outside 102	RD: CW Rutting	Internal		No Action Required	
42182916	Permanent repair required	06/05/2025	Outside 98-100	RD: CW Rutting	Internal		Uncommitted	50174270

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road		Feature Type: Road Asset		Area: North West Locality		
Batch: 41227579 - Inspection Batch		Route: NW_CF1_BroomhallEast1		Date: 06/05/2025				
42182924	Replace 2 broken tactiles Relay 2 rocking tactiles	06/05/2025	At junction with carrick knowe parkway	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50159986
42182960	Relay 1 whin kerb (Kerb lying on fw at wall)	06/05/2025	Outside 6	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50179582
42182939	Patch required Approx 7m x 2m	06/05/2025	Outside Kwik fit	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41227291 - Inspection Batch		Route: Ad hoc Route		Date: 01/05/2025				
42182708	Permanent footway repair required	01/05/2025	At Union Park	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50179413
Batch: 41227146 - Inspection Batch		Route: Ad hoc Route		Date: 30/04/2025				
42182615	1 cw pothole	30/04/2025	At junction with castle avenue	RD: CW Pothole	Internal		Committed	50179337
Batch: 41219248 - Inspection Batch No actionable defects found		Route: NW_CW1_East1		Date: 17/02/2025				
Batch: 41218917 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175859	Pothole on carriageway	13/02/2025	Junction Meadowhouse Road	RD: CW Pothole	Internal		Committed	50174988
Batch: 41218916 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175858	Pothole on carriageway	13/02/2025	Junction Castle Avenue	RD: CW Pothole	Internal		Committed	50174987
Batch: 41218914 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175857	Permanent repair required	13/02/2025	various holes	RD: CW Rutting	Internal		Uncommitted	50174986
Batch: 41218913 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175856	Pothole on carriageway	13/02/2025	Bus stop outside Union Park	RD: CW Pothole	Internal		Committed	50174985
Batch: 41218912 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175855	Pothole on carriageway	13/02/2025	Outside Scotmid	RD: CW Pothole	Internal		Committed	50174984
Batch: 41218910 - Inspection Batch		Route: Ad hoc Route		Date: 13/02/2025				
42175854	Pothole on carriageway	13/02/2025	Outside Kwik Fit	RD: CW Pothole	Internal		Committed	50174983
Batch: 41217819 - Inspection Batch		Route: Ad hoc Route		Date: 06/02/2025				
42175166	Make safe over lay	06/02/2025	Under railway bridge (southbound)	RD: CW Cracked/Broken	Internal		Committed	50174440
Batch: 41217544 - Inspection Batch		Route: Ad hoc Route		Date: 05/02/2025				
42174939	Permanent repair required	05/02/2025	Outside 98-100	RD: CW Rutting	Internal		No Action Required	
Batch: 41217541 - Inspection Batch		Route: Ad hoc Route		Date: 05/02/2025				
42174936	Pothole on carriageway	05/02/2025	Outside 98-100	RD: CW Pothole	Internal		Committed	50174267
Batch: 41216777 - Inspection Batch		Route: Ad hoc Route		Date: 29/01/2025				
42174335	Pothole on carriageway	29/01/2025	Outside 64	RD: CW Pothole	Internal		Committed	50173830
Batch: 41214558 - Inspection Batch		Route: NW_CW1_East1		Date: 14/01/2025				
42172968	2 potholes	14/01/2025	At bus stop outside time hair	RD: CW Pothole	Internal		Committed	50172801
Batch: 41212724 - Inspection Batch		Route: Ad hoc Route		Date: 03/01/2025				
42172029	Pothole on carriageway	03/01/2025	Junction Castle Avenue	RD: CW Pothole	Internal		Committed	50172074

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 34009885	Logged by: [REDACTED]	on: 01/05/2025 10:49
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: between 118-132 Saughton Rd N, Corstorphine, Please inspect pavement opposite Carrick Knowe Parish Church		
Location: 118-132 Saughton Rd N, Corstorphine,		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50179413	Defect Number: 42182708	
Enquiry No.: 2098723	Logged by: Verint CRM Connector	on: 19/02/2026 18:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just beside the traffic island heading towards Corstorphine. Deep pot hole		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2098467	Logged by: Verint CRM Connector	on: 19/02/2026 13:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Saughton Road north in a terrible state with several Potholes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2098459	Logged by: Verint CRM Connector	on: 19/02/2026 13:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Near the junction of Roull Road and Saughton Road north		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2097491	Logged by: Verint CRM Connector	on: 18/02/2026 08:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The pothole here has been an issue for a long time. It's location opposite the island makes it very difficulty to avoid hitting.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2097355	Logged by: Verint CRM Connector	on: 17/02/2026 21:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: At the junction of saughton road north/roulle road large pothole		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2096961	Logged by: Verint CRM Connector	on: 17/02/2026 13:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a pothole at the traffic island beside the shops at Carrick Knowe. The pothole is opposite Scotmid, Carrick Knowe. This is unavoidable due to the location and the traffic island. Can this please be repaired urgently.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2096764	Logged by: Verint CRM Connector	on: 17/02/2026 10:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: At the traffic island on Saughton Road North just before you left on to Roull Road there is a huge pothole. Due to the location it is hard to avoid it unless you drive on the pavement. This needs to be repaired asap before cars are damaged.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2096017	Logged by: Verint CRM Connector	on: 16/02/2026 11:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just outside Kwik Fit	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2095322	Logged by: Verint CRM Connector	on: 15/02/2026 07:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road near the pavement side has broken up at an island crossing opposite the small shopping complex at Saughton Road North, Just before the turn to Roull Road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2094843	Logged by: Verint CRM Connector	on: 13/02/2026 21:39
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple big holes at the bus stop with debris all over the pavement	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2093185	Logged by: Verint CRM Connector	on: 11/02/2026 23:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Junction with Tylers Acre Saughton Road is riddled with potholes, ruts, poor repairs etc, making it a hazard for driving and cycling	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2093184	Logged by: Verint CRM Connector	on: 11/02/2026 23:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: South bound carriageway outside Kwik Fit. An area of road requiring urgent attention	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50191969	Defect Number: 42199564	

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2093095	Logged by: Verint CRM Connector	on: 11/02/2026 19:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: It's hard to choose the worst potholes on this stretch of road. There are so many. Ones at the junction are so hard to miss	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50191973	Defect Number: 42199570	
Enquiry No.: 2092750	Logged by: Verint CRM Connector	on: 11/02/2026 13:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road surface is breaking up badly at the bus stop outside 162 saughton road north. It has been previously patched but this has failed. It looks like it may be due to tree roots?	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50191970	Defect Number: 42199566	
Enquiry No.: 2090390	Logged by: Verint CRM Connector	on: 07/02/2026 13:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole on the road which is nearly Impossible to avoid as there stopping place for pedestrians in middle of road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50191642	Defect Number: 42199170	
Enquiry No.: 2077954	Logged by: Verint CRM Connector	on: 16/01/2026 21:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just past the advert boards before the junction to Broomfield Crecent	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50190505	Defect Number: 42197679	
Enquiry No.: 2074021	Logged by: Verint CRM Connector	on: 11/01/2026 13:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just outside Kwik fit on the south bound side of the road. It's a deep pothole that is a danger to cyclists as well as a risk of causing damage to vehicles. There was a pothole there a few months ago that was patched.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2072656	Logged by: Verint CRM Connector	on: 08/01/2026 17:16
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside 8 Sycamore Gardens there is a large pothole in the road. (Saughton Road North)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2060959	Logged by: Verint CRM Connector	on: 19/12/2025 10:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pothole on Saughton Road North at junction with Castle Avenue and a smaller one on opposite side of road at same junction	Contact:	
Enquiry No.: 2055686	Logged by: Verint CRM Connector	on: 09/12/2025 19:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a significantly large pothole on saughton road north before the opening in to roull road. This must have been reported recently as it was filled but due to poor workmanship, the hole has reappeared and probably worse. The road network in the whole area is absolutely shocking and with road closures nearby, the volume of traffic has almost doubled causing serious issues. GET IT SORTED PLEASE.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2055646	Logged by: Verint CRM Connector	on: 09/12/2025 18:08
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Road.		
Type:Foliage / Bush		
Location: Tree fallen on road	Contact:	
Enquiry No.: 2055577	Logged by: Verint CRM Connector	on: 09/12/2025 16:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole at junction.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50188980	Defect Number: 42195825	
Enquiry No.: 2055497	Logged by: Verint CRM Connector	on: 09/12/2025 14:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on the road heading north on Saughton Road North	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2054708	Logged by: Verint CRM Connector	on: 08/12/2025 10:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: deep pothole on Saughton Road North just before you turn left into Dovecot Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2052458

Service: Roads General

Desc.:

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 02/12/2025 16:36

Classification: Request for service

Location: The road has been sinking for ages and this has been filled several times before, again another large pothole has appeared. (How many times can a road be unsatisfactorily repaired)???

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2046336	Logged by: Verint CRM Connector	on: 20/11/2025 15:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is an incredibly deep, square pothole just before the turn onto Roull Road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2045699	Logged by: Verint CRM Connector	on: 19/11/2025 15:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole in the road which has burst my fairly new tyre	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2045680	Logged by: Verint CRM Connector	on: 19/11/2025 15:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Category 1 pothole - wheel /axle breaker. Between pavement and island on northbound side	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50187205	Defect Number: 42193568	
Enquiry No.: 2045645	Logged by: Verint CRM Connector	on: 19/11/2025 14:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole which has already caused damage to several cars At a pelican crossing so a pedestrian could potentially trip	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 2017012	Logged by: Verint CRM Connector	on: 20/09/2025 22:08
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Obscuring sign/light. Location:Pavement. Type:Foliage / Bush		
Location: Sign being obstructed by bush/tree growth.	Contact:	
Enquiry No.: 1999760	Logged by: Verint CRM Connector	on: 20/08/2025 07:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very large deep pothole. Looks dangerous	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1999018	Logged by: Verint CRM Connector	on: 18/08/2025 23:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on the road outside Kwik fit.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1998975	Logged by: Verint CRM Connector	on: 18/08/2025 21:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Repair in road damaged causing a tarmac "wave" and creating a very uneven surface. A Car has been seen to be sent into oncoming lane as driver did not compensate for the directional change the damaged surface caused.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1998371	Logged by: Verint CRM Connector	on: 18/08/2025 09:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge deep pothole outside Kwikfit. Will cause serious damage. Urgent.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1998364	Logged by: Verint CRM Connector	on: 18/08/2025 09:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole outside Kwikfit on zig zag lines at pedestrian crossing	Contact:	
Enquiry No.: 1998313	Logged by: Verint CRM Connector	on: 18/08/2025 09:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large dangerous pothole for pedestrians and cars outside Kwik fit	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1998255	Logged by: Verint CRM Connector	on: 18/08/2025 07:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on southbound carriageway outside KwikFit.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1997298	Logged by: Verint CRM Connector	on: 15/08/2025 18:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole adjacent to 100d Saughton Road North Edinburgh EH127JN	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50183769	Defect Number: 42188625	

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1997293	Logged by: Verint CRM Connector	on: 15/08/2025 18:24
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: 2 potholes outside Kwikfit 69B Saughton Road North Edinburgh EH127JB	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1997289	Logged by: Verint CRM Connector	on: 15/08/2025 18:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 2 potholes on road adjacent to 76 Saughton Road North Edinburgh EH127JX	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50183772	Defect Number: 42188628	
Enquiry No.: 1993048	Logged by: Verint CRM Connector	on: 08/08/2025 19:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole appearing on road between Kwik Fit & No.71	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50183768	Defect Number: 42188623	
Enquiry No.: 1948656	Logged by: Verint CRM Connector	on: 15/05/2025 18:17
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Corner of carrick knowe road and Saughton Road. Someone has smashed into the bollard on the corner and ripped it out the ground leaving a bollard sized hole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1948014	Logged by: Verint CRM Connector	on: 14/05/2025 16:57
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: There is a metal bollard been hit by a vehicle and is lying on the pavement/road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50179937	Defect Number: 42183544	
Enquiry No.: 1902282	Logged by: Verint CRM Connector	on: 11/02/2025 18:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1902268	Logged by: Verint CRM Connector	on: 11/02/2025 18:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: various holes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50174986	Defect Number: 42175857	

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1902267	Logged by: Verint CRM Connector	on: 11/02/2025 18:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: various holes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50174984	Defect Number: 42175855	
Enquiry No.: 1899046	Logged by:	on: 05/02/2025 11:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: At the junction coming from carricknowe towards saughton road. Basically under the tram bridge. The whole road is crumbling and massive potholes	Contact:	
Location: At the junction coming from carricknowe towards saughton road. Basically under the tram bridge. The whole road is crumbling and massive potholes		
Enquiry No.: 1897960	Logged by: Verint CRM Connector	on: 03/02/2025 16:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Uneven surface since pavement extension	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50174267	Defect Number: 42174936	
Enquiry No.: 1894258	Logged by: Verint CRM Connector	on: 28/01/2025 12:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pot hole at crossing	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Job Number: 50173830	Defect Number: 42174335	
Enquiry No.: 1891452	Logged by:	on: 23/01/2025 14:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: The pavement is opposite St David's and Carrick Knowe parish church. The pavement has multiple crators along it, approximately 8. This is a main pavement used by local people including elderly to access local shops. The pavement is progressively getting worse and requires attention.	Contact:	
Location: The pavement is opposite St David's and Carrick Knowe parish church. The pavement has multiple crators along it, approximately 8. This is a main pavement used by local people including elderly to access local shops. The pavement is progressively getting worse and requires attention.		
Enquiry No.: 1888036	Logged by: Verint CRM Connector	on: 17/01/2025 01:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: At the bus stop outside 164 saughton Road North	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1881364	Logged by: Verint CRM Connector	on: 06/01/2025 18:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken area been reported before	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1881098 Service: Roads General Desc.: Location: Road is full of uneven road and potholes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/01/2025 14:47 Classification: Request for service Contact:
Enquiry No.: 1878415 Service: Roads General Desc.: Location: Large pothole on road heading north	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/01/2025 02:02 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1878397 Service: Roads General Desc.: Location: Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 02/01/2025 22:59 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road	Feature Type: Road Asset
Enquiry No.: 1878332 Service: Roads General Desc.: Location: Belter of a pothole heading towards Corstorphine - debris all over the road at the junction with castle ave	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 02/01/2025 19:44 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50172074	Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road Defect Number: 42172029	Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road		Feature Type: Road Asset		Area: North West Locality	
50172074	Pothole on carriageway (RD: CW Junction Castle Avenue Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2025	06/01/2025	Act. ROAD/82100123
50172801	2 potholes (RD: CW Pothole)	At bus stop outside time hair	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/01/2025	15/01/2025	Act. ROAD/82100712
50173830	Pothole on carriageway (RD: CW Outside 64 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/01/2025	30/01/2025	Act. ROAD/82101457
50174267	Pothole on carriageway (RD: CW Outside 98-100 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/02/2025	05/02/2025	Act. ROAD/82101802
50174440	Make safe over lay (RD: CW Cracked/Broken)	Under railway bridge (southbound)	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	06/02/2025	09/02/2025	Act. ROAD/82101956
50174983	Pothole on carriageway (RD: CW Outside Kwik Fit Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	16/02/2025	Act. ROAD/82102393
50174984	Pothole on carriageway (RD: CW Outside Scotmid Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	16/02/2025	Act. ROAD/82102394
50174985	Pothole on carriageway (RD: CW Bus stop outside Union Park Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	17/02/2025	Act. ROAD/82102395
50174987	Pothole on carriageway (RD: CW Junction Castle Avenue Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	14/02/2025	Act. ROAD/82102409

Effective: 01/01/2025 to 21/02/2026
Service: Roads General
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road		Feature Type: Road Asset		Area: North West Locality	
50174988	Pothole on carriageway (RD: CW Junction Meadowhouse Road Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	14/02/2025	Act. ROAD/82102411
50179337	1 cw pothole (RD: CW Pothole)	At junction with castle avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/04/2025	01/05/2025	Act. ROAD/82105586
50179582	Relay 1 whin kerb (Kerb lying on fw at wall) (RD: FW Kerb Dislodged/Rocking)	Outside 6	RD: Cat 3 - 60 Day	Job Complete	06/05/2025	07/05/2025	Act. ROAD/82105798
50179597	Renew granite around both manholes (RD: FW Grano Cracked/Broken)	Outside Shirley's grooming services	RD: Cat 3 - 60 Day	Job Complete	06/05/2025	07/05/2025	Act. ROAD/82105805
50179937	Replace damaged bollard (RD: Bollard Damage/Missing/New)	Outside 135	RD: Cat 3 - 60 Day	Job Complete	15/05/2025	17/07/2025	Act. ROAD/82106060
50183768	Pothole on carriageway (RD: CW Pothole)	Outside Kwik Fit	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/08/2025	19/08/2025	Act. ROAD/82108451
50183769	Pothole on carriageway (RD: CW Pothole)	Outside Scotmid	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/08/2025	19/08/2025	Act. ROAD/82108452
50183772	Pothole on carriageway (RD: CW Pothole)	Outside 78	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/08/2025	19/08/2025	Act. ROAD/82108455
50186479	1 cw pothole (RD: CW Pothole)	Outside time hair	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/11/2025	06/11/2025	Act. ROAD/82110186
50186563	1 cw pothole (RD: CW Pothole)	At junction with castle avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/11/2025	07/11/2025	Act. ROAD/82110237
50187205	1no pothole (RD: CW Pothole)	At the corner of Roull Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/11/2025	20/11/2025	Act. ROAD/82110682
50187342	1 cw pothole (RD: CW Pothole)	Outside 176	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/11/2025	24/11/2025	Act. ROAD/82110790
50188017	1 cw pothole (RD: CW Pothole)	At junction with roull road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/12/2025	04/12/2025	Act. ROAD/82111287
50188980	1no pothole (RD: CW Pothole)	At the junction with Castle Avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/12/2025	30/12/2025	Act. ROAD/82112060
50189633	1 cw pothole (RD: CW Pothole)	Outside kwik fit	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/01/2026	15/01/2026	Act. ROAD/82112593
50190252	Pothole (RD: CW Pothole)	Opposite church at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/01/2026	26/01/2026	Act. ROAD/82113086
50190505	Pothole (RD: CW Pothole)	In bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/01/2026	28/01/2026	Act. ROAD/82113294
50191642	Pothole (RD: CW Pothole)	At road island	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	12/02/2026	Act. ROAD/82114224
50191643	Pothole (RD: CW Pothole)	Outside 71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	12/02/2026	Act. ROAD/82114225
50191644	Pothole (RD: CW Pothole)	At entrance to kwick fit	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	12/02/2026	Act. ROAD/82114226
50191645	Pothole (RD: CW Pothole)	Opposite gas shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	12/02/2026	Act. ROAD/82114227

Effective: 01/01/2025 to 21/02/2026

Service: Roads General

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Hall Terrace south to Saughton Road		Feature Type: Road Asset		Area: North West Locality	
50191969	1 no pothole (RD: CW Pothole)	South bound carriageway outside Kwik Fit.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/02/2026	24/02/2026	Act. ROAD/82114492
50191970	2no potholes (RD: CW Pothole)	At bus stop next to time hair	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/02/2026	24/02/2026	Act. ROAD/82114493
50191973	1no pothole (RD: CW Pothole)	Before the rail bridge after the junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/02/2026	24/02/2026	Act. ROAD/82114494
50192441	Potholes (RD: CW Pothole)	At bus stop outside time hair	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2026	21/02/2026	Act. ROAD/82114921
50192443	Pothole around ironwork (RD: CW Pothole)	At bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	02/03/2026	Act. ROAD/82114923
50192444	Pothole (RD: CW Pothole)	After kwick fit entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	02/03/2026	Act. ROAD/82114924
50192445	Pothole (RD: CW Pothole)	beside the island crossing	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2026	21/02/2026	Act. ROAD/82114925
50192446	Pothole (RD: CW Pothole)	At junction with castle avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	02/03/2026	Act. ROAD/82114926