

Effective: 01/01/2025 to 21/02/2026

Service: Accident Claims (All Services)

Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Saughton Road North (7903234)

Locality: Corstorphine, Edinburgh, City of Edinburgh

Area: North West Locality

Customer Services

Enquiry No.: 2099367

Service: Accident Claims (All Services)

Desc.:

Location: Pothole northbound on saughton road north just before roull road at the pedestrian crossing

Logged by: Verint CRM Connector

Subject: Accident Claim Roads/Lighting

on: 20/02/2026 19:50

Classification: Accident Claim

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Enquiry No.: 2095171

Service: Accident Claims (All Services)

Desc.:

Location: It's right beside the island crossing at the shops. It's unmissable, gaping hole in the road.

Logged by: Verint CRM Connector

Subject: Accident Claim Roads/Lighting

on: 14/02/2026 17:18

Classification: Accident Claim

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Job Number: 50192445

Defect Number: 42200112

Enquiry No.: 2093309

Service: Accident Claims (All Services)

Desc.:

Location: This pothole is deep and dangerous, it has tore the side wall in my passenger front tyre and probably more damage due ti the depth of it, it is a puddle at present so very deceiving, there are also several more. These are all on the shop side of the street going from the Kwik Fit to the row of Shops.

Logged by: Verint CRM Connector

Subject: Accident Claim Roads/Lighting

on: 12/02/2026 09:26

Classification: Accident Claim

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Enquiry No.: 2045637

Service: Accident Claims (All Services)

Desc.:

Location: There is a massive pothole on the road. I unfortunately hit it on Friday evening about 6pm which was unavoidable as it was dark. I've had to have a new tyre fitted today and I'd like to claim compensation for my new tyre. This pothole is still there and it's very dangerous for all drivers. I won't be the only one who's had to get a new tyre. I will include pics.

Logged by: Verint CRM Connector

Subject: Accident Claim Roads/Lighting

on: 19/11/2025 14:36

Classification: Accident Claim

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Enquiry No.: 2030479

Service: Accident Claims (All Services)

Desc.:

Location: There is a significant rise in the tarmac probably due to soft tarmac which has then solidified into a wave shaped indent in the road

Logged by: Verint CRM Connector

Subject: Accident Claim Roads/Lighting

on: 20/10/2025 06:57

Classification: Accident Claim

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset

Job Number: 50185828

Defect Number: 42206742

Effective: 01/01/2025 to 21/02/2026
Service: Accident Claims (All Services)
Site: Saughton Road North (7903234)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1998954
Service: Accident Claims (All Services)
Desc.:
Location: A big pothole on the southbound side of the road outside Kwikfit. 69b

Logged by: Verint CRM Connector
Subject: Accident Claim Roads/Lighting

on: 18/08/2025 20:27
Classification: Accident Claim
Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Hall Terrace south to Saughton Road

Feature Type: Road Asset