

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: South Gyle Broadway (7900533)

Locality: South Gyle, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41268807 - Inspection Batch		Route:	Ad hoc Route			Date:	05/08/2026
42212578	1 number pothole	05/08/2026	At pinned location as no features available	RD: CW Pothole	Internal		Committed	50200967
Batch:	41268806 - Inspection Batch		Route:	Ad hoc Route			Date:	05/08/2026
42212577	2 number potholes	05/08/2026	At pinned location as no features available	RD: CW Pothole	Internal		Committed	50200966
Batch:	41268272 - Inspection Batch		Route:	Ad hoc Route			Date:	29/07/2026
42212080	Tree root pushing up tar and needs resurfaced with HRA and red chips Approximately 3m x 2m	29/07/2026	At bus stop near lamppost SDW10	RD: FW Tree Root Tar	Internal		Committed	50200569
Batch:	41266145 - Inspection Batch		Route:	NW_CW1_East1			Date:	29/06/2026
	No actionable defects found							
Batch:	41265326 - Inspection Batch		Route:	Ad hoc Route			Date:	09/06/2026
42208640	Syl skm signage to be replaced	09/06/2026	Exact Location https://maps.app.goo.gl/h5FAtdbyxAoief	NSL: Pole or and Sign Install	Internal		Committed	50198275
Batch:	41263384 - Inspection Batch		Route:	Ad hoc Route			Date:	18/05/2026
42206600	1 number pothole	18/05/2026	At pinned location on roundabout	RD: CW Pothole	Internal		Committed	50197009
Batch:	41263383 - Inspection Batch		Route:	Ad hoc Route			Date:	18/05/2026
42206599	2 number potholes	18/05/2026	On roundabout at pinned location	RD: CW Pothole	Internal		Committed	50197008
Batch:	41259852 - Inspection Batch		Route:	NW_CF1_SouthGyleBroadway1			Date:	31/03/2026
42203376	Tree roots pushing through tar Approx 4m x 2m	31/03/2026	At lp 57	RD: FW Tree Root Tar	Internal		Uncommitted	50177400
42203387	1x2m patch	31/03/2026	At open till late gyle sign	RD: FW HRA Depression/Sunker	Internal		Uncommitted	50105330
42203394	Tree roots pushing up tar	31/03/2026	At lamppost 38	RD: FW Tree Root Tar	Internal		Uncommitted	50105338
42203392	Tree roots pushing through tar Approx 2m x 1m	31/03/2026	Approx 20m from gogarloch road	RD: FW Tree Root Tar	Internal		Uncommitted	50177412
42203399		31/03/2026		RD: CW Cracked/Broken	Internal		Uncommitted	50156172
42203374	relay 4 sunken tactiles	31/03/2026	Outside entrance to heineken	RD: FW Slabs Rocking	Internal		Uncommitted	50132522
42203401	1 pothole at gully	31/03/2026	Just as you come onto south gyle broadway from gogar roundabout	RD: CW Pothole	Internal		Committed	50194771
42203391	Tree roots pushing through tar Approx 0.5m x 0.5m	31/03/2026	Approx 10m from gogarloch road	RD: FW Tree Root Tar	Internal		No Action Required	
42203375		31/03/2026	Outside lane at south gyle Broadway breaking up	RD: CW Rutting	Internal		Uncommitted	50105305
42203396	Tree roots pushing through tar Approx 2m x 2m	31/03/2026	At south Gyle Wynd bus stop to city	RD: FW Tree Root Tar	Internal		Committed	50132543
42203395	Tree roots pushing through tar Approx 1m x 2m	31/03/2026	Approx 10m east of lp38	RD: FW Tree Root Tar	Internal		Committed	50132540

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 3 - From Gogar Roundabout to South Gyle Access		Feature Type: Road Asset		Area: North West Locality		
Batch: 41259852 - Inspection Batch		Route: NW_CF1_SouthGyleBroadway1				Date: 31/03/2026		
42203386	1m x 1m patch required on crossing	31/03/2026	At crossing on southbound lane opposite JP Morgan	RD: CW Cracked/Broken	Internal		Uncommitted	50105326
42203403	Tree roots pushing through tar Approx 1m x 1m	31/03/2026	Approx 10m from gogarloch road	RD: FW Tree Root Tar	Internal		Committed	50177411
42203388	Cracked and broken surface	31/03/2026	Coming from South Gyle Broadway at the left turn into Gogarloch.	RD: CW Cracked/Broken	Internal		Uncommitted	50190132
42203390	Cracked broken surface	31/03/2026	Gogar road Junctions on Roundabout	RD: CW Cracked/Broken	Internal		Uncommitted	50187565
42203393	Patch required approx 10m x 2m	31/03/2026	Just as you come of roundabout Opposite south gyle business park	RD: CW Cracked/Broken	Internal		Uncommitted	50194770
42203383	Patch required Approx 1m x 1m	31/03/2026	On roundabout between Edinburgh park and entrance to Gyle centre	RD: CW Cracked/Broken	Internal		Uncommitted	50156181
42203397	Patch required around manhole	31/03/2026	At lamppost 4	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50105343
42203385	Patch required Approx 10m x 2.5m	31/03/2026	As you come of slip road from Glasgow road onto south Gyle broadway	RD: CW Rutting	Internal		Uncommitted	50156182
42203382	Carriageway breaking up at junction	31/03/2026	Edinburgh park approach to roundabout	RD: CW Rutting	Internal		Uncommitted	50105314
42203398		31/03/2026		RD: CW Cracked/Broken	Internal		Uncommitted	50156169
42203377	Tree roots pushing up tar for 15m	31/03/2026	At the side of no6	RD: FW Tree Root Tar	Internal		Committed	50105311
42203400	Cracked broken surface	31/03/2026	Entire roundabout	RD: CW Cracked/Broken	Internal		Uncommitted	50190801
Batch: 41259149 - Inspection Batch		Route: NW_CW1_East1				Date: 24/03/2026		
No actionable defects found								
Batch: 41255927 - Inspection Batch		Route: Ad hoc Route				Date: 28/02/2026		
42200779	1 no pothole	28/02/2026	Entrance to roundabout at the stones office building to let	RD: CW Pothole	Internal		Committed	50192944
Batch: 41254483 - Inspection Batch		Route: Ad hoc Route				Date: 20/02/2026		
42200093	1no pothole	20/02/2026	At bus stop next to lamppost SDW10	RD: CW Pothole	Internal		Committed	50192426
Batch: 41254473 - Inspection Batch		Route: Ad hoc Route				Date: 20/02/2026		
42200081	2no potholes	20/02/2026	On approach to roundabout from South Gyle access	RD: CW Pothole	Internal		Committed	50192415
Batch: 41254462 - Inspection Batch		Route: Ad hoc Route				Date: 20/02/2026		
42200069	4no potholes	20/02/2026	On East side of roundabout	RD: CW Pothole	Internal		Committed	50192403
Batch: 41254461 - Inspection Batch		Route: Ad hoc Route				Date: 20/02/2026		
42200068	7no potholes	20/02/2026	On west side of roundabout	RD: CW Pothole	Internal		Committed	50192402
Batch: 41252781 - Inspection Batch		Route: Ad hoc Route				Date: 10/02/2026		
42199077	Refresh all lane markings and at junctions	10/02/2026	From Goya's roundabout to gyle centre round about	RD: Markings Refresh	Internal		Uncommitted	50191553
Batch: 41252109 - Inspection Batch		Route: Ad hoc Route				Date: 06/02/2026		
42198686	1 cw pothole	06/02/2026	On roundabout at south gyle wynd	RD: CW Pothole	Internal		Committed	50191257
Batch: 41251215 - Inspection Batch		Route: Ad hoc Route				Date: 30/01/2026		
42198109	Cracked broken surface	30/01/2026	Entire roundabout	RD: CW Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 24/07/2025 to 26/08/2026

Service: Roads General

Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.		
Asset:	1.00	Asset - Locn.:	Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type:	Road Asset		Area:	North West Locality		
Batch:	41249368 - Inspection Batch			Route:	Ad hoc Route			Date:	21/01/2026	
42197263	Pothole in cross track	21/01/2026	Southgyle Broadway, heading eastwards towards Gyle roundabout right hand lane	RD: CW Pothole	Internal		Committed		50190138	
Batch:	41249363 - Inspection Batch			Route:	Ad hoc Route				Date:	21/01/2026
42197258	Pothole	21/01/2026	Coming off south gyle onto roundabout in middle of lanes	RD: CW Pothole	Internal		Committed		50190133	
Batch:	41249362 - Inspection Batch			Route:	Ad hoc Route				Date:	21/01/2026
42197257	Cracked and broken surface	21/01/2026	Coming from South Gyle Broadway at the left turn into Gogarloch.	RD: CW Cracked/Broken	Internal		No Action Required			
Batch:	41249361 - Inspection Batch			Route:	Ad hoc Route				Date:	21/01/2026
42197256	Pothole	21/01/2026	Coming off roundabout at that junction	RD: CW Pothole	Internal		Committed		50190131	
Batch:	41249359 - Inspection Batch			Route:	Ad hoc Route				Date:	21/01/2026
42197255	Please renew 3 possibly 4 damaged railings on road island	21/01/2026	Just before/after roundabout	RD: Railing Damage/Missing/Nev	Internal		Committed		50190130	
Batch:	41248503 - Inspection Batch			Route:	NW_CW1_East1				Date:	15/01/2026
42196618	1 cw pothole	15/01/2026	At south gyle wynd bus stop to city	RD: CW Pothole	Internal		Committed		50189641	
Batch:	41244625 - Inspection Batch			Route:	Ad hoc Route				Date:	15/12/2025
42195267	Pothole	15/12/2025	Inside lane of roundabout	RD: CW Pothole	Internal		Committed		50188510	
Batch:	41244624 - Inspection Batch			Route:	Ad hoc Route				Date:	15/12/2025
42195266	Pothole	15/12/2025	Just after crossing heading to gyle roundabout	RD: CW Pothole	Internal		Committed		50188509	
Batch:	41244623 - Inspection Batch			Route:	Ad hoc Route				Date:	15/12/2025
42195265	Cracked broken carrigeway	15/12/2025	Inside lane heading to gyle roundabout just before crossing	RD: CW Cracked/Broken	Internal		Uncommitted		50188508	
Batch:	41243420 - Inspection Batch			Route:	Ad hoc Route				Date:	02/12/2025
42194493	Pothole	02/12/2025	At junction with roundabout lane heading for s gyle crescent	RD: CW Pothole	Internal		Committed		50187909	
Batch:	41242897 - Inspection Batch			Route:	Ad hoc Route				Date:	26/11/2025
42194043	Cracked broken surface	26/11/2025	Gogar road Junctions on Roundabout	RD: CW Cracked/Broken	Internal		No Action Required			
Batch:	41242418 - Inspection Batch			Route:	NW_CW1_East1				Date:	24/11/2025
	No actionable defects found									
Batch:	41237867 - Inspection Batch			Route:	Ad hoc Route				Date:	03/10/2025
42190481	5no potholes	03/10/2025	Where the slip road meets the bypass either side of lp47	RD: CW Pothole	Internal		Committed		50185131	
Batch:	41234767 - Inspection Batch			Route:	NW_CW1_East1				Date:	15/08/2025
	No actionable defects found									

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 3 - From Gogar Roundabout to South Gyle Access		Feature Type: Road Asset		Area: North West Locality		
Batch: 41234277 - Inspection Batch			Route: Ad hoc Route			Date: 07/08/2025		
42188236	Damaged junction box on verge	07/08/2025	Lpost SDW04	RU: Utility Apparatus	Internal		Uncommitted	50183460

Customer Services

Enquiry No.: 34010795		Logged by: [REDACTED]		on: 06/02/2026 12:43	
Service: Roads General		Subject: Road Markings: Defective		Classification: Request for service	
Desc.: White lining at South Gyle Broadway					
Location: please inspect white lines at ped xing near tramline				Contact: 0	
Plot Number: 1.00		Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access			Feature Type: Road Asset
Job Number: 50191553		Defect Number: 42199077			
Enquiry No.: 34010456		Logged by: [REDACTED]		on: 13/10/2025 10:31	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.: please inspect surface of of the carriageway condition on South Gyle Roundabout, adjacent to Morrisons Petrol Station at the Gyle shopping centre					
Location: South Gyle Broadway				Contact:	
Plot Number: 1.00		Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access			Feature Type: Road Asset
Enquiry No.: 34010455		Logged by: [REDACTED]		on: 13/10/2025 10:26	
Service: Roads General		Subject: Road Markings: Defective		Classification: Request for service	
Desc.: Please inspect road markings on South Gyle Roundabout, adjacent to Morrisons Petrol Station at the Gyle shopping centre,					
Location: south gyle roundabout				Contact: 0	
Plot Number: 1.00		Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access			Feature Type: Road Asset
Enquiry No.: 2203018		Logged by: Verint CRM Connector		on: 25/08/2026 12:22	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: Many areas of lifted tarmac causing puddles to form in rain and fast traffic going through them splashing people waiting in bus shelter which opens o to road. Very uneven surface when pedestrians crossing from one side to other. Possible trip hazard on busy road.				Contact:	
Plot Number: 1.00		Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access			Feature Type: Road Asset
Enquiry No.: 2198390		Logged by: [REDACTED]		on: 17/08/2026 14:17	
Service: Roads General		Subject: Road: General Enquiry		Classification: General Enquiry	
Desc.: Road surface is unaven and bits a flying up into the air when its raining. This is worst at the bus shelter and the guttering is so bad people are fvlooded at the bus stoppp. This been like this for months					
Location: South Gyle Broadway				Contact:	
Enquiry No.: 2191969		Logged by: Verint CRM Connector		on: 06/08/2026 11:41	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: road lines faded and need to be repainted				Contact:	
Plot Number: 1.00		Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access			Feature Type: Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2190887 Service: Roads General Desc.: Location: Large pothole in failing road crossing track	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/08/2026 18:16 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50200966	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access Defect Number: 42212577	Feature Type: Road Asset
Enquiry No.: 2186841 Service: Roads General Desc.: Location: Tree roots pushing out on tarmac at bus stop.Which I tripped over and fell.in doing so hurt my self .	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 28/07/2026 10:35 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50200569	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access Defect Number: 42212080	Feature Type: Road Asset
Enquiry No.: 2185901 Service: Roads General Desc.: Problem: Overgrown. Location:Pavement. Type:Foliage / Bush Location: South Gyle Broadway, between Gogarloch roundabout and Gyle roundabout. Trees all overhanging, bushes overgrown, all spreading onto pavement the whole way along this part of the road.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 26/07/2026 12:53 Classification: Request for service Contact:
Enquiry No.: 2182219 Service: Roads General Desc.: Location: Uneven tarmac widespread across road, skidding with vehicle wheels, multiple areas of potholes/road damage.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/07/2026 17:16 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2178175 Service: Roads General Desc.: Location: Right next to the bus stop, top layer of tar has come off	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/07/2026 17:21 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2162946 Service: Roads General Desc.: Location: Very deep potholes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/06/2026 17:34 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2157230 **Logged by:** [REDACTED] **on:** 03/06/2026 08:00

Service: Roads General **Subject:** Road: General Enquiry **Classification:** General Enquiry

Desc.: Summary

First name : [REDACTED]

Last name : [REDACTED]

email : [REDACTED]

telephone number : [REDACTED]

Full address : [REDACTED]

What area does your complaint relate to ? : road_travel_parking

If your comments relate to a council service for which you have an account then please provide an account number :

Short description of complaint : A lane was closed at rush hour on South Gyle Broadway between the Gogar Roundabout and the Gyle Roundabout today, Tuesday 01/06. It cause major delays

Please provide the details of the complaint : As above, a lane closure was put in place between the Gogar Roundabout and the Gyle Roundabout at rush hour on 01/06/26. The main entrance to Edinburgh Park is accessed by that roundabout. The two workers were working on the inside of the pavement and their van was blocking the road. Why were they given permission to close a lane at 8am on a Tuesday morning? No-one seemed to know what the issue was, I was listening to Forth One the whole time and they weren't aware of any closure so they could warn drivers, the queues just kept building. It took me 2 hours to get from the Hermiston Gait to my office in Edinburgh Park, part of my journey that should have taken 5 minutes. Colleagues had similar issues. Speaking to a resource planner in my office they had a lot of staff unable to get in to start work so whole businesses were affected. Every road approaching the Gogar roundabout was affected with thousands of drivers stuck, the whole roundabout was getting stuck completely for 3 hours (my final colleague was able to finally get in at 11am when he should have been in by 9.30). Colleagues who managed to get some warning to avoid the area didn't fair much better due to the roadworks at Sighthill. Buses would also be affected due to this because of the issues caused by 2 oblivious workmen.

How would you like us to deal with this? : Do not give permission in the future for any lane closures on key roads like this during rush hour. Identify the company that was doing the work and feed back to them that closing a lane on a main thoroughfare at rush hour isn't acceptable or sensible to anyone with an ounce of common sense. They were working on something next to the trams but I didn't see the name on the van, but as they had closed a lane, I would assume they would have had to have permission so the council should have a record of the company.

Location: between the Gogar Roundabout and the Gyle Roundabout

Contact:

Enquiry No.: 2156613 **Logged by:** [REDACTED] **on:** 02/06/2026 10:05

Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** General Enquiry

Desc.: the roadworks that have started today has caused very big tail backs on all routes into edinburgh he would like to know who gave permissn for this on rush hour

Location: the roadworks that have started today has caused very big tail backs on all routes into edinburgh he would like to know who gave permissn for this on rush hour **Contact:**

Enquiry No.: 2152314 **Logged by:** Verint CRM Connector **on:** 25/05/2026 09:26

Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Carriageway littered with potholes, open joints and broken surfacing. Dangerous for all road users trying to join SGBway **Contact:**

Plot Number: 1.00

Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access

Feature Type: Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2151525 **Logged by:** Verint CRM Connector **on:** 22/05/2026 18:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: road breaking up at bus stop north side of Southgyle Broadway both lanes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2148139 **Logged by:** Verint CRM Connector **on:** 16/05/2026 15:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The whole roundabout is wrecked. Full of potholes. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50197008 **Defect Number:** 42206599

Enquiry No.: 2148112 **Logged by:** Verint CRM Connector **on:** 16/05/2026 14:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Traffic lights coming out of the Gyle on to Broadway turning into town. Lights still getting stuck on red until a vehicle comes opp side to turn right into Gyle shopping car park. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2144190 **Logged by:** Verint CRM Connector **on:** 08/05/2026 14:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes and crumbling surface. Dangerous for all road users when trying to join SGB, especially cyclists. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2133336 **Logged by:** Verint CRM Connector **on:** 20/04/2026 07:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole stretch **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2133330 **Logged by:** Verint CRM Connector **on:** 20/04/2026 07:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous potholes on the entire stretch of the roundabout **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2131097 **Logged by:** Verint CRM Connector **on:** 15/04/2026 13:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Roundabout is littered with potholes and uneven repairs , car moves and slides when going round. Accidents waiting to happen **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2129229 **Logged by:** Verint CRM Connector **on:** 12/04/2026 08:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The slip road here onto gyle Broadway has lots of holes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2129170 **Logged by:** Verint CRM Connector **on:** 11/04/2026 21:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Uneven surface coming of roundabout eastbound. The original road surface below is coming through in multiple places. **Contact:**

Enquiry No.: 2126088 **Logged by:** Verint CRM Connector **on:** 06/04/2026 17:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pot holes on roundabout & south gyle broadway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2117729 **Logged by:** Verint CRM Connector **on:** 22/03/2026 18:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road is full of holes and cracked tarmac all the way along to the south gyle access difficult to get photos on a busy road. it would be good if you could inspect the area for yourselves. I'm sure the team that put tarmac on on the roundabout at gogarloch road can confirm that there were more holes to be filled **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2112690 **Logged by:** Verint CRM Connector **on:** 14/03/2026 17:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Whole surface breaking up.both sides of carriageway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2110739 **Logged by:** Verint CRM Connector **on:** 11/03/2026 17:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Lots of pot holes on the round about going into Gogarloch. Since our flat tyre pot holes have all had a temporary fix. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2109374 **Logged by:** Verint CRM Connector **on:** 09/03/2026 16:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2109068 **Logged by:** Verint CRM Connector **on:** 09/03/2026 11:59
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Footway on south side of South Gyle Broadway is badly damaged/broken up by tree roots. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2108074 **Logged by:** Verint CRM Connector **on:** 06/03/2026 21:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Critical issue, most of the roundabout has large potholes in it, needs fixed ASAP due to difficult driving conditions to avoid massive potholes so not to damage my car **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2107928 **Logged by:** Verint CRM Connector **on:** 06/03/2026 15:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There's a really big and deep pothole. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2107773 **Logged by:** Verint CRM Connector **on:** 06/03/2026 12:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: very bad pothole around entire roundabout almost blow my tire out, disgraceful **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2107454 **Logged by:** Verint CRM Connector **on:** 05/03/2026 21:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The whole roundabout has massive holes in the road more to the inside lane and off to roundabout down south gyle broadway towards the Travelodge **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2106750 **Logged by:** Verint CRM Connector **on:** 04/03/2026 23:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Series of potholes on the roundabout. Where South Gyle Broadway meets Gogarloch Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2106739 **Logged by:** Verint CRM Connector **on:** 04/03/2026 22:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: massive potholes around the entire roundabout becoming unavoidable and damaging tires **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2106738 **Logged by:** Verint CRM Connector **on:** 04/03/2026 22:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the condition of this entire roundabout is poor, there is multiple lines of potholes are unavoidable and will cause damage to tyres or vehicles if not fixed soon **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2106726 **Logged by:** Verint CRM Connector **on:** 04/03/2026 22:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: South gyle Broadway.....roundabouts are atrocious with deep potholes. Accidents are going to happen with vehicles steering out of lanes to avoid the deep trenches all round the roundabouts. This follows o. The whole road to the next roundabout. Vehicle damage and or accidents will most definitely occur. This has also been like this for several weeks and getting worse. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2106414 **Logged by:** Verint CRM Connector **on:** 04/03/2026 13:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large potholes at roundabout **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2106365 **Logged by:** Verint CRM Connector **on:** 04/03/2026 12:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Crumbling surface **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2105797 **Logged by:** [REDACTED] **on:** 03/03/2026 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: I understand you get a lot of emails regarding the condition of the roads. I just want to report an unsuitable and unsafe part of road at South gyle Broadway. It's two area's of the road that goes around the roundabout, there is no way to miss the very large holes that cover the width of the road. I've enclosed a picture of the roundabout and also a picture of part of the hole in the road.
Location: **Contact:**

Enquiry No.: 2105548 **Logged by:** Verint CRM Connector **on:** 03/03/2026 10:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The substantial number of large potholes on this roundabout have previously been reported, however, nothing whatsoever has been done to repair these. You clearly think they fall into your category 5 list of priorities. **Contact:**

Based upon the state of the roadway, instead of Edinburgh being looked upon as a world class city, it could easily be mistaken for a third world shanty town.

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2105119 **Logged by:** Verint CRM Connector **on:** 02/03/2026 15:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Update from customer - top coat to road is causing stones/ grit to fly into the air and hit pedestrian s waiting for the bus. Road defects men that when itv rainsd water is lying on thesurface causing water tobe spalshed on to pedestrians waiting for bus when normal traffic is going by
Location: first bus stop on left hand side after Gogarloch roundabout heading into town - pothole to be assessed and repaired ASAP **Contact:**

Enquiry No.: 2104843 **Logged by:** Verint CRM Connector **on:** 02/03/2026 09:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This is getting bad, pot holes all over this roundabout. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2104766 **Logged by:** [REDACTED] **on:** 02/03/2026 08:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Numerous potholes around the entire roundabout
Location: **Contact:**

Enquiry No.: 2104535 **Logged by:** Verint CRM Connector **on:** 01/03/2026 16:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Uneven road surface **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2103879 **Logged by:** Verint CRM Connector **on:** 27/02/2026 22:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: GET THIS ROAD FIXED **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2102328 **Logged by:** Verint CRM Connector **on:** 25/02/2026 17:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole.... Deep and extremely wide... drove over and my car rattled to the core. Going to cause some massive damage **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Job Number: 50192944 **Defect Number:** 42200779

Enquiry No.: 2101622 **Logged by:** Verint CRM Connector **on:** 24/02/2026 19:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole that is now effectively a massive hole in the road. Cars wheels/tyres are being significantly damaged. Potholes here have been reported numerous time by many people over last 2/3 weeks. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2101351 **Logged by:** Verint CRM Connector **on:** 24/02/2026 13:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100989 **Logged by:** Verint CRM Connector **on:** 24/02/2026 04:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes on the roundabout one large on in particular on my pin **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100969 **Logged by:** Verint CRM Connector **on:** 23/02/2026 22:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large deep pothole. Dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100967 **Logged by:** Verint CRM Connector **on:** 23/02/2026 22:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Entire roundabout dangerous for all road users. Huge potholes, large poorly repaired sections reopened. Open joints. Accident waiting to happen. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100824 **Logged by:** Verint CRM Connector **on:** 23/02/2026 17:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the length of this road is a complete mess, requires resurfaced **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100772 **Logged by:** Verint CRM Connector **on:** 23/02/2026 16:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous pot holes all around this round about **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2100569 **Logged by:** Verint CRM Connector **on:** 23/02/2026 13:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The round about is littered with massive pot holes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2100027 **Logged by:** Verint CRM Connector **on:** 22/02/2026 16:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 large potholes on this roundabout if you exit Gogarloch Rd and are turning right on roundabout towards Gyle Centre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2099125 **Logged by:** Verint CRM Connector **on:** 20/02/2026 13:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The whole roundabout is in very bad condition, have to swerve all over the road to avoid hitting deep holes ,this needs repaired ASAP before someone get injured or a car is badly damaged , this whole area needs looking as there are holes everywhere, I have reported this many times and still nothing has been done **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2098886 **Logged by:** Verint CRM Connector **on:** 20/02/2026 08:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Roundabout circulatory carriageway is full of potholes which means you need to have your eyes on the road surface all the time to avoid. Very unsafe **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2098848 **Logged by:** Verint CRM Connector **on:** 19/02/2026 23:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes round this roundabout. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2098426 **Logged by:** Verint CRM Connector **on:** 19/02/2026 12:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Row of potholes and uneven tarmac at entrance to round about. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Job Number: 50192415 **Defect Number:** 42200081

Enquiry No.: 2097849 **Logged by:** Verint CRM Connector **on:** 18/02/2026 14:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Coming from South Gyle Broadway, onto South Gyle access and round to the business park, there are a number of huge potholes which have been there for weeks. Unable to stop safely to take photos. This has cause damage to the suspension of my car and I have to use this route weekly to get to work. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2097566 **Logged by:** Verint CRM Connector **on:** 18/02/2026 09:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the whole roundabout is in bad condition, there are several reports of potholes already from over a week ago, this is going to damage someones car if not repaired soon. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2097562 **Logged by:** Verint CRM Connector **on:** 18/02/2026 09:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the roundabout is peppered with potholes all around and they are getting worse every day. unable to take photos due to reporting at home and not at the actual site. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2096687 **Logged by:** Verint CRM Connector **on:** 17/02/2026 08:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The entire roundabout is covered in potholes on the road. Urgent repair required to prevent major damage to vehicles and/or accident. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Job Number: 50192402 **Defect Number:** 42200068

Enquiry No.: 2096686 **Logged by:** Verint CRM Connector **on:** 17/02/2026 08:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole on the road. Urgent repair required to prevent major damage to vehicles and/or accident. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2096535 **Logged by:** Verint CRM Connector **on:** 16/02/2026 20:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Avoiding the mass of potholes on Glasgow Road, came round by the traffic lights heading for the City of Edinburgh Bypass and hit a pot hole. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2096511 **Logged by:** Verint CRM Connector **on:** 16/02/2026 19:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: As you come out of the Gyle shopping centre and turn left onto south gyle broadway, near Morrisons petroleum stations many pot holes in road. Quite dangerous! **Contact:**

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2096378 **Logged by:** Verint CRM Connector **on:** 16/02/2026 17:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at bus stop "repaired" a couple of weeks ago is back as bad as before **Contact:**
"repair "

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50192426 **Defect Number:** 42200093

Enquiry No.: 2096193 **Logged by:** Verint CRM Connector **on:** 16/02/2026 14:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The roundabout and the road leading to south Gyle Cres is full of potholes. Very dangerous and it's not just one pothole it's the whole roundabout full of them that need to be avoided or it will damage cars. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2095726 **Logged by:** Verint CRM Connector **on:** 15/02/2026 19:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole on the road that will damage tyres if hit. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2094991 **Logged by:** Verint CRM Connector **on:** 14/02/2026 11:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous large potholes on roundabout at Gogarloch road to south Gyle roadway. Causing damage to cars. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50192403 **Defect Number:** 42200069

Enquiry No.: 2094714 **Logged by:** Verint CRM Connector **on:** 13/02/2026 17:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Just on slip road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2093894 **Logged by:** Verint CRM Connector **on:** 12/02/2026 17:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole on inside lane of roundabout south gyle Broadway as you turn right having exited from Gogarloch road. Vehicles have to manoeuvre to avoid additional issue for motorbikes due to filling with rainwater. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2093401 **Logged by:** Verint CRM Connector **on:** 12/02/2026 10:43
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement has broken up due to tree roots. Now unusable for walking or wheeling **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2093159 **Logged by:** Verint CRM Connector **on:** 11/02/2026 21:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the roundabout at south gyle broadway it's full of pot holes which are getting bigger by the day! Which needs addressing as this is causing issues when trying to navigate round the roundabout. This must be causing damage to cars . **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2093092 **Logged by:** Verint CRM Connector **on:** 11/02/2026 19:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road on the roundabout is riddled with holes. Particularly bad when the roads merge onto it **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2092907 **Logged by:** Verint CRM Connector **on:** 11/02/2026 15:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This stretch of road is ridiculous Hazardous potholes which i am sick of reporting **Contact:**

Enquiry No.: 2092129 **Logged by:** Verint CRM Connector **on:** 10/02/2026 15:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The roundabout is littered with potholes and is getting increasingly dangerous to navigate especially cyclists will end up coming off their bikes and being injured. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2091751 **Logged by:** Verint CRM Connector **on:** 10/02/2026 08:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Major pot hole on road at roundabout and on road approaching the roundabout toward the south gyle business park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2091418 **Logged by:** Verint CRM Connector **on:** 09/02/2026 14:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Severe pot hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2091409 Service: Roads General Desc.: Location: OPEN JOINTS CRACKED ROAD SURFACE	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/02/2026 14:23 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2091398 Service: Roads General Desc.: Location: open hole on roundabout tyres go into it	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/02/2026 14:13 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2091189 Service: Roads General Desc.: Location: Crumbling carriageway, littered with potholes and open joints. Dangerous for two wheeled road users. Reported previously	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/02/2026 10:31 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2090458 Service: Roads General Desc.: Location: All the roundabout surface is in terrible condition with multiple holes all the way round it ,now getting to the stage where wheel damage will occur, the wholes in this location are now becoming a joke and have been reported many times	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 07/02/2026 14:51 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2090010 Service: Roads General Desc.: Location: The whole roundabout has a large number of potholes on it. it seems to be worse where the joints are in the middle of the road.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/02/2026 14:16 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2087710 Service: Roads General Desc.: Location: South Gyle broadway roundabout which is next to Gyle Avenue	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/02/2026 06:58 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2087709 Service: Roads General Desc.: Location: The roundabout at South Gyle Broadway	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/02/2026 06:55 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2087202 **Logged by:** Verint CRM Connector **on:** 02/02/2026 11:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The roundabout on South Gyle Broadway at the top of Gogarloch Road has loads of large pot holes round it. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2084833 **Logged by:** Verint CRM Connector **on:** 28/01/2026 21:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: hole near the join on point of bypass **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2083078 **Logged by:** Verint CRM Connector **on:** 26/01/2026 12:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken surfacing, uneven and dangerous to joining traffic. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2083077 **Logged by:** Verint CRM Connector **on:** 26/01/2026 12:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken surfacing, poorly reinstated potholes, dangerous condition for all road users. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2080292 **Logged by:** Verint CRM Connector **on:** 21/01/2026 09:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Roundabout is full of uneven road and potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2080291 **Logged by:** Verint CRM Connector **on:** 21/01/2026 09:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road is full of potholes around the roundabout Have to swerve to avoid!!!! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Job Number: 50190801 **Defect Number:** 42203400

Enquiry No.: 2080023 **Logged by:** Verint CRM Connector **on:** 20/01/2026 16:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Southgyle Broadway, heading eastwards towards Gyle Centre roundabout. Large pothole on offside lane, adjacent to central reservation. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Job Number: 50190138 **Defect Number:** 42197263

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2079342 Service: Roads General Desc.: Location: multiple potholes at roundabout - BLYTH & BLYTH, CORNERSTONE, SOUTH GYLE CRESCENT, EDINBURGH, EH12 9EB	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/01/2026 17:00 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190131	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access Defect Number: 42197256	Feature Type: Road Asset
Enquiry No.: 2076996 Service: Roads General Desc.: Location: Roundabout, huge gaping hole, damaged my tyre. Unacceptable, been there for ages. In middle of lanes on roundabout on South Gyle Broadway at the left turn into Gogarloch.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/01/2026 14:53 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190132	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access Defect Number: 42203388	Feature Type: Road Asset
Enquiry No.: 2076959 Service: Roads General Desc.: Location: pothole at bus stop to city	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/01/2026 14:18 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2066619 Service: Roads General Desc.: Location: Hole at the start of the bypass.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/12/2025 19:53 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2062607 Service: Roads General Desc.: Location: When you are driving on South Gyle Broadway, there used to be bollards in the gap between the two sides. These have since been removed which is now encouraging cars to do U Turns in a very dangerous place. Photos attached for better reference. There has been a few near misses since this change and only a matter of time before an accident.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 23/12/2025 11:52 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset
Enquiry No.: 2059057 Service: Roads General Desc.: Location: There are so many holes all around this roundabout. Can't point out just one, whole surface needs redone	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/12/2025 20:19 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 3 - From Gogar Roundabout to South Gyle Access	Feature Type: Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2056972 **Logged by:** Verint CRM Connector **on:** 11/12/2025 14:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: in inside lane as you come from gogar roundabout towards gyle roundabout, large deep pothole, very dangerous, damaged car wheel and tyre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50188508 **Defect Number:** 42195265

Enquiry No.: 2055400 **Logged by:** Verint CRM Connector **on:** 09/12/2025 12:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Joins in the road are open caused tire damage the round about has holes all round it and its worst as you drive off the roundabout into gogarloch **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2055121 **Logged by:** Verint CRM Connector **on:** 08/12/2025 20:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous potholes on roundabout. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50188510 **Defect Number:** 42195267

Enquiry No.: 2052312 **Logged by:** Verint CRM Connector **on:** 02/12/2025 13:23
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: footpath raised because of roots growing under footpath heading east from Gogarloch **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2051819 **Logged by:** Verint CRM Connector **on:** 01/12/2025 14:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a pot hole soon after you join the bypass. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2050530 **Logged by:** Verint CRM Connector **on:** 28/11/2025 13:45
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: trip hazard on footpath due to vegetation roots growing under footpath, the footpath has been raised **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2050197 **Logged by:** Verint CRM Connector **on:** 28/11/2025 07:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Middle of the roadnon the round about. Large pothole which will cause damage to vehicles. This looks like a previous repair has failed and is crumbling. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50187909 **Defect Number:** 42194493

Enquiry No.: 2048593 **Logged by:** Verint CRM Connector **on:** 25/11/2025 12:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken up srufacing/large open joints and potholes. Dangerous. Reported several times previously and no repairs carried out. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2048592 **Logged by:** Verint CRM Connector **on:** 25/11/2025 12:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes and broken up surfacing. Poorly repaired previously. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50187565 **Defect Number:** 42203390

Enquiry No.: 2047109 **Logged by:** Verint CRM Connector **on:** 22/11/2025 10:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The roundabout on South Gyle broadway at the Gyle as you approach it travelling towards Gogar. There are 3 lanes but the road markings have worn away/ come off and over the last few months there have been lots of near misses as people are unable to follow the Highway Code for lane placement. Please can the arrows be repainted to avoid a collision **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2044755 **Logged by:** Verint CRM Connector **on:** 18/11/2025 07:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road outside Forrester High School damaged and holding large amounts of water. Traffic causing entire pavement and pedestrians to be soaked. **Contact:**

Enquiry No.: 2021771 **Logged by:** Verint CRM Connector **on:** 01/10/2025 07:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road between traffic lights and Forrester high school entrance is damaged and holding large amount of water when raining. People on pavement being soaked when traffic hitting water. **Contact:**

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2019970 **Logged by:** Verint CRM Connector **on:** 27/09/2025 06:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Start of the bypass, coming onto the bypass from Glasgow Road. Lane 1 has a huge pothole on the slight corner bit **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 2016269 **Logged by:** Verint CRM Connector **on:** 18/09/2025 22:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sliproad from South Gyle where it joins City Bypass.
The seam, approx 30 metres, where the 2 carriageways meet has a large gap throughout its length and requires filling - try driving over it and feel the bumps! Reported previously and received confirmation that it had been repaired, however it wasn't. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50185131 **Defect Number:** 42190481

Enquiry No.: 2013925 **Logged by:** Verint CRM Connector **on:** 14/09/2025 15:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are a few deep holes as you first join on to the City bypass. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 1995768 **Logged by:** Verint CRM Connector **on:** 14/08/2025 08:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Carriageway crumbling and uneven. Poorly repaired. Dangerous for road users, especially cyclists trying to navigate roundabout. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset

Enquiry No.: 1991843 **Logged by:** [REDACTED] **on:** 07/08/2025 08:38
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Sunken toby cover
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 3 - From Gogar Roundabout to South Gyle Access **Feature Type:** Road Asset
Job Number: 50183460 **Defect Number:** 42188236

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 3 - From Gogar Roundabout to South Gyle Access		Feature Type: Road Asset		Area: North West Locality	
50105311	Tree roots pushing up tar for 15m (RD: FW Tree Root Tar)	At the side of no6	RD: Cat 4 - Programmed	Job Committed	04/02/2022	04/02/2023	Est. ROAD/82116783

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 3 - From Gogar Roundabout to South Gyle Access		Feature Type: Road Asset		Area: North West Locality	
50120181	Road Markings: Defective - please see document attached....Road Markings Missing/Deteriorated Category: Roads/highways Give Way road markings are no longer visible. This is on the slip road from Glasgow Road onto South Gyle Broadway. (Enquiry 1447277)refresh carriageway markings (RD: Markings Refresh)	Glasgow Road/South Gyle Broadway slip Road	RD: Cat 4 - Programmed	Reschedule: TM Required	18/10/2022	18/10/2023	Est. ROAD/82105610
50132540	Tree roots pushing through tar (RD: FW Tree Root Tar)	Approx 10m east of Ip38	RD: Cat 4 - Programmed	Job Committed	21/03/2023	21/03/2024	Est. ROAD/82116784
50132543	Tree roots pushing through tar (RD: FW Tree Root Tar)	At south Gyle Wynd bus stop Eastbound	RD: Cat 4 - Programmed	Job Committed	21/03/2023	21/03/2024	Est. ROAD/82116785
50177411	Tree roots pushing through tar Approx 0.5m x 0.5m (RD: FW Tree Root Tar)	Approx 10m from gogarloch road	RD: Cat 4 - Programmed	Job Committed	21/03/2025		ROAD/82116786
50180841	Refresh markings on roundabout (RD: Markings Refresh)	Junction Gogarloch Road	RD: Cat 4 - Programmed	Job Committed	04/06/2025		ROAD/82114543
50181079	Direction Arrows required (RD: Markings Refresh)	Junction Edinburgh Park and South Gyle Broadway	RD: Cat 4 - Programmed	Job Scheduled	09/06/2025		ROAD/82114542
50185131	5no potholes (RD: CW Pothole)	Where the slip road meets the bypass either side of Ip47	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/10/2025	09/10/2025	Act. ROAD/82109347
50187909	Pothole (RD: CW Pothole)	At junction with roundabout lane heading for s gyle crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/12/2025	04/12/2025	Act. ROAD/82111206
50188509	Pothole (RD: CW Pothole)	Just after crossing heading to gyle roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/12/2025	16/12/2025	Act. ROAD/82111671
50188510	Pothole (RD: CW Pothole)	Inside lane of roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/12/2025	16/12/2025	Act. ROAD/82111672
50189641	1 cw pothole (RD: CW Pothole)	At south gyle wynd bus stop to city	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/01/2026	15/01/2026	Act. ROAD/82112599
50190130	Please renew 3 possibly 4 damaged railings on road island (RD: Railing Damage/Missing/New)	Just before/after roundabout	RD: Cat 3 - 60 Day	Job Complete	21/01/2026	10/02/2026	Act. ROAD/82112971
50190131	Pothole (RD: CW Pothole)	Coming off roundabout at that junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2026	22/01/2026	Act. ROAD/82112972
50190133	Pothole (RD: CW Pothole)	Coming off south gyle onto roundabout in middle of lanes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2026	22/01/2026	Act. ROAD/82112973
50190138	Pothole in cross track (RD: CW Pothole)	Southgyle Broadway, heading eastwards towards Gyle roundabout right hand lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2026	22/01/2026	Act. ROAD/82112978

Site History Report

Effective: 24/07/2025 to 26/08/2026
Service: Roads General
Site: South Gyle Broadway (7900533)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 3 - From Gogar Roundabout to South Gyle Access		Feature Type: Road Asset		Area: North West Locality	
50191257	1 cw pothole (RD: CW Pothole)	On roundabout at south gyle wynd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2026	11/02/2026	Act. ROAD/82113905
50192402	7no potholes (RD: CW Pothole)	On west side of roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	08/03/2026	Act. ROAD/82114885
50192403	4no potholes (RD: CW Pothole)	On East side of roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	08/03/2026	Act. ROAD/82114886
50192415	2no potholes (RD: CW Pothole)	On approach to roundabout from South Gyle access	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	08/03/2026	Act. ROAD/82114895
50192426	1no pothole (RD: CW Pothole)	At bus stop next to lamppost SDW10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	08/03/2026	Act. ROAD/82114906
50192944	1 no pothole (RD: CW Pothole)	Entrance to roundabout at the stones office building to let	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2026	08/03/2026	Act. ROAD/82115348
50194771	1 pothole at gully (RD: CW Pothole)	Just as you come onto south gyle broadway from gogar roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2026	01/04/2026	Act. ROAD/82116745
50197008	2 number potholes (RD: CW Pothole)	On roundabout at pinned location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/05/2026	20/05/2026	Act. ROAD/82118501
50197009	1 number pothole (RD: CW Pothole)	At pinned location on roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/05/2026	20/05/2026	Act. ROAD/82118502
50198275	Syl skm signage to be replaced (NSL: Pole or and Sign Install)	Exact Location https://maps.app.goo.gl/h5FAtdby	Parking Operations	Job Scheduled	09/06/2026	04/08/2026	Est. NSL/40221
50200569	Tree root pushing up tar and needs resurfaced with HRA and red chips Approximately 3m x 2m (RD: FW Tree Root Tar)	At bus stop near lamppost SDW10	RD: Cat 3 - 60 Day	Job Committed	29/07/2026	21/10/2026	Est. ROAD/82121302
50200966	2 number potholes (RD: CW Pothole)	At pinned location as no features available	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2026	06/08/2026	Act. ROAD/82121656
50200967	1 number pothole (RD: CW Pothole)	At pinned location as no features available	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2026	06/08/2026	Act. ROAD/82121657