

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Corstorphine Road (7905055)

Locality: Murrayfield, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41209033 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	28/11/2024
	No actionable defects found							
Batch:	41208699 - Inspection Batch			Route:	Ad hoc Route		Date:	27/11/2024
42169911	Broken footway box	27/11/2024	Lpost 13	RU: Utility Apparatus	Internal		Uncommitted	50170406
Batch:	41206497 - Inspection Batch			Route:	Ad hoc Route		Date:	05/11/2024
42168354	Pothole on carriageway	05/11/2024	Pedestrian crossing at Balgreen Road heading east	RD: CW Pothole	Internal		Committed	50169195
Batch:	41205875 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	30/10/2024
42168004	1no pothole	30/10/2024	Eastbound lane opposite Western Place	RD: CW Pothole	Internal		Committed	50168959
Batch:	41203365 - Inspection Batch			Route:	Ad hoc Route		Date:	14/10/2024
42166539	Pothole on carriageway	14/10/2024	Lpost 57	RD: CW Pothole	Internal		Committed	50167993
Batch:	41202556 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	07/10/2024
42166112	1no pothole	07/10/2024	Eastbound lane opposite Western Place	RD: CW Pothole	Internal		Committed	50167661
Batch:	41202050 - Inspection Batch			Route:	Ad hoc Route		Date:	02/10/2024
42165771	1no pothole	02/10/2024	Eastbound lane opposite lp crh66	RD: CW Pothole	Internal		Committed	50167367
Batch:	41199830 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	03/09/2024
	No actionable defects found							
Batch:	41198755 - Inspection Batch			Route:	NW_CF1_CorstorphineRoad1		Date:	15/08/2024
42163680	permanent repair required to carriageway	15/08/2024	Lpost 56	RD: CW Rutting	Internal		Uncommitted	50134810
42163672	Patch required Approx 1m x 1m	15/08/2024	Opposite 225	RD: CW Cracked/Broken	Internal		No Action Required	
42163706	Damaged bollard	15/08/2024	At Western Corner	RD: Bollard Damage/Missing/Ne	Internal		Archived	50165396
42163695	permanent repair required to carriageway	15/08/2024	Lpost 57	RD: CW Rutting	Internal		No Action Required	
42163678	permanent repair required	15/08/2024	Inside lane outside Murrayfield Hospital	RD: CW Rutting	Internal		No Action Required	
42163692	2 cw potholes	15/08/2024	At lp crh52	RD: CW Pothole	Internal		Committed	50165388
42163689	raise carriageway gully frame	15/08/2024	Lpost 42	RD: Gully Damaged/Sunken	Internal		Archived	50135726
42163670	Patching required Around manhole & gully	15/08/2024	Opposite entrance to autofoam car wash	RD: CW Cracked/Broken	Internal		No Action Required	
42163671	Relay kerb	15/08/2024	Exit from Holiday Inn	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42163690	1 fw pothole	15/08/2024	Opposite 82	RD: FW HRA Pothole	Internal		Committed	50165387
42163677	Patch required Approx 8m x 3m	15/08/2024	Opposite lp crh77	RD: CW Cracked/Broken	Internal		Archived	50142884
42163694	Patch required Approx 2.5m x 1m	15/08/2024	Opposite 102	RD: CW Cracked/Broken	Internal		No Action Required	
42163700	reset low carriageway gully frame	15/08/2024	Outside Autofoam car wash	RD: Gully Damaged/Sunken	Internal		Uncommitted	50135724
42163693	patch required around gully	15/08/2024	Opposite beechwood mains	RD: CW Cracked/Broken	Internal		No Action Required	
42163696	Please reset sunken manhole on cw	15/08/2024	Opposite murrayfield hospital	RU: Utility Apparatus	Internal		Uncommitted	50165391
42163679		15/08/2024		RD: Markings Refresh	Internal		Archived	50118200

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41198755 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1			Date: 15/08/2024			
42163674	Patching required Approx 1m x 1m & 1.5m x 0.5m	15/08/2024	Opposite the bridge club	RD: CW Cracked/Broken	Internal		No Action Required	
42163683	Patch required around manhole	15/08/2024	Outside 74	RD: CW Cracked/Broken	Internal		No Action Required	
42163691	Patch required Approx 6m x 1m	15/08/2024	Opposite 98	RD: CW Cracked/Broken	Internal		No Action Required	
42163684	Patch required Approx 2m x 1m	15/08/2024	Opposite 72	RD: CW Cracked/Broken	Internal		No Action Required	
42163704	Damaged bollard	15/08/2024	At Western Corner	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42163698	Patch required Approx 3m x 1m	15/08/2024	At Ip crh77	RD: CW Cracked/Broken	Internal		No Action Required	
42163703	Junction markings faded	15/08/2024	At Western Corner	RD: Markings Refresh	Internal		No Action Required	
42163705	Junction markings faded	15/08/2024	At Western Corner	RD: Markings Refresh	Internal		Archived	50165395
42163676	Patch required Approx 7m x 1m	15/08/2024	At Ip crh80	RD: CW Cracked/Broken	Internal		No Action Required	
42163688	Replace 1 broken 600 x 450 slab	15/08/2024	Outside murrayfield pharmacy	RD: FW Slabs Broken/Missing	Internal		Committed	50165386
42163682	Patch required Approx 2m x 1m	15/08/2024	At junction with Belmont crescent	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41198590 - Inspection Batch		Route: Ad hoc Route			Date: 14/08/2024			
42163574	Noisy carriageway manhole	14/08/2024	Outside 39	RU: Utility Apparatus	Internal		Uncommitted	50165309
Batch: 41198000 - Inspection Batch		Route: North Mobile Inspection Route			Date: 05/08/2024			
42163061	2no potholes	05/08/2024	Opp LP65	RD: CW Pothole	Internal		Committed	50164918
Batch: 41197919 - Inspection Batch		Route: Ad hoc Route			Date: 05/08/2024			
42163033	Replace damaged bollard	05/08/2024	Junction Ormidale Terrace	RD: Bollard Damage/Missing/Nev	Internal		Committed	50164890
Batch: 41195769 - Inspection Batch		Route: North Mobile Inspection Route			Date: 02/07/2024			
No actionable defects found								
Batch: 41193672 - Inspection Batch		Route: Ad hoc Route			Date: 05/06/2024			
42159075	Gully choked	05/06/2024	Pedestrian crossing at Balgreen Road	Gully: Blocked / Flooding	Internal		Committed	50161797
Batch: 41193528 - Inspection Batch		Route: Ad hoc Route			Date: 04/06/2024			
42158890	Reset gully frames	04/06/2024	Outside 40,22	RD: Gully Damaged/Sunken	Internal		Committed	50161701
Batch: 41193527 - Inspection Batch		Route: Ad hoc Route			Date: 04/06/2024			
42158889	Noisy carriageway manhole	04/06/2024	Junction Ellersly Road	RU: Utility Apparatus	Internal		Uncommitted	50161700
Batch: 41193525 - Inspection Batch		Route: Ad hoc Route			Date: 04/06/2024			
42158887	Noisy carriageway manhole	04/06/2024	Junction Ellersly Road	RU: Utility Apparatus	Internal		Uncommitted	50161699
Batch: 41193455 - Inspection Batch		Route: North Mobile Inspection Route			Date: 03/06/2024			
No actionable defects found								
Batch: 41192601 - Inspection Batch		Route: Ad hoc Route			Date: 23/05/2024			
42157870	Refresh carriageway markings	23/05/2024	Balgreen Road to Murrayfield Hospital	RD: Markings Refresh	Internal		Uncommitted	50160905
Batch: 41192225 - Inspection Batch		Route: Ad hoc Route			Date: 17/05/2024			
42157506	Pothole on carriageway	17/05/2024	Pothole on carriageway	RD: CW Pothole	Internal		Committed	50160595
Batch: 41192224 - Inspection Batch		Route: Ad hoc Route			Date: 17/05/2024			
42157505	Pothole on carriageway	17/05/2024	Lpost 84	RD: CW Pothole	Internal		Committed	50160594

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41192223 - Inspection Batch			Route: Ad hoc Route			Date: 17/05/2024	
42157504	Pothole on carriageway	17/05/2024	Lpost 78	RD: CW Pothole	Internal		Committed	50160593
Batch:	41192222 - Inspection Batch			Route: Ad hoc Route			Date: 17/05/2024	
42157503	Pothole on carriageway	17/05/2024	Lpost 60	RD: CW Pothole	Internal		Committed	50160592
Batch:	41192221 - Inspection Batch			Route: Ad hoc Route			Date: 17/05/2024	
42157502	Relay kerb	17/05/2024	Exit from Holiday Inn	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
Batch:	41192219 - Inspection Batch			Route: Ad hoc Route			Date: 17/05/2024	
42157500	Pothole on carriageway	17/05/2024	Lpost 55 heading west	RD: CW Pothole	Internal		Committed	50160589
Batch:	41192095 - Inspection Batch			Route: Ad hoc Route			Date: 15/05/2024	
42157350	Pothole on carriageway	15/05/2024	Lpost 78-68	RD: CW Pothole	Internal		Committed	50160469
Batch:	41191670 - Inspection Batch			Route: Ad hoc Route			Date: 13/05/2024	
42156989	Pothole on carriageway	13/05/2024	Lpost 73(heading west)	RD: CW Pothole	Internal		Committed	50160194
Batch:	41191374 - Inspection Batch			Route: Ad hoc Route			Date: 07/05/2024	
42156632	Pothole on carriageway	07/05/2024	Lpost 71	RD: CW Pothole	Internal		Committed	50159970
Batch:	41191349 - Inspection Batch			Route: North Mobile Inspection Route			Date: 07/05/2024	
	No actionable defects found							
Batch:	41190860 - Inspection Batch			Route: Ad hoc Route			Date: 01/05/2024	
42156119	Pothole on carriageway	01/05/2024	Junction Murrayfield Avenue	RD: CW Pothole	Internal		Committed	50159557
Batch:	41190701 - Inspection Batch			Route: Ad hoc Route			Date: 29/04/2024	
42155895	Pothole on carriageway	29/04/2024	Lpost 48	RD: CW Pothole	Internal		Committed	50159420
Batch:	41190700 - Inspection Batch			Route: Ad hoc Route			Date: 29/04/2024	
42155894	Pothole on carriageway	29/04/2024	Lpost 63,61,58,outside 102,94	RD: CW Pothole	Internal		Committed	50159419
Batch:	41190625 - Inspection Batch			Route: Ad hoc Route			Date: 29/04/2024	
42155803	Pothole on carriageway bus lane	29/04/2024	Balgreen Road to lpost 69	RD: CW Pothole	Internal		Committed	50159336
Batch:	41189624 - Inspection Batch			Route: Ad hoc Route			Date: 16/04/2024	
42154818	2no potholes	16/04/2024	At the junction with Kaimes rd	RD: CW Pothole	Internal		Committed	50158455
Batch:	41188292 - Inspection Batch			Route: North Mobile Inspection Route			Date: 03/04/2024	
	No actionable defects found							
Batch:	41188058 - Inspection Batch			Route: Ad hoc Route			Date: 02/04/2024	
42153396	Reset gully frame	02/04/2024	Lpost 32	RD: Gully Damaged/Sunken	Internal		Committed	50157127
Batch:	41186787 - Inspection Batch			Route: Ad hoc Route			Date: 19/03/2024	
42152137	1no Cw pothole	19/03/2024	Opposite lp CRH78	RD: CW Pothole	Internal		Committed	50156232
Batch:	41184572 - Inspection Batch			Route: North Mobile Inspection Route			Date: 03/03/2024	
42149983	1 pothole	03/03/2024	Opposite lamppost 62	RD: CW Pothole	Internal		Committed	50154628
42149984	1 pothole	03/03/2024	Foot of speed camera at beechwood mains	RD: CW Pothole	Internal		No Action Required	

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41184572 - Inspection Batch		Route: North Mobile Inspection Route				Date: 03/03/2024		
42149987	6 potholes	03/03/2024	Outside 96	RD: CW Pothole	Internal		Committed	50154631
42149986	2 potholes	03/03/2024	Foot of speed camera at beechwood mains	RD: CW Pothole	Internal		Committed	50154630
42149982	2 potholes	03/03/2024	Opposite lamppost 66	RD: CW Pothole	Internal		Committed	50154627
42149985	1 pothole	03/03/2024	Foot of speed camera at beechwood mains	RD: CW Pothole	Internal		Committed	50154629
Batch: 41181342 - Inspection Batch		Route: North Mobile Inspection Route				Date: 05/02/2024		
42146404	1no pothole	05/02/2024	At the junction with Belmont Crescent	RD: CW Pothole	Internal		Committed	50152175
Batch: 41181196 - Inspection Batch		Route: Ad hoc Route				Date: 05/02/2024		
42146302	Pothole on carriageway	05/02/2024	Outside Silvan House	RD: CW Pothole	Internal		Committed	50152117
Batch: 41181161 - Inspection Batch		Route: Ad hoc Route				Date: 05/02/2024		
42146284	Pothole on carriageway inside lane	05/02/2024	Opposite Western Place	RD: CW Pothole	Internal		Committed	50152105
Batch: 41180895 - Inspection Batch		Route: Ad hoc Route				Date: 01/02/2024		
42145938	Pothole on carriageway , outside lane	01/02/2024	Lpost 81 heading west before Pinkhill	RD: CW Pothole	Internal		Committed	50151872
Batch: 41180382 - Inspection Batch		Route: Ad hoc Route				Date: 29/01/2024		
42145424	Pothole on carriageway	29/01/2024	Outside 135	RD: CW Pothole	Internal		Committed	50151481
Batch: 41179930 - Inspection Batch		Route: Ad hoc Route				Date: 24/01/2024		
42144998	3no potholes	24/01/2024	At Balgreen rd westbound	RD: CW Pothole	Internal		Committed	50151102
Batch: 41179929 - Inspection Batch		Route: Ad hoc Route				Date: 24/01/2024		
42144997	2no potholes	24/01/2024	Opposite Balgreen rd city bound	RD: CW Pothole	Internal		Committed	50151101
Batch: 41179779 - Inspection Batch		Route: Ad hoc Route				Date: 24/01/2024		
42144849	Flooding on footway/carriageway	24/01/2024	Junction Ellersly Road	Gully: Blocked / Flooding	Internal		Committed	50150991
Batch: 41179778 - Inspection Batch		Route: Ad hoc Route				Date: 24/01/2024		
42144848	Pothole on footway	24/01/2024	Junction Ellersly Road (east junction)	RD: FW HRA Pothole	Internal		Committed	50150990
Batch: 41178792 - Inspection Batch		Route: Ad hoc Route				Date: 17/01/2024		
42144215	Road: Defective / Damaged (Enquiry 1678768) pothole on carriageway,inside lane	17/01/2024	Outside 135	RD: CW Pothole	Internal		Committed	50150368
Batch: 41178360 - Inspection Batch		Route: Ad hoc Route				Date: 15/01/2024		
42143960	Road: Defective / Damaged (Enquiry 1677393) replace damaged gully frame and brander	15/01/2024	Outside Spire hospital	RD: Gully Damaged/Sunken	Internal		Committed	50150094
Batch: 41178358 - Inspection Batch		Route: Ad hoc Route				Date: 15/01/2024		
42143958	Pothole on carriageway	15/01/2024	Lpost 65 heading west	RD: CW Pothole	Internal		Committed	50150092
Batch: 41178356 - Inspection Batch		Route: Ad hoc Route				Date: 15/01/2024		
No actionable defects found								

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality		
Batch: 41177654 - Inspection Batch				Route: Ad hoc Route		Date: 08/01/2024		
42143359	Road: Defective / Damaged (Enquiry 1672520) pothole on carriageway,inside lane	08/01/2024	Outside Holiday Inn	RD: CW Pothole	Internal		Committed	50149505
Batch: 41176690 - Inspection Batch				Route: North Mobile Inspection Route		Date: 03/01/2024		
42143109	2no potholes	03/01/2024	Eastbound lane opposite Ip CRH66	RD: CW Pothole	Internal		Committed	50149223
42143114	1no pothole	03/01/2024	At the junction with Murrayfield Avenue	RD: CW Pothole	Internal		Committed	50149228
42143111	3no potholes	03/01/2024	At Ip CRH56	RD: CW Pothole	Internal		Committed	50149225
Batch: 41176538 - Inspection Batch				Route: Ad hoc Route		Date: 03/01/2024		
42142990	Pavement: Damaged / Defective (Enquiry 1668348) gully chocked	03/01/2024	Outside Corstorphine Hospital	Gully: Blocked / Flooding	Internal		Committed	50149087
Batch: 41175301 - Inspection Batch				Route: Ad hoc Route		Date: 21/12/2023		
42142685	Pothole on carriageway bus lane heading east	21/12/2023	Passed exit from Holiday Inn	RD: CW Pothole	Internal		Committed	50148773
Batch: 41174310 - Inspection Batch				Route: Ad hoc Route		Date: 13/12/2023		
42141796	2 cw potholes	13/12/2023	At junction with balgreen road	RD: CW Pothole	Internal		Committed	50147890
Batch: 41173321 - Inspection Batch				Route: North Mobile Inspection Route		Date: 04/12/2023		
42140963	1no pothole	04/12/2023	At the junction with Belmont Crescent	RD: CW Pothole	Internal		Committed	50147062
Batch: 41173199 - Inspection Batch				Route: Ad hoc Route		Date: 01/12/2023		
42140859	Road: Defective / Damaged (Enquiry 1653712) pothole on carriageway	01/12/2023	Bus stop outside The Holiday Inn	RD: CW Pothole	Internal		Committed	50147009
Batch: 41173081 - Inspection Batch				Route: Ad hoc Route		Date: 30/11/2023		
42140764	Road: Defective / Damaged (Enquiry 1652790) make safe carriageway in hra(inside lane)	30/11/2023	Outside Spire hospital	RD: CW Pothole	Internal		Committed	50146924
Batch: 41172434 - Inspection Batch				Route: Ad hoc Route		Date: 21/11/2023		
42140090	Road: Defective / Damaged (Enquiry 1647365) pothole on carriageway	21/11/2023	Heading east opposite Western Place	RD: CW Pothole	Internal		Committed	50146266
Batch: 41172263 - Inspection Batch				Route: Ad hoc Route		Date: 20/11/2023		
42139961	Road: Defective / Damaged (Enquiry 1646384) pothole on carriageway outside lane	20/11/2023	Outside 135	RD: CW Pothole	Internal		Committed	50146153
Batch: 41172054 - Inspection Batch				Route: Ad hoc Route		Date: 16/11/2023		
42139717	Install new gully next to gully 39008	16/11/2023	Outside 135	RD: Gully Damaged/Sunken	Internal		Committed	50145933
Batch: 41171742 - Inspection Batch				Route: Ad hoc Route		Date: 13/11/2023		
42139422	Flooding carriageway and footway	13/11/2023	Outside Corstorphine Hospital	Gully: Blocked / Flooding	Internal		Committed	50145630
Batch: 41171249 - Inspection Batch				Route: Ad hoc Route		Date: 06/11/2023		
42138759	Pothole on carriageway	06/11/2023	Junction Balgreen Road	RD: CW Pothole	Internal		Committed	50145119

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41170849 - Inspection Batch				Route: Ad hoc Route			Date: 02/11/2023	
42138498	Road Markings: refresh stop markings	02/11/2023	At Western Corner	RD: Markings Refresh	Internal		Uncommitted	50144867
Batch: 41170537 - Inspection Batch				Route: Ad hoc Route			Date: 31/10/2023	
42138365	Pothole on carriageway inside lane	31/10/2023	Lpost 86	RD: CW Pothole	Internal		Committed	50144739
Batch: 41170535 - Inspection Batch				Route: Ad hoc Route			Date: 31/10/2023	
42138364	Road: Defective / Damaged (Enquiry 1635866) pothole on carriageway inside lane	31/10/2023	Lpost 84	RD: CW Pothole	Internal		Committed	50144738
Batch: 41170533 - Inspection Batch				Route: Ad hoc Route			Date: 31/10/2023	
42138363	Road: Defective / Damaged (Enquiry 1635866) pothole on carriageway inside lane	31/10/2023	Lpost 78	RD: CW Pothole	Internal		Committed	50144737
Batch: 41170147 - Inspection Batch				Route: North Mobile Inspection Route			Date: 26/10/2023	
42138064	1no pothole	26/10/2023	At the junction with Belmont Crescent	RD: CW Pothole	Internal		Committed	50144520
Batch: 41168383 - Inspection Batch				Route: Ad hoc Route			Date: 12/10/2023	
42137413	1no pothole	12/10/2023	Opposite Western Place	RD: CW Pothole	Internal		Committed	50143900
Batch: 41167759 - Inspection Batch				Route: Ad hoc Route			Date: 05/10/2023	
42137050	Road: Defective / Damaged (Enquiry 1623515) reset loose carriageway gully frame	05/10/2023	Bus stop outside Holiday Inn	RD: Gully Damaged/Sunken	Internal		Uncommitted	50143578
Batch: 41167758 - Inspection Batch				Route: Ad hoc Route			Date: 05/10/2023	
42137049	Road: Defective / Damaged (Enquiry 1623515) pothole on carriageway	05/10/2023	Bus stop outside Holiday Inn	RD: CW Pothole	Internal		Committed	50143577
Batch: 41167467 - Inspection Batch				Route: North Mobile Inspection Route			Date: 02/10/2023	
42136903	1no pothole	02/10/2023	At the junction of Belmont Crescent	RD: CW Pothole	Internal		Committed	50143417
Batch: 41167018 - Inspection Batch				Route: Ad hoc Route			Date: 28/09/2023	
42136808	Road: Defective / Damaged (Enquiry 1619952) flooding on carriageway/footway	28/09/2023	Outside Corstorphine Hospital	Gully: Blocked / Flooding	Internal		Committed	50143293
Batch: 41167017 - Inspection Batch				Route: Ad hoc Route			Date: 28/09/2023	
42136807	Road: Defective / Damaged (Enquiry 1619880) pothole on carriageway	28/09/2023	Outside Enterprise car rental	RD: CW Pothole	Internal		Committed	50143292
Batch: 41165955 - Inspection Batch				Route: NW_CF1_CorstorphineRoad1			Date: 20/09/2023	
42136451	Patch required Approx 2.5m x 1m	20/09/2023	Opposite 102	RD: CW Cracked/Broken	Internal		No Action Required	
42136437	permanent repair required to carriageway	20/09/2023	Lpost 34	RD: CW Pothole	Internal		Archived	50129007
42136424	Patching required Approx 1m x 1m & 1m x 0.5m	20/09/2023	Opposite entrance to autofoam car wash	RD: CW Cracked/Broken	Internal		No Action Required	
42136447		20/09/2023		RD: CW Cracked/Broken	Internal		Archived	50118192

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41165955 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1				Date: 20/09/2023	
42136425	Patch required Approx 1m x 1m	20/09/2023	Opposite 225	RD: CW Cracked/Broken	Internal		No Action Required	
42136413	Patch required around manhole Approx 2m x 2m	20/09/2023	Opposite entrance to silvan house	RD: CW Cracked/Broken	Internal		No Action Required	
42136439		20/09/2023		RD: CW Rutting	Internal		Archived	50112432
42136454	Cw cracked broken	20/09/2023	At lamppost CRH74	RD: CW Cracked/Broken	Internal		Archived	50142902
42136446	raise carriageway gully frame	20/09/2023	Lpost 42	RD: Gully Damaged/Sunken	Internal		No Action Required	
42136449		20/09/2023		RD: CW Cracked/Broken	Internal		Archived	50118188
42136432	1 cw pothole	20/09/2023	At entrance to Murrayfield hospital	RD: CW Pothole	Internal		Committed	50142887
42136436	Patch required Approx 2m x 1m	20/09/2023	At junction with Belmont crescent	RD: CW Cracked/Broken	Internal		No Action Required	
42136429	Damaged lite sign pole	20/09/2023	Near lamppost 74	RD: SFP Damaged Signage	Internal		Uncommitted	50118182
42136453	Cw cracked broken	20/09/2023	At lamppost CRH74	RD: CW Cracked/Broken	Internal		No Action Required	
42136412		20/09/2023		RD: FW HRA Cracked/Broken	Internal		Archived	50142867
42136410	Footway and carriageway broken	20/09/2023	O/S entrance to no 136	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42136457	reset low carriageway gully frame	20/09/2023	Outside Autofoam car wash	RD: Gully Damaged/Sunken	Internal		No Action Required	
42136456	Junction markings faded	20/09/2023	At St Catherine's Gardens	RD: Markings Refresh	Internal		Action Required	
42136435	permanent repair required to carriageway	20/09/2023	Lpost 56	RD: CW Rutting	Internal		No Action Required	
42136430	permanent repair required	20/09/2023	Inside lane outside Murrayfield Hospital	RD: CW Rutting	Internal		No Action Required	
42136427	Patch required Approx 8m x 3m	20/09/2023	Opposite lp crh77	RD: CW Cracked/Broken	Internal		No Action Required	
42136450	Patch required Approx 6m x 1m	20/09/2023	Opposite 98	RD: CW Cracked/Broken	Internal		No Action Required	
42136452	Road: Defective / Damaged (Enquiry 1519362)permanent repair required to carriageway	20/09/2023	Lpost 57	RD: CW Rutting	Internal		No Action Required	
42136448	Patch required Approx 2m x 1m	20/09/2023	Opposite 72	RD: CW Cracked/Broken	Internal		No Action Required	
42136459	1 cw pothole	20/09/2023	Outside entrance to silvan house	RD: CW Pothole	Internal		Committed	50142904
Batch:	41164104 - Inspection Batch		Route: Ad hoc Route				Date: 01/09/2023	
42135309	Pothole on carriageway	01/09/2023	Lpost 75	RD: CW Pothole	Internal		Committed	50141980
Batch:	41163761 - Inspection Batch		Route: North Mobile Inspection Route				Date: 28/08/2023	
	No actionable defects found							
Batch:	41162018 - Inspection Batch		Route: North Mobile Inspection Route				Date: 28/07/2023	
	No actionable defects found							
Batch:	41161438 - Inspection Batch		Route: Ad hoc Route				Date: 20/07/2023	
42132376	1no pothole	20/07/2023	At Belmont Crescent	RD: CW Pothole	Internal		Committed	50139633
Batch:	41161367 - Inspection Batch		Route: Ad hoc Route				Date: 19/07/2023	
42132272	Pavement: Damaged / Defective (Enquiry 1583853) make safe	19/07/2023	Opposite 4	RD: FW Grano Pothole	Internal		Committed	50139531

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41160548 - Inspection Batch			Route: Ad hoc Route				Date: 06/07/2023	
42131378	Damaged speed reducing measures sign on a lamppost.	06/07/2023	96 Corstorphine Road	RD: Unlit Sign Damaged/Missing	Internal		Committed	50138887
Please remove this and the end board, and dispose in skip.								
Batch: 41160323 - Inspection Batch			Route: North Mobile Inspection Route				Date: 03/07/2023	
42131214	1no pothole	03/07/2023	At the junction of Belmont Crescent	RD: CW Pothole	Internal		Committed	50138755
Batch: 41160060 - Inspection Batch			Route: Ad hoc Route				Date: 28/06/2023	
42130926	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1572781) footway gullies chocked	28/06/2023	Outside Chinese Consulate	Gully: Blocked - Hand Clear	Internal		Committed	50138514
Batch: 41158521 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 05/06/2023	
Batch: 41156774 - Inspection Batch			Route: Ad hoc Route				Date: 09/05/2023	
42127021	Gully chocked	09/05/2023	Opposite 78	Gully: Blocked / Flooding	Internal		Committed	50135728
Batch: 41156772 - Inspection Batch			Route: Ad hoc Route				Date: 09/05/2023	
42127019	Road: Defective / Damaged (Enquiry 1547511) raise carriageway gully frame	09/05/2023	Lpost 42	RD: Gully Damaged/Sunken	Internal		No Action Required	
Batch: 41156770 - Inspection Batch			Route: Ad hoc Route				Date: 09/05/2023	
42127017	RD: Gully Cover Damaged - What is the problem with the gully : damaged. What surface is the gully on : road. Specify_damage : sunken in surface (Enquiry 1547301)reset low carriageway gully frame	09/05/2023	Outside Autofoam car wash	RD: Gully Damaged/Sunken	Internal		No Action Required	
Batch: 41156637 - Inspection Batch			Route: Ad hoc Route				Date: 05/05/2023	
42126793	Low carriageway box	05/05/2023	Lpost 79, heading west	RU: Utility Apparatus	Internal		Uncommitted	50135586
Batch: 41156632 - Inspection Batch			Route: Ad hoc Route				Date: 05/05/2023	
42126788	Pothole on carriageway heading west outside lane	05/05/2023	Lpost 79	RD: CW Pothole	Internal		Committed	50135581
Batch: 41156249 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 01/05/2023	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41155855 - Inspection Batch		Route: Ad hoc Route			Date: 26/04/2023			
42126114	RD: Gully Cover Damaged - What is the problem with the gully : damaged. What surface is the gully on : road. Specify_damage : sunken in surface (Enquiry 1543165)reset uneven carriageway gully frame	26/04/2023	Junction Murrayfield Gardens	RD: Gully Damaged/Sunken	Internal		Committed	50135118
Batch: 41155412 - Inspection Batch		Route: Ad hoc Route			Date: 24/04/2023			
42125824	Road: Defective / Damaged (Enquiry 1540968)permanent repair required to carriageway	24/04/2023	Lpost 56	RD: CW Rutting	Internal		No Action Required	
Batch: 41155411 - Inspection Batch		Route: Ad hoc Route			Date: 24/04/2023			
42125823	Pothole on carriageway	24/04/2023	Lpost 57,lpost 59	RD: CW Pothole	Internal		Committed	50134809
Batch: 41154794 - Inspection Batch		Route: Ad hoc Route			Date: 14/04/2023			
42125234	Pothole on carriageway inside lane	14/04/2023	Outside 92	RD: CW Pothole	Internal		Committed	50134277
Batch: 41154793 - Inspection Batch		Route: Ad hoc Route			Date: 14/04/2023			
42125233	Road: Defective / Damaged (Enquiry 1536753)uplift cones	14/04/2023	Traffic island outside 92	RD: Other Defect Type	Internal		Committed	50134276
Batch: 41154640 - Inspection Batch		Route: Ad hoc Route			Date: 12/04/2023			
42125114	Pothole on footway	12/04/2023	Outside 70 + 78	RD: FW HRA Pothole	Internal		Committed	50134155
Batch: 41154173 - Inspection Batch		Route: North Mobile Inspection Route			Date: 05/04/2023			
42124766	1no pothole	05/04/2023	At the junction with Belmont Crescent	RD: CW Pothole	Internal		Committed	50133790
Batch: 41153850 - Inspection Batch		Route: Ad hoc Route			Date: 03/04/2023			
42124466	Public Utilities: General (Enquiry 1527496)noisy carriageway manhole	03/04/2023	Outside 38	RU: Utility Apparatus	Internal		Uncommitted	50133531
Batch: 41153849 - Inspection Batch		Route: Ad hoc Route			Date: 03/04/2023			
42124465	Public Utilities: General (Enquiry 1527496)loose and noisy carriageway manhole	03/04/2023	Near lpost 34 heading east from Ellersly Road	RU: Utility Apparatus	Internal		Uncommitted	50133530
Batch: 41152707 - Inspection Batch		Route: Ad hoc Route			Date: 17/03/2023			
42122839	Road: Defective / Damaged (Enquiry 1524154)permanent repair required	17/03/2023	Inside lane outside Murrayfield Hospital	RD: CW Rutting	Internal		No Action Required	
Batch: 41152366 - Inspection Batch		Route: Ad hoc Route			Date: 16/03/2023			
42122601	Road: Defective / Damaged (Enquiry 1523665) pothole on carriageway	16/03/2023	Junction Balgreen Road heading east at pedestrian crossing	RD: CW Pothole	Internal		Committed	50132085
Batch: 41151597 - Inspection Batch		Route: North Mobile Inspection Route			Date: 08/03/2023			
42121658	1no pothole	08/03/2023	At lp CRH65	RD: CW Pothole	Internal		Committed	50131430
42121663	1no pothole	08/03/2023	At lp CRH79	RD: CW Pothole	Internal		Committed	50131432

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41151516 - Inspection Batch				Route: Ad hoc Route			Date: 07/03/2023	
42121534	Road: Defective / Damaged (Enquiry 1519362)permanent repair required to carriageway	07/03/2023	Lpost 57	RD: CW Rutting	Internal		No Action Required	
Batch: 41151355 - Inspection Batch				Route: Ad hoc Route			Date: 06/03/2023	
42121383	Road: Defective / Damaged (Enquiry 1518984) pothole on carriageway	06/03/2023	Junction Balgreen Road,inside lane	RD: CW Pothole	Internal		Committed	50131195
Batch: 41150682 - Inspection Batch				Route: Ad hoc Route			Date: 27/02/2023	
42120478	1 cw pothole	27/02/2023	Opposite 80	RD: CW Pothole	Internal		Committed	50130563
Batch: 41150681 - Inspection Batch				Route: Ad hoc Route			Date: 27/02/2023	
42120476	Patch required Approx 12m x 1.5m	27/02/2023	Opposite 74 at bus stop	RD: CW Cracked/Broken	Internal		Committed	50130561
Batch: 41149505 - Inspection Batch				Route: North Mobile Inspection Route			Date: 16/02/2023	
No actionable defects found								
Batch: 41149006 - Inspection Batch				Route: Ad hoc Route			Date: 14/02/2023	
42118482	Road: Defective / Damaged (Enquiry 1509343) pothole on carriageway	14/02/2023	Junction Balgreen Road, outside lane heading west	RD: CW Pothole	Internal		Committed	50129200
Batch: 41148554 - Inspection Batch				Route: Ad hoc Route			Date: 10/02/2023	
42118231	Road: Defective / Damaged (Enquiry 1507665)permanent repair required to carriageway	10/02/2023	Lpost 34	RD: CW Pothole	Internal		No Action Required	
Batch: 41148425 - Inspection Batch				Route: Ad hoc Route			Date: 09/02/2023	
42118068	Road: Defective / Damaged (Enquiry 1507106) pothole on carriageway	09/02/2023	Junction Balgreen Road	RD: CW Pothole	Internal		Committed	50128846
Batch: 41148240 - Inspection Batch				Route: Ad hoc Route			Date: 07/02/2023	
42117755	Road: Defective / Damaged (Enquiry 1506122) pothole on carriageway	07/02/2023	Bus stop outside Tennis club	RD: CW Pothole	Internal		Committed	50128623
Batch: 41147545 - Inspection Batch				Route: Ad hoc Route			Date: 31/01/2023	
42116954	Road: Defective / Damaged - Pothole (Enquiry 1490863)	31/01/2023	Silvan house westbound in joint	RD: CW Pothole	Internal		Committed	50128000
Batch: 41147542 - Inspection Batch				Route: Ad hoc Route			Date: 31/01/2023	
42116952	Road: Defective / Damaged - Pothole (Enquiry 1490863)	31/01/2023	Silvan house westbound	RD: CW Pothole	Internal		Committed	50127999
Batch: 41146200 - Inspection Batch				Route: Ad hoc Route			Date: 24/01/2023	
42116180	Road: Defective / Damaged (Enquiry 1493513) pothole on carriageway	24/01/2023	Outside 231	RD: CW Pothole	Internal		Committed	50127251
Batch: 41144894 - Inspection Batch				Route: Ad hoc Route			Date: 20/01/2023	
42115951	Road: Defective / Damaged (Enquiry 1489352)	20/01/2023	Greenlane between western corner and Murrayfield road	RD: CW Pothole	Internal		Committed	50126978

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41144879 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2023
42115939	Road: Defective / Damaged (Enquiry 1491966)	20/01/2023	end of the bus lane heading out of town, prior to pinkhill	RD: CW Pothole	Internal		Committed	50126964
Batch:	41144878 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2023
42115938	Road: Defective / Damaged (Enquiry 1492245)	20/01/2023	West of balgreen rod at gully at bus stop	RD: CW Pothole	Internal		Committed	50126963
Batch:	41144875 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2023
42115935	Road: Defective / Damaged (Enquiry 1488569)	20/01/2023	City bound	RD: CW Pothole	Internal		Committed	50126960
Batch:	41144871 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2023
42115931	Road: Defective / Damaged (Enquiry 1488569)	20/01/2023	City bound	RD: CW Pothole	Internal		Committed	50126956
Batch:	41144870 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2023
42115930	Road: Defective / Damaged (Enquiry 1488569)	20/01/2023		RD: CW Pothole	Internal		Committed	50126955
Batch:	41143359 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	12/01/2023
42114952	3no potholes	12/01/2023	Outside no98	RD: CW Pothole	Internal		Committed	50126036
Batch:	41142063 - Inspection Batch			Route:	Ad hoc Route		Date:	04/01/2023
42114112	Pothole on carriageway	04/01/2023	Outside 235,junction Kaimes Road	RD: CW Pothole	Internal		Committed	50125299
Batch:	41141429 - Inspection Batch			Route:	Ad hoc Route		Date:	29/12/2022
42113866	Road: Defective / Damaged - (Enquiry 1480559)pothole carriageway	29/12/2022	Junction Kaimes Road	RD: CW Pothole	Internal		Committed	50125005
Batch:	41140959 - Inspection Batch			Route:	Ad hoc Route		Date:	28/12/2022
42113772	Road: Defective / Damaged (Enquiry 1479961)permanent repair required to carriageway	28/12/2022	Lpost 62,at bus stop	RD: CW Rutting	Internal		Uncommitted	50124906
Batch:	41140958 - Inspection Batch			Route:	Ad hoc Route		Date:	28/12/2022
42113771	Road: Defective / Damaged (Enquiry 1480012) pothole on carriageway	28/12/2022	Junction Murrayfield Gardens	RD: CW Pothole	Internal		Committed	50124905
Batch:	41139620 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	16/12/2022
	No actionable defects found							
Batch:	41136452 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	23/11/2022
42111917	1 carriageway pothole	23/11/2022	Opposite no74	RD: CW Pothole	Internal		Committed	50122885
Batch:	41136289 - Inspection Batch			Route:	Ad hoc Route		Date:	21/11/2022
42111811	1no pothole	21/11/2022	Westbound at lp CRH75	RD: CW Pothole	Internal		Committed	50122755
Batch:	41136170 - Inspection Batch			Route:	Ad hoc Route		Date:	20/11/2022
42111693	1 carriageway pothole	20/11/2022	At lamppost 75	RD: CW Pothole	Internal		Committed	50122636

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41134463 - Inspection Batch		Route: Ad hoc Route				Date: 31/10/2022	
42110068	1 cw pothole	31/10/2022	Outside silvan house	RD: CW Pothole	Internal		Committed	50121142
Batch:	41134462 - Inspection Batch		Route: Ad hoc Route				Date: 31/10/2022	
42110067	1 cw pothole	31/10/2022	Opposite 20	RD: CW Pothole	Internal		Committed	50121141
Batch:	41133088 - Inspection Batch		Route: North Mobile Inspection Route				Date: 20/10/2022	
	No actionable defects found							
Batch:	41131268 - Inspection Batch		Route: North Mobile Inspection Route				Date: 21/09/2022	
	No actionable defects found							
Batch:	41130521 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1				Date: 01/09/2022	
42106704	Dig out damaged footway & resurface in HRA	01/09/2022	North footway breaking up leaving uneven surface , East & west of I / p CRH 74	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42106724	Pothole	01/09/2022	Adjacent to number 91	RD: CW Pothole	Internal		Committed	50118197
42106739		01/09/2022		RD: CW Cracked/Broken	Internal		Uncommitted	50195401
42106699	Junction markings faded	01/09/2022	At St Catherine's Gardens	RD: Markings Refresh	Internal		No Action Required	
42106726	Junction markings faded	01/09/2022	At Western Corner	RD: Markings Refresh	Internal		No Action Required	
42106721	Pothole	01/09/2022	Outside number 135 in bus lane	RD: CW Pothole	Internal		Committed	50118194
42106734	Open joint x 2	01/09/2022	At lampost 70	RD: CW Open Joint	Internal		Committed	50118205
42106725	Damaged bollard	01/09/2022	At Western Corner	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42106710	Pothole	01/09/2022	Adjacent to balgreen road. At nature reserve gate	RD: CW Pothole	Internal		Committed	50118184
42106708	Pothole	01/09/2022	Cover surround at lampost 56	RD: CW Pothole	Internal		Committed	50118183
42106702	Pothole	01/09/2022	Near lampost 76	RD: CW Pothole	Internal		Committed	50118179
42106716	Dig out damaged carriageway and resurface in HRA	01/09/2022	West bound carriageway bus lane breaking up leaving uneven surfaces from I/p CRH 46	RD: CW Cracked/Broken	Internal		No Action Required	
42106720	Gully surround	01/09/2022	At lampost 42	RD: CW Pothole	Internal		Committed	50118193
42106714	Dig	01/09/2022	West bound carriageway bus lane breaking up leaving uneven surfaces from opposite no 94	RD: CW Cracked/Broken	Internal		No Action Required	
42106717		01/09/2022		RD: CW Cracked/Broken	Internal		Archived	50118190
42106727	Pothole	01/09/2022	At junction with western gardens	RD: CW Pothole	Internal		Committed	50118198
42106731	Cover missing on fw make safe required	01/09/2022	Outside number 38	RD: Other Defect Type	Internal		Committed	50118202
42106711	Cover missing see pics. Make safe required	01/09/2022	Near lampost 54	RD: Gully Brander Missing	Internal		Committed	50118185
42106712	Cw broken cracked at covers	01/09/2022	At lampost 55	RD: CW Cracked/Broken	Internal		Uncommitted	50118186
42106701	Pothole	01/09/2022	In bus lane . Across cw from murrayside care home see. Pics	RD: CW Pothole	Internal		Committed	50118178
42106703	Cw cracked broken	01/09/2022	At lampost CRH74	RD: CW Cracked/Broken	Internal		No Action Required	
42106729	Refresh all markings	01/09/2022	Entire cw including all junctions	RD: Markings Refresh	Internal		No Action Required	
42106707	Damaged lite sign pole	01/09/2022	Near lampost 74	RD: SFP Damaged Signage	Internal		No Action Required	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41130521 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1			Date: 01/09/2022			
42106700	Cw broken cracked	01/09/2022	At at catherines gardens	RD: CW Cracked/Broken	Internal		Uncommitted	50118177
42106706		01/09/2022		RD: FW HRA Cracked/Broken	Internal		Archived	50118180
42106741	Pothole	01/09/2022	At crossing adjacent to the murrayfield bar	RD: CW Pothole	Internal		Committed	50118211
42106742	Gully surround	01/09/2022	Adjacent to rolls royce	RD: CW Pothole	Internal		Committed	50118212
42106709	Dig out damaged carriageway & resurface in HRA	01/09/2022	Carriageway rutting leaving ueven surface on west bound carriageway from west of junction with balgreen road for 25m	RD: CW Rutting	Internal		Uncommitted	50195400
42106719	Cw cracked broken	01/09/2022	Near lamppost 42	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41129713 - Inspection Batch		Route: North Mobile Inspection Route			Date: 18/08/2022			
No actionable defects found								
Batch: 41128504 - Inspection Batch		Route: Ad hoc Route			Date: 01/08/2022			
42105328	Unsigned pole rusted at base, very loose and hanging across the footway.	01/08/2022	Corstorphine Road, 10m prior to the junction for Ormidale Terrace	RD: Unlit Sign Damaged/Missing	Internal		Committed	50116993
Cut pole down and make hole safe from trip hazard.								
Batch: 41127768 - Inspection Batch		Route: Ad hoc Route			Date: 18/07/2022			
42104911	Road: Defective / Damaged (Enquiry 1408425)permanent repair required to carriageway in hra	18/07/2022	Outside 102,lpost 54,outside 96	RD: CW Rutting	Internal		Uncommitted	50116632
Batch: 41127712 - Inspection Batch		Route: North Mobile Inspection Route			Date: 15/07/2022			
No actionable defects found								
Batch: 41127399 - Inspection Batch		Route: Ad hoc Route			Date: 12/07/2022			
42104637	Pavement: Damaged / Defective (Enquiry 1405511) pothole on footway	12/07/2022	Outside Corstorphine hospital	RD: FW HRA Pothole	Internal		Committed	50116440
Batch: 41127121 - Inspection Batch		Route: Ad hoc Route			Date: 07/07/2022			
42104465	Leak coming from patch next to water toby	07/07/2022	Outside 231	RU: Utility Apparatus	Internal		Uncommitted	50116294
Batch: 41126218 - Inspection Batch		Route: NW_CW1_East1			Date: 21/06/2022			
42103633	1no pothole	21/06/2022	Outside no89	RD: CW Pothole	Internal		Committed	50115561
Batch: 41126009 - Inspection Batch		Route: Ad hoc Route			Date: 17/06/2022			
42103548	Pothole on carriageway inside lane	17/06/2022	Lpost 65	RD: CW Pothole	Internal		Committed	50115457
Batch: 41125133 - Inspection Batch		Route: Ad hoc Route			Date: 31/05/2022			
42102600	Replace damaged bollard	31/05/2022	Outside 93	RD: Bollard Damage/Missing/Nev	Internal		Committed	50114602
Batch: 41124537 - Inspection Batch		Route: NW_CW1_East1			Date: 20/05/2022			
42101651	Overlay marked area approx 2x10m	20/05/2022	At lamppost CRH74	RD: CW Cracked/Broken	Internal		Committed	50113974
42101652	5 carriageway potholes	20/05/2022	Outside Murrayfield hospital	RD: CW Pothole	Internal		Committed	50113975

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41123852 - Inspection Batch		Route: Ad hoc Route			Date: 11/05/2022			
42100953	Pothole on carriageway	11/05/2022	Murrayfield Avenue junction Corstorphine Road	RD: CW Pothole	Internal		Committed	50113366
Batch: 41122881 - Inspection Batch		Route: Ad hoc Route			Date: 27/04/2022			
42099877	Road: Defective / Damaged (Enquiry 1366218)permanent repair required to carriageway in hra	27/04/2022	Outside 40	RD: CW Rutting	Internal		No Action Required	
Batch: 41122672 - Inspection Batch		Route: NW_CW1_East1			Date: 21/04/2022			
42099739	1 carriageway pothole	21/04/2022	Outside 40	RD: CW Pothole	Internal		Committed	50112201
Batch: 41122365 - Inspection Batch		Route: Ad hoc Route			Date: 13/04/2022			
42099424	Road: Defective / Damaged (Enquiry 1360533)noisy carriageway manhole	13/04/2022	Outside 98	RU: Utility Apparatus	Internal		Uncommitted	50111849
Batch: 41120161 - Inspection Batch No actionable defects found		Route: NW_CW1_East1			Date: 22/03/2022			
Batch: 41119264 - Inspection Batch		Route: Ad hoc Route			Date: 14/03/2022			
42096001	Pothole on carriageway	14/03/2022	Junction Balgreen Road heading west	RD: CW Pothole	Internal		Committed	50108976
Batch: 41116504 - Inspection Batch		Route: NW_CW1_East1			Date: 22/02/2022			
42093826	1 carriageway pothole	22/02/2022	Opposite 91	RD: CW Pothole	Internal		Committed	50107164
42093756	1 carriageway pothole	22/02/2022	At cruickshank gardens	RD: CW Pothole	Internal		Committed	50107095
42093828	1 carriageway pothole	22/02/2022	Opposite 20	RD: CW Pothole	Internal		Committed	50107166
42093752	1 carriageway pothole	22/02/2022	At lamppost CRH77	RD: CW Pothole	Internal		Committed	50107090
Batch: 41116432 - Inspection Batch		Route: Ad hoc Route			Date: 21/02/2022			
42093715	Road: Defective / Damaged (Enquiry 1330324) pothole on carriageway	21/02/2022	Outside 235	RD: CW Pothole	Internal		Committed	50107048
Batch: 41115695 - Inspection Batch		Route: Ad hoc Route			Date: 15/02/2022			
42092857	Road: Defective / Damaged (Enquiry 1326386) pothole on carriageway inside lane	15/02/2022	Outside 40	RD: CW Pothole	Internal		Committed	50106303
Batch: 41114789 - Inspection Batch		Route: Ad hoc Route			Date: 06/02/2022			
42092123	1no pothole	06/02/2022	Opposite no91	RD: CW Pothole	Internal		Committed	50105484
Batch: 41114788 - Inspection Batch		Route: Ad hoc Route			Date: 06/02/2022			
42092122	1no pothole	06/02/2022	Opposite no103	RD: CW Pothole	Internal		Committed	50105483
Batch: 41113690 - Inspection Batch		Route: NW_CW1_East1			Date: 21/01/2022			
42090361	4 carriageway potholes	21/01/2022	Opposite 91	RD: CW Pothole	Internal		Committed	50103729
42090365	1 carriageway pothole	21/01/2022	At Edinburgh zoo from city bus stop	RD: CW Pothole	Internal		Committed	50103733
42090363	1 carriageway pothole	21/01/2022	At lamppost CRH65	RD: CW Pothole	Internal		Committed	50103731

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41113312 - Inspection Batch		Route: Ad hoc Route			Date: 17/01/2022			
42089688	Road: Defective / Damaged (Enquiry 1308441)noisy carriageway manhole	17/01/2022	Junction Ellersly Road	RU: Utility Apparatus	Internal		Uncommitted	50103162
Batch: 41112581 - Inspection Batch		Route: Ad hoc Route			Date: 10/01/2022			
42088714	1no pothole	10/01/2022	At the entrance to Murrayfield Hospital	RD: CW Pothole	Internal		Committed	50102241
Batch: 41111507 - Inspection Batch		Route: NW_CW1_East1			Date: 21/12/2021			
No actionable defects found								
Batch: 41111335 - Inspection Batch		Route: Ad hoc Route			Date: 20/12/2021			
42087746	Pothole on carriageway inside lane	20/12/2021	Junction Balgreen Road	RD: CW Pothole	Internal		Committed	50100918
Batch: 41108291 - Inspection Batch		Route: NW_CW1_East1			Date: 25/11/2021			
42085240	2 carriageway potholes	25/11/2021	At St. John's gardens	RD: CW Pothole	Internal		Committed	50098523
Batch: 41105122 - Inspection Batch		Route: NW_CW1_East1			Date: 22/10/2021			
No actionable defects found								
Batch: 41101257 - Inspection Batch		Route: NW_CW1_East1			Date: 22/09/2021			
42079006	1no pothole	22/09/2021	Opposite Balgreen Road	RD: CW Pothole	Internal		Committed	50092391
42079023	1no pothole	22/09/2021	At the junction of Western Gardens	RD: CW Pothole	Internal		Committed	50092403
Batch: 41099265 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1			Date: 01/09/2021			
42077112	Raise kerb and reinstate footway	01/09/2021	Due to a dip in the pavement area is full of water o/s 12 Western Terrace	RD: FW Kerbs Damaged/Missing	Internal		Archived	5004993
42077124	Break out existing HRA carriageway and relay with 40mm hra wearing course and 60mm asphalt base course,replace carriageway markings as required.	01/09/2021	outside small gate 94 corstorphine road, repair made month or so ago! busses go to buss stop and all repair is thrown all over pavement and wall over vehicles and against front window when its raining! repair is no longer there!! would suggest a more permanent repair to stop damage to gate wall and vehicles. quite honestly we are a bit miffed to say the least about having to do this all the time! ...please help! thank you for listening!	RD: CW Cracked/Broken	Internal		Uncommitted	5004109
42077171	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	At lp 52	RD: CW Pothole	Internal		Archived	50003218
42077136	Cw cracked broken	01/09/2021	At lamppost CRH74	RD: CW Cracked/Broken	Internal		No Action Required	
42077172	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp lp 56	RD: CW Pothole	Internal		Archived	50003220
42077121	Gully Chocked	01/09/2021	Lpost 48	Gully: Blocked / Flooding	Internal		Archived	5012442
42077108	Side entry gully open causing a trip on footway	01/09/2021	Side entry gully on footway opposite junction with Ormidale terrace, at l/p no13	RD: Gully Brander Missing	Internal		Archived	5013643

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41099265 - Inspection Batch			Route:	NW_CF1_CorstorphineRoad1		Date:	01/09/2021
42077122	Pothole	01/09/2021	Just before Belmont Crescent at gas toby	RD: CW Pothole	Internal		Committed	50090930
42077159	Gully chocked flooding carriageway and footway	01/09/2021	Outside 136	Gully: Blocked / Flooding	Internal		Uncommitted	5004051
42077114	Low carriageway gully frame	01/09/2021	Outside 34	RD: Gully Damaged/Sunken	Internal		Uncommitted	5003130
42077164	Road: Defective / Damaged (Enquiry 597872)	01/09/2021	East bound road from western corner has new pot hole just before No.40 and sunken drainage grates outside 36-38.	RD: CW Pothole	Internal		Archived	50090995
42077170	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp lp 49	RD: CW Pothole	Internal		Archived	50003217
42077129	Pothole	01/09/2021	At lamppost CRH64	RD: CW Pothole	Internal		Committed	50090941
42077130	Potholes x 2	01/09/2021	Near lamppost CRH67	RD: CW Pothole	Internal		Committed	50090943
42077142	Pothole at gully	01/09/2021	Opp car wash	RD: CW Pothole	Internal		Committed	50090952
42077162	3 x tree root push ups patches required. 3 x 1.5. 6 x 1.2. And 0.3 x 0.3	01/09/2021	Between lamppost CRH 99 and 100	RD: FW Tree Root Tar	Internal		Committed	50090969
42077100	Missing Toby cover on footway	01/09/2021	Between no 2 and 4	RU: Utility Apparatus	Internal		Uncommitted	50090910
42077126	Break out and relay existing kerb and HRA footway.Form drop crossings with 20mm upstand and adjust street furniture as required.	01/09/2021	Corstorphine Road outside Corstorphine Hospital	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	5002184
42077163	Markings faded	01/09/2021	Junction Murrayfield Gardens	RD: Markings Refresh	Internal		Uncommitted	5003141
42077134	Dig out damaged footway & resurface in HRA	01/09/2021	North footway breaking up leaving uneven surface , East & west of l / p CRH 74	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42077166	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp lp 56	RD: CW Pothole	Internal		Archived	50003212
42077165	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp lp 58	RD: CW Pothole	Internal		Archived	50003211
42077167	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp lp 50	RD: CW Pothole	Internal		Archived	50003213
42077135	Patching required for carriageway	01/09/2021	Between the Zoo & Ormidale Terrace junction city bound side the road when on taking the Airport bus is ridiculously bumpy. It's a pain for me and surely an embarrassment for the city due to the tourists using this route. It is also fairly bad on the car lane too.	RD: CW Cracked/Broken	Internal		Uncommitted	5002868
42077127	Pothole	01/09/2021	10m before turn to Balgreen Road heading east	RD: CW Pothole	Internal		Committed	50090938
42077131	Chocked gullys, flooding on carriageway and footway	01/09/2021	Corstorphine Road outside Spire Hospital	Gully: Blocked / Flooding	Internal		Archived	5004799
42077138	Uplift signs and cones from footway	01/09/2021	Lpost 80	RD: Other Defect Type	Internal		Archived	5007050
42077102	Potholes x 2	01/09/2021	Opp Rolls Royce	RD: CW Pothole	Internal		Committed	50090912

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41099265 - Inspection Batch			Route: NW_CF1_CorstorphineRoad1				Date: 01/09/2021	
42077106	Trip at footway manhole make safe with tar	01/09/2021	O/S no 17 on corner	RD: FW HRA Pothole	Internal		Committed	50090921
42077160	Footway and carriageway broken	01/09/2021	O/S entrance to no 136	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42077118	Loose footway flags	01/09/2021	Outside 50	RD: FW Slabs Rocking	Internal		Archived	5006563
42077158	Flooding on carriageway	01/09/2021	Outside 136	Gully: Blocked / Flooding	Internal		Archived	5012440
42077123	Potholes x 2	01/09/2021	O/S no 98	RD: CW Pothole	Internal		Committed	50090932
42077074	Markings faded loading only	31/08/2021	Shops at Western Corner	RD: Markings Refresh	Internal		Archived	5012446
42077069	Trip on footway make safe with tar as marked	31/08/2021	At bus stop at lamppost CRH42	RD: FW HRA Pothole	Internal		Committed	50090875
42077065	Gully Chocked	31/08/2021	Outside 76	Gully: Blocked / Flooding	Internal		Archived	5012449
42077064	Flooding on carriageway	31/08/2021	Opposite 82	Gully: Blocked / Flooding	Internal		Archived	5012443
42077061	Replace missing kerb	31/08/2021	Opposite 92	RD: FW Kerbs Damaged/Missing	Internal		Archived	5006558
42077077	Junction markings faded	31/08/2021	At Western Corner	RD: Markings Refresh	Internal		No Action Required	
42077073	Box Junction faded	31/08/2021	Junction Western Corner	RD: Markings Refresh	Internal		Uncommitted	5003140
42077070	Markings faded loading only	31/08/2021	Outside 131	RD: Markings Refresh	Internal		Archived	5012445
42077060	Dig	31/08/2021	West bound carriageway bus lane breaking up leaving uneven surfaces from opposite no 94	RD: CW Cracked/Broken	Internal		No Action Required	
42077058	Potholes x 3	31/08/2021	Junction with Balgreen Road	RD: CW Pothole	Internal		Committed	50090871
42077057	Dig out damaged carriageway & resurface in HRA	31/08/2021	Carriageway rutting leaving ueven surface on west bound carriageway from west of junction with balgreen road for 25m	RD: CW Rutting	Internal		No Action Required	
42077055	Pothole	31/08/2021	Opp lamppost 76 heading west	RD: CW Pothole	Internal		Committed	50090869
42077052	Junction markings faded	31/08/2021	At St Catherine's Gardens	RD: Markings Refresh	Internal		No Action Required	
42077051	Keep clear markings faded	31/08/2021	Junction St Catherine Gardens	RD: Markings Refresh	Internal		Archived	5012441
42077062	Pothole	31/08/2021	At lamppost CHR46	RD: CW Pothole	Internal		Committed	50090873
42077054	Pothole	31/08/2021	Opp lamppost CRH 78 heading West	RD: CW Pothole	Internal		Committed	50090868
42077076	Keep clear markings faded	31/08/2021	Junction Western Gardens	RD: Markings Refresh	Internal		Archived	5012447
42077071	Break out existing HRA carriageway and relay with 40mm hra wearing course and 60mm asphalt base course,,replace carriageway markings as required.	31/08/2021	Corstorphine Road junction Saughtonhall Drive	RD: CW Cracked/Broken	Internal		Uncommitted	5004110
42077063	Dig out damaged carriageway and resurface in HRA	31/08/2021	West bound carriageway bus lane breaking up leaving uneven surfaces from l/p CRH 46	RD: CW Cracked/Broken	Internal		No Action Required	
42077059	Potholes x 3	31/08/2021	10 to 15m west of lamppost CRH57	RD: CW Pothole	Internal		Committed	50090872
42077168	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Outside 133	RD: CW Pothole	Internal		Archived	50003215
42077075	Damaged bollard	31/08/2021	Outside 105	RD: Bollard Damage/Missing/Nev	Internal		Archived	5006559
42077120	Pothole	01/09/2021	O/S no 74 at manhole	RD: CW Pothole	Internal		Committed	50090929
42077099	Potholes x 2	01/09/2021	At lamppost CRH32 heading east	RD: CW Pothole	Internal		Committed	50090909

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41099265 - Inspection Batch		Route: NW_CF1_CorstorphineRoad1			Date: 01/09/2021			
42077169	Road: Defective / Damaged (Enquiry 619300)	01/09/2021	Opp Ip 45	RD: CW Pothole	Internal		Archived	50003216
42077157	Clean gully's	01/09/2021	Gullies on east bound carriageway at junction for Corstorphine hospital	Gully: Blocked / Flooding	Internal		Archived	5012799
42077078	Damaged bollard	31/08/2021	At Western Corner	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42077066	Pothole	31/08/2021	10m west of lamppost Ch 42	RD: CW Pothole	Internal		Committed	50090874
42077156	Chocked gully	01/09/2021	Outside 136 Corstorphine Road	Gully: Blocked / Flooding	Internal		Uncommitted	5003129
42077139	Gully Chocked	01/09/2021	Lpost 81 Corstorphine Road	Gully: Blocked / Flooding	Internal		Archived	5012444
42077056	Pothole	31/08/2021	3m west of lamppost 65	RD: CW Pothole	Internal		Committed	50090870
42077068	Cw cracked broken	31/08/2021	Near lamppost 42	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41098908 - Inspection Batch		Route: NW_CW1_East1			Date: 25/08/2021			
42076623	1no pothole	25/08/2021	Eastbound lane at Ip CRH79	RD: CW Pothole	Internal		Committed	50090421
Batch: 41098010 - Inspection Batch		Route: Ad hoc Route			Date: 12/08/2021			
42075756	C/W patch 7 x1.5	12/08/2021	Corstorphine Road at Balgreen Road West bound	RD: CW Cracked/Broken	Internal		Committed	50089394
Batch: 41097024 - Inspection Batch		Route: Ad hoc Route			Date: 27/07/2021			
42074425	Road: Defective / Damaged (Enquiry 1215560)gully's chocked	27/07/2021	Outside 39-41-43	Gully: Blocked / Flooding	Internal		Committed	50088258
Batch: 41096900 - Inspection Batch		Route: NW_CW1_East1			Date: 26/07/2021			
42074204	3no potholes	26/07/2021	Lamppost CRH81 next to bus stop	RD: CW Pothole	Internal		Committed	50088133
Batch: 41096487 - Inspection Batch		Route: Ad hoc Route			Date: 20/07/2021			
42073745	Road: Defective / Damaged (Enquiry 1211065) Pothole on carriageway	20/07/2021	Junction Western Gardens	RD: CW Pothole	Internal		Committed	50087705
Batch: 41096420 - Inspection Batch		Route: Ad hoc Route			Date: 19/07/2021			
42073714		19/07/2021		RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50087647
Batch: 41095019 - Inspection Batch		Route: NW_CW1_East1			Date: 28/06/2021			
No actionable defects found								
Batch: 41094501 - Inspection Batch		Route: Ad hoc Route			Date: 17/06/2021			
42071336	Pothole on carriageway	17/06/2021	Outside Silvan House	RD: CW Pothole	Internal		Committed	50085405
Batch: 41092853 - Inspection Batch		Route: NW_CW1_East1			Date: 24/05/2021			
42069479	1no pothole at gully	24/05/2021	Opposite Belmont crescent	RD: CW Pothole	Internal		Committed	50083639
Batch: 41092462 - Inspection Batch		Route: Ad hoc Route			Date: 17/05/2021			
42069065	Road: Defective / Damaged (Enquiry 1175123) Pothole on carriageway	17/05/2021	Lpost 74	RD: CW Pothole	Internal		Committed	50083157
Batch: 41090490 - Inspection Batch		Route: NW_CW1_East1			Date: 16/04/2021			
No actionable defects found								

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset		Area: North West Locality	
Batch: 41089492 - Inspection Batch			Route: Ad hoc Route				Date: 01/04/2021	
42066318	Pothole on carriageway outside lane	01/04/2021	Lpost 66	RD: CW Pothole	Internal		Committed	50080273
Batch: 41089491 - Inspection Batch			Route: Ad hoc Route				Date: 01/04/2021	
42066317	Road: Defective / Damaged (Enquiry 1151113) Pothole on carriageway outside lane	01/04/2021	Lpost 73	RD: CW Pothole	Internal		Committed	50080272
Batch: 41087910 - Inspection Batch No actionable defects found			Route: NW_CW1_East1				Date: 17/03/2021	
Batch: 41087535 - Inspection Batch			Route: Ad hoc Route				Date: 16/03/2021	
42064176	Road: Defective / Damaged (Enquiry 1139709)	16/03/2021	Potholes on eastbound side of road between Pinkhill and entrance to Murrayfield Hospital.lpost 78,74,70	RD: CW Pothole	Internal		Committed	50078322
Batch: 41086949 - Inspection Batch			Route: Ad hoc Route				Date: 09/03/2021	
42063754	Road: Defective / Damaged (Enquiry 1137256)	09/03/2021	Lpost 73,79,81	RD: CW Pothole	Internal		Committed	50077850
Batch: 41083976 - Inspection Batch			Route: NW_CW1_East1				Date: 19/02/2021	
42061903	5no pothole	19/02/2021	At the junction with Cruikshank Gardens	RD: CW Pothole	Internal		Committed	50073154
42061897	5no potholes	19/02/2021	Opposite entrance to Murrayfield hospital	RD: CW Pothole	Internal		Committed	50075699
Batch: 41083918 - Inspection Batch			Route: Ad hoc Route				Date: 19/02/2021	
42061851	Road: Defective / Damaged (Enquiry 1124756) pothole on carriageway	19/02/2021	Large potholes on the road at entrance to Spire Hospital, Murrayfield.	RD: CW Pothole	Internal		Committed	50075659
Batch: 41083524 - Inspection Batch			Route: Ad hoc Route				Date: 17/02/2021	
42061601	Pothole on carriageway inside lane at box	17/02/2021	Outside the Murrayfield Hotel	RD: CW Pothole	Internal		Committed	50075390
Batch: 41083521 - Inspection Batch			Route: Ad hoc Route				Date: 17/02/2021	
42061598	Low carriageway box	17/02/2021	Outside the Murrayfield Hotel	RU: Utility Apparatus	Internal		Uncommitted	50075387
Batch: 41083519 - Inspection Batch			Route: Ad hoc Route				Date: 17/02/2021	
42061597	Pavement: Damaged / Defective (Enquiry 1121093)reinstatement required on footway and gully's need cleaned out	17/02/2021	Outside 37	RU: Utility Reinstatement	Internal		Uncommitted	50075386
Batch: 41082392 - Inspection Batch			Route: Ad hoc Route				Date: 12/02/2021	
42061049	Road: Defective / Damaged (Enquiry 1115820) Pothole on carriageway	12/02/2021	Lpost 60, heading east	RD: CW Pothole	Internal		Committed	50074779
Batch: 41082329 - Inspection Batch			Route: Ad hoc Route				Date: 11/02/2021	
42060997	Covers: Damaged / Defective - loose/noisy manhole cover (Enquiry 1114955)	11/02/2021	at junct with Belmont Crescent	RU: Utility Apparatus	Internal		Uncommitted	50074717

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41081528 - Inspection Batch		Route: Ad hoc Route				Date: 05/02/2021	
42060704	Road: Defective / Damaged (Enquiry 1113230)flooding on carriageway	05/02/2021	Water accumulating by the kerb. The water tends to build up there when it has been raining for a while. It is a hazard for cyclists.Entrance to Spire hospital	Gully: Blocked / Flooding	Internal		Committed	50074204
Batch:	41080344 - Inspection Batch		Route: Ad hoc Route				Date: 01/02/2021	
42060175	Road: Defective / Damaged (Enquiry 1109698) Pothole on carriageway	01/02/2021	New potholes East bound carriageway outside no. 40 Corstorphine Road and just west of this on same Side of road. Outside 40 pothole likely to grow quickly as it did two years ago, when damage caused to car.between 38-40	RD: CW Pothole	Internal		Committed	50073618
Batch:	41079222 - Inspection Batch		Route: NW_CW1_East1				Date: 28/01/2021	
42059788	1no pothole	28/01/2021	At the junction with Cruikshank Gardens	RD: CW Pothole	Internal		No Action Required	
Batch:	41078191 - Inspection Batch		Route: Ad hoc Route				Date: 26/01/2021	
42059444	Low carriageway box	26/01/2021	Lpost 64 inside lane heading east	RU: Utility Apparatus	Internal		Uncommitted	50072837
Batch:	41078187 - Inspection Batch		Route: Ad hoc Route				Date: 26/01/2021	
42059443	Road: Defective / Damaged (Enquiry 1106247) Pothole on carriageway inside lane	26/01/2021	Large pothole around Gas manhole cover. In bus lane eastbound.lpost64 heading east,lpost 57 to 67 heading west	RD: CW Pothole	Internal		Committed	50072834
Batch:	41076314 - Inspection Batch		Route: Ad hoc Route				Date: 19/01/2021	
42059098	Road: Defective / Damaged (Enquiry 1102353) pothole on carriageway	19/01/2021	pothole on east bound carriageway. Buses hit this and the house shakes. Please fix soon.Outside 38	RD: CW Pothole	Internal		Committed	50072360
Batch:	41071929 - Inspection Batch		Route: NW_CW1_East1				Date: 29/12/2020	
	No actionable defects found							
Batch:	41071790 - Inspection Batch		Route: Ad hoc Route				Date: 23/12/2020	
42058068	Road: Defective / Damaged (Enquiry 1088423) pothole on carriageway heading east ,lpost 78-72	23/12/2020	Pothole present in bus lane on turning to spire hospital. Looks deep and sounded deep when my car went over the top of it.	RD: CW Pothole	Internal		Committed	50070887
Batch:	41069794 - Inspection Batch		Route: NW_CW1_East1				Date: 24/11/2020	
	No actionable defects found							
Batch:	41069637 - Inspection Batch		Route: Ad hoc Route				Date: 23/11/2020	
42055911	Road: Defective / Damaged (Enquiry 1073251) Pothole on carriageway	23/11/2020	Pothole east bound carriageway, outside 36	RD: CW Pothole	Internal		Committed	50067938

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41068779 - Inspection Batch				Route: Ad hoc Route			Date: 10/11/2020	
42055294	Loose carriageway manhole	10/11/2020	Outside 41	RU: Utility Apparatus	Internal		Uncommitted	50066740
Batch: 41068778 - Inspection Batch				Route: Ad hoc Route			Date: 10/11/2020	
42055293	Pothole on carriageway	10/11/2020	Outside 41	RD: CW Pothole	Internal		Committed	50066739
Batch: 41068173 - Inspection Batch				Route: NW_CW1_East1			Date: 29/10/2020	
42054860	CW pothole in bus lane on wheel track.	29/10/2020	Opposite CRH76 lamppost	RD: CW Pothole	Internal		Committed	50065859
Batch: 41066967 - Inspection Batch				Route: Ad hoc Route			Date: 14/10/2020	
42054389	Reset bollard	14/10/2020	Outside 105	RD: Bollard Damage/Missing/Nev	Internal		Committed	50064836
Batch: 41066964 - Inspection Batch				Route: Ad hoc Route			Date: 14/10/2020	
42054387	Pothole on carriageway inside lane	14/10/2020	Junction Murrayfield Avenue	RD: CW Pothole	Internal		Committed	50064834
Batch: 41066535 - Inspection Batch				Route: Ad hoc Route			Date: 12/10/2020	
42054306	Pothole on carriageway inside lane	12/10/2020	Lpost 77	RD: CW Pothole	Internal		Committed	50064626
Batch: 41065270 - Inspection Batch				Route: NW_CW1_East1			Date: 01/10/2020	
No actionable defects found								
Batch: 41062276 - Inspection Batch				Route: NW_CW1_East1			Date: 26/08/2020	
No actionable defects found								
Batch: 41061751 - Inspection Batch				Route: Ad hoc Route			Date: 18/08/2020	
42052584	Road: Defective / Damaged (Enquiry 1022495)pothole on carriageway	18/08/2020	pothole and sunken road - 235 CORSTORPHINE ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 7AR	RD: CW Pothole	Internal		Committed	50060536

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41061744 - Inspection Batch			Route: Ad hoc Route				Date: 18/08/2020	
42052577	Road: Defective / Damaged (Enquiry 976238)carriageway repair required around manhole 2.0*2.0	18/08/2020	Hello, There is a damaged manhole cover that is crumbling outside my property on the busy road. As large vehicles pass over it, vibrations are passing through into the house. I am very concerned on the impact to my property. Please can this be repaired. Additionally, the drain on the same road outside our property appears to be blocked as when it rains heavily a large puddle appears and water streams down the drives into the properties. Thanks and regards, 	RD: CW Pothole	Internal		Committed	50060505
Batch: 41061743 - Inspection Batch			Route: Ad hoc Route				Date: 18/08/2020	
42052576	Road: Defective / Damaged (Enquiry 1022017)pothole on carriageway at manhole	18/08/2020	Reference: W5P9ND54-101000163311	RD: CW Pothole	Internal		Committed	50060504
			- since reporting this in mid-March I have had no updates, the manhole is disintegrating into the road and needs fixed please. Outside 39					
Batch: 41060517 - Inspection Batch			Route: Ad hoc Route				Date: 27/07/2020	
42051974	Road: Defective / Damaged (Enquiry 1010608)	27/07/2020	Pothole on west bound carriageway slow lane approximately 5m west of l/p no CRH 65	RD: CW Pothole	Internal		Committed	50059170
			Hot temp make safe					
Batch: 41060160 - Inspection Batch			Route: NW_CW1_East1				Date: 14/07/2020	
			No actionable defects found					
Batch: 41059135 - Inspection Batch			Route: NW_CW1_East1				Date: 23/06/2020	
42051020	4 Carriageway potholes. Make safe.	23/06/2020	Eastbound between LP CRH60 and CRH58	RD: CW Pothole	Internal		Committed	50057082
42051015	8 Carriageway potholes. Make safe.	23/06/2020	At Western Place	RD: CW Pothole	Internal		Committed	50057074
42051021	8 Carriageway potholes. Make safe.	23/06/2020	Eastbound between LP CRH32 and CRH30	RD: CW Pothole	Internal		Committed	50057083
42051019	5 Carriageway potholes. Make safe.	23/06/2020	Eastbound before TL CRH60	RD: CW Pothole	Internal		Committed	50057081
42051018	5 Carriageway potholes. Make safe.	23/06/2020	Eastbound just after LP CRH76	RD: CW Pothole	Internal		Committed	50057080
42051023	1 Carriageway pothole. Make safe.	23/06/2020	Outside no 231	RD: CW Pothole	Internal		Committed	50057086

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41059135 - Inspection Batch				Route: NW_CW1_East1			Date: 23/06/2020	
42051017	2 Carriageway potholes. Make safe.	23/06/2020	Eastbound opp LP CRH77	RD: CW Pothole	Internal		Committed	50057079
Batch: 41058247 - Inspection Batch No actionable defects found				Route: NW_CW1_East1			Date: 26/05/2020	
Batch: 41057160 - Inspection Batch No actionable defects found				Route: NW_CW1_East1			Date: 27/04/2020	
Batch: 41056969 - Inspection Batch				Route: Ad hoc Route			Date: 21/04/2020	
42049902	Road: Defective / Damaged (Enquiry 981526)	21/04/2020	Pothole around ironworks west bound at merge arrow, opp the murrayfield house hotel, outside no39	RD: CW Pothole	Internal		Committed	50055813
Batch: 41056521 - Inspection Batch No actionable defects found				Route: NW_CW1_East1			Date: 07/04/2020	
Batch: 41056045 - Inspection Batch No actionable defects found				Route: NW_CW1_East1			Date: 24/03/2020	
Batch: 41055475 - Inspection Batch				Route: Ad hoc Route			Date: 16/03/2020	
42048969	H	16/03/2020	Pothole on west bound carriageway bus lane at l/p no 62	RD: CW Pothole	Internal		Committed	50054824
Batch: 41055474 - Inspection Batch				Route: Ad hoc Route			Date: 16/03/2020	
42048968	Road: Defective / Damaged (Enquiry 967243)hot t	16/03/2020	Metal plate over sunken gully has come loose	RD: CW Pothole	Internal		Committed	50054823
Batch: 41054459 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048045	H	02/03/2020	Potholes on city bound carriageway bus lane at l/p no 56	RD: CW Pothole	Internal		Committed	50053851
Batch: 41054458 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048044	H	02/03/2020	Potholes on city bound carriageway bus lane at l/p no 58	RD: CW Pothole	Internal		Committed	50053850
Batch: 41054456 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048042	H	02/03/2020	Pothole on city bound carriageway bus lane at gully opposite l/p no 62	RD: CW Pothole	Internal		Committed	50053848
Batch: 41054455 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048041	H	02/03/2020	Pothole on city bound carriageway bus lane approximately 5m east of l/p no 63	RD: CW Pothole	Internal		Committed	50053847
Batch: 41054454 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048040	H	02/03/2020	Pothole on city bound carriageway bus lane between l/p no 64 & l/p no 63	RD: CW Pothole	Internal		Committed	50053846
Batch: 41054453 - Inspection Batch				Route: Ad hoc Route			Date: 02/03/2020	
42048039	Hot temp make safe	02/03/2020	Pothole on city bound carriageway bus lane opposite l/p no 65	RD: CW Pothole	Internal		Committed	50053845

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41054451 - Inspection Batch		Route: Ad hoc Route				Date: 02/03/2020	
42048037	Hot temp make	02/03/2020	Pothole on city bound carriageway bus lane at junction with Murrayfield hospital	RD: CW Pothole	Internal		Committed	50053843
Batch:	41054450 - Inspection Batch		Route: Ad hoc Route				Date: 02/03/2020	
42048036	H	02/03/2020	Potholes on city bound carriageway at l/p no 72	RD: CW Pothole	Internal		Committed	50053842
Batch:	41054449 - Inspection Batch		Route: Ad hoc Route				Date: 02/03/2020	
42048035	H	02/03/2020	Potholes on city bound carriageway opposite l/p no 75	RD: CW Pothole	Internal		Committed	50053841
Batch:	41054448 - Inspection Batch		Route: Ad hoc Route				Date: 02/03/2020	
42048034	H	02/03/2020	Pothole on city bound carriageway bus lane approximately 5m east of l/p no 84	RD: CW Pothole	Internal		Committed	50053840
Batch:	41054420 - Inspection Batch		Route: NW_CW1_East1				Date: 02/03/2020	
42048028	H	02/03/2020	Potholes on west bound carriageway bus lane at l/p no 71	RD: CW Pothole	Internal		Committed	50053834
42048030	H	02/03/2020	Pothole on west bound carriageway bus lane opposite l/p no 76	RD: CW Pothole	Internal		Committed	50053836
42048025	H	02/03/2020	Pothole on west bound carriageway bus lane at bus stop outside Murrayfield Lawn tennis club	RD: CW Pothole	Internal		Committed	50053831
42048027	Hot temp make safe	02/03/2020	Pothole on west bound carriageway bus lane at l/p no 65	RD: CW Pothole	Internal		Committed	50053833
Batch:	41054412 - Inspection Batch		Route: Ad hoc Route				Date: 02/03/2020	
42048024	H	02/03/2020	Pothole on city bound carriageway bus lane at gully approximately 15m west of junction with Murrayfield gardens	RD: CW Pothole	Internal		Committed	50053830
Batch:	41053737 - Inspection Batch		Route: Ad hoc Route				Date: 25/02/2020	
42047361	Hot temp make safe	25/02/2020	Pothole on city bound carriageway in yellow hatch box after junction with Corstorphine hospital	RD: CW Pothole	Internal		Committed	50053151
Batch:	41053736 - Inspection Batch		Route: Ad hoc Route				Date: 25/02/2020	
42047360	Hot temp	25/02/2020	Potholes & depressions on west bound carriageway opposite l/p	RD: CW Pothole	Internal		Committed	50053150
Batch:	41053734 - Inspection Batch		Route: Ad hoc Route				Date: 25/02/2020	
42047358	H	25/02/2020	Pothole on west bound carriageway approximately 5m East of junction with Cruikshank gardens	RD: CW Pothole	Internal		Committed	50053148
Batch:	41053731 - Inspection Batch		Route: Ad hoc Route				Date: 25/02/2020	
42047355	H	25/02/2020	Pothole on west bound carriageway at junction with Cruikshank gardens	RD: CW Pothole	Internal		Committed	50053146

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality		
Batch: 41053730 - Inspection Batch				Route: Ad hoc Route		Date: 25/02/2020		
42047354	H	25/02/2020	Potholes on west bound carriageway approximately 20m East of junction with pink hill	RD: CW Pothole	Internal		Committed	50053145
Batch: 41053187 - Inspection Batch				Route: Ad hoc Route		Date: 21/02/2020		
42046893	Remove Corstorphine hospital sign from l/p	21/02/2020	Disused sign on l/p CRH 104,	RD: Unlit Sign Damaged/Missing	Internal		Committed	50052688
Batch: 41052713 - Inspection Batch				Route: Ad hoc Route		Date: 18/02/2020		
42046531	Road: Defective / Damaged (Enquiry 957364)	18/02/2020	Surface water over carriageway at junction with Murrayfield hospital	Gully: Blocked / Flooding	Internal		Committed	50052296
Remove surface water								
Batch: 41052536 - Inspection Batch				Route: NW_CW1_East1		Date: 17/02/2020		
No actionable defects found								
Batch: 41052512 - Inspection Batch				Route: Ad hoc Route		Date: 17/02/2020		
42046343	H	17/02/2020	Pothole on city bound carriageway bus lane at junction with Murrayfield hospital	RD: CW Pothole	Internal		Committed	50052129
Batch: 41052496 - Inspection Batch				Route: Ad hoc Route		Date: 17/02/2020		
42046331	Hot temp make safe, overlay over Toby	17/02/2020	Pothole on city bound carriageway bus lane outside The Bothy	RD: CW Pothole	Internal		Committed	50052117
Batch: 41052461 - Inspection Batch				Route: Ad hoc Route		Date: 17/02/2020		
42046313	H	17/02/2020	Potholes on city bound carriageway bus lane at both sides of junction with old Corstorphine hospital	RD: CW Pothole	Internal		Committed	50052099
Batch: 41051640 - Inspection Batch				Route: Ad hoc Route		Date: 10/02/2020		
42045777	Road: Defective / Damaged (Enquiry 952614)	10/02/2020	Pothole on city bound carriageway bus lane outside no 40	RD: CW Pothole	Internal		Committed	50051549
Hot temp make safe								
Batch: 41051444 - Inspection Batch				Route: Ad hoc Route		Date: 05/02/2020		
42045537	Road: Defective / Damaged (Enquiry 951193)	05/02/2020	potholes on carriageway at junction with Cruickshank gardens	RD: CW Pothole	Internal		Committed	50051308
Hot temp make safe								
Batch: 41051415 - Inspection Batch				Route: NW_CW1_East1		Date: 05/02/2020		
No actionable defects found								
Batch: 41051312 - Inspection Batch				Route: Ad hoc Route		Date: 04/02/2020		
42045444	H	04/02/2020	Potholes on west bound carriageway approximately 10 west of l/p no 103	RD: CW Pothole	Internal		Committed	50051206

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41051291 - Inspection Batch		Route: Ad hoc Route				Date: 04/02/2020	
42045442	Hot temp make safe	04/02/2020	Potholes on west bound carriageway bus lane opposite no 105	RD: CW Pothole	Internal		Committed	50051204
Batch:	41051280 - Inspection Batch		Route: Ad hoc Route				Date: 04/02/2020	
42045438	H	04/02/2020	Pothole on west bound carriageway bus lane at bus stop opposite no 22	RD: CW Pothole	Internal		Committed	50051200
Batch:	41051031 - Inspection Batch		Route: Ad hoc Route				Date: 31/01/2020	
42045206	H	31/01/2020	Pothole on west bound carriageway bus lane at l/p no 62	RD: CW Pothole	Internal		Committed	50050950
Batch:	41051030 - Inspection Batch		Route: Ad hoc Route				Date: 31/01/2020	
42045205	Road: Defective / Damaged (Enquiry 949241)	31/01/2020	Temporary metal plate over sunken gully at l/p no 62 is loose and requires hot temp around metal plate to stop rattling	RD: CW Pothole	Internal		Committed	50050948
	Hot temp make safe							
Batch:	41050921 - Inspection Batch		Route: Ad hoc Route				Date: 30/01/2020	
42045090	Road: Defective / Damaged (Enquiry 947839)	30/01/2020	Pothole on city bound carriageway bus lane at gully opposite Rolls-Royce car showroom	RD: CW Pothole	Internal		Committed	50050799
	Hot temp make safe							
Batch:	41050912 - Inspection Batch		Route: Ad hoc Route				Date: 30/01/2020	
42045074	Road: Defective / Damaged (Enquiry 946457)	30/01/2020	make safe on manhole cover outside Murraybrugh house office block	RD: CW Pothole	Internal		Committed	50050759
	Hot temp make safe							
Batch:	41050906 - Inspection Batch		Route: Ad hoc Route				Date: 30/01/2020	
42045065	H	30/01/2020	Pothole on city bound carriageway bus lane opposite l/p 62	RD: CW Pothole	Internal		Committed	50050744
Batch:	41050904 - Inspection Batch		Route: Ad hoc Route				Date: 30/01/2020	
42045063	H	30/01/2020	Pothole on city bound carriageway bus lane between l/p 78 & l/p 76	RD: CW Pothole	Internal		Committed	50050742
Batch:	41050266 - Inspection Batch		Route: Ad hoc Route				Date: 22/01/2020	
42044514	Dig	22/01/2020	West bound carriageway bus lane breaking up leaving uneven surfaces from opposite no 94	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41050265 - Inspection Batch		Route: Ad hoc Route				Date: 22/01/2020	
42044513	Dig out damaged carriageway and resurface in HRA	22/01/2020	West bound carriageway bus lane breaking up leaving uneven surfaces from l/p CRH 46	RD: CW Cracked/Broken	Internal		No Action Required	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41050098 - Inspection Batch		Route: Ad hoc Route			Date: 21/01/2020			
42044355	H	21/01/2020	Potholes & depressions on west bound carriageway at junction with Balgreen road	RD: CW Pothole	Internal		Committed	50050055
Batch: 41049978 - Inspection Batch No actionable defects found		Route: NW_CW1_East1			Date: 20/01/2020			
Batch: 41049966 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044209	H	20/01/2020	Potholes on west bound carriageway bus lane between l/p no 52 & l/p no 55	RD: CW Pothole	Internal		Committed	50049897
Batch: 41049962 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044205	Hot temp make safe, overlay area & uplift debris from foot	20/01/2020	Potholes & depressions on west bound carriageway bus lane opposite no 94	RD: CW Pothole	Internal		Committed	50049893
Batch: 41049961 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044204	Hot temp make safe , overlay area	20/01/2020	Potholes on west bound carriageway bus lane approximately 5m west of l/p CRH 46	RD: CW Pothole	Internal		Committed	50049892
Batch: 41049959 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044202	H	20/01/2020	Potholes & depressions on west bound carriageway bus lane opposite no 82	RD: CW Pothole	Internal		Committed	50049890
Batch: 41049947 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044186	H	20/01/2020	Pothole on city bound carriageway bus lane opposite no 103	RD: CW Pothole	Internal		Committed	50049872
Batch: 41049945 - Inspection Batch		Route: Ad hoc Route			Date: 20/01/2020			
42044183	H	20/01/2020	Pothole on city bound carriageway bus lane approximately 5m east of l/p CRH 56	RD: CW Pothole	Internal		Committed	50049869
Batch: 41049724 - Inspection Batch		Route: Ad hoc Route			Date: 15/01/2020			
42043911	Road: Defective / Damaged (Enquiry 940617)	15/01/2020	Carriageway damaged on bus lane outside no 40	RD: CW Cracked/Broken	Internal		Uncommitted	50195397
Dig out damaged carriageway and resurface in HRA								
Batch: 41049722 - Inspection Batch		Route: Ad hoc Route			Date: 15/01/2020			
42043909	Road: Defective / Damaged (Enquiry 940617)	15/01/2020	Pothole on city bound carriageway bus lane outside no 40	RD: CW Pothole	Internal		Committed	50049602
Hot temp make safe								
Batch: 41049276 - Inspection Batch No actionable defects found		Route: NW_CW1_East1			Date: 09/01/2020			

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41049196 - Inspection Batch		Route: Ad hoc Route				Date: 09/01/2020	
42043542	Clear surface rain water	09/01/2020	Surface water over carriageway and footway at junction with Corstorphine hospital	Gully: Blocked / Flooding	Internal		Committed	50049209
Batch:	41049008 - Inspection Batch		Route: Ad hoc Route				Date: 08/01/2020	
42043499	Road: Defective / Damaged (Enquiry 934039) Dig out damaged carriageway and resurface in HRA	08/01/2020	Carriageway damaged on west bound carriageway fast lane approximately 10m west of l/p no 21	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41049007 - Inspection Batch		Route: Ad hoc Route				Date: 08/01/2020	
42043498	Road: Defective / Damaged (Enquiry 934039) Hot temp make safe	08/01/2020	Pothole on west bound carriageway approximately 5m west of l/p no 21	RD: CW Pothole	Internal		Committed	50049139
Batch:	41048917 - Inspection Batch		Route: Ad hoc Route				Date: 07/01/2020	
42043411	Hot temp make safe	07/01/2020	Potholes on west bound carriageway slow lane opposite l/p no 53	RD: CW Pothole	Internal		Committed	50049061
Batch:	41048916 - Inspection Batch		Route: Ad hoc Route				Date: 07/01/2020	
42043410	Hot temp make safe	07/01/2020	Potholes on west bound carriageway slow lane at l/p no 52	RD: CW Pothole	Internal		Committed	50049060
Batch:	41048915 - Inspection Batch		Route: Ad hoc Route				Date: 07/01/2020	
42043409	Hot temp make safe, over lay area , & uplift debris from footway	07/01/2020	Potholes on west bound carriageway slow lane opposite no 92 & no 94	RD: CW Pothole	Internal		Committed	50049059
Batch:	41048914 - Inspection Batch		Route: Ad hoc Route				Date: 07/01/2020	
42043408	Hot temp make safe	07/01/2020	Potholes on west bound carriageway slow lane opposite no 86	RD: CW Pothole	Internal		Committed	50049058
Batch:	41048843 - Inspection Batch		Route: Ad hoc Route				Date: 06/01/2020	
42043335	Hot temp make safe	06/01/2020	Potholes on city bound carriageway both lanes at junction with old Corstorphine hospital	RD: CW Pothole	Internal		Committed	50048967
Batch:	41048842 - Inspection Batch		Route: Ad hoc Route				Date: 06/01/2020	
42043334	Hot temp make safe	06/01/2020	Pothole on city bound carriageway at junction with kaines road	RD: CW Pothole	Internal		Committed	50048966

Customer Services

Enquiry No.: 34008589

Service: Roads General

Desc.: 94, 96 and 98 Corstorphine Road , please inspect road surafce.

Location: O/S No's 94, 96 and 98 Corstorphine Road

Logged by:

Subject: Road: Defective / Damaged

on: 30/05/2024 15:07

Classification: Request for service

Contact:

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 34008389 **Logged by:** [REDACTED] **on:** 15/04/2024 09:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Corstorphine Road at Western Terrace. please inspect two kerb side drains on the north of the road have dropped by about 4-5 inches and the road surface around them is disintegrating. .
Location: Corstorphine Road **Contact:**

Enquiry No.: 34008388 **Logged by:** [REDACTED] **on:** 15/04/2024 09:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Corstorphine Road at Western Terrace please inspect for a rocking manhole cover.
Location: Corstorphine Road **Contact:**

Enquiry No.: 34008153 **Logged by:** [REDACTED] **on:** 21/02/2024 10:50
Service: Roads General **Subject:** Drainage: General Enquiry **Classification:** General Enquiry
Desc.: Please inspect blocked gully outside Corstorphine Hospital and Murrayfield Hospital are not functioning correctly which is resulted in flooding of the road and pavement
Location: Corstorphine Road **Contact:**

Enquiry No.: 34007701 **Logged by:** [REDACTED] **on:** 01/11/2023 13:19
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Corstorphine Rd at Ellersly Rd Road (heading east). Advance Stop Line (at the traffic lights) worn
Location: Corstorphine Rd at Ellersly Rd Road (heading east) **Contact:** 0

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50144867 **Defect Number:** 42138498

Enquiry No.: 34007693 **Logged by:** [REDACTED] **on:** 30/10/2023 09:31
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Corstorphine Rd at Saughtonhall Road heading west please inspect Advance Stop Line (at the traffic lights) worn
Location: Corstorphine Road **Contact:** Joyce Harkin

Enquiry No.: 34005259 **Logged by:** [REDACTED] **on:** 12/05/2022 09:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Corstorphine road,western corner to murrayfield avenue please inspect road surface.
Location: Corstorphine road **Contact:** derek shade

Enquiry No.: 34003823 **Logged by:** [REDACTED] **on:** 07/07/2021 11:33
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: please make arrangements for the foliage to be cut back in advance of the bus lane sign and bus lane camera sign at the above location
Location: 10 metres East of Ormidale Terrace **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34002867 **Logged by:** [REDACTED] **on:** 10/12/2020 10:22
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Overgrown Trees
Location: between Ormidale Terrace and Murrayfield Gardens **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 34002840	Logged by: [REDACTED]	on: 08/12/2020 09:40
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Tree covering street light		
Location: Outside 233	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 34002839	Logged by: [REDACTED]	on: 08/12/2020 09:37
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Tree covering street light		
Location: 235	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 30009019	Logged by: [REDACTED]	on: 03/02/2020 16:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole: See Attached		
Location: Corstorphine Road: pothole on road at the bus stop opposite of Edinburgh Zoo	Contact:	
Enquiry No.: 1863685	Logged by: Verint CRM Connector	on: 26/11/2024 13:05
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Access plate on the pavement is broken	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50170406	Defect Number: 42169911	
Enquiry No.: 1843473	Logged by: Verint CRM Connector	on: 11/10/2024 14:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Inside bus lane totally collapsed - at least 4 sizeable potholes over lanes 1 and 2 on approach to and through the traffic lights. Danger to life if struck by motorcyclist.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50167993	Defect Number: 42166539	
Enquiry No.: 1833360	Logged by: Verint CRM Connector	on: 18/09/2024 11:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: big depression and multiple potholes lead to risk of death or serious injury to cyclists and pedestrians. buses are launched through the area and risk losing control. in wet weather pedestrians are soaked by splashes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1815865 **Logged by:** Verint CRM Connector **on:** 14/08/2024 09:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: The manhole and small plate nearby are sinking and have created a "bump" which is sending massive vibrations through our property. This is gradually worsening and cracks are beginning to appear in the house! The tar of the road is no cracking and I am terrified of the implications of this worsening on the house. A huge amount of very fast moving bus traffic uses this stretch, please fix the manhole, the shaking of the house is hugely affecting our sleep. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50165309 **Defect Number:** 42163574

Enquiry No.: 1813974 **Logged by:** Verint CRM Connector **on:** 10/08/2024 18:49
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service

Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush

Location: Tree has blown over in the wind blocking the footway and causing danger to pedestrians **Contact:**

Enquiry No.: 1813471 **Logged by:** Verint CRM Connector **on:** 09/08/2024 16:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service

Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush

Location: **Contact:**

Enquiry No.: 1810014 **Logged by:** Verint CRM Connector **on:** 02/08/2024 14:30
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: Obviously a car has driven in to the black bollard and uprooted it totally out, not only is the bollard lying on the pavement but also a deep hole with large pieces of damaged pavement remains and is a danger to pedestrians, prams and disabled access. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50164890 **Defect Number:** 42163033

Enquiry No.: 1804242 **Logged by:** Verint CRM Connector **on:** 24/07/2024 10:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Uneven and sunken road surface between lamppost CRH89 and the bus stop **Contact:**

Enquiry No.: 1804233 **Logged by:** Verint CRM Connector **on:** 24/07/2024 10:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Sunken drain at lamppost CRH55 **Contact:**

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1804228	Logged by: Verint CRM Connector	on: 24/07/2024 10:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road breaking up with potholes between lampposts CRH50 and CRH52	Contact:	
Enquiry No.: 1804225	Logged by: Verint CRM Connector	on: 24/07/2024 09:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Drain sunken at lampposts CRH48	Contact:	
Enquiry No.: 1803667	Logged by: Verint CRM Connector	on: 23/07/2024 13:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken drain at lampposts CRH48	Contact:	
Enquiry No.: 1803657	Logged by: Verint CRM Connector	on: 23/07/2024 12:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road breaking up and pot holes between lampposts CRH44 and CRH46	Contact:	
Enquiry No.: 1803648	Logged by: Verint CRM Connector	on: 23/07/2024 12:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot holes and road breaking up between lampposts CRH34 and CRH32	Contact:	
Enquiry No.: 1803638	Logged by: Verint CRM Connector	on: 23/07/2024 12:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside 98 in bus lane broken Road pot holes	Contact:	
Enquiry No.: 1803637	Logged by: Verint CRM Connector	on: 23/07/2024 12:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside Twin lions hotel at bus stop	Contact:	
Enquiry No.: 1803624	Logged by: Verint CRM Connector	on: 23/07/2024 12:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside murryfield hospital heading towards city pot holes	Contact:	
Enquiry No.: 1803619	Logged by: Verint CRM Connector	on: 23/07/2024 12:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside murryfield hospital road uneven and pot holes	Contact:	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1795063	Logged by: Verint CRM Connector	on: 09/07/2024 09:11
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush		
Location: Several low hanging branches on north pavement along Corstorphine Rd between Zoo exit and Balgreen Rd.		Contact:
Enquiry No.: 1788378	Logged by: Abbi Gallagher	on: 26/06/2024 17:49
Service: Roads General	Subject: Public Utilities: General	Classification: General Enquiry
Desc.: can someone please arrange for the roadwork signs on Corstorphine Road just before Murrayfield Road to be placed somewhere that isn't blocking access to wheelchair users? Blocking of pavements for disabled people is not helpful ȷ		
Location: Corstorphine Road just before Murrayfield Road		Contact:
Enquiry No.: 1772543	Logged by: Verint CRM Connector	on: 04/06/2024 23:41
Service: Roads General	Subject: Public Utilities: General	Classification: Request for service
Desc.:		
Location: Noisy utilities cover in middle of junction and carriageway. Damaged my car today!!		Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1772540	Logged by: Verint CRM Connector	on: 04/06/2024 23:39
Service: Roads General	Subject: Public Utilities: General	Classification: Request for service
Desc.:		
Location: Manhole cover in middle of lane into town has collapsed and noisy causing sleepless nights for residents. It is also a danger to road users incl cyclists.		Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1769438	Logged by: Verint CRM Connector	on: 01/06/2024 13:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Manhole cover is loose and is causing noise disruption to residents when traffic passes over it. Also dangerous to cyclists using the road. Located in East-direction lane of Corstorphine Road in the middle of Western Corner.		Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50161699	Defect Number: 42158887	
Enquiry No.: 1767182	Logged by: Verint CRM Connector	on: 30/05/2024 09:07
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Obscuring sight line. Location:Road. Type:Foliage / Bush		
Location: Hi, Corstorphine Road near junction w Balgreen Rd, city-bound. Tailbacks forcing buses to run close to curb. Overgrown trees pushing pedestrians to curb, and obscuring vision for both pedestrians and drivers. 900 service before this came closer and mirror much lower near curb/heads. I feel it's a safety risk especially at busy times/with traffic tailback in car lane.		Contact:

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1764169 **Logged by:** Verint CRM Connector **on:** 27/05/2024 14:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: recently opened pot holes and generally very uneven surface on bus lane for cycling **Contact:**
on

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1764168 **Logged by:** Verint CRM Connector **on:** 27/05/2024 14:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: recently opened pot holes and generally very uneven surface on bus lane for cycling **Contact:**
on

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1764166 **Logged by:** Verint CRM Connector **on:** 27/05/2024 14:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: recently opened pot holes and generally very uneven surface on bus lane for cycling **Contact:**
on

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1760460 **Logged by:** Verint CRM Connector **on:** 23/05/2024 13:14
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Trees overhanging on north-side pavement along c 150m stretch of road. **Contact:**
Pedestrians witnessed being forced to step onto road/oncoming traffic to avoid this
obstruction of footpath.

Enquiry No.: 1759452 **Logged by:** Gayle Skeldon **on:** 22/05/2024 15:48
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Called to request that the road markings are refreshed as they are all faded
Location: From top of Balgreen Road going west to the turnoff for Murraygfield hospital **Contact:** Catherine Johnstone

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50160905 **Defect Number:** 42157870

Enquiry No.: 1758649 **Logged by:** Verint CRM Connector **on:** 21/05/2024 19:33
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Large overhanging trees along this stretch of Corstorphine Rd are forcing
pedestrians to step into bus lane and danger from traffic. **Contact:**

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1756385	Logged by: Verint CRM Connector	on: 19/05/2024 10:13
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Footpath. Type:Foliage / Bush		
Location: North end of Traquair Alley. Tree over grown hindering both the path & access to the pedestrian crossing.	Contact:	
Enquiry No.: 1754822	Logged by: Verint CRM Connector	on: 16/05/2024 12:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: damaged road surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754816	Logged by: Verint CRM Connector	on: 16/05/2024 12:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: damaged road surface and manhole sinking	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754814	Logged by: Verint CRM Connector	on: 16/05/2024 12:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: uneven and damaged road surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754811	Logged by: Verint CRM Connector	on: 16/05/2024 12:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: uneven road surface damaged	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754808	Logged by: Verint CRM Connector	on: 16/05/2024 12:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: road surface damaged and broken	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50160589	Defect Number: 42157500	
Enquiry No.: 1754792	Logged by: Verint CRM Connector	on: 16/05/2024 12:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: damaged road surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1754783	Logged by: Verint CRM Connector	on: 16/05/2024 12:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: road surface damaged	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754781	Logged by: Verint CRM Connector	on: 16/05/2024 12:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: damage to road surface and drain	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754778	Logged by: Verint CRM Connector	on: 16/05/2024 12:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: road cracked and broken	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754770	Logged by: Verint CRM Connector	on: 16/05/2024 11:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: sinking drain and road uneven surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754763	Logged by: Verint CRM Connector	on: 16/05/2024 11:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: broken and uneven road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754760	Logged by: Verint CRM Connector	on: 16/05/2024 11:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: broken and uneven	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754750	Logged by: Verint CRM Connector	on: 16/05/2024 11:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: bus surface broken up	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1754741	Logged by: Verint CRM Connector	on: 16/05/2024 11:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: drain sinking at kerb also manhole sinking	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50160591	Defect Number: 42214390	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1754732 **Logged by:** Verint CRM Connector **on:** 16/05/2024 11:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: potholes at bus stop outside the zoo at Holiday Inn **Contact:**

Enquiry No.: 1753622 **Logged by:** Verint CRM Connector **on:** 14/05/2024 16:24
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Low hanging tree branches between Spire Hospital access and Balgreen Road **Contact:**

Enquiry No.: 1750331 **Logged by:** Verint CRM Connector **on:** 08/05/2024 16:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Surface of the moon **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1750330 **Logged by:** Verint CRM Connector **on:** 08/05/2024 16:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large deep pothole in lane 2 opposite hospital entrance. West bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50160194 **Defect Number:** 42156989

Enquiry No.: 1749447 **Logged by:** Verint CRM Connector **on:** 07/05/2024 11:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a large extended linear pothole in the road driving east to west. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50159970 **Defect Number:** 42156632

Enquiry No.: 1745953 **Logged by:** Verint CRM Connector **on:** 30/04/2024 20:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There's a deep pothole on Costorphine Rd eastbound lane, just below the junction of Murrayfield avenue. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50159557 **Defect Number:** 42156119

Enquiry No.: 1745793 **Logged by:** Verint CRM Connector **on:** 30/04/2024 15:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large patches failed in bus lane city bound.
Like surface on the moon. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1745790	Logged by: Verint CRM Connector	on: 30/04/2024 15:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole in lane 2 opposite hospital entrance	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1743836	Logged by: Verint CRM Connector	on: 26/04/2024 15:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:	while driving along Corstorphine road, I encountered a large and deep pothole that I was unable to avoid due to heavy traffic. The	
	I implore you to take immediate action to address the hazardous potholes on Corstorphine Road and other roads in our community. Repairs must be conducted promptly to prevent further damage to vehicles and to ensure the safety of all road users.	
Location: Deep potholes, one after another on Corstophine road in a bus lane, unavoidable if using both lanes, especially if cars are side by side. Its close to where I've pin pointed , also very close to the pavement which could be dangerous for pedestrians	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50159336	Defect Number: 42155803	
Enquiry No.: 1737013	Logged by: Verint CRM Connector	on: 15/04/2024 15:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: On city bound bus lane there is an area of road surface that is significantly damaged. Could be described as a depression. Is very bumpy when going over on bus and bordering on dangerous when riding bike.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1732564	Logged by: Verint CRM Connector	on: 08/04/2024 13:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: significant damage in bus lane eastbound	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1729919	Logged by: Verint CRM Connector	on: 04/04/2024 11:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: very difficult to cycle within the bus lane safely when the road surface is so poor	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1729824	Logged by: Verint CRM Connector	on: 04/04/2024 10:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Reported these road issues on 20th March they continue to pose a threat to Life.I did note submit a picture at that time but have now added some of the many problems on this stretch of carriageway from Western Corner to the Murrayfield Hotel	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1729811	Logged by: Verint CRM Connector	on: 04/04/2024 10:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Reported these pot holes and dropped drains on the 20th March 2024.to date they continue to pose a life threatening Problem for anyone using this stretch of Corstorphine Road From western Corner to the Murrayfield Hotel stretch. I did not provide a photo on that occasion but have now added some. Please be under no illusion These defects are dangerous and a serious threat to Life.They need to be attended ASAP	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1724241	Logged by: Verint CRM Connector	on: 25/03/2024 15:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes and sunken drains that are blocked from leaves and pieces of tarmac.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50157127	Defect Number: 42153396	
Enquiry No.: 1724220	Logged by: Verint CRM Connector	on: 25/03/2024 14:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This pothole is at the junction of Balgreen Road & Corstorphine Road	Contact:	
Enquiry No.: 1724150	Logged by: Verint CRM Connector	on: 25/03/2024 13:22
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Numerous potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1721268 **Logged by:** Verint CRM Connector **on:** 20/03/2024 09:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large pot holes and sunken drains/manhole covers on the near side east bound carriageway from Western Corner to the Murrayfield Hotel. These defectives are more noticeable now while because of the new electrical cable installations in the centre of the road drivers are forced to use this defective and dangerous inside lane. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1719994 **Logged by:** Verint CRM Connector **on:** 18/03/2024 13:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Current roadworks are taking place on the stretch Western Corner to Murrayfield Road. One rocking drain is now rattling and two kerb side drains have dropped about 4 inches and the road surface around them is falling apart. Is the contractor obliged to resolve the problems they have created by the introduction of the restrictions? **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1719682 **Logged by:** Verint CRM Connector **on:** 17/03/2024 23:32
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: **Contact:**

Enquiry No.: 1719654 **Logged by:** Verint CRM Connector **on:** 17/03/2024 21:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Terrible condition of road and making it impossible to drive safely! So uneven and filled with potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1719651 **Logged by:** Verint CRM Connector **on:** 17/03/2024 21:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Terrible condition of road and making it impossible to drive safely! So uneven and filled with potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1719302 Logged by: Verint CRM Connector on: 17/03/2024 07:51
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: There are a series of potholes in the bus lane before and after the entrance to the Spire hospital. They are very dangerous for cyclists. They cause a cyclist (me) to swerve around them. This causes me and other cyclists to move throughout the lane and not keep a straight path. This is turn could be causing confusion for drivers. The potholes if not avoided could cause cyclists to be bumped off the bike and into traffic causing a potentially fatal accident. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1712529 Logged by: Verint CRM Connector on: 05/03/2024 17:29
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Both the east and westbound bus lanes on western terrace, from the junction at western corner to the junction of murrayfield road in its entirety. Contact:

There are multiple collapsed drains, collapsed manholes, significant potholes that may cause a danger to life along this stretch of road. These cannot be avoided due to the current road works which means the bus lane must be used.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1711376 Logged by: Verint CRM Connector on: 04/03/2024 09:33
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Road surface in need to urgent emergency repair. Severe potholes and damaged surface. Danger to motorists, cyclists, pedestrians and extremely unpleasant for bus passengers. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1710472 Logged by: Verint CRM Connector on: 02/03/2024 08:54
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: It is just by the entrance of a drive. [REDACTED] Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1708920 Logged by: Verint CRM Connector on: 28/02/2024 17:52
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: deep water filled pothole eastbound at speed camera Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1708432	Logged by: Verint CRM Connector	on: 28/02/2024 10:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1708384	Logged by: [REDACTED]	on: 28/02/2024 09:40
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: please see document attached thanks		
Location: please see document attached thanks	Contact:	
Enquiry No.: 1708209	Logged by: Verint CRM Connector	on: 27/02/2024 21:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large stretch of crumbling uneven road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1707047	Logged by: Verint CRM Connector	on: 26/02/2024 13:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Frequently take bus into town from Corstorphine. The journey is horrendous because of the potholes on the road. The ride is so bumpy and dangerous for people, especially the elderly, who have to move on the bus when alighting or disembarking.	Contact:	
Enquiry No.: 1706236	Logged by: Verint CRM Connector	on: 24/02/2024 22:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole in road in front of Enterprise Rent-a-car	Contact:	
Enquiry No.: 1698292	Logged by: Verint CRM Connector	on: 13/02/2024 06:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a thin but deep strip of damaged road measuring roughly two metres long in the typical tyre line on the left when heading westwards.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1695298	Logged by: Verint CRM Connector	on: 08/02/2024 07:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several long, deep cracks in road surface going towards Corstorphine. Needs sorting ASAP before there is an accident with cars swerving to avoid them	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1695095	Logged by: Verint CRM Connector	on: 07/02/2024 17:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole in bus/cycle lane.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1695093	Logged by: Verint CRM Connector	on: 07/02/2024 17:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes in bus/cycle lane.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1695062	Logged by: Verint CRM Connector	on: 07/02/2024 16:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Eastbound bus lane, Corstorphine Road, near Murrayside Care home. Road surface heavily broken with several potholes in right side of bus lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1693560	Logged by: Verint CRM Connector	on: 05/02/2024 16:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road condition and pot holes in bus lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1692976	Logged by: Verint CRM Connector	on: 05/02/2024 00:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Westbound carriageway. Just after slight bend to right. Several large lateral cracks in the surface, exactly on wheel line through the bend. Drivers having to swerve into bus lane to avoid	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1692300	Logged by: Verint CRM Connector	on: 03/02/2024 13:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes and failed surface in lane 2	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50152117	Defect Number: 42146302	
Enquiry No.: 1692297	Logged by: Verint CRM Connector	on: 03/02/2024 13:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1692294	Logged by: Verint CRM Connector	on: 03/02/2024 13:30
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large deep pothole after bus stop	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50152105	Defect Number: 42146284	

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1690983	Logged by: Verint CRM Connector	on: 01/02/2024 15:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several deep potholes next to loading bay	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1690555	Logged by: Verint CRM Connector	on: 01/02/2024 09:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Three large holes as you turn into Balgreen Road from Corstorphine Road. I'm surprised these weren't filled in when a team was out last week filling in similiar holes ten feet away as they were blindingly obvious.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1689786	Logged by: Verint CRM Connector	on: 31/01/2024 12:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The section of St John's Road and Corstorphine Road for about 1 mile between Corstorphine and Murray field is cracked and potholed to a dangerous degree for cyclists, buses and cars (all of which I use on that road). The bus / cycle lane is worst on the side going towards the city centre. When cycling I have to regularly deviate around holes to avoid damage or an accident, which puts me at risk from other traffic.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1689569	Logged by: Verint CRM Connector	on: 31/01/2024 09:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Manhole and new potholes around	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50151872	Defect Number: 42145938	
Enquiry No.: 1689566	Logged by: Verint CRM Connector	on: 31/01/2024 09:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes with the sunken surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1688690	Logged by: Verint CRM Connector	on: 30/01/2024 07:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There are 2 potholes in close proximity as you turn right off Glasgow Road. They are so severe they are risking suspension and damage.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1688187	Logged by: Verint CRM Connector	on: 29/01/2024 13:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: series of potholes, westbound	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1687381	Logged by: Verint CRM Connector	on: 28/01/2024 09:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a large pothole in the middle of the road at the junction from corstorphine road and balgreen road heading West towards airport.	Contact:	
Enquiry No.: 1685899	Logged by: Verint CRM Connector	on: 25/01/2024 17:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two massive potholes in outside lane driving west	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50151481	Defect Number: 42145424	
Enquiry No.: 1683887	Logged by: Verint CRM Connector	on: 23/01/2024 15:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1683027	Logged by: Verint CRM Connector	on: 22/01/2024 14:47
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: On the pavement where City Fibre's recent excavations meet the roadway, a gap in their patching has been exposed (see photo). It is a tripping hazard for pedestrians so should be fixed. I feel sure this should be at City Fibre's expense. I also do not recall the roadway being as prone to flooding. Have City Fibre damaged the road drain too?	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50150990	Defect Number: 42144848	
Enquiry No.: 1678768	Logged by: Verint CRM Connector	on: 15/01/2024 18:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road breaking up around gully at bus stop	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50150368	Defect Number: 42144215	
Enquiry No.: 1678582	Logged by: Verint CRM Connector	on: 15/01/2024 15:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Gully collapsed at entrance to Spire Hospital	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1672522	Logged by: Verint CRM Connector	on: 06/01/2024 06:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole on westbound carriageway	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1672521	Logged by: Verint CRM Connector	on: 06/01/2024 06:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: small pothole on the road. Not deep. On eastbound carriageway opposite silvan house	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1672520	Logged by: Verint CRM Connector	on: 06/01/2024 06:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole. Previous repair went bad. Opposite crossing on eastbound carriageway	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50149505	Defect Number: 42143359	
Enquiry No.: 1672519	Logged by: Verint CRM Connector	on: 06/01/2024 06:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: opposite the entrance to Silvan House on the eastbound carriageway between the bus lane and the normal road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1670844	Logged by: Verint CRM Connector	on: 03/01/2024 20:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole forming	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1670843	Logged by: Verint CRM Connector	on: 03/01/2024 20:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole just before pedestrian crossing, eastbound carriageway	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1670271	Logged by: Verint CRM Connector	on: 03/01/2024 11:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes in bus lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1665114 **Logged by:** Verint CRM Connector **on:** 21/12/2023 10:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken surface with pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1663780 **Logged by:** Verint CRM Connector **on:** 18/12/2023 19:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This stretch of road is dangerous to cycle on. the bus lane is so badly deteriorated that even the buses avoid driving on where they can. as a cyclist i have little choice but to use the bus lane here. The road has been in a poor state for the whole two years that i have lived in Edinburgh and it is getting worse al the time. whole stretch of road from Corstorphine towards Haymarket is poor but this particular point is unacceptable **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1661572 **Logged by:** Verint CRM Connector **on:** 14/12/2023 11:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: road holes and depressions result in water pooling and vehicles bouncing. this creates a danger to pedestrians. even today in sunny weather a pedestrian was soaked, he wasn't happy. this happens every day. furthermore failing to mend the road surface, when raining, you are leaving a huge danger to the public as vehicles bounce and lose traction. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1660657 **Logged by:** Verint CRM Connector **on:** 13/12/2023 06:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Eastbound carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1660496 **Logged by:** Verint CRM Connector **on:** 12/12/2023 18:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two big potholes have opened up at the right turn off Corstorphine Road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1654487 **Logged by:** Verint CRM Connector **on:** 02/12/2023 15:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the 100/X18 bus stop in front of the Holiday Inn on the side of road heading towards city centre. Significant pothole that will tear a tyre wall and, at worst, send a cyclist over their handle bars. **Contact:**

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1653712	Logged by: Verint CRM Connector	on: 01/12/2023 08:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole in bus stop bus box, will cause damage to busses and or cyclists	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50147009	Defect Number: 42140859	
Enquiry No.: 1653037	Logged by: Verint CRM Connector	on: 30/11/2023 06:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Long stretch of pot holes, broken surface and uneven road. Unable to turn into the HOSPITAL until last minute to avoid damage to car.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1652790	Logged by: Verint CRM Connector	on: 29/11/2023 14:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The bus lane at the foot of the hill leading to spire is riddled with potholes. It's impossible to count how many holes there are. It's been like this for months	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50146924	Defect Number: 42140764	
Enquiry No.: 1646384	Logged by: Verint CRM Connector	on: 17/11/2023 19:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole in outside lane of westbound carriageway.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50146153	Defect Number: 42139961	
Enquiry No.: 1642526	Logged by: Verint CRM Connector	on: 11/11/2023 09:19
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes and broken surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1642518	Logged by: Verint CRM Connector	on: 11/11/2023 09:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of growing potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1641381	Logged by: Verint CRM Connector	on: 09/11/2023 07:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Absolute travesty of a collection of pothole, cracked and erroded surface for the entire bus land from the top of Pinkhill to Balgreen Road, but especially at the entrance to the hospital.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1638550	Logged by: Verint CRM Connector	on: 04/11/2023 09:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside Murrayfield hospital entrance. Road surface crumbling.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1638299	Logged by: Verint CRM Connector	on: 03/11/2023 14:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole at eastbound Airlink and express services bus stop	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1637193	Logged by: [REDACTED]	on: 02/11/2023 08:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Two large and deep potholes		
Location: at the bus stop opposite Edinburgh Zoo	Contact:	
Enquiry No.: 1636523	Logged by: [REDACTED]	on: 01/11/2023 09:18
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: can somoen phone mr McKeenan back about his Blocked Gully that keeps happeing right outside his house and would like somoen to contact him to get this sorted		
Location: 135 Corstorphine Road.	Contact: Grant McKeenan	
Enquiry No.: 1635867	Logged by: Verint CRM Connector	on: 31/10/2023 08:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Numerous potholes / bad fretting in lane 1 approaching hospital	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1635866	Logged by: Verint CRM Connector	on: 31/10/2023 08:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole lane 1 just after hotel	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50144737	Defect Number: 42138363	
Enquiry No.: 1630524	Logged by: Verint CRM Connector	on: 20/10/2023 07:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Uneven road surface causing many bumps to buses in the bus lane travelling west to east.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1630523	Logged by: Verint CRM Connector	on: 20/10/2023 07:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Uneven road surface causing many bumps for buses in the bus lane.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1625157 **Logged by:** Verint CRM Connector **on:** 08/10/2023 18:01
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Flooding preventing use of pavement and crossing. This is an issue whenever there is significant rainfall. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1625073 **Logged by:** Verint CRM Connector **on:** 08/10/2023 14:29
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: Four traffic cones on the pavement outside our house . They have been there for weeks, for no good reason. We want them removed, please. **Contact:**

Enquiry No.: 1624851 **Logged by:** Verint CRM Connector **on:** 07/10/2023 18:16
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Traquair Alley North next to Corstorphine Road. Overgrown bushes & trees obstructing pathway. **Contact:**

Enquiry No.: 1623938 **Logged by:** Verint CRM Connector **on:** 05/10/2023 18:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Bus lane Road surface Eastbound just prior to, at and beyond the junction / entrance into nufield littered with pot holes.
Just punctured both tyres on my bike please resurface that area
I'm now on bus I can get photos tomorrow if you require them ? **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1623515 **Logged by:** Verint CRM Connector **on:** 05/10/2023 09:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at Airlink/ Citylink Bus Stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50143577 **Defect Number:** 42137049

Enquiry No.: 1620350 **Logged by:** Verint CRM Connector **on:** 28/09/2023 13:19
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Ivy overhanging wall on one side and overgrown bushes on the other making it very difficult to use steps down to Traquair Alley **Contact:**

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1619952	Logged by: Verint CRM Connector	on: 27/09/2023 16:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: blocked culvert. Water builds up when it rains.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50143293	Defect Number: 42136808	
Enquiry No.: 1619880	Logged by: Verint CRM Connector	on: 27/09/2023 14:16
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Between Edinburgh zoo and murrayfield hospital lots of potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50143292	Defect Number: 42136807	
Enquiry No.: 1618870	Logged by: Verint CRM Connector	on: 25/09/2023 12:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The bus lane turning left into the hospital has potholes and is very bumpy	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1614692	Logged by: Verint CRM Connector	on: 15/09/2023 14:43
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Footpath. Type:Foliage / Bush		
Location: Traquair Alley steps and path next to Silvan House with Ivy and bushes narrowing the path.	Contact:	
Enquiry No.: 1610082	Logged by: Verint CRM Connector	on: 07/09/2023 09:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Corstorphine Road Eastbound at entrance to Spire Murrayfield	Contact:	
Road surface is very uneven and has many potholes.		
This is a major issue to patients that are in pain requiring orthopaedic surgery and post-operative patients		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1599563 Logged by: Verint CRM Connector on: 17/08/2023 13:58
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Causing Obstruction.
Location: Pavement.
Type: Foliage / Bush
Location: Customers Comment: The state of Corstorphine Road is atrocious. There's a full tree branch blocking the path of pavement which is extremely dangerous. There's pot holes everywhere.

Contact:

Enquiry No.: 1599560 Logged by: Verint CRM Connector on: 17/08/2023 13:55
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
Location: Customers Comment: The state of Corstorphine Road is atrocious. There's a full tree branch blocking the path of pavement which is extremely dangerous. There's pot holes everywhere.

Contact:

Enquiry No.: 1597359 Logged by: Verint CRM Connector on: 14/08/2023 13:57
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:
Location: Gaurd rail is broken outside the Zoo on Corstorphine Road

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1593282 Logged by: Verint CRM Connector on: 06/08/2023 13:02
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
Location: This is the newly constructed junction at the bottom of Murrayfield avenue. The junction has been made too narrow so cars turning right out of the junction do not leave enough room for those turning left. I don't know why the junction was changed like this but it is leading to unnecessary congestion and frustration

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1583853 Logged by: Verint CRM Connector on: 19/07/2023 09:21
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:
Location: Rebar steel protruding from footway surface

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Job Number: 50139531 Defect Number: 42132272

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1576722 **Logged by:** Verint CRM Connector **on:** 05/07/2023 09:43
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: Large speed measure sign on St Johns Road opposite house number 96, the sign looks broken on the lamp post and is it still required **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50138887 **Defect Number:** 42131378

Enquiry No.: 1568727 **Logged by:** Verint CRM Connector **on:** 19/06/2023 10:44
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Opposite the Scot Hut near the Forestry Commission.
 On road lights set up on main road into Corstorphine, making it a one lane road. However, no work seemed to be taking place by Scottish Water, but the impact on the rest of Edinburgh actually getting to work was massive. Surely if you authroise work to be carried out on our behalf the least that could be done would be to ensure it takes place and in a timely manner. Please let me know what has been done to make this better asap **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1565222 **Logged by:** Verint CRM Connector **on:** 11/06/2023 18:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface in east bound bus/cycle lane heavily degraded, causing cyclists to swerve into main carriageway to avoid pot holes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1561091 **Logged by:** Verint CRM Connector **on:** 02/06/2023 14:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1559788 **Logged by:** Verint CRM Connector **on:** 31/05/2023 11:52
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
 Location:Footpath.
 Type:Foliage / Bush
Location: Several low hanging tree branches blocking citybound footpath between Spire Murrayfield Hospital Entrance and Balgreen Road **Contact:**

Enquiry No.: 1559016 **Logged by:** Verint CRM Connector **on:** 30/05/2023 10:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: After murrayfield Road going west the road is a disgrace all uneven very dangerous **Contact:**

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1558795 **Logged by:** Verint CRM Connector **on:** 29/05/2023 22:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are several large broken sections of the road in the bus & cycle lane. **Contact:**

These begin around 15m prior to the Spire Hospital entrance on Corstorphine Road and finish just after that junction.

The broken surface is significantly and dangerous for cyclists, such as myself. You must quickly dodge them or risk a potential puncture or being bumped out of a safe position on the road.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1551574 **Logged by:** [REDACTED] **on:** 16/05/2023 08:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Road surface has been breaking up for months. Is dangerous to cyclists - makes me move put of the bus lane. Also causes serious shaking and discomfort to bus passengers. Would not be surprised if buses are being damaged.
Location: **Contact:**

Enquiry No.: 1547976 **Logged by:** Verint CRM Connector **on:** 08/05/2023 00:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes on bus lane before the turning into spire hospital. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1547511 **Logged by:** Verint CRM Connector **on:** 05/05/2023 23:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken drain **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50135726 **Defect Number:** 42163689

Enquiry No.: 1546814 **Logged by:** Verint CRM Connector **on:** 04/05/2023 13:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on main (Corstorphine Road). West bound carriageway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50135581 **Defect Number:** 42126788

Enquiry No.: 1540968 **Logged by:** Verint CRM Connector **on:** 21/04/2023 14:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Approximately 8-10 large potholes at the entrance to Murrayfield (in the bus lane prior to the opening. Very difficult to navigate between them some quite deep. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50134810 **Defect Number:** 42163680

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1540571 Logged by: Verint CRM Connector on: 21/04/2023 09:17
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: huge areas of the road surface have broken up leaving a large ,very uneven surface across both the bus land and the other lane, heading into the city , at the junction of Corstorphine Road and the turning into Spire Murrayfield hospital. Contact:

Enquiry No.: 1540511 Logged by: Verint CRM Connector on: 21/04/2023 07:56
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Road surface broken up both directions between Chinese Consulate and 30 Corstorphine Road. Extremely dangerous for cyclists as cars are swerving to avoid dangerous surface and cyclists may be knocked off by uneven surface Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1536753 Logged by: Verint CRM Connector on: 13/04/2023 17:03
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Traffic cones been left on traffic island on Corstorphine Road near junction with Belmont Crescent Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
 Job Number: 50134276 Defect Number: 42125233

Enquiry No.: 1532582 Logged by: Verint CRM Connector on: 04/04/2023 12:46
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: A recently built crossing island, had no-one, lighting or signs warning of changed road layout. On 31/3/23 @ 0230-0300 going towards Corstorphine, I hit the curb of this island and sustained damage to drivers side tyres consistent with hitting a curb. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1532305 Logged by: Verint CRM Connector on: 04/04/2023 05:49
 Service: Roads General Subject: Public Utilities: General Classification: Request for service
 Desc.:
 Location: Double manhole on eastbound carriageway inner lane completely loose and clanking which can be heard from inside homes on Wallace Gardens and Ellersly Road Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1531348 Logged by: Verint CRM Connector on: 01/04/2023 09:37
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: There is a deep pothole in lane two/ middle of the road. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1527857 **Logged by:** Verint CRM Connector **on:** 24/03/2023 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 3 large potholes on carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1527541 **Logged by:** Verint CRM Connector **on:** 23/03/2023 22:35
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Western Corner bus stop (eastbound) there is a pothole on the greenway around a metal grid on the road causing danger to pedestrians and cyclists and a noise nuisance **Contact:**

Enquiry No.: 1527496 **Logged by:** Verint CRM Connector **on:** 23/03/2023 19:31
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Near Ellersley Road Junction and Western Corner bus stop on Corstorphine Road going west into the city, massive holes around manhole cover, photo below. Externely noisy when buses and vehicles go over the lid. Looks really dangerous. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50133531 **Defect Number:** 42124466

Enquiry No.: 1526021 **Logged by:** Verint CRM Connector **on:** 21/03/2023 10:55
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: opposite western place at the bus stop - loose manhole cover rattling on the crumbling road surface - to be attended to ASAP as the manhole is spread across the east -bound carriage way **Contact:**

Enquiry No.: 1525567 **Logged by:** [REDACTED] **on:** 20/03/2023 13:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: opposite side of the zoo **Contact:**

Enquiry No.: 1524406 **Logged by:** Verint CRM Connector **on:** 17/03/2023 10:22
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Several areas of pavement were damaged by work done by City Fibre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1524154 **Logged by:** Verint CRM Connector **on:** 16/03/2023 17:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Long stretch of potholes, large in length and depth. impossible to avoid when driving and and turning into junction for Spire Murrayfield. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50132263 **Defect Number:** 42188955

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1523673 **Logged by:** Verint CRM Connector **on:** 15/03/2023 23:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Patch work has disintegrated and a hole roughly 6 inches deep and roughly 1 sq ft stretching from the middle of the lane going towards Roseburn.
The pavement has also been left in an unfinished state with loose debris strewn across the pavement and road causing a hazard for both vehicles and pedestrians.
debris ranges in size from gravel to golf ball sized rocks.

The area around the manhole has also deteriorated and is a tripping hazard.

This is brand new work completed in last the month.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1522658 **Logged by:** Verint CRM Connector **on:** 14/03/2023 09:32
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: caller advised urgent matter as keeping him awake at night

Location: west-bound on junction of Murrayfield Avenue/ Place - opposite laundrette - straddling across 2 lanes on corstorphine Road **Contact:**

Enquiry No.: 1518984 **Logged by:** Verint CRM Connector **on:** 05/03/2023 22:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: pothole big enough to burst a tyre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50131195 **Defect Number:** 42121383

Enquiry No.: 1516099 **Logged by:** Verint CRM Connector **on:** 27/02/2023 14:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: large pothole east-bound . danger to cyclists. easting/northing: 321341/672919 **Contact:**

Enquiry No.: 1515787 **Logged by:** Verint CRM Connector **on:** 26/02/2023 22:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Rut in the middle of the road causing 2 wheeled traffic pedal and motor traffic to swerve to avoid getting stuck **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1515669 **Logged by:** Verint CRM Connector **on:** 26/02/2023 15:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The manhole cover is completely wrecked, all the tarmac has given away around it and when vehicles go over the manhole cover jumps up and down. Every time this happens the house shakes and it makes a terrible noise, keeping us up at night and awake in the morning. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1511380 **Logged by:** Verint CRM Connector **on:** 17/02/2023 12:58
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service

Desc.: Problem: Overgrown.
 Location: Park.
 Type: Foliage / Bush

Location: Large trees located in the Corstorphine Nature Reserve are adjacent to the boundary of our home at 114 Corsorphine Rd - one substantial tree looks ot me to have a rotten trunk - the branches also over hang our garden; if the tree fell it would fall on our garden room apart for the obvious Health and Safety concern to my family and indeed people in the nature reserve . Photos attached - can this be inspected pls - I think it is potentially dangerous. Remaining trees overhanging also need checked

Contact:

Enquiry No.: 1510652 **Logged by:** Verint CRM Connector **on:** 16/02/2023 10:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Downie terrace and number 321 also opp the zoo potholes

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1510527 **Logged by:** Verint CRM Connector **on:** 16/02/2023 06:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Very loose ironworks in bus lane east of bus stop

Contact:

Enquiry No.: 1509343 **Logged by:** Verint CRM Connector **on:** 13/02/2023 17:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Pothole on westbound carriageway at junction with balgreen road

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50129200 **Defect Number:** 42118482

Enquiry No.: 1509273 **Logged by:** Verint CRM Connector **on:** 13/02/2023 15:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Outside 231 Corstorphine Road - whole channel extends from 231 all the way back to before the zoo - difficult to miss due to the bus lane. On same side of road as Forestry Comission

Contact:

Enquiry No.: 1507665 **Logged by:** Verint CRM Connector **on:** 09/02/2023 16:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: There are really dangerous crack/holes being created around a manhole cover. When the vehicles go over the manhole it is rising and dropping out of the ground. If a bicycle of car was to go into the hole there could be an accident.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50129007 **Defect Number:** 42136437

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1507106	Logged by: Verint CRM Connector	on: 08/02/2023 17:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: potholes on Corstorphine road near Balgreen junction	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50128846	Defect Number: 42118068	
Enquiry No.: 1506173	Logged by: Verint CRM Connector	on: 07/02/2023 10:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot hole Explore my tyre	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1503909	Logged by: [REDACTED]	on: 02/02/2023 14:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: including downie terrace whole stretch all the way to 231 corstorphine road. there are several potholes very deep opposite the zoo. potholes both side of road for around 300 yards		
Location: including downie terrace whole stretch all the way to 231 corstorphine road. there are several potholes very deep opposite the zoo. potholes both side of road for around 300 yards	Contact:	
Enquiry No.: 1496088	Logged by: Verint CRM Connector	on: 19/01/2023 22:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This whole section of road needs resurfaced it's a disgrace after all the recent house building works	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1494187	Logged by: Verint CRM Connector	on: 17/01/2023 12:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Roads required resurfaced, several areas crumbling on this road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1493513	Logged by: Verint CRM Connector	on: 16/01/2023 14:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside 231, (this been reporting this for about 6 months and still not been fixed	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50127251	Defect Number: 42116180	
Enquiry No.: 1492756	Logged by: Verint CRM Connector	on: 15/01/2023 15:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole at side of the road in front of the bus stop. People are getting splashed by vehicles driving vier it, even if they are going slow. Photo added if rhe pothole and the bus stop number.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1492245	Logged by: Verint CRM Connector	on: 14/01/2023 13:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole with steep edges about 5-8 com deep and about 5cm across . The pothole is in the wesbound buss lane at a distnce from the curb that makes it a major hazrd to cyclists	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50126963	Defect Number: 42115938	
Enquiry No.: 1491969	Logged by: Verint CRM Connector	on: 13/01/2023 22:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading out of town, had to weave through a load of them	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1491966	Logged by: Verint CRM Connector	on: 13/01/2023 22:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: I got what felt like two big ones towards the end of the bus lane heading out of town, as I was turning left down pinkhill	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50126964	Defect Number: 42115939	
Enquiry No.: 1491690	Logged by: Verint CRM Connector	on: 13/01/2023 14:26
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: large pothole outside zoo on Corstorphine Road heading eastbound towards city - to be repaired ASAP - check both sides for pot holes	Contact:	
Enquiry No.: 1489352	Logged by: Verint CRM Connector	on: 10/01/2023 17:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The green lane between Western Corner and the Murrayfield Hotel is in a terrible state, with rocking drains, potholes and crumbling tarmac. However, today was a show of total disrespect for the locals and the money being wasted by EDC. The lane is hardly green anyway, the condition is terrible and yet today a previous trench (probably the cable guys) was painted a bright green. What a shambles and complete waste of money, I hope the images show it in its full glory.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50126978	Defect Number: 42115951	
Enquiry No.: 1487370	Logged by: Verint CRM Connector	on: 08/01/2023 13:51
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Drain on pavement between 231 and 235 corstorphine road is blocked, resulting in the pavement being regularly flooded. Can it be looked at please.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1486140 **Logged by:** [REDACTED] **on:** 06/01/2023 14:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: claim form sent please see document attached thanks
Location: claim form sent please see document attached thanks **Contact:**

Enquiry No.: 1485938 **Logged by:** [REDACTED] **on:** 06/01/2023 11:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole
Location: outside Silvan House (forestry commission), 231 Corstorphine road **Contact:**

Enquiry No.: 1485515 **Logged by:** Verint CRM Connector **on:** 05/01/2023 23:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface breaking up all carriageways- very dangerous as I have to cross this
on my brompton bike to access my property **Contact:**
Location:1-11 Western Terrace, EH12

Enquiry No.: 1485348 **Logged by:** Verint CRM Connector **on:** 05/01/2023 18:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside 231 Corstorphine Road at Silvan House, severe pothole westbound in line
with the outer wheel track with tarmac fragments on the road. **Contact:**

Enquiry No.: 1484670 **Logged by:** Verint CRM Connector **on:** 05/01/2023 00:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole burst my tire **Contact:**

Enquiry No.: 1484391 **Logged by:** Verint CRM Connector **on:** 04/01/2023 16:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep Pothole in road causing tyre damage **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1482604 **Logged by:** Verint CRM Connector **on:** 01/01/2023 15:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole. Westbound carriageway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1481481 **Logged by:** [REDACTED] **on:** 30/12/2022 09:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: claim form sent please see document attached thanks
Location: claim form sent please see document attached thanks **Contact:**

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1481203	Logged by: Verint CRM Connector	on: 29/12/2022 15:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Approximate location shown. Eastbound main lane (not bus lane). Multiple deep potholes causing damage to my vehicle (puncture) and apparently lots of other cars according to kwikfit. Possibly sunken drain and potholes (too dark to see)	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1480559	Logged by: Amy Toye	on: 28/12/2022 13:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Large potholes, caused customers tyre to pop.		
Location: Near the function of St Johns road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50125005	Defect Number: 42113866	
Enquiry No.: 1480012	Logged by: Verint CRM Connector	on: 27/12/2022 09:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole in the road. There is road works happening to the road currently however, the workman have left the cones in such a way that you're forced to drive over the pothole. Which subsequently damages the vehicle.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50124905	Defect Number: 42113771	
Enquiry No.: 1479961	Logged by: Verint CRM Connector	on: 26/12/2022 21:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pot hole shredded my tyre and left us stranded .	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1479219	Logged by: Verint CRM Connector	on: 22/12/2022 18:15
Service: Roads General	Subject: Pavement: Missing Slab / Kerb	Classification: Customer Emergency
Desc.:		
Location: [REDACTED] I was going along St John's Road when I encountered a section of pavement that did not a down dropped kerb and, more importantly, up dropped kerb. [REDACTED] [REDACTED] [REDACTED] e.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1464153	Logged by: Verint CRM Connector	on: 20/11/2022 13:42
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Tree fall blocking pavement.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1461544 **Logged by:** [REDACTED] **on:** 15/11/2022 14:09
Service: Roads General **Subject:** Road Safety: General Enquiry **Classification:** General Enquiry
Desc.: please see document attached thanks
Location: please see document attached thanks **Contact:**

Enquiry No.: 1451619 **Logged by:** [REDACTED] **on:** 27/10/2022 09:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Hello, could you task someone to repair the potholes and missing sections of road surface on Corstorphine Rd. The road surface is badly damaged and had been for weeks between the Junction on Murrayfield Rd Ellersley Rd (Western Corner). Further along Corstorphine Rd. Where the entrance is into Vermilion and Guide Dogs there is a manhole with a large pothole on it and several potholes surrounding it.
Location: Corstorphine Rd - between the Junction on Murrayfield Rd Ellersley Rd (Western Corner). **Contact:**

Enquiry No.: 1450195 **Logged by:** Verint CRM Connector **on:** 24/10/2022 14:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Scottish water investigation into large depression says it is poorly backfilled by previous contractor. Pedestrians are being splashed by passing traffic. Noise is harmful. Vibrations too. Please fix. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1447405 **Logged by:** Verint CRM Connector **on:** 17/10/2022 17:18
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Corner of Murrayfield Rd/Corstorphine Rd, pedestrian crossing. My husband slipped on the unmarked trench going down Murrayfield Rd trying to cross over the pedestrian crossing on Corstorphine Rd - about 12.15 today. Dangerous to cross - no footpath. I phoned Cityfibre about 12.30 to report. Nothing's happened so far. I've attached 2 photos. Can you make this safe please? [REDACTED] **Contact:**

Enquiry No.: 1440808 **Logged by:** Verint CRM Connector **on:** 03/10/2022 15:37
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Between Murrayfield hospital access and Corstorphine Hill access lots of low hanging branches forcing people off the footpath to avoid **Contact:**

Enquiry No.: 1434255 **Logged by:** Verint CRM Connector **on:** 20/09/2022 20:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: From the lights at Ellersley road jct to western gardens, both sides of the road have significant damage causing cars to straddle the middle of the lane and bus lane to avoid the potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1429153 **Logged by:** Verint CRM Connector **on:** 12/09/2022 18:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: You might want to fix the pot holes between Western corner and Roseburn, especially given the Cortège on Tuesday. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1425921 **Logged by:** Verint CRM Connector **on:** 30/08/2022 23:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: long section of road (at least 100 yards) has partially disintegrated, lots of pot holes, gaps, long crumbled sections, loose gravel, severely damaged road markings etc etc - very poor condition from pedestrian crossing at Chinese Consulate to Western Corner **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1425696 **Logged by:** Verint CRM Connector **on:** 29/08/2022 09:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: please attend to the holes depressions in the road. **Contact:**

*** you only say it has been reported before but you dont say what action you instruct. ***

please advise what you intend to do to resolve the problem.

pedestrian are being soaked by splashes when vehicles driving by
the house is being damaged by the vibrations as a result
our sleep is being ruined by the noise of vehicles bumping in the depression
pedestrian are at risk should a bus lose control whilst lifted and weight lessened on tyres.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1425293 **Logged by:** Verint CRM Connector **on:** 24/08/2022 09:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: i have reported this issue but it has not been fixed. today another pedestrian was soaked as a bus went through the hollow which had collected rainwater. i have it on video if you want to call by. **Contact:**

the holes in the road are also dangerous to pedestrian should a bus lose control.
the holes are a noise hazard keeping me and neighbours awake. the holes are causing vibration damage to the houses nearby.

come and see the video of yet another pedestrian being soaked.

regards
[REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1423794

Service: Roads General

Desc.:

Location: Blocked gullies on the south side of Corstorphine Road at EH12 5QQ. Flash flooding imminent.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/08/2022 17:42

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Enquiry No.: 1423758

Service: Roads General

Desc.:

Location: Flooded pavement almost impassible following installation of new pedestrian crossing. Particularly bad on south side but appears north side also has issues. Drainage channel does not hit the road causing backup of water.

Logged by: Verint CRM Connector

Subject: Pavement: Damaged / Defective

on: 15/08/2022 16:57

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Enquiry No.: 1420880

Service: Roads General

Desc.:

Location: 231 - outside the old forestry commission, outside zoo and hotel and problems with drains as well - multiple potholes - drivers are having to straddle both lanes to avoid the potholes from western corner all the way into the West End (Shandwick Place)

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 10/08/2022 09:34

Classification: Request for service

Contact:

Enquiry No.: 1411015

Service: Roads General

Desc.:

Location: Redundant signage pole rusted at the base and on the verge of falling

Logged by: Verint CRM Connector

Subject: Traffic Sign:Defective/Damaged

on: 22/07/2022 13:46

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Job Number: 50116993

Defect Number: 42105328

Enquiry No.: 1409619

Service: Roads General

Desc.:

Location: this reallyy is a serious problem. the holes are large and deep.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 20/07/2022 11:22

Classification: Request for service

Contact:

i notice that this issue does not appear on your map.

please note that attempts to repair in the past have been woefully inadequate and short-lived. however, now that you have replaced the drains outside 98 the consequential damage outside 96 will be no longer need repeating once these current holes and depressions are repaired.

please come and listen to the noise and feel the tremours.

thank you



Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1409360 **Logged by:** Verint CRM Connector **on:** 19/07/2022 19:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 4 deep holes is road surface.
loud noise every time a bus goes past.
building trembles every time.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1408425 **Logged by:** Verint CRM Connector **on:** 18/07/2022 10:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hello

Contact:

There is a serious issue with four large holes in the road surface that causes several problems. Buses drive into the holes. The noise and banging as each bus passes is unbearable and probably well above the decibel threshold. The energy released causes large banging in this house and is beginning to damage the fabric of the building. There is a risk of damaging vehicles with the holes. There is a risk that as buses are launched into the air they are not safe for those at the busstop.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50116632 **Defect Number:** 42104911

Enquiry No.: 1405511 **Logged by:** Verint CRM Connector **on:** 12/07/2022 09:34
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Sinkhole appearing on unfinished section of new Kaimes Rd Crossing adding to significant trip hazards in the area

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50116440 **Defect Number:** 42104637

Enquiry No.: 1402069 **Logged by:**  **on:** 04/07/2022 17:28
Service: Roads General **Subject:** Spill: Oil / Petrol / Diesel **Classification:** Customer Emergency
Desc.: RTA - debris from RTA on road, police phoned asking if we could clear it up. Incident No. 1794 4/7/22
Location: 134 Corstorphine Road

Contact:

Enquiry No.: 1393770 **Logged by:** Verint CRM Connector **on:** 16/06/2022 20:21
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Branches blocking large section of narrow pavement.

Contact:

Enquiry No.: 1393763 **Logged by:** Verint CRM Connector **on:** 16/06/2022 20:06
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Just east of the exit from the zoo and holiday inn. Ivy/bush blocking half the pavement

Contact:

OUT OF SCOPE

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1389680 **Logged by:** Verint CRM Connector **on:** 08/06/2022 21:08
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Overhanging trees on the pavement, so overgrown you can't walk on the pavement. **Contact:**

Enquiry No.: 1381300 **Logged by:** Verint CRM Connector **on:** 24/05/2022 09:24
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Several trees overhanging to low levels next to the city bound carriageway and blocking the pavement at a few locations between Western Corner and Murrayfield Road **Contact:**

Enquiry No.: 1379800 **Logged by:** [REDACTED] **on:** 20/05/2022 11:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole
Location: at junct with Kaimes Road **Contact:**

Enquiry No.: 1378358 **Logged by:** Verint CRM Connector **on:** 17/05/2022 17:02
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: This has already been reported (ref 101001218725). I received an email today indicating that this issue has been resolved. Sticking a cone in the whole in the pavement DOES NOT resolve the issue. Can this issue please be resolved properly ASAP. Thank you **Contact:**

Enquiry No.: 1377430 **Logged by:** Verint CRM Connector **on:** 16/05/2022 10:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 100m of very rough road surface - 2/3 Western Gardens, Edinburgh, EH12 5QD **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1377425 **Logged by:** Verint CRM Connector **on:** 16/05/2022 10:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Very rough road surface **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1376681 Logged by: Verint CRM Connector on: 13/05/2022 21:24
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: I would just like to say the road surface In Edinburgh and the surrounding areas are appalling and are in desperate need of attention, [REDACTED] Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1375974 Logged by: Verint CRM Connector on: 12/05/2022 14:46
 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
 Desc.:

Problem: Overgrown.
 Location: Footpath.
 Type: Foliage / Bush
 Location: This is a yearly issue. The Traquair Alley & Balgreen Path (cycling & people footpath going round Carrick Knowe golf course) has heavy over grown trees, large foliage bushes, grass & weeds obstructing people walking along that path. This is a heavily used path for all people and cyclists. Also at the entrance of Traquair Alley from the St John Road side entrance heavy foliage & over hanging branches right at the steps side..... [REDACTED] Contact:

Enquiry No.: 1374588 Logged by: Verint CRM Connector on: 10/05/2022 10:47
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Deep split Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1371725 Logged by: Verint CRM Connector on: 03/05/2022 22:38
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:

Location: During roadworks, a lamp post has been removed directly outside 235 Corstorphine Road. A massive hole has been left in the pavement. The hole is not fenced off or marked with cones. Further the street lights in this area have not worked here for weeks making this even more of a hazard. Contact:

Enquiry No.: 1371333 Logged by: Verint CRM Connector on: 03/05/2022 11:41
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:

Location: next to the wall there has been a removal of lamp post and there is a hole 18 inches deep no cover or barrier please can you check this out is a safety hazard Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1366218 **Logged by:** Verint CRM Connector **on:** 22/04/2022 11:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: A very large pothole has appeared again on the main road bus lane directly outside 40 Corstorphine road EH12 6HS, this has been a continual and recurring issue of being repaired and then opening up again, this is a huge concern to all of the neighbours here who own vehicles which are in danger of being damaged, please can this issue be addressed as soon as possible before anything happens to our vehicles. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50112432 **Defect Number:** 42136439

Enquiry No.: 1360533 **Logged by:** Verint CRM Connector **on:** 12/04/2022 09:45
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:

Location: The manhole cover just west of lamppost CRH51 (outside 98 Corstorphine Road) is a loose cover. So whenever a vehicle in the bus lane drives over it, it creates a loud bang/rattle that is proving disruptive to local residents (particularly at night). It is also a concern as it could be a safety issue for damaging a vehicle's tire. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50111849 **Defect Number:** 42099424

Enquiry No.: 1351423 **Logged by:** Verint CRM Connector **on:** 25/03/2022 14:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1347202 **Logged by:** Verint CRM Connector **on:** 18/03/2022 09:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: loose manhole cover at the main crossroads AFTER the ZOO at western corner (east-bound) traffic lights - outside Mcgregors hairdressing Salon **Contact:**

Enquiry No.: 1344425 **Logged by:** Verint CRM Connector **on:** 13/03/2022 16:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: There are a large number of pot holes on Corstorphine Road. The road is in very poor condition and dangerous. **Contact:**

Enquiry No.: 1343198 **Logged by:** Verint CRM Connector **on:** 10/03/2022 18:26
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.

Location:Verge / Grass area .
Type:Foliage / Bush

Location: Tree opposite the Rolls Royce garage is about to fall into path and road. Also masonry block further West towards bus stop is literally about to fall with young tree pushing onto wall approximately 6ft from ground level. **Contact:**

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1342383 **Logged by:** [REDACTED] **on:** 09/03/2022 15:44
Service: Roads General **Subject:** Public Utilities: General **Classification:** General Enquiry

Desc.: From: <do-not-reply@edinburgh.gov.uk>
Date: Wednesday, March 9, 2022, 9:13:31 AM
To: <Customer.Care@edinburgh.gov.uk>
Subject: Email to be generated to Customer Care Team

CRM Number: 101001147488

Reference Number:

Customer name:

Address:

Contact details: craigmackay5@hotmail.com

Customers Comment: On Corstorphine Road at Western Corner if you are heading East, (outside Dixon Heaney and Safe,Simple,Secure Shop) at the traffic lights cross road there is an extremely loose drain/manhole cover which has sunken below the road level. It moves every time a car, bus or lorry goes over it making a loud noise. I also have concerns it may get worse and do damage to a vehicle. It should be looked at and fixed ASAP.

Customers previous reported issue:

Any previous reference numbers linking to current complaint:

Location:**Contact:**

Enquiry No.: 1341448 **Logged by:** Verint CRM Connector **on:** 08/03/2022 12:17
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service

Desc.:

Location: Collapsed Double Manhole Risk - Severe Rattling Noise Pollution
Category: Potholes

Contact:

Per the previous report a double manhole cover has collapsed on the inside lane of Eastbound carriageway by c 40mm and clatters everytime a vehicle crosses it. Sound measures in excess of 100Db at Location and over 82Db at 100 metres range [REDACTED] homes in Wallace Gardens and in radius. Requires urgent repair

Location:

Easting/Northing: 321957/673131 (55.944864, -3.251127)

Nearest road to the pin placed on the ma

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1340709 Logged by: Verint CRM Connector on: 07/03/2022 12:23
 Service: Roads General Subject: Public Utilities: General Classification: Request for service

Desc.:
 Location: Tarmac surrounding a BT iron cover on rd is higher and the area is not flush with the cover; when traffic goes over it, especially heavy vehicles, the resulting pressure noise is like an explosion. Apart from constant noise, the iron covering will crack and fall in. This is a very busy crossing in all directions for pedestrians as well as traffic and an accident is waiting to happen. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1340432 Logged by: Verint CRM Connector on: 06/03/2022 22:25
 Service: Roads General Subject: Public Utilities: General Classification: Request for service

Desc.:
 Location: The noise is very loud due to the drain over becoming loose. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1340374 Logged by: Verint CRM Connector on: 06/03/2022 19:40
 Service: Roads General Subject: Public Utilities: General Classification: Request for service

Desc.:
 Location: Manhole cover is making very loud noise throughout the day and night. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1340111 Logged by: Verint CRM Connector on: 06/03/2022 11:03
 Service: Roads General Subject: Public Utilities: General Classification: Request for service

Desc.:
 Location: Manhole cover has come loose and every time traffic passes over it there is a loud bang. Mahole is located at Western Corner on the side whhere Corstorphine Rd joins Ellersley Drive. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1339199 Logged by: Verint CRM Connector on: 04/03/2022 11:02
 Service: Roads General Subject: Public Utilities: General Classification: Request for service

Desc.:
 Location: Manhole cover subsiding & clanging
 Category: Roads/highways Contact:

At the Western Corner junction, on the west bound lane a manhole cover has subsided about 40 mm and is clattering very loadly every time a bus or HGV passes over it.

Location:
 Easting/Northing: 321961/673127 (55.944827, -3.251064)
 Nearest road to the pin placed on the map (automatically generated by Bing Maps):
 51 Corstorphine Road, Edinburgh, EH

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1338810 **Logged by:** Verint CRM Connector **on:** 03/03/2022 17:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: uneven road with visible dips and top layers worn - entire road needs resurfaced - 99A CORSTORPHINE ROAD, MURRAYFIELD, EDINBURGH, EH12 5QB **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1336291 **Logged by:** Verint CRM Connector **on:** 28/02/2022 15:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A dangerous pothole which has damaged my tire & had to get a new one **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1332534 **Logged by:** Verint CRM Connector **on:** 23/02/2022 10:22
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: The manhole cover is seriously indented and the road is in danger of collapsing around it. The cover/indentation is on the main road with many buses and HGV's going over it each day. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1331620 **Logged by:** Verint CRM Connector **on:** 22/02/2022 09:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Very deep large pothole on west bound carriageway near Zoo. Deep enough to seriously damage car suspension, or cause accident to cyclist. **Contact:**

Enquiry No.: 1331392 **Logged by:** Verint CRM Connector **on:** 21/02/2022 19:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole, hit at 5.20pm. [REDACTED] **Contact:**
[REDACTED]
Approx 1ft x1ft and deep.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1331345 **Logged by:** Verint CRM Connector **on:** 21/02/2022 17:58
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Collapsed Manhole cover - significant clattering as vehicles cross **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1330324 **Logged by:** Verint CRM Connector **on:** 20/02/2022 11:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: large pothole - risk of puncture or damage to tyre / wheel **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50107048 **Defect Number:** 42093715

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1328240 **Logged by:** Verint CRM Connector **on:** 16/02/2022 23:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The location is approximate. I am sorry that I cannot give a more precise location. **Contact:**

The pothole is wide. It is easy to spot.

Thank you in advance for fixing it.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1328231 **Logged by:** Verint CRM Connector **on:** 16/02/2022 23:26
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Manhole Cover at Western Corner junction is loose and excessively noisy when vehicles pass over and its getting much worse every day, particularly bad when buses and lorries go over it. **Contact:**

Enquiry No.: 1327323 **Logged by:** Verint CRM Connector **on:** 15/02/2022 21:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: I'm reporting an issue on behalf of all the residents living in the block of flats on western gardens. We are finding the roads are getting continuously worse and everytime a bus passes by the flats shake, to the point where ornaments, vases are shaking. We filled in cracks in the ceiling when we moved in 3 years ago but they are cracking open again from vibrations from traffic on the road. There is new housing getting built off Corstorphine road and the heavy vehicles are making this even worse. **Contact:**

Enquiry No.: 1326386 **Logged by:** Verint CRM Connector **on:** 14/02/2022 15:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes in eastbound bus lane at entrance to 40 Corstorphine Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50106303 **Defect Number:** 42092857

Enquiry No.: 1326029 **Logged by:** Verint CRM Connector **on:** 14/02/2022 10:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in Westbound lane next to silvan house entrance **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1323520 **Logged by:** Verint CRM Connector **on:** 09/02/2022 21:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot hole at junction. Causes buses to cross over into other lane. Likely to cause accident. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1320625 Logged by: Verint CRM Connector on: 05/02/2022 08:48
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: There is a defect on both the road and the pavement. The pavement has a large divet where a utility cover sits and the pavement is. There is similarly one on the road at the same point. Contact:

Enquiry No.: 1320449 Logged by: Verint CRM Connector on: 04/02/2022 15:43
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: Road sign is obscured by tree branches 50 yards from Western Corner - reported by Contact:

Enquiry No.: 1313807 Logged by: Verint CRM Connector on: 25/01/2022 20:59
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: A man hole cover is broken and it is moving up and down when vehicles are going over it. It looks quite dangerous. The picture doesn't really convey what I'm saying but there it is anyway. The metal covers are moving a fair bit. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1309485 Logged by: Verint CRM Connector on: 18/01/2022 16:27
Service: Roads General Subject: Public Utilities: General Classification: General Enquiry
Desc.:
Location: Follow on of ticket 101001077236. Contact:
It has been reported that the issue is fixed, but I'm still hearing gunshot sounds.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1308441 Logged by: Verint CRM Connector on: 17/01/2022 10:12
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Drain cover in road becoming submerged and unbalanced, causing several gunshot noises every time a bus car truck passes over. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50103162 Defect Number: 42089688

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1306183 **Logged by:** Verint CRM Connector **on:** 12/01/2022 16:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Corstorphine Road at Corstorphine Hospital junction. **Contact:**

Significant flooding of road and pavement area during heavy rain due to blocked drain. This has been reported on blocked gullies since last year but has not been dealt with - it is so large pavement is nearly impassible during heavy rain with frequent soaking from passing vehicles.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1306172 **Logged by:** Verint CRM Connector **on:** 12/01/2022 16:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: To west of hospital entrance is long stretch of rutted road that is extremely dangerous to cycle over **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1304130 **Logged by:** Verint CRM Connector **on:** 09/01/2022 22:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Very large pothole just outside the Bupa hospital City bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1296185 **Logged by:** Verint CRM Connector **on:** 26/12/2021 21:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A massive hole at the entrance to the Spire Murrayfield hospital on Corstorphine road near the kerb in the bus lane. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1295585 **Logged by:** **on:** 24/12/2021 14:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole
Location: in bus lane at entrance to Murrayfield Hospital - heading into Edinburgh **Contact:**

Enquiry No.: 1242760 **Logged by:** Verint CRM Connector **on:** 10/09/2021 08:47
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: ///swaps.transit.clubs **Contact:**
Forcing pedestrians onto the busy St. John's road

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1240038 **Logged by:** Verint CRM Connector **on:** 05/09/2021 20:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken, damaged and uneven road surfaces in the bus lane all along the Corstorphine Road from the Western Corner. Road surface is slanting in towards the footpath. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1216961 **Logged by:** Verint CRM Connector **on:** 28/07/2021 14:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a hollow in the bus lane which launches all buses into the air to then land on a previously repaired hole in the road. The cause is the hollow the symptom is the hole.

My concern is the safety of people standing at the bus stop 20 metres away. As buses are launched into the air (weight no longer on the tyres) means they will be out of control. On an icy or wet day this might mean a fatality.

Please take this risk seriously and repair the hole and hollow. The problem worsens daily. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1215560 **Logged by:** Verint CRM Connector **on:** 26/07/2021 15:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Completely and partially blocked drains and galleys which are contributing to flash floods during and after thunderstorms and cloudbursts, this causing water damage to properties in EH12 5QQ. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50088258 **Defect Number:** 42074425
Enquiry No.: 1215467 **Logged by:** Verint CRM Connector **on:** 26/07/2021 13:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: A number of tree branches hanging low right along Corstorphine Rd leading to pedestrians walking on the road to avoid. **Contact:**

Enquiry No.: 1211065 **Logged by:** Verint CRM Connector **on:** 19/07/2021 15:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface has broken creating huge craters, only safe way to avoid these is by driving into the bus lane. Causing severe damage to suspension on cars and a hazard for cyclists as it crosses onto the cycle area. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50087705 **Defect Number:** 42073745

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1210825 Logged by: Verint CRM Connector on: 19/07/2021 11:42
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: The road has a major problem outside 41 and 39 Corstorphine Road. The road is not level and sinks towards the gates of these 2 properties. When there is a lot of rain it comes down the hill from the area and we get significant flooding in these properties. The road urgently needs levelled. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
 Job Number: 50087647 Defect Number: 42073714

Enquiry No.: 1206009 Logged by: Verint CRM Connector on: 10/07/2021 17:02
 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Other.
 Location: Cycleway.
 Type: Foliage / Bush
 Location: Dead tree next to cycle/footpath. On the corner of Traquair Alley behind Forestry building. Contact:

Enquiry No.: 1198278 Logged by: Verint CRM Connector on: 29/06/2021 10:29
 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Causing Obstruction.
 Location: Footpath.
 Type: Foliage / Bush
 Location: Traquair Alley now very narrow at Corstorphine Rd due to overgrown Ivy on one side and hedge on the other Contact:

Enquiry No.: 1197407 Logged by: Verint CRM Connector on: 27/06/2021 17:27
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Several potholes in the bus lane eastbound getting larger very quickly as buses bounce going across them. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1194115 Logged by: Verint CRM Connector on: 21/06/2021 08:10
 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Overgrown.
 Location: Footpath.
 Type: Foliage / Bush
 Location: Overhanging foliage is causing an obstruction on public path. A [REDACTED] It also obscures the bus stop. Contact:

Enquiry No.: 1192793 Logged by: [REDACTED] on: 18/06/2021 09:02
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.: claim form not sent please see 3 documents attached thanks
 Location: claim form not sent please see 3 documents attached thanks Contact:

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1175123 **Logged by:** Verint CRM Connector **on:** 14/05/2021 17:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: See point on map - before entrance to hospital - Spire Murrayfield Hospital, 118 Corstorphine Rd, Edinburgh EH12 6TU - large pothole on main road needs to be fixed asap **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50083157 **Defect Number:** 42069065

Enquiry No.: 1151113 **Logged by:** Verint CRM Connector **on:** 31/03/2021 12:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: see point on map - potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50080272 **Defect Number:** 42066317

Enquiry No.: 1150596 **Logged by:** Verint CRM Connector **on:** 30/03/2021 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: My reference is 101000594978 and I reported this issue over 2 weeks ago. Can you please tell me when this is going to be fixed? Thanks **Contact:**

Enquiry No.: 1147509 **Logged by:** Verint CRM Connector **on:** 25/03/2021 09:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole - travelling East into city 30yds from entrance to Murrayfield Hospital about 20 feet long **Contact:**

Enquiry No.: 1146249 **Logged by:** Verint CRM Connector **on:** 23/03/2021 11:25
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.:
Location: There is a NO TURN RIGHT sign here when turning out of the hospital grounds which I would say is unnecessary. I have seen several cars turn right out of this junction safely and with no bother at all. Is there a reason this is here or can this be removed? **Contact:**

Enquiry No.: 1142593 **Logged by:** Verint CRM Connector **on:** 17/03/2021 19:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a manhole cover that appears to have changed or got damaged recently, everytime a vehicle goes over it, it makes a very loud noise. This a very busy road so it is quite annoying. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1141174 **Logged by:** Verint CRM Connector **on:** 16/03/2021 08:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Damaged manhole cover in Corstorphine Road, at the Belmont Crescent Junction. It makes a loud cracking noise when traffic hits it. The manhole cover frame support seems to have failed. The noise is a serious nuisance and if the structure deteriorates further it will become dangerous! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1140520 **Logged by:** Verint CRM Connector **on:** 15/03/2021 09:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A man hole in the middle of the road appears to have been worked on recently outside 92 Corstorphine Road (Twin Lions Hotel) in Edinburgh as there is fresh tarmac. Now every time a car, bus, etc. goes over there is a loud noise as its clearly not secure, and it is very annoying particularly at night as it is keeping the local residents awake **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1140183 **Logged by:** Verint CRM Connector **on:** 14/03/2021 12:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road access over pavement on either side of the car rental company has not been properly re-instated after roadworks **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1139709 **Logged by:** Verint CRM Connector **on:** 12/03/2021 20:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes on eastbound side of road between Pinkhill and entrance to Murrayfield Hospital. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50078322 **Defect Number:** 42064176

Enquiry No.: 1137256 **Logged by:** Verint CRM Connector **on:** 09/03/2021 12:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: see map - pothole - poor repair **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50077850 **Defect Number:** 42063754

Enquiry No.: 1137252 **Logged by:** Verint CRM Connector **on:** 09/03/2021 12:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole outside bupa hospital entrance - see map **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1137117	Logged by: Verint CRM Connector	on: 09/03/2021 10:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Enquiry No.: 1132519	Logged by: Verint CRM Connector	on: 01/03/2021 21:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive wide pothole. Just before the 'left hand bend' road sign.	Contact:	

I had to swerve to avoid crashing on it when I was on my bicycle just now.

Please repair it properly so that it is safe for bicycles to travel over in wet conditions.
 If the road repair isn't flat then it creates a risk of crashing.

Thank you in advance for fixing it.

Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
--------------------------	--	---------------------------------

Enquiry No.: 1128776	Logged by: [REDACTED]	on: 24/02/2021 11:24
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: please see ref number 1114955 at junctoin with corstorphine road and belmont crescent. man from water board came out and put a marking around the manhole cover in middle of road around 10 days days ago and has not returned to deal with this problem. the mahole cover is keeping resident at number 2 belmont crescent who is elderly awake. can you plesse make contact with water board agian to have this resolved. the traffic is busy from around 4 am onwards.		
Location: [REDACTED]	Contact:	

Enquiry No.: 1127450	Logged by: Verint CRM Connector	on: 22/02/2021 19:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Corstorphine Road. Outside murrayfield hospital. East bound 2 x massive pot holes	Contact:	

Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
--------------------------	--	---------------------------------

Enquiry No.: 1127296	Logged by: Verint CRM Connector	on: 22/02/2021 15:51
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Beside the pedestrian crossing close to junction of Murrayfield road and corstorphine road. Recent fibre works haven't been tidied up/finished. A large hole is in the pavement as not been filled in. I have reported problems about this recently but didn't see how bad the hole(s) are until today as I think a covering has been taken away	Contact:	

Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
--------------------------	--	---------------------------------

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1126545	Logged by: Verint CRM Connector	on: 21/02/2021 17:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 2 large potholes have opened up at access road to hospital	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1124813	Logged by: Verint CRM Connector	on: 19/02/2021 08:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole eastbound bus lane at junction leading to Hospital	Contact:	
Enquiry No.: 1124756	Logged by: Verint CRM Connector	on: 18/02/2021 22:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large potholes on the road at entrance to Spire Hospital, Murrayfield.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50075659	Defect Number: 42061851	
Enquiry No.: 1122975	Logged by: Verint CRM Connector	on: 17/02/2021 10:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The drain cover at the bottom of Belmont Crescent is broken. This is causing a loud bang every time a vehicle drives over it which is nearly every vehicle heading into town.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1122351	Logged by: Gayle Skeldon	on: 16/02/2021 16:08
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: who do I contact regarding road/pavements works for the fibre works in the Murrayfield area? The works are finished on this section but cones still left out, bus stop out of use and also a lot of debris about! Thanks		
Location: It's on corstorphine road outside the tennis club and towards Riversdale crescent.	Contact:	
Enquiry No.: 1121093	Logged by: Verint CRM Connector	on: 15/02/2021 16:21
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Please see attached email trail	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50075386	Defect Number: 42061597	
Enquiry No.: 1114955	Logged by: [REDACTED]	on: 08/02/2021 12:42
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: loose/noisy manhole cover		
Location: at junct with Belmont Crescent	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50074717	Defect Number: 42060997	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1113783	Logged by: Verint CRM Connector	on: 05/02/2021 19:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole on middle of the road just outside the Zoo	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1113230	Logged by: Verint CRM Connector	on: 05/02/2021 00:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Water accumulating by the kerb.	Contact:	
The water tends to build up there when it has been raining for a while.		
It is a hazard for cyclists.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50074204	Defect Number: 42060704	
Enquiry No.: 1109698	Logged by: Verint CRM Connector	on: 30/01/2021 15:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: New potholes East bound carriageway outside no. 40 Corstorphine Road and just west of this on same Side of road. Outside 40 pothole likely to grow quickly as it did two years ago, when damage caused to car.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50073618	Defect Number: 42060175	
Enquiry No.: 1106247	Logged by: Verint CRM Connector	on: 24/01/2021 22:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole around Gas manhole cover. In bus lane eastbound.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50072834	Defect Number: 42059443	
Enquiry No.: 1102353	Logged by: Verint CRM Connector	on: 18/01/2021 11:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole on east bound carriageway. Buses hit this and the house shakes. Please fix soon.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50072360	Defect Number: 42059098	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1102235 **Logged by:** Verint CRM Connector **on:** 18/01/2021 09:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Cable Fibre dug a trench yesterday on the pavement (EH12 5QG) between the Chinese Consulate and Murrayfield Tennis Club. They erected barriers with a temporary footpath, [REDACTED]. It is extremely dangerous. I phoned the company yesterday but nothing happened. I have spoken to a foreman this morning and he said they will put in a bridge. We have had no warning about these works. They have also shut off the bottom of Murrayfield Rd and top of Riversdale Cres - is this legal? **Contact:**

Enquiry No.: 1088423 **Logged by:** Verint CRM Connector **on:** 22/12/2020 11:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole present in bus lane on turning to spire hospital. Looks deep and sounded deep when my car went over the top of it. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50070887 **Defect Number:** 42058068

Enquiry No.: 1078434 **Logged by:** Verint CRM Connector **on:** 02/12/2020 11:25
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush

Location: Obstructing the view of the bus lane camera and associated signage. **Contact:**

Enquiry No.: 1073251 **Logged by:** Verint CRM Connector **on:** 22/11/2020 09:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole east bound carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1066318 **Logged by:** Verint CRM Connector **on:** 10/11/2020 07:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole causing significant vibration in house, was repaired within 6 months and keeps deteriorating. Something much more substantial required. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1053176 **Logged by:** Verint CRM Connector **on:** 13/10/2020 11:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Previous repair cracking and about to pot hole again east bound carriageway outside drive for no 40. Previously this caused a burst tyre on my car. Also, this together with sunken drains in the east bound bus lane and the larger buses now using this road is resulting in increased palpable vibrations in our conservation area 1850's building. New cracks have begun to appear in ceilings and I have heard shifting rubble or similar in the walls when buses have hit the damaged road areas. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1043014 **Logged by:** Verint CRM Connector **on:** 21/09/2020 14:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Young(ish) tree growing behind the retaining wall here has pushed out the wall coping stones so that they now project by approx 100mm from face of wall. This is a hazard for pedestrians on this narrow pavement and a danger to public safety. It wouldn't take much to dislodge them. Located 2 metres east of the Ormidale Terrace bus stop, so near where people queue for the bus. Movement appears to have increased recently. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1022495 **Logged by:** Verint CRM Connector **on:** 14/08/2020 13:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: pothole and sunken road - [REDACTED] **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50060536 **Defect Number:** 42052584

Enquiry No.: 1022017 **Logged by:** Verint CRM Connector **on:** 13/08/2020 17:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Reference: W5P9ND54-101000163311 **Contact:**

- since reporting this in mid-March I have had no updates, the manhole is disintegrating into the road and needs fixed please.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50060504 **Defect Number:** 42052576

Enquiry No.: 1021876 **Logged by:** Verint CRM Connector **on:** 13/08/2020 14:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Hi - I am wanting to know if the retaining wall between Corstorphine Road and South Beechwood is ever inspected. If so , how often is it inspected and can I see the reports.
 Thanks
 [REDACTED] **Contact:**

Enquiry No.: 1010608 **Logged by:** Verint CRM Connector **on:** 21/07/2020 09:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole roughly 20 feet before the road sign for 'Murrayfield Hospital'. **Contact:**

It is dangerous for cyclists (especially when it is filled with rain water).

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50059170 **Defect Number:** 42051974

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 998622 **Logged by:** Verint CRM Connector **on:** 24/06/2020 13:01
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush

Location: There are a large number of overhanging tree branches blocking the pavements to the northside of Corstorphine Road. This spans from the Roseburn junction to the Western Terrace junction and is forcing pedestrians and runners to go onto the road which is increasing the risks of accidents. **Contact:**

Enquiry No.: 998014 **Logged by:** Verint CRM Connector **on:** 23/06/2020 10:28
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Footpath.
Type:Foliage / Bush

Location: overgrown tree covering speed camera - THE GATE LODGE, BEECHMOUNT HOUSE, 102 CORSTORPHINE ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 6TZ **Contact:**

Enquiry No.: 994276 **Logged by:** Verint CRM Connector **on:** 15/06/2020 07:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush

Location: The trees, bushes and holly are very overgrown opposite the attached address on the public pavement. I have many times had to walk on the road to avoid being hurt by the foliage or bend down to do this. **Contact:**

Enquiry No.: 992379 **Logged by:** Verint CRM Connector **on:** 08/06/2020 11:01
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush

Location: Overgrown branches along Corstorphine Road, roughly opposite Kwik Fit. The branches hang so low you are forced on to the road to walk past. **Contact:**

Enquiry No.: 989928 **Logged by:** Verint CRM Connector **on:** 01/06/2020 08:05
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Cycleway.
Type:Foliage / Bush

Location: The cycle pathway from the Traquair Alley/Pinkhill area to Balgreen is beginning to get overgrown with weeds etc. on both side of the path. The pathway is busy with pedestrians, runners and cyclists and due to coronavirus it is now getting difficult to socially distance because of the overgrowth. The overgrowth happens around this time every year and I would be grateful if this concern could please be addressed. Thank you. **Contact:**

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 988185

Service: Roads General

Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush

Location: The issue is with a large tree in the corner of 235 Corstorphine Road. It's overgrown, with branches hanging low over the pavement and also obscuring the street light SBL001. In the recent high winds the benches were banging heavily against the lamp post.

Logged by: Verint CRM Connector

Subject: Trees & Foliage: Defect

on: 25/05/2020 20:07

Classification: Request for service

Contact:

Enquiry No.: 981526

Service: Roads General

Desc.: Damaged loose manhole cover on corstorphine road. Outside Murrayfield Hotel. Very loose and noisy. Road surface broken.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 19/04/2020 11:03

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50055813

Feature Id - Location: Whole Street

Defect Number: 42049902

Feature Type: Road Asset

Enquiry No.: 976238

Service: Roads General

Desc.: Hello,

Location: Hello,

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 18/03/2020 14:04

Classification: Request for service

Contact:

There is a damaged manhole cover that is crumbling [REDACTED] on the busy road. As large vehicles pass over it, vibrations are passing through into the house. [REDACTED]

Additionally, the drain on the same road outside our property appears to be blocked as when it rains heavily a large puddle appears and water streams down the drives into the properties.

Thanks and regards,

[REDACTED]

Plot Number: 1.00

Job Number: 50060505

Feature Id - Location: Whole Street

Defect Number: 42052577

Feature Type: Road Asset

Enquiry No.: 975556

Service: Roads General

Desc.: The manhole outside 39/41 Corstorphine road is disintegrating at a rapid rate. This is a high traffic area and causes noise and vibration disruption [REDACTED]. This is an urgent matter requiring repair

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 17/03/2020 08:31

Classification: Request for service

Contact:

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 970179 Logged by: Verint CRM Connector on: 03/03/2020 16:32
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: The hole, on the city bound side of the road, at this location, which has already been the subject of numerous repair jobs, requires repair again. Would it not be worthwhile carrying out a "proper" repair of this large hole, instead of the usual "patch" job? Contact:

Enquiry No.: 967449 Logged by: Verint CRM Connector on: 27/02/2020 14:12
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: In the cycle/bus lane on both sides of Corstorphine Road between Pinkhill and Western Corner there are potholes and breaks in the road surface that are positively dangerous to cyclists, especially in the dark and in the wet when it's more difficult to spot them. They are NOT a recent phenomenon! The next page allows only one type of defect to be recorded - a true description of the situation merits more than one. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 967243 Logged by: Verint CRM Connector on: 27/02/2020 09:25
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: On St John's Road heading towards Corstorphine after junction with Balgreen Road as per map. Temporary drain cover out of place causing it to rock everytime traffic goes over it (bus lane so heavy vehicles) causing very loud clanging sound easily audible in nearby houses day and night. Already reported, told was fixed, has NOT been fixed. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Job Number: 50054823 Defect Number: 42048968

Enquiry No.: 962049 Logged by: on: 18/02/2020 10:02
 Service: Roads General Subject: Parking: General Enquiry Classification: General Enquiry
 Desc.: pothole on the road has damaged the car had to get tyre changed over
 Location: this happend outside out 122 Costorphine road Contact: Mrs Pinkinton

Enquiry No.: 960769 Logged by: Verint CRM Connector on: 15/02/2020 13:12
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Large pothole on Corstorphine Road on eastbound side at entrance to Spire Murrayfield Hospital. I hit this waterfilled pothole in rush hour on 12 Feb. Contact:

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 960199	Logged by: Verint CRM Connector	on: 14/02/2020 10:16
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50052688	Defect Number: 42046893	
Enquiry No.: 959923	Logged by: Verint CRM Connector	on: 13/02/2020 17:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Nasty pothole which is in the puddle right at the junction so you don't realise it's there and then once you've hit it you realise it's massive, in the bus lane heading towards town / the side of the road heading up the hill to the hospital	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 957364	Logged by: Verint CRM Connector	on: 10/02/2020 08:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: When it has been raining a large volume of water lies on the road at the bottom of the road here and when buses pass in the bus lane a wall of water is sprayed across the pavement soaking anyone that is walking. This has happened to me twice in the last couple of weeks. The only alternative is to cross the very busy road where there are no traffic lights to avoid this section of pavement. I would really appreciate it if you could take a look and see if anything can be done.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50052296	Defect Number: 42046531	
Enquiry No.: 957157	Logged by: Verint CRM Connector	on: 09/02/2020 14:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: tree blown over and lying on roadway	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 955796	Logged by: Verint CRM Connector	on: 06/02/2020 08:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: large hole at bus stop on opposite side from edinburgh zoo (zoo is at 134 Corstorphine road)	Contact:	

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 952614 Logged by: Verint CRM Connector on: 31/01/2020 08:18
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Previously patched section of road at drive entrance is severely crumbled again. I expect this to develop into large potholes in the next week or so like the last time, given the volume of bus traffic along this section.

Contact:

[REDACTED] This is
breaking up already.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50051549 Defect Number: 42045777

Enquiry No.: 951193 Logged by: Verint CRM Connector on: 29/01/2020 08:50
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: pothole after subsidence after roadworks

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50051308 Defect Number: 42045537

Effective: 01/01/2020 to 30/11/2024

Service: Roads General

Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 949973

Service: Roads General

Desc.:

Logged by:

Subject: Road Markings: Defective

on: 27/01/2020 07:12

Classification: Request for service

I have reported the pothole to the council, upon inspection there was faded white markings around it.

the pothole as it was within the yellow box. Upon striking it, I heard a very loud bang,

Pothole is located on Corstorphine Rd, Heading eastbound towards city centre, near the end of the yellow box for the entrance of the now closed Corstorphine Hospital on the left hand side. On the right hand side is 231 Silvan house. On the left hand side of the road, the first lamppost after the pothole has the sign for parking at the zoo. Before the pothole on the left hand side is Kaimes Rd and on the Right is Cruikshank Gardens. Although not beside it, these are the closest streets.

Contact:

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No



Emma Keddi

Enquiry No.: 949241 Logged by: Verint CRM Connector on: 24/01/2020 17:09
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Temporary drain cover in bus lane on road just after junction between balgreen road and at Johns road has become loose causing large pothole and very loud clunking noise every time traffic goes over. Easily heard in nearby house. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50050948 Defect Number: 42045205

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 947839 **Logged by:** Verint CRM Connector **on:** 22/01/2020 22:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole - 3 MURRAYFIELD PLACE, EDINBURGH, CITY OF EDINBURGH, EH12 6AA **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50050799 **Defect Number:** 42045090

Enquiry No.: 946457 **Logged by:** Verint CRM Connector **on:** 21/01/2020 08:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: * This has been reported before *
Loose and noisy manhole cover on A8 Corstorphine Road outside Murrayburgh House office block. On westbound carriageway. Every bus hits it. A temporary patch up repair was attempted in November of last year but has failed already. Has been raised several times. Just needs a proper repair rather than a patch up. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50050759 **Defect Number:** 42045074

Enquiry No.: 945426 **Logged by:** Verint CRM Connector **on:** 19/01/2020 19:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Seems to be a broken water pipe, and the constant water has eroded the road. big chunks of tarmac being thrown onto pavement, and on cold nights the water is freezing and making the pavement treacherous. Very dangerous for cyclists and pedestrians. Damage stretches from up near Balgreen road down toward Western Cnr. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 945321 **Logged by:** Verint CRM Connector **on:** 19/01/2020 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive potholes in bus lane, absolute stoaters (westbound) **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 940617 **Logged by:** Verint CRM Connector **on:** 12/01/2020 10:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: repaired surface outside entrance to 40 corstorphine road broken down. Pothole reformed and generally cracked tarmac **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50049602 **Defect Number:** 42043909
Enquiry No.: 939222 **Logged by:** Verint CRM Connector **on:** 09/01/2020 16:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole caused damage to car **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 939213
Service: Roads General
Desc.:
Location:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 09/01/2020 16:52
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
42705347	Gully: Flooding - Flooding from gully can someone be sent out to sort this (Enquiry 849112)	at the back of 235 corstorphine road / cruikshank gdns	RG: Gully - High Priority	Job Complete	26/06/2019	04/06/2020	Act. RDGC14/10004325
50046558	Road: Defective / Damaged (Enquiry 914813)	Blocked gully on west bound carriageway slow lane	RG: Gully - Standard Priority	Job Complete	27/11/2019	15/06/2020	Act. RDGC14/82000537
	Opposite junction with Belmont crescent (Gully: Blocked - HP Jet Req'd)						
50048966	Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway at junction with kaimes road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2020	10/01/2020	Act. ROAD/82030159
50048967	Hot temp make safe (RD: CW Pothole)	Potholes on city bound carriageway both lanes at junction with old Corstorphine hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2020	10/01/2020	Act. ROAD/82030160
50049058	Hot temp make safe (RD: CW Pothole)	Potholes on west bound carriageway slow lane opposite no 86	RD: Cat 2 - 5 Day	Job Complete	07/01/2020	08/01/2020	Act. ROAD/82030230
50049059	Hot temp make safe, over lay area , & uplift debris from footway (RD: CW Pothole)	Potholes on west bound carriageway slow lane opposite no 92 & no 94	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/01/2020	08/01/2020	Act. ROAD/82030231
50049060	Hot temp make safe (RD: CW Pothole)	Potholes on west bound carriageway slow lane at l/p no 52	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/01/2020	09/01/2020	Act. ROAD/82030232
50049061	Hot temp make safe (RD: CW Pothole)	Potholes on west bound carriageway slow lane opposite l/p no 53	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/01/2020	09/01/2020	Act. ROAD/82030233
50049139	Road: Defective / Damaged (Enquiry 934039)	Pothole on west bound carriageway approximately 5m west of l/p no 21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2020	12/01/2020	Act. ROAD/82030306
	Hot temp make safe (RD: CW Pothole)						
50049209	Clear surface rain water (Gully: Blocked / Flooding)	Surface water over carriageway and footway at junction with Corstorphine hospital	RG: Gully - High Priority	Job Complete	09/01/2020	17/09/2020	Act. RDGC14/82000618

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50049602	Road: Defective / Damaged (Enquiry 940617) Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway bus lane outside no 40	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/01/2020	16/01/2020	Act. ROAD/82030671
50049869	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane approximately 5m east of I/p CRH 56	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	23/01/2020	Act. ROAD/82030875
50049872	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane opposite no 103	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	23/01/2020	Act. ROAD/82030878
50049890	H (RD: CW Pothole)	Potholes & depressions on west bound carriageway bus lane opposite no 82	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	24/01/2020	Act. ROAD/82030894
50049892	Hot temp make safe , overlay area (RD: CW Pothole)	Potholes on west bound carriageway bus lane approximately 5m west of I/p CRH 46	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	24/01/2020	Act. ROAD/82030895
50049893	Hot temp make safe, overlay area & uplift debris from foot (RD: CW Pothole)	Potholes & depressions on west bound carriageway bus lane opposite no 94	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	24/01/2020	Act. ROAD/82030896
50049897	H (RD: CW Pothole)	Potholes on west bound carriageway bus lane between I/p no 52 & I/p no 55	RD: Cat 2 - 5 Day	Job Complete	20/01/2020	26/01/2020	Act. ROAD/82030899
50050055	H (RD: CW Pothole)	Potholes & depressions on west bound carriageway at junction with Balgreen road	RD: Cat 2 - 5 Day	Job Complete	21/01/2020	23/01/2020	Act. ROAD/82031009
50050742	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane between I/p 78 & I/p 76	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031594
50050744	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane opposite I/p 62	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031596
50050759	Road: Defective / Damaged (Enquiry 946457) Hot temp make safe (RD: CW Pothole)	make safe on manhole cover outside Murraybrugh house office block	RD: Cat 2 - 5 Day	Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031606
50050799	Road: Defective / Damaged (Enquiry 947839) Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway bus lane at gully opposite Rolls-Royce car showroom	RD: Cat 2 - 5 Day	Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031619

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50050948	Road: Defective / Damaged (Enquiry 949241) Hot temp make safe (RD: CW Pothole)	Temporary metal plate over sunken gully at l/p no 62 is loose and requires hot temp around metal plate to stop rattling	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2020	02/02/2020	Act. ROAD/82031717
50050950	H (RD: CW Pothole)	Pothole on west bound carriageway bus lane at l/p no 62	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2020	02/02/2020	Act. ROAD/82031718
50051200	H (RD: CW Pothole)	Pothole on west bound carriageway bus lane at bus stop opposite no 22	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/02/2020	05/02/2020	Act. ROAD/82031933
50051204	Hot temp make safe (RD: CW Pothole)	Potholes on west bound carriageway bus lane opposite no 105	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/02/2020	05/02/2020	Act. ROAD/82031937
50051206	H (RD: CW Pothole)	Potholes on west bound carriageway approximately 10 west of l/p no 103	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2020	07/02/2020	Act. ROAD/82031939
50051308	Road: Defective / Damaged (Enquiry 951193) Hot temp make safe (RD: CW Pothole)	potholes on carriageway at junction with Cruickshank gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/02/2020	05/02/2020	Act. ROAD/82032036
50051549	Road: Defective / Damaged (Enquiry 952614) Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway bus lane outside no 40	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/02/2020	10/02/2020	Act. ROAD/82032271
50052099	H (RD: CW Pothole)	Potholes on city bound carriageway bus lane at both sides of junction with old Corstorphine hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032774
50052117	Hot temp make safe, overlay over Toby (RD: CW Pothole)	Pothole on city bound carriageway bus lane outside The Bothy	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032790
50052129	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane at junction with Murrayfield hospital	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	17/02/2020	17/02/2020	Act. ROAD/82032800
50052296	Road: Defective / Damaged (Enquiry 957364) Remove surface water (Gully: Blocked / Flooding)	Surface water over carriageway at junction with Murrayfield hospital	RG: Gully - Standard Priority	Job Complete	18/02/2020	27/11/2020	Act. RDGC14/82000796
50052688	Remove Corstorphine hospital sign from l/p (RD: Unlit Sign Damaged/Missing)	Disused sign on l/p CRH 104,	RD: Cat 3 - 60 Day	Job Complete	21/02/2020	24/09/2020	Act. ROAD/82033294

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50053145	H (RD: CW Pothole)	Potholes on west bound carriageway approximately 20m East of junction with pink hill	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2020	26/02/2020	Act. ROAD/82033686
50053146	H (RD: CW Pothole)	Pothole on west bound carriageway at junction with Cruikshank gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2020	29/02/2020	Act. ROAD/82033687
50053148	H (RD: CW Pothole)	Pothole on west bound carriageway approximately 5m East of junction with Cruikshank gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2020	26/02/2020	Act. ROAD/82033689
50053150	Hot temp (RD: CW Pothole)	Potholes & depressions on west bound carriageway opposite l/p	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2020	03/03/2020	Act. ROAD/82033691
50053151	Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway in yellow hatch box after junction with Corstorphine hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2020	26/02/2020	Act. ROAD/82033692
50053830	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane at gully approximately 15m west of junction with Murrayfield gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034305
50053831	H (RD: CW Pothole)	Pothole on west bound carriageway bus lane at bus stop outside Murrayfield Lawn tennis club	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	02/03/2020	Act. ROAD/82034306
50053833	Hot temp make safe (RD: CW Pothole)	Pothole on west bound carriageway bus lane at l/p no 65	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034308
50053834	H (RD: CW Pothole)	Potholes on west bound carriageway bus lane at l/p no 71	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034309
50053836	H (RD: CW Pothole)	Pothole on west bound carriageway bus lane opposite l/p no 76	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	02/03/2020	Act. ROAD/82034311
50053840	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane approximately 5m east of l/p no 84	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034314
50053841	H (RD: CW Pothole)	Potholes on city bound carriageway opposite l/p no 75	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034315
50053842	H (RD: CW Pothole)	Potholes on city bound carriageway at l/p no 72	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034316
50053843	Hot temp make (RD: CW Pothole)	Pothole on city bound carriageway bus lane at junction with Murrayfield hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034317
50053845	Hot temp make safe (RD: CW Pothole)	Pothole on city bound carriageway bus lane opposite l/p no 65	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034319

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No


Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50053846	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane between l/p no 64 & l/p no 63	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034320
50053847	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane approximately 5m east of l/p no 63	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034321
50053848	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane at gully opposite l/p no 62	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034322
50053850	H (RD: CW Pothole)	Potholes on city bound carriageway bus lane at l/p no 58	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034324
50053851	H (RD: CW Pothole)	Potholes on city bound carriageway bus lane at l/p no 56	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034325
50054823	Road: Defective / Damaged (Enquiry 967243)hot t (RD: CW Pothole)	Metal plate over sunken gully has come loose	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2020	17/03/2020	Act. ROAD/82035140
50054824	H (RD: CW Pothole)	Pothole on west bound carriageway bus lane at l/p no 62	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2020	16/03/2020	Act. ROAD/82035141
50055813	Road: Defective / Damaged (Enquiry 981526) (RD: CW Pothole)	Pothole around ironworks west bound at merge arrow, opp the murrayfield house hotel, outside no39	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/04/2020	22/04/2020	Act. ROAD/82035953
50057074	8 Carriageway potholes. Make safe. (RD: CW Pothole)	At Western Place	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036854
50057079	2 Carriageway potholes. Make safe. (RD: CW Pothole)	Eastbound opp LP CRH77	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036856
50057080	5 Carriageway potholes. Make safe. (RD: CW Pothole)	Eastbound just after LP CRH76	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036857
50057081	5 Carriageway potholes. Make safe. (RD: CW Pothole)	Eastbound before TL CRH60	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036858
50057082	4 Carriageway potholes. Make safe. (RD: CW Pothole)	Eastbound between LP CRH60 and CRH58	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036859
50057083	8 Carriageway potholes. Make safe. (RD: CW Pothole)	Eastbound between LP CRH32 and CRH30	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036860
50057086	1 Carriageway pothole. Make safe. (RD: CW Pothole)	Outside no 231	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/06/2020	24/06/2020	Act. ROAD/82036862
50059170	Road: Defective / Damaged (Enquiry 1010608)	Pothole on west bound carriageway slow lane approximately 5m west of l/p no CRH 65	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	27/07/2020	28/07/2020	Act. ROAD/82038154
	Hot temp make safe (RD: CW Pothole)						

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50060504	Road: Defective / Damaged (Enquiry 1022017) pothole on carriageway at manhole (RD: CW Pothole)	Reference: W5P9ND54-101000163311 - since reporting this in mid-March I have had no updates, the manhole is disintegrating into the road and needs fixed please. Outside 39 Hello, There is a damaged manhole cover that is crumbling outside my property on the busy road. As large vehicles pass over it, vibrations are passing through into the house.  Additionally, the drain on the same road outside our property appears to be blocked as when it rains heavily a large puddle appears and water streams down the drives into the properties. Thanks and regards, 	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/08/2020	18/08/2020	Act. ROAD/82038705
50060505	Road: Defective / Damaged (Enquiry 976238) carriageway repair required around manhole 2.0*2.0 (RD: CW Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2020	18/08/2020	Act. ROAD/82038706
50060536	Road: Defective / Damaged (Enquiry 1022495) pothole on carriageway (RD: CW Pothole)	pothole and sunken road - 	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/08/2020	18/08/2020	Act. ROAD/82038712
50061119	Manhole reset required. See photos. Would also benefit from new manhole frame and cover. Nighshift attended and set up TM. Located on Corstorphine Road between Ballgreen Road and Saughton Hall Road	Located on Corstorphine Road between Ballgreen Road and Saughton Hall Road	RD: Follow Up Job	Job Cancelled	24/08/2020	24/08/2020	Act. ROAD/82038912

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50061374	Re-set and reinstate manhole cover - possible new M/H required RD: Out of Hours Emergency - Rod Mathieson (Lothian buses) - 0131 475 0198 called to report a collapsed manhole cover on Corstorphine Road between Ballgreen Road and Saughton Hall Road passed to Eddie @ OOH Roads (Enquiry 1025944)	collapsed manhole cover on Corstorphine Road between Ballgreen Road and Saughton Hall Road	RD: Follow Up Job	Job Complete	27/08/2020	30/08/2020	Act. ROAD/82039004
50064626	Pothole on carriageway inside lane (RD: CW Pothole)	Lpost 77	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/10/2020	13/10/2020	Act. ROAD/82040208
50064834	Pothole on carriageway inside lane (RD: CW Pothole)	Junction Murrayfield Avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/10/2020	15/10/2020	Act. ROAD/82040305
50064836	Reset bollard (RD: Bollard Damage/Missing/New)	Outside 105	RD: Cat 3 - 60 Day	Job Complete	14/10/2020	15/10/2020	Act. ROAD/82040306
50065859	CW pothole in bus lane on wheel track. (RD: CW Pothole)	Opposite CRH76 lamppost	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/10/2020	29/10/2020	Act. ROAD/82040767
50066739	Pothole on carriageway (RD: CW Pothole)	Outside 41	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/11/2020	11/11/2020	Act. ROAD/82041117
50067938	Road: Defective / Damaged (Enquiry 1073251) Pothole on carriageway (RD: CW Pothole)	Pothole east bound carriageway, outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/11/2020	24/11/2020	Act. ROAD/82041581
50070887	Road: Defective / Damaged (Enquiry 1088423) pothole on carriageway heading east ,lpost 78-72 (RD: CW Pothole)	Pothole present in bus lane on turning to spire hospital. Looks deep and sounded deep when my car went over the top of it.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/12/2020	24/12/2020	Act. ROAD/82042860
50072360	Road: Defective / Damaged (Enquiry 1102353) pothole on carriageway (RD: CW Pothole)	pothole on east bound carriageway. Buses hit this and the house shakes. Please fix soon.Outside 38	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/01/2021	20/01/2021	Act. ROAD/82043488
50072834	Road: Defective / Damaged (Enquiry 1106247) Pothole on carriageway inside lane (RD: CW Pothole)	Large pothole around Gas manhole cover. In bus lane eastbound.lpost64 heading east,lpost 57 to 67 heading west	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/01/2021	28/01/2021	Act. ROAD/82043696
50073154	1no pothole (RD: CW Pothole)	At the junction with Cruikshank Gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2021	23/02/2021	Act. ROAD/82043880

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50073618	Road: Defective / Damaged (Enquiry 1109698) Pothole on carriageway (RD: CW Pothole)	New potholes East bound carriageway outside no. 40 Corstorphine Road and just west of this on same Side of road. Outside 40 pothole likely to grow quickly	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/02/2021	05/02/2021	Act. ROAD/82044136
50074204	Road: Defective / Damaged (Enquiry 1113230) flooding on carriageway (Gully: Blocked / Flooding)	Water accumulating by the kerb. The water tends to build up there when it has been raining for a while. It is a hazard for cyclists. Entrance to Spire hospital	RG: Gully - Standard Priority	Job Complete	05/02/2021	06/02/2021	Act. ROAD/82044456
50074779	Road: Defective / Damaged (Enquiry 1115820) Pothole on carriageway (RD: CW Pothole)	Lpost 60, heading east	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/02/2021	17/02/2021	Act. ROAD/82044738
50075390	Pothole on carriageway inside lane at box (RD: CW Pothole)	Outside the Murrayfield Hotel	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2021	19/02/2021	Act. ROAD/82045112
50075659	Road: Defective / Damaged (Enquiry 1124756) pothole on carriageway (RD: CW Pothole)	Large potholes on the road at entrance to Spire Hospital, Murrayfield.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/02/2021	23/02/2021	Act. ROAD/82045252
50075699	5no potholes (RD: CW Pothole)	Opposite entrance to Murrayfield hospital	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/02/2021	24/02/2021	Act. ROAD/82045271
50077850	Road: Defective / Damaged (Enquiry 1137256) (RD: CW Pothole)	Lpost 73,79,81	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/03/2021	10/03/2021	Act. ROAD/82046606
50078322	Road: Defective / Damaged (Enquiry 1139709) (RD: CW Pothole)	Potholes on eastbound side of road between Pinkhill and entrance to Murrayfield Hospital. Lpost 78,74,70	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2021	16/03/2021	Act. ROAD/82046878
50080272	Road: Defective / Damaged (Enquiry 1151113) Pothole on carriageway outside lane (RD: CW Pothole)	Lpost 73	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/04/2021	02/04/2021	Act. ROAD/82048109
50080273	Pothole on carriageway outside lane (RD: CW Pothole)	Lpost 66	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/04/2021	02/04/2021	Act. ROAD/82048110
50083157	Road: Defective / Damaged (Enquiry 1175123) Pothole on carriageway (RD: CW Pothole)	Lpost 74	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/05/2021	20/05/2021	Act. ROAD/82049756
50083639	1no pothole at gully (RD: CW Pothole)	Opposite Belmont crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/05/2021	24/05/2021	Act. ROAD/82050030

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50085405	Pothole on carriageway (RD: CW Outside Silvan House Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/06/2021	18/06/2021	Act. ROAD/82051031
50087705	Road: Defective / Damaged (Enquiry 1211065) Pothole on carriageway (RD: CW Pothole)	Junction Western Gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/07/2021	20/07/2021	Act. ROAD/82052127
50088133	3no potholes (RD: CW Pothole)	Lamppost CRH81 next to bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/07/2021	28/07/2021	Act. ROAD/82052411
50088258	Road: Defective / Damaged (Enquiry 1215560) gully's chocked (Gully: Blocked / Flooding)	Outside 39-41-43	RG: Gully - Standard Priority	Job Complete	27/07/2021	29/07/2021	Act. ROAD/82052513
50089394	C/W patch 7 x1.5 (RD: CW Cracked/Broken)	Corstorphine Road at Balgreen Road West bound	RD: Cat 3 - 60 Day	Job Complete	12/08/2021	16/08/2021	Act. ROAD/82053110
50090421	1no pothole (RD: CW Pothole)	Eastbound lane at Ip CRH79	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/08/2021	26/08/2021	Act. ROAD/82053643
50090868	Pothole (RD: CW Pothole)	Opp lamppost CRH 78 heading West	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053928
50090869	Pothole (RD: CW Pothole)	Opp lamppost 76 heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053929
50090870	Pothole (RD: CW Pothole)	3m west of lamppost 65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053930
50090871	Potholes x 3 (RD: CW Pothole)	Junction with Balgreen Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053931
50090872	Potholes x 3 (RD: CW Pothole)	10 to 15m west of lamppost CRH57	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053932
50090873	Pothole (RD: CW Pothole)	At lamppost CHR46	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053933
50090874	Pothole (RD: CW Pothole)	10m west of lamppost Ch 42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053934
50090875	Trip on footway make safe with tar as marked (RD: FW HRA Pothole)	At bus stop at lamppost CRH42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2021	02/09/2021	Act. ROAD/82053935
50090909	Potholes x 2 (RD: CW Pothole)	At lamppost CRH32 heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053952
50090912	Potholes x 2 (RD: CW Pothole)	Opp Rolls Royce	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053953
50090921	Trip at footway manhole make safe with tar (RD: FW HRA Pothole)	O/S no 17 on corner	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053962
50090929	Pothole (RD: CW Pothole)	O/S no 74 at manhole	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053969
50090930	Pothole (RD: CW Pothole)	Just before Belmont Crescent at gas toby	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053970
50090932	Potholes x 2 (RD: CW Pothole)	O/S no 98	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	02/09/2021	Act. ROAD/82053971

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50090938	Pothole (RD: CW Pothole)	10m before turn to Balgreen Road heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	03/09/2021	Act. ROAD/82053973
50090941	Pothole (RD: CW Pothole)	At lamppost CRH64	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	03/09/2021	Act. ROAD/82053976
50090943	Potholes x 2 (RD: CW Pothole)	Near lamppost CRH67	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	03/09/2021	Act. ROAD/82053978
50090952	Pothole at gully (RD: CW Pothole)	Opp car wash	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	03/09/2021	Act. ROAD/82053982
50090969	3 x tree root push ups patches required. 3 x 1.5. 6 x 1.2. And 0.3 x 0.3 (RD: FW Tree Root Tar)	Between lamppost CRH 99 and 100	RD: Cat 3 - 60 Day	Job Complete	01/09/2021	20/09/2021	Act. ROAD/82053993
50092391	1no pothole (RD: CW Pothole)	Opposite Balgreen Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/09/2021	23/09/2021	Act. ROAD/82054527
50092403	1no pothole (RD: CW Pothole)	At the junction of Western Gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/09/2021	23/09/2021	Act. ROAD/82054535
50098523	2 carriageway potholes (RD: CW Pothole)	At St. John's gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/11/2021	25/11/2021	Act. ROAD/82056852
50100918	Pothole on carriageway inside lane (RD: CW Pothole)	Junction Balgreen Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/12/2021	22/12/2021	Act. ROAD/82057831
50102241	1no pothole (RD: CW Pothole)	At the entrance to Murrayfield Hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/01/2022	11/01/2022	Act. ROAD/82058433
50103729	4 carriageway potholes (RD: CW Pothole)	Opposite 91	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	22/01/2022	Act. ROAD/82059105
50103731	1 carriageway pothole (RD: CW Pothole)	At lamppost CRH65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	22/01/2022	Act. ROAD/82059107
50103733	1 carriageway pothole (RD: CW Pothole)	At Edinburgh zoo from city bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	22/01/2022	Act. ROAD/82059109
50105483	1no pothole (RD: CW Pothole)	Opposite no103	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2022	07/02/2022	Act. ROAD/82059835
50105484	1no pothole (RD: CW Pothole)	Opposite no91	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2022	07/02/2022	Act. ROAD/82059836
50106303	Road: Defective / Damaged (Enquiry 1326386) pothole on carriageway inside lane (RD: CW Pothole)	Outside 40	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/02/2022	17/02/2022	Act. ROAD/82060254
50107048	Road: Defective / Damaged (Enquiry 1330324) pothole on carriageway (RD: CW Pothole)	Outside 235	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2022	22/02/2022	Act. ROAD/82060670
50107090	1 carriageway pothole (RD: CW Pothole)	At lamppost CRH77	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060702
50107095	1 carriageway pothole (RD: CW Pothole)	At cruickshank gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060705
50107164	1 carriageway pothole (RD: CW Pothole)	Opposite 91	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060754

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50107166	1 carriageway pothole (RD: CW Pothole)	Opposite 20	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060756
50108976	Pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/03/2022	15/03/2022	Act. ROAD/82061681
50112201	1 carriageway pothole (RD: CW Pothole)	Outside 40	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/04/2022	22/04/2022	Act. ROAD/82063336
50113366	Pothole on carriageway (RD: CW Pothole)	Murrayfield Avenue junction Corstorphine Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/05/2022	11/05/2022	Act. ROAD/82063931
50113974	Overlay marked area approx 2x10m (RD: CW Cracked/Broken)	At lamppost CRH74	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2022	23/05/2022	Act. ROAD/82064300
50113975	5 carriageway potholes (RD: CW Pothole)	Outside Murrayfield hospital	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2022	23/05/2022	Act. ROAD/82064301
50114602	Replace damaged bollard (RD: Bollard Damage/Missing/New)	Outside 93	RD: Cat 4 - Programmed	Job Complete	31/05/2022	06/06/2022	Act. ROAD/82064636
50115457	Pothole on carriageway inside lane (RD: CW Pothole)	Lpost 65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/06/2022	20/06/2022	Act. ROAD/82065057
50115561	1no pothole (RD: CW Pothole)	Outside no89	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/06/2022	22/06/2022	Act. ROAD/82065123
50116440	Pavement: Damaged / Defective (Enquiry 1405511) pothole on footway (RD: FW HRA Pothole)	Outside Corstorphine hospital	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/07/2022	13/07/2022	Act. ROAD/82065530
50116993	Unsigned pole rusted at base, very loose and hanging across the footway. Cut pole down and make hole safe from trip hazard. (RD: Unlit Sign Damaged/Missing)	Corstorphine Road, 10m prior to the junction for Ormidale Terrace	RD: Cat 2 - 5 Day	Job Complete	01/08/2022	04/08/2022	Act. ROAD/82065862
50118178	Pothole (RD: CW Pothole)	In bus lane . Across cw from murrayside care home see. Pics	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066592
50118179	Pothole (RD: CW Pothole)	Near lamppost 76	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066593
50118183	Pothole (RD: CW Pothole)	Cover surround at lamppost 56	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066594
50118184	Pothole (RD: CW Pothole)	Adjacent to balgreen road. At nature reserve gate	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066595
50118185	Cover missing see pics. Make safe required (RD: Gully Brander Missing)	Near lamppost 54	RD: Cat 3 - 60 Day	Job Complete	01/09/2022	23/09/2022	Act. ROAD/82066596
50118193	Gully surround (RD: CW Pothole)	At lamppost 42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066597
50118194	Pothole (RD: CW Pothole)	Outside number 135 in bus lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066598
50118197	Pothole (RD: CW Pothole)	Adjacent to number 91	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066599

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50118198	Pothole (RD: CW Pothole)	At junction with western gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066600
50118202	Cover missing on fw make safe required (RD: Other Defect Type)	Outside number 38	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	22/09/2022	Act. ROAD/82066601
50118205	Open joint x 2 (RD: CW Open Joint)	At lamppost 70	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066604
50118211	Pothole (RD: CW Pothole)	At crossing adjacent to the murrayfield bar	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066606
50118212	Gully surround (RD: CW Pothole)	Adjacent to rolls royce	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2022	02/09/2022	Act. ROAD/82066607
50121141	1 cw pothole (RD: CW Pothole)	Opposite 20	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/10/2022	01/11/2022	Act. ROAD/82068040
50121142	1 cw pothole (RD: CW Pothole)	Outside silvan house	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/10/2022	01/11/2022	Act. ROAD/82068041
50122636	1 carriageway pothole (RD: CW Pothole)	At lamppost 75	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/11/2022	21/11/2022	Act. ROAD/82068670
50122755	1no pothole (RD: CW Pothole)	Westbound at Ip CRH75	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/11/2022	22/11/2022	Act. ROAD/82068717
50122885	1 carriageway pothole (RD: CW Pothole)	Opposite no74	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/11/2022	24/11/2022	Act. ROAD/82068801
50124905	Road: Defective / Damaged (Enquiry 1480012) pothole on carriageway (RD: CW Pothole)	Junction Murrayfield Gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/12/2022	28/12/2022	Act. ROAD/82069938
50125005	Road: Defective / Damaged - Large potholes, caused customers tyre to pop. (Enquiry 1480559) pothole carriageway (RD: CW Pothole)	Junction Kaimes Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/12/2022	30/12/2022	Act. ROAD/82070031
50125299	Pothole on carriageway (RD: CW Pothole)	Outside 235,junction Kaimes Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/01/2023	09/01/2023	Act. ROAD/82070223
50126036	3no potholes (RD: CW Pothole)	Outside no98	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2023	18/01/2023	Act. ROAD/82070737
50126955	Road: Defective / Damaged (Enquiry 1488569) (RD: CW Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	27/01/2023	Act. ROAD/82071340
50126956	Road: Defective / Damaged (Enquiry 1488569) (RD: CW Pothole)	City bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	27/01/2023	Act. ROAD/82071341
50126960	Road: Defective / Damaged (Enquiry 1488569) (RD: CW Pothole)	City bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	27/01/2023	Act. ROAD/82071345
50126963	Road: Defective / Damaged (Enquiry 1492245) (RD: CW Pothole)	West of balgreen rod at gully at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2023	21/01/2023	Act. ROAD/82071348

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50126964	Road: Defective / Damaged (Enquiry 1491966) (RD: CW Pothole)	end of the bus lane heading out of town, prior to pinkhill	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2023	21/01/2023	Act. ROAD/82071349
50126978	Road: Defective / Damaged (Enquiry 1489352) (RD: CW Pothole)	Greenlane between western corner and Murrayfield road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	27/01/2023	Act. ROAD/82071361
50127251	Road: Defective / Damaged (Enquiry 1493513) pothole on carriageway (RD: CW Pothole)	Outside 231	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2023	27/01/2023	Act. ROAD/82071542
50127999	Road: Defective / Damaged - Pothole (Enquiry 1490863) (RD: CW Pothole)	Silvan house westbound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2023	16/04/2023	Act. ROAD/82072075
50128000	Road: Defective / Damaged - Pothole (Enquiry 1490863) (RD: CW Pothole)	Silvan house westbound in joint	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2023	03/03/2023	Act. ROAD/82072076
50128623	Road: Defective / Damaged (Enquiry 1506122) pothole on carriageway (RD: CW Pothole)	Bus stop outside Tennis club	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2023	13/02/2023	Act. ROAD/82072447
50128846	Road: Defective / Damaged (Enquiry 1507106) pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/02/2023	13/02/2023	Act. ROAD/82072556
50129200	Road: Defective / Damaged (Enquiry 1509343) pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road, outside lane heading west	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2023	15/02/2023	Act. ROAD/82072766
50130561	Patch required Approx 12m x 1.5m (RD: CW Cracked/Broken)	Opposite 74 at bus stop	RD: Cat 3 - 60 Day	Job Complete	27/02/2023	06/03/2023	Act. ROAD/82073521
50130563	1 cw pothole (RD: CW Pothole)	Opposite 80	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2023	01/03/2023	Act. ROAD/82073523
50131195	Road: Defective / Damaged (Enquiry 1518984) pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road, inside lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/03/2023	07/03/2023	Act. ROAD/82073866
50131430	1no pothole (RD: CW Pothole)	At Ip CRH65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2023	09/03/2023	Act. ROAD/82073999
50131432	1no pothole (RD: CW Pothole)	At Ip CRH79	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2023	09/03/2023	Act. ROAD/82074001
50132085	Road: Defective / Damaged (Enquiry 1523665) pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road heading east at pedestrian crossing	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2023	16/03/2023	Act. ROAD/82074360
50133790	1no pothole (RD: CW Pothole)	At the junction with Belmont Crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/04/2023	06/04/2023	Act. ROAD/82075386
50134155	Pothole on footway (RD: FW HRA Pothole)	Outside 70 + 78	RD: Cat 3 - 60 Day	Job Complete	12/04/2023	13/04/2023	Act. ROAD/82075702
50134276	Road: Defective / Damaged (Enquiry 1536753) uplift cones (RD: Other Defect Type)	Traffic island outside 92	RD: Cat 3 - 60 Day	Job Complete	14/04/2023	20/04/2023	Act. ROAD/82075803

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50134277	Pothole on carriageway inside lane (RD: CW Pothole)	Outside 92	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/04/2023	17/04/2023	Act. ROAD/82075804
50134809	Pothole on carriageway (RD: CW Pothole)	Lpost 57,lpost 59	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	24/04/2023	Act. ROAD/82076194
50135118	RD: Gully Cover Damaged - What is the problem with the gully : damaged. What surface is the gully on : road. Specify_damage : sunken in surface (Enquiry 1543165)reset uneven carriageway gully frame (RD: Gully Damaged/Sunken)	Junction Murrayfield Gardens	RD: Cat 3 - 60 Day	Job Complete	26/04/2023	05/05/2023	Act. RDGC14/82005469
50135581	Pothole on carriageway heading west outside lane (RD: CW Pothole)	Lpost 79	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/05/2023	11/05/2023	Act. ROAD/82076805
50135728	Gully choked (Gully: Blocked / Flooding)	Opposite 78	RG: Gully - Standard Priority	Job Complete	09/05/2023	07/05/2026	Act. RDGC14/82005490
50138514	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1572781) footway gullies choked (Gully: Blocked - Hand Clear)	Outside Chinese Consulate	RG: Gully - Standard Priority	RD: Made Safe Job Complete	28/06/2023	13/07/2023	Act. RDGC14/82005572
50138755	1no pothole (RD: CW Pothole)	At the junction of Belmont Crescent	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/07/2023	04/07/2023	Act. ROAD/82078791
50138887	Damaged speed reducing measures sign on a lamppost.	96 Corstorphine Road	RD: Cat 3 - 60 Day	Job Complete	06/07/2023	09/07/2023	Act. ROAD/82078870
50139531	Please remove this and the end board, and dispose in skip. (RD: Unlit Sign Damaged/Missing) Pavement: Damaged / Defective (Enquiry 1583853) make safe (RD: FW Grano Pothole)	Opposite 4	RD: Cat 3 - 60 Day	Job Complete	19/07/2023	20/07/2023	Act. ROAD/82079245
50139633	1no pothole (RD: CW Pothole)	At Belmont Crescent	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/07/2023	21/07/2023	Act. ROAD/82079301
50141980	Pothole on carriageway (RD: CW Pothole)	Lpost 75	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2023	04/09/2023	Act. ROAD/82080430
50142887	1 cw pothole (RD: CW Pothole)	At entrance to Murrayfield hospital	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/09/2023	21/09/2023	Act. ROAD/82080865
50142904	1 cw pothole (RD: CW Pothole)	Outside entrance to silvan house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/09/2023	21/09/2023	Act. ROAD/82080876

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50143292	Road: Defective / Damaged (Enquiry 1619880) pothole on carriageway (RD: CW Pothole)	Outside Enterprise car rental	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/09/2023	28/09/2023	Act. ROAD/82081091
50143293	Road: Defective / Damaged (Enquiry 1619952) flooding on carriageway/footway (Gully: Blocked / Flooding)	Outside Corstorphine Hospital	RG: Gully - Standard Priority	Job Complete	28/09/2023	21/02/2024	Act. RDGC14/82005753
50143417	1no pothole (RD: CW Pothole)	At the junction of Belmont Crescent	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/10/2023	03/10/2023	Act. ROAD/82081189
50143577	Road: Defective / Damaged (Enquiry 1623515) pothole on carriageway (RD: CW Pothole)	Bus stop outside Holiday Inn	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/10/2023	05/10/2023	Act. ROAD/82081318
50143900	1no pothole (RD: CW Pothole)	Opposite Western Place	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/10/2023	12/10/2023	Act. ROAD/82081566
50144520	1no pothole (RD: CW Pothole)	At the junction with Belmont Crescent	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/10/2023	30/10/2023	Act. ROAD/82081965
50144737	Road: Defective / Damaged (Enquiry 1635866) pothole on carriageway inside lane (RD: CW Pothole)	Lpost 78	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/10/2023	02/11/2023	Act. ROAD/82082146
50144738	Road: Defective / Damaged (Enquiry 1635866) pothole on carriageway inside lane (RD: CW Pothole)	Lpost 84	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/10/2023	02/11/2023	Act. ROAD/82082147
50144739	Pothole on carriageway inside lane (RD: CW Pothole)	Lpost 86	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/10/2023	02/11/2023	Act. ROAD/82082148
50144844	Advance Stop Line (at the traffic lights) worn Road Safety issue; line so worn it may not be seen and camera cannot be enforced	At Ellersly Road eastbound	Non Routine (One Off Works)	Job Complete	01/11/2023	03/11/2023	Act. ROAD/82082228
50145119	Pothole on carriageway (RD: CW Pothole)	Junction Balgreen Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/11/2023	06/11/2023	Act. ROAD/82082375
50145630	Flooding carriageway and footway (Gully: Blocked / Flooding)	Outside Corstorphine Hospital	RG: Gully - Standard Priority	Job Complete	13/11/2023	21/02/2024	Act. RDGC14/82005888
50145933	Install new gully next to gully 39008 (RD: Gully Damaged/Sunken)	Outside 135	RG: Gully - Standard Priority	Job Complete	16/11/2023	22/01/2024	Act. ROAD/82082810
50146153	Road: Defective / Damaged (Enquiry 1646384) pothole on carriageway outside lane (RD: CW Pothole)	Outside 135	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/11/2023	21/11/2023	Act. ROAD/82082913
50146266	Road: Defective / Damaged (Enquiry 1647365) pothole on carriageway (RD: CW Pothole)	Heading east opposite Western Place	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/11/2023	22/11/2023	Act. ROAD/82082988

Effective: 01/01/2020 to 30/11/2024
Service: Roads General
Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50146924	Road: Defective / Damaged (Enquiry 1652790) make safe carriageway in hra(inside lane) (RD: CW Pothole)	Outside Spire hospital	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/11/2023	03/12/2023	Act. ROAD/82083353
50147009	Road: Defective / Damaged (Enquiry 1653712) pothole on carriageway (RD: CW Pothole)	Bus stop outside The Holiday Inn	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/12/2023	03/12/2023	Act. ROAD/82083405
50147062	1no pothole (RD: CW Pothole)	At the junction with Belmont Crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/12/2023	04/12/2023	Act. ROAD/82083433
50147890	2 cw potholes (RD: CW Pothole)	At junction with balgreen road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/12/2023	13/12/2023	Act. ROAD/82083936
50148773	Pothole on carriageway bus lane heading east (RD: CW Pothole)	Passed exit from Holiday Inn	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/12/2023	22/12/2023	Act. ROAD/82084529
50149087	Pavement: Damaged / Defective (Enquiry 1668348) gully choked (Gully: Blocked / Flooding)	Outside Corstorphine Hospital	RG: Gully - Standard Priority	Job Complete	03/01/2024	21/02/2024	Act. RDGC14/82006020
50149223	2no potholes (RD: CW Pothole)	Eastbound lane opposite lp CRH66	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/01/2024	06/01/2024	Act. ROAD/82084826
50149225	3no potholes (RD: CW Pothole)	At lp CRH56	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/01/2024	06/01/2024	Act. ROAD/82084828
50149228	1no pothole (RD: CW Pothole)	At the junction with Murrayfield Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/01/2024	06/01/2024	Act. ROAD/82084831
50149505	Road: Defective / Damaged (Enquiry 1672520) pothole on carriageway,inside lane (RD: CW Pothole)	Outside Holiday Inn	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2024	09/01/2024	Act. ROAD/82085004
50150092	Pothole on carriageway (RD: CW Pothole)	Lpost 65 heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/01/2024	16/01/2024	Act. ROAD/82085365
50150094	Road: Defective / Damaged (Enquiry 1677393) replace damaged gully frame and brander (RD: Gully Damaged/Sunken)	Outside Spire hospital	RD: Cat 3 - 60 Day	Job Complete	15/01/2024	22/01/2024	Act. ROAD/82085367
50150368	Road: Defective / Damaged (Enquiry 1678768) pothole on carriageway,inside lane (RD: CW Pothole)	Outside 135	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2024	24/01/2024	Act. ROAD/82085556
50150990	Pothole on footway (RD: FW HRA Pothole)	Junction Ellersly Road (east junction)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2024	31/01/2024	Act. ROAD/82085955
50150991	Flooding on footway/carriageway (Gully: Blocked / Flooding)	Junction Ellersly Road	RG: Gully - Standard Priority	Job Complete	24/01/2024	27/05/2024	Act. RDGC14/82006063
50151101	2no potholes (RD: CW Pothole)	Opposite Balgreen rd city bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2024	31/01/2024	Act. ROAD/82086042
50151102	3no potholes (RD: CW Pothole)	At Balgreen rd westbound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2024	31/01/2024	Act. ROAD/82086043

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50151481	Pothole on carriageway (RD: CW Outside 135 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/01/2024	02/02/2024	Act. ROAD/82086332
50151872	Pothole on carriageway , outside lane (RD: CW Pothole)	Lpost 81 heading west before Pinkhill	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2024	02/02/2024	Act. ROAD/82086611
50152105	Pothole on carriageway inside lane (RD: CW Pothole)	Opposite Western Place	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/02/2024	06/02/2024	Act. ROAD/82086783
50152117	Pothole on carriageway (RD: CW Pothole)	Outside Silvan House	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/02/2024	09/02/2024	Act. ROAD/82086795
50152175	1no pothole (RD: CW Pothole)	At the junction with Belmont Crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/02/2024	09/02/2024	Act. ROAD/82086837
50154627	2 potholes (RD: CW Pothole)	Opposite lamppost 66	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2024	05/03/2024	Act. ROAD/82088544
50154628	1 pothole (RD: CW Pothole)	Opposite lamppost 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2024	05/03/2024	Act. ROAD/82088545
50154629	1 pothole (RD: CW Pothole)	Foot of speed camera at beechwood mains	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	03/03/2024	03/03/2024	Act. ROAD/82088546
50154630	2 potholes (RD: CW Pothole)	Foot of speed camera at beechwood mains	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	03/03/2024	03/03/2024	Act. ROAD/82088547
50154631	6 potholes (RD: CW Pothole)	Outside 96	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2024	05/03/2024	Act. ROAD/82088548
50156232	1no Cw pothole (RD: CW Pothole)	Opposite Ip CRH78	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/03/2024	25/03/2024	Act. ROAD/82089658
50157127	Reset gully frame (RD: Gully Damaged/Sunken)	Lpost 32	RD: Cat 2 - 5 Day	Job Complete	02/04/2024	21/04/2024	Act. ROAD/82090307
50158455	2no potholes (RD: CW Pothole)	At the junction with Kaimes rd	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/04/2024	16/04/2024	Act. ROAD/82091344
50158830	please refresh all white on westbound and eastbound approach to Balgreen Road	east and west of Balgreen Road including zigzag markings	Non Routine (One Off Works)	Job Complete	19/04/2024	23/04/2024	Act. ROAD/82091602
50159336	Pothole on carriageway bus lane (RD: CW Pothole)	Balgreen Road to lpost 69	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/04/2024	01/05/2024	Act. ROAD/82091906
50159419	Pothole on carriageway (RD: CW Pothole)	Lpost 63,61,58,outside 102,94	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/04/2024	05/05/2024	Act. ROAD/82091964
50159420	Pothole on carriageway (RD: CW Pothole)	Lpost 48	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/04/2024	30/04/2024	Act. ROAD/82091965
50159557	Pothole on carriageway (RD: CW Pothole)	Junction Murrayfield Avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/05/2024	02/05/2024	Act. ROAD/82092064
50159970	Pothole on carriageway (RD: CW Pothole)	Lpost 71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/05/2024	08/05/2024	Act. ROAD/82092311
50160194	Pothole on carriageway (RD: CW Pothole)	Lpost 73(heading west)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2024	16/05/2024	Act. ROAD/82092418
50160469	Pothole on carriageway (RD: CW Pothole)	Lpost 78-68	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2024	19/05/2024	Act. ROAD/82092611
50160589	Pothole on carriageway (RD: CW Pothole)	Lpost 55 heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2024	19/05/2024	Act. ROAD/82092664

Effective: 01/01/2020 to 30/11/2024
 Service: Roads General
 Site: Corstorphine Road (7905055)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50160592	Pothole on carriageway (RD: CW Lpost 60 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2024	19/05/2024	Act. ROAD/82092665
50160593	Pothole on carriageway (RD: CW Lpost 78 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2024	19/05/2024	Act. ROAD/82092666
50160594	Pothole on carriageway (RD: CW Lpost 84 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2024	19/05/2024	Act. ROAD/82092667
50160595	RD: CW Pothole	Pothole on carriageway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2024	19/05/2024	Act. ROAD/82092668
50161701	Reset gully frames (RD: Gully Damaged/Sunken)	Outside 40,22	RD: Cat 3 - 60 Day	Job Complete	04/06/2024	23/06/2024	Act. RDGC14/82006502
50161797	Gully chocked (Gully: Blocked / Flooding)	Pedestrian crossing at Balgreen Road	RG: Gully - Standard Priority	Job Complete	05/06/2024	17/08/2024	Act. RDGC14/82006510
50164890	Replace damaged bollard (RD: Bollard Damage/Missing/New)	Junction Ormidale Terrace	RD: Cat 3 - 60 Day	Job Complete	05/08/2024	06/08/2024	Act. ROAD/82095370
50164918	2no potholes (RD: CW Pothole)	Opp LP65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2024	06/08/2024	Act. ROAD/82095394
50165386	Replace 1 broken 600 x 450 slab (RD: FW Slabs Broken/Missing)	Outside murrayfield pharmacy	RD: Cat 3 - 60 Day	Job Complete	15/08/2024	16/08/2024	Act. ROAD/82095652
50165387	1 fw pothole (RD: FW HRA Pothole)	Opposite 82	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/08/2024	15/08/2024	Act. ROAD/82095653
50165388	2 cw potholes (RD: CW Pothole)	At lp crh52	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/08/2024	15/08/2024	Act. ROAD/82095654
50167367	1no pothole (RD: CW Pothole)	Eastbound lane opposite lp crh66	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/10/2024	03/10/2024	Act. ROAD/82096844
50167661	1no pothole (RD: CW Pothole)	Eastbound lane opposite Western Place	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/10/2024	08/10/2024	Act. ROAD/82097011
50167993	Pothole on carriageway (RD: CW Pothole)	Lpost 57	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/10/2024	15/10/2024	Act. ROAD/82097256
50168959	1no pothole (RD: CW Pothole)	Eastbound lane opposite Western Place	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/10/2024	31/10/2024	Act. ROAD/82097883
50169195	Pothole on carriageway (RD: CW Pothole)	Pedestrian crossing at Balgreen Road heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/11/2024	07/11/2024	Act. ROAD/82098042