

Effective: 01/01/2020 to 28/02/2020
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Site: St John's Road (7903285)

Locality: Corstorphine, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41052666 - Inspection Batch		Route:	Ad hoc Route			Date:	18/02/2020
42046484	H	18/02/2020	Pothole on west bound carriageway slow lane at gully outside no 309	RD: CW Pothole	Internal		Committed	50052253
Batch:	41052543 - Inspection Batch No actionable defects found		Route:	NW_CW1_East1			Date:	17/02/2020
Batch:	41052459 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046311	H	17/02/2020	Pothole on city bound carriageway outside no 16	RD: CW Pothole	Internal		Committed	50052097
Batch:	41052456 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046308	H	17/02/2020	Potholes on city bound carriageway opposite no 81	RD: CW Pothole	Internal		Committed	50052094
Batch:	41052455 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046306	H	17/02/2020	Potholes on city bound carriageway outside no 26	RD: CW Pothole	Internal		Committed	50052092
Batch:	41052453 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046303	H	17/02/2020	Pothole on city bound carriageway bus lane outside no 192	RD: CW Pothole	Internal		Committed	50052089
Batch:	41052451 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046300	H	17/02/2020	Pothole on west bound carriageway at l/p no 42	RD: CW Pothole	Internal		Committed	50052087
Batch:	41052450 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2020
42046298	Hot	17/02/2020	Pothole on city bound carriageway at l/p no 49	RD: CW Pothole	Internal		Committed	50052085
Batch:	41051850 - Inspection Batch		Route:	Ad hoc Route			Date:	12/02/2020
42045930	H	12/02/2020	Potholes on city bound carriageway bus lane approximately 5m east of junction with Corstorphine bank drive	RD: CW Pothole	Internal		Committed	50051716
Batch:	41051646 - Inspection Batch		Route:	Ad hoc Route			Date:	10/02/2020
42045783	Damaged fire hydrant cover and frame	10/02/2020	Damaged fire hydrant cover on City bound carriageway at junction with Clermiston road	RU: Utility Apparatus	Internal		Uncommitted	50051560
Batch:	41051406 - Inspection Batch No actionable defects found		Route:	NW_CW1_East1			Date:	05/02/2020
Batch:	41051167 - Inspection Batch		Route:	Ad hoc Route			Date:	03/02/2020
42045314	H	03/02/2020	Potholes on city bound carriageway slow lane outside no 204	RD: CW Pothole	Internal		Committed	50051074

Effective: 01/01/2020 to 28/02/2020
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality		
Batch: 41050929 - Inspection Batch				Route: Ad hoc Route		Date: 30/01/2020		
42045098	H	30/01/2020	Pothole on city bound carriageway outside no 20	RD: CW Pothole	Internal		Committed	50050813
Batch: 41050925 - Inspection Batch				Route: Ad hoc Route		Date: 30/01/2020		
42045094	Road: Defective / Damaged (Enquiry 947447)	30/01/2020	Pothole on carriageway outside no 24	RD: CW Pothole	Internal		Committed	50050810
Hot temp make safe								
Batch: 41049970 - Inspection Batch				Route: NW_CW1_East1		Date: 20/01/2020		
No actionable defects found								
Batch: 41049880 - Inspection Batch				Route: Ad hoc Route		Date: 17/01/2020		
42044094	Clean out gully	17/01/2020	Gully block on west bound carriageway outside no 309	Gully: Blocked / Flooding	Internal		Committed	50049779
Batch: 41049879 - Inspection Batch				Route: Ad hoc Route		Date: 17/01/2020		
42044093	Hot temp make safe	17/01/2020	Pothole on west bound carriageway outside no 309	RD: CW Pothole	Internal		Committed	50049778
Batch: 41049721 - Inspection Batch				Route: Ad hoc Route		Date: 15/01/2020		
42043908	Hot temp make safe	15/01/2020	Pothole on City bound carriageway bus lane opposite mimi's bakehouse	RD: CW Pothole	Internal		Committed	50049601
Batch: 41049268 - Inspection Batch				Route: NW_CW1_East1		Date: 09/01/2020		
No actionable defects found								
Batch: 41049184 - Inspection Batch				Route: Ad hoc Route		Date: 09/01/2020		
42043538	Hot temp make safe	09/01/2020	Pothole on east bound carriageway bus lane outside St. Anne's parish church at bus stop	RD: CW Pothole	Internal		Committed	50049205
Batch: 41048882 - Inspection Batch				Route: Ad hoc Route		Date: 07/01/2020		
42043374	Pavement: Damaged / Defective (Enquiry 930180)	07/01/2020	Pedestrian guardrail and access gate damaged after RTA. On footway outside no 121	RD: Railing Damage/Missing/New	Internal		Committed	50049025
Replace damaged guard rails and Access gate								

Customer Services

Enquiry No.: 34001812 **Logged by:** **on:** 17/01/2020 10:34
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: I have posted I hedge infringement letter to no 34
Location: Overgrown foliage on footway & carriageway outside no 34 **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Effective: 01/01/2020 to 28/02/2020
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 34001807 **Logged by:** [REDACTED] **on:** 15/01/2020 11:02
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Outside no 184
Location: Overgrown foliage on footway , blocking sign and traffic signals **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 30009006 **Logged by:** [REDACTED] **on:** 16/01/2020 16:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Broken Crumbling Surface at Gully: See Attached
Location: St John,s Road: Heading West Inside Lane Befoe Drumbrae Roundabout & Bank of Scotland **Contact:**

Enquiry No.: 964498 **Logged by:** Verint CRM Connector **on:** 21/02/2020 20:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole opened up on the site of a previous repair adjacent to manhole - outside lane of St John's Rd heading towards airport. **Contact:**

Nearest kerbside properties for reference are McColls/Post Office and MiMi's Bakehouse.

Too dark to take a photo and too busy with traffic.

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 962155 **Logged by:** Verint CRM Connector **on:** 18/02/2020 12:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: large pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 962082 **Logged by:** Verint CRM Connector **on:** 18/02/2020 10:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on the inside lane travelling west on St John's Road just before the Drumbrae roundabout. **Contact:**

Enquiry No.: 961715 **Logged by:** Verint CRM Connector **on:** 17/02/2020 15:55
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: Update: Road sign still face down on St John's Road this pm plus spotted another one close to Drumbrae South rbt EH12 (2 pics) **Contact:**

Enquiry No.: 961701 **Logged by:** Verint CRM Connector **on:** 17/02/2020 15:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: yclists beware large pothole opened up on St John's Road EH12 westbound near Drumbrae South roundabout. Difficult to see it when full of water. (2 pics) #edintravel @edinhelp @harts_cyclery @CorstorphineCC @FrankRoss06 **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Effective: 01/01/2020 to 28/02/2020
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 961043 **Logged by:** Verint CRM Connector **on:** 16/02/2020 12:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: There is a large pothole on the 2nd lane west heading road close to McColls convenience store. Is is close to the middle of the road and is causing lots of motorists to swerve to the left (1st lane) to avoid it or into the oncoming traffic on the east heading 2nd lane road. This needs fills asap. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 960741 **Logged by:** Verint CRM Connector **on:** 15/02/2020 12:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Deep and wide pothole on the road near to the kerb where cyclists cycle - there is no room to avoid it when traffic is busy and a cyclist could be badly hurt. It is just outside no. 309 St John's Road on the west-bound side of the road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 960738 **Logged by:** Verint CRM Connector **on:** 15/02/2020 12:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Deep pothole near the middle of the road just where cars move over to turn right into Corstorphine Bank Drive. Almost opposite RS McClls, 265 St John's Road. It's next to a drain cover. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 959969 **Logged by:** Verint CRM Connector **on:** 13/02/2020 18:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush

Location: overhanging tree - 111-113 ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 6NN **Contact:**

Enquiry No.: 953075 **Logged by:** [REDACTED] **on:** 31/01/2020 19:09
Service: Roads General **Subject:** Covers: Missing **Classification:** Customer Emergency
Desc.: missing cover - outside restearaunt eastern pavillion. opposite subway.
Location: St John's Road - outside the Eastern Pavilion **Contact:**

Enquiry No.: 952418 **Logged by:** Verint CRM Connector **on:** 30/01/2020 16:55
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Missing toby cover in the middle of the pavement, directly in front of the door to no 48 St Johns road. The drain is very deep and someone will probably have a very nasty accident soon, as the pavement is busy. The hole is about six inches square. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Effective: 01/01/2020 to 28/02/2020
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 952318 **Logged by:** [REDACTED] **on:** 30/01/2020 15:07
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: @edintravel @edinhelp @CorstorphineCC @FrankRoss06 @LivingStreetsEd And another road sign face down on SJR EH12 at RBS near Featherhall Ave. Just seen @HBSTraffic heading along SJR.
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 952309 **Logged by:** [REDACTED] **on:** 30/01/2020 14:54
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: @edintravel @edinhelp @CorstorphineCC @FrankRoss06 @LivingStreetsEd FYI there's another road sign face down on SJR EH12 by TSB at The Glebe. #triphazard
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 951933 **Logged by:** [REDACTED] **on:** 30/01/2020 09:03
Service: Roads General **Subject:** Covers: Missing **Classification:** Customer Emergency
Desc.: Missing manhole cover
Location: o/s no 50 on pavement **Contact:**

Enquiry No.: 951292 **Logged by:** [REDACTED] **on:** 29/01/2020 10:01
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Hey @edinhelp, had a constituent come into @agcolehamilton office to say that there is a dislodged manhole cover at the junction of Clermiston Rd North and St John's Road. Any way this could be looked at ASAP? Thanks!
Location: at the junction of Clermiston Rd North and St John's Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset
Job Number: 50051560 **Defect Number:** 42045783

Enquiry No.: 949547 **Logged by:** Verint CRM Connector **on:** 25/01/2020 14:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: POTHLES IN CAR PARK - 245 ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 7XD **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 949545 **Logged by:** Verint CRM Connector **on:** 25/01/2020 14:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: POTHOLE IN CAR PARK - 245A ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 7XD **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset

Enquiry No.: 947447 **Logged by:** Verint CRM Connector **on:** 22/01/2020 13:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface is breaking up with a number of potholes appearing every week **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 6 - From Kames Road to Drum Brae South **Feature Type:** Road Asset
Job Number: 50050810 **Defect Number:** 42045094

Effective: 01/01/2020 to 28/02/2020
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 940676 **Logged by:** Verint CRM Connector **on:** 12/01/2020 13:12
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Grass
Location: Overhanging trees on 34 ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 6PA - trees are are overgrown and hazardous to pedestrians with overhanging branches at eye level **Contact:**

Enquiry No.: 940675 **Logged by:** Verint CRM Connector **on:** 12/01/2020 13:09
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Overhanging trees on 36 ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 6PA - first of all trees are covering street lights and secondly they are overgrown and hazardous to pedestrians **Contact:**

Enquiry No.: 940669 **Logged by:** Verint CRM Connector **on:** 12/01/2020 12:55
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Hedge covering traffic signal - overgrown and needs cuts asap - on 184 ST JOHN'S ROAD, EDINBURGH, CITY OF EDINBURGH, EH12 8BE just after Templeland Road where the traffic crossing is. **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality	
50046562	Road: Defective / Damaged (Enquiry 915939)	Sunken drain on west bound carriageway outside no 89	RD: Cat 2 - 5 Day	Job Complete	27/11/2019	16/01/2020	Act. ROAD/82028630
	Place steel plate over sunken gully frame (RD: CW Steel Plate Required)						
50049025	Pavement: Damaged / Defective (Enquiry 930180)	Pedestrian guardrail and access gate damaged after RTA. On footway outside no 121	RD: Cat 3 - 60 Day	Job Complete	07/01/2020	11/06/2020	Act. ROAD/82030202
	Replace damaged guard rails and Access gate (RD: Railing Damage/Missing/New)						
50049205	Hot temp make safe (RD: CW Pothole)	Pothole on east bound carriageway bus lane outside St. Anne's parish church at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/01/2020	09/01/2020	Act. ROAD/82030341

Effective: 01/01/2020 to 28/02/2020
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality	
50049601	Hot temp make safe (RD: CW Pothole)	Pothole on City bound carriageway bus lane opposite mimi's bakehouse	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/01/2020	16/01/2020	Act. ROAD/82030670
50049778	Hot temp make safe (RD: CW Pothole)	Pothole on west bound carriageway outside no 309	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/01/2020	20/01/2020	Act. ROAD/82030802
50049779	Clean out gully (Gully: Blocked / Flooding)	Gully block on west bound carriageway outside no 309	RG: Gully - Standard Priority	Job Complete	17/01/2020	29/10/2020	Act. RDGC14/82000629
50050810	Road: Defective / Damaged (Enquiry 947447)	Pothole on carriageway outside no 24	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031623
	Hot temp make safe (RD: CW Pothole)						
50050813	H (RD: CW Pothole)	Pothole on city bound carriageway outside no 20	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2020	31/01/2020	Act. ROAD/82031626
50051074	H (RD: CW Pothole)	Potholes on city bound carriageway slow lane outside no 204	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/02/2020	04/02/2020	Act. ROAD/82031812
50051716	H (RD: CW Pothole)	Potholes on city bound carriageway bus lane approximately 5m east of junction with Corstorphine bank drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/02/2020	13/02/2020	Act. ROAD/82032416
50052085	Hot (RD: CW Pothole)	Pothole on city bound carriageway at l/p no 49	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032762
50052087	H (RD: CW Pothole)	Pothole on west bound carriageway at l/p no 42	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	22/02/2020	Act. ROAD/82032764
50052089	H (RD: CW Pothole)	Pothole on city bound carriageway bus lane outside no 192	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032766
50052092	H (RD: CW Pothole)	Potholes on city bound carriageway outside no 26	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032768
50052094	H (RD: CW Pothole)	Potholes on city bound carriageway opposite no 81	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	19/02/2020	Act. ROAD/82032770
50052097	H (RD: CW Pothole)	Pothole on city bound carriageway outside no 16	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2020	18/02/2020	Act. ROAD/82032772
50052253	H (RD: CW Pothole)	Pothole on west bound carriageway slow lane at gully outside no 309	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	18/02/2020	18/02/2020	Act. ROAD/82032902