

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: St John's Road (7903285)			Locality: Corstorphine, Edinburgh, City of Edinburgh			Area: North West Locality		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality		
Batch: 41270379 - Inspection Batch			Route: NW_FW1_Corstorphine1			Date: 01/09/2026		
42214075	Remove old pole stump and make safe with tar	01/09/2026	Outside 63	RD: Other Defect Type	Internal		Committed	50201975
42214072	Patch required approx 1m x 1m	01/09/2026	Outside bank of Scotland	RD: CW Cracked/Broken	Internal		Uncommitted	50201972
42214077	1 pothole	01/09/2026	Outside old bank of Scotland	RD: CW Pothole	Internal		Committed	50201977
Batch: 41269559 - Inspection Batch			Route: Ad hoc Route			Date: 19/08/2026		
42213194	Missing water toby cover and damaged frame on footpath	19/08/2026	Opposite Toby Carvery on footpath	RU: Utility Apparatus	Internal		Uncommitted	50201472
Batch: 41269419 - Inspection Batch			Route: Ad hoc Route			Date: 17/08/2026		
42213074	Missing Toby cover	17/08/2026	Opposite toby carvery	RU: Utility Apparatus	Internal		Uncommitted	50201376
Batch: 41269167 - Inspection Batch			Route: North Mobile Inspection Route			Date: 12/08/2026		
No actionable defects found								
Batch: 41269056 - Inspection Batch			Route: SfP_NorthWest			Date: 11/08/2026		
No actionable defects found								
Batch: 41269005 - Inspection Batch			Route: Ad hoc Route			Date: 10/08/2026		
42212787	1 number pothole	10/08/2026	At bus stop opposite Nationwide Bank	RD: CW Pothole	Internal		Committed	50201150
Batch: 41268932 - Inspection Batch			Route: Ad hoc Route			Date: 07/08/2026		
42212727	1 number pothole	07/08/2026	At exit of roundabout heading towards city	RD: CW Pothole	Internal		Committed	50201091
Batch: 41268833 - Inspection Batch			Route: NW_FW1_Corstorphine1			Date: 05/08/2026		
42212604	1 pothole	05/08/2026	Outside guitar guitar	RD: CW Pothole	Internal		Committed	50200992
42212602	Patch required Approx 2m x 1.5m	05/08/2026	Outside 26	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50169888
Batch: 41268576 - Inspection Batch			Route: Ad hoc Route			Date: 03/08/2026		
42212422	2number potholes	03/08/2026	Opposite number 87	RD: CW Pothole	Internal		Committed	50200835
Batch: 41268573 - Inspection Batch			Route: Ad hoc Route			Date: 03/08/2026		
42212420	1 number pothole	03/08/2026	At lamppost SBL13	RD: CW Pothole	Internal		Committed	50200833
Batch: 41267258 - Inspection Batch			Route: Ad hoc Route			Date: 14/07/2026		
42211132	1 number pothole	14/07/2026	Opposite number 73	RD: CW Pothole	Internal		Committed	50199929
Batch: 41267159 - Inspection Batch			Route: SfP_NorthWest			Date: 14/07/2026		
No actionable defects found								
Batch: 41266836 - Inspection Batch			Route: North Mobile Inspection Route			Date: 08/07/2026		
No actionable defects found								
Batch: 41266696 - Inspection Batch			Route: NW_FW1_Corstorphine1			Date: 07/07/2026		
42210600	Relay 6 rocking & uneven perfectas	07/07/2026	Outside pizza hut	RD: FW Slabs Rocking	Internal		Committed	50199620
42210608	1 pothole	07/07/2026	Outside 83	RD: CW Pothole	Internal		Committed	50199623
42210594	Relay 1 rocking slab	07/07/2026	Outside Dunbar funeral care	RD: FW Slabs Rocking	Internal		Committed	50199616

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41266696 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 07/07/2026
42210584	Replace 1 broken perfecta Replace 1 missing perfecta Relay 1 rocking perfecta	07/07/2026	Outside the white lady	RD: FW Slabs Broken/Missing	Internal		Committed	50199612
42210581	1 pothole	07/07/2026	Outside 32	RD: FW HRA Pothole	Internal		Committed	50199609
Batch:	41265925 - Inspection Batch			Route:	Ad hoc Route			Date: 23/06/2026
42209596	Manhole on carriageway low and damaging surrounding surface previous LA Ref: 1735260	23/06/2026	Outside number 83	RU: Utility Apparatus	Internal		Uncommitted	50198952
Batch:	41265921 - Inspection Batch			Route:	Ad hoc Route			Date: 23/06/2026
42209592	1 number pothole	23/06/2026	Outside number 192	RD: CW Pothole	Internal		Committed	50198948
Batch:	41265810 - Inspection Batch			Route:	Ad hoc Route			Date: 22/06/2026
42209355	1 number pothole	22/06/2026	At entrance to old Bank Of Scotland heading into town	RD: CW Pothole	Internal		Committed	50198814
Batch:	41264983 - Inspection Batch			Route:	Ad hoc Route			Date: 08/06/2026
42208381	1 number pothole	08/06/2026	Outside number 305 on crossing	RD: CW Pothole	Internal		Committed	50198152
Batch:	41264481 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 01/06/2026
42207780	1 pothole	01/06/2026	Outside 297	RD: FW HRA Pothole	Internal		Committed	50197803
Batch:	41264257 - Inspection Batch			Route:	Ad hoc Route			Date: 28/05/2026
42207462	1 number pothole	28/05/2026	At junction of Kaimes Road	RD: CW Pothole	Internal		Committed	50197599
Batch:	41263973 - Inspection Batch			Route:	SfP_NorthWest			Date: 26/05/2026
	No actionable defects found							
Batch:	41263652 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 20/05/2026
	No actionable defects found							
Batch:	41263364 - Inspection Batch			Route:	Ad hoc Route			Date: 18/05/2026
42206575	1 number pothole	18/05/2026	Outside St Ninians church	RD: CW Pothole	Internal		Committed	50196992
Batch:	41263360 - Inspection Batch			Route:	Ad hoc Route			Date: 18/05/2026
42206569	1 number pothole	18/05/2026	Opposite number 85 eastbound	RD: CW Pothole	Internal		Committed	50196990
Batch:	41263277 - Inspection Batch			Route:	Ad hoc Route			Date: 15/05/2026
42206476	1 number pothole	15/05/2026	Outside St Anne's church	RD: CW Pothole	Internal		Committed	50196920
Batch:	41262188 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 01/05/2026
	No actionable defects found							
Batch:	41262087 - Inspection Batch			Route:	SfP_NorthWest			Date: 30/04/2026
	No actionable defects found							
Batch:	41260971 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 14/04/2026
	No actionable defects found							

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41260889 - Inspection Batch		Route:	Ad hoc Route			Date:	14/04/2026
42204166	Utility cover broken	14/04/2026	At the junction of saint johns road and balgrave road	RU: Utility Apparatus	Internal		Uncommitted	50195375
Batch:	41260179 - Inspection Batch		Route:	NW_FW1_Corstorphine1			Date:	02/04/2026
42203615	Loose box on footway (This has been reported twice before LA ref 3725248 and 3721581)	02/04/2026	Outside farmers autocare	RU: Utility Apparatus	Internal		Uncommitted	50194900
42203619	5 potholes	02/04/2026	Outside 299	RD: FW HRA Pothole	Internal		Committed	50194903
42203622	1 pothole	02/04/2026	Outside 190a	RD: CW Pothole	Internal		Committed	50194904
42203611	1 pothole	02/04/2026	Outside 83	RD: CW Pothole	Internal		Committed	50194898
Batch:	41259851 - Inspection Batch		Route:	Ad hoc Route			Date:	31/03/2026
42203373	Heaving tar	31/03/2026	At bus stop Charles Wilson Butcher	RD: CW Subsidence/Heaving	Internal		Uncommitted	50194765
Batch:	41259616 - Inspection Batch No actionable defects found		Route:	Mobile Inspection Strategic			Date:	29/03/2026
Batch:	41259412 - Inspection Batch No actionable defects found		Route:	SfP_NorthWest			Date:	26/03/2026
Batch:	41259292 - Inspection Batch		Route:	Ad hoc Route			Date:	25/03/2026
42202962	Cracked broken Fw surface	25/03/2026	From 297 to junction of Meadowplace Road.	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50194529
Batch:	41258859 - Inspection Batch No actionable defects found		Route:	Mobile Inspection Strategic			Date:	22/03/2026
Batch:	41258057 - Inspection Batch No actionable defects found		Route:	Mobile Inspection Strategic			Date:	15/03/2026
Batch:	41257287 - Inspection Batch No actionable defects found		Route:	North Mobile Inspection Route			Date:	09/03/2026
Batch:	41257180 - Inspection Batch No actionable defects found		Route:	Mobile Inspection Strategic			Date:	08/03/2026
Batch:	41257035 - Inspection Batch No actionable defects found		Route:	SfP_NorthWest			Date:	06/03/2026
Batch:	41256909 - Inspection Batch		Route:	NW_FW1_Corstorphine1			Date:	05/03/2026
42201367	Patch required Approx 2m x 2m	05/03/2026	Outside 303	RD: CW Cracked/Broken	Internal		Committed	50179393
42201366	Relay 1 rocking & 2 sunken slabs	05/03/2026	Outside pizza hut	RD: FW Slabs Rocking	Internal		Committed	50193369
42201368	1 pothole	05/03/2026	Outside 303	RD: CW Pothole	Internal		Committed	50193370
Batch:	41256007 - Inspection Batch No actionable defects found		Route:	Mobile Inspection Strategic			Date:	01/03/2026
Batch:	41254597 - Inspection Batch		Route:	Mobile Inspection Strategic			Date:	22/02/2026
42200227	2no Cw potholes	22/02/2026	Outside no26	RD: CW Pothole	Internal		Committed	50192533
42200228	1no Cw pothole	22/02/2026	Opposite no85	RD: CW Pothole	Internal		Committed	50192534

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41254004 - Inspection Batch		Route:	Ad hoc Route			Date:	18/02/2026
42199776	2no potholes	18/02/2026	just after roundabout in eastbound lane.	RD: CW Pothole	Internal		Committed	50192143
Batch:	41253910 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2026
42199739	1no pothole	17/02/2026	pothole on westbound lane	RD: CW Pothole	Internal		Committed	50192105
Batch:	41253489 - Inspection Batch		Route:	Mobile Inspection Strategic			Date:	14/02/2026
42199438	1no pothole	14/02/2026	At the corner of St Ninian's Road	RD: CW Pothole	Internal		Committed	50191867
42199436	2no potholes	14/02/2026	Near the junction with Corstorphine Bank Drive	RD: CW Pothole	Internal		Committed	50191865
42199442	1no pothole	14/02/2026	At the bus stop outside St Anne Church	RD: CW Pothole	Internal		Committed	50191870
42199437	1no pothole	14/02/2026	Outside no192	RD: CW Pothole	Internal		Committed	50191866
42199439	1no pothole	14/02/2026	Opposite no73	RD: CW Pothole	Internal		Committed	50191868
Batch:	41253268 - Inspection Batch		Route:	Ad hoc Route			Date:	13/02/2026
42199353	1 cw pothole	13/02/2026	Outside 303	RD: CW Pothole	Internal		Committed	50191784
Batch:	41252203 - Inspection Batch		Route:	Mobile Inspection Strategic			Date:	07/02/2026
42198730	1no pothole	07/02/2026	Outside the old Bank of Scotland	RD: CW Pothole	Internal		Committed	50191299
42198731	2no potholes	07/02/2026	Outside no24	RD: CW Pothole	Internal		Committed	50191300
42198726	1no pothole	07/02/2026	Outside no303	RD: CW Pothole	Internal		Committed	50191295
42198732	2no potholes	07/02/2026	Opposite no79	RD: CW Pothole	Internal		Committed	50191301
Batch:	41252024 - Inspection Batch		Route:	NW_FW1_Corstorphine1			Date:	05/02/2026
42198631	Sunken box on fw	05/02/2026	Outside farmers autocare	RU: Utility Apparatus	Internal		Uncommitted	50191217
Batch:	41251861 - Inspection Batch		Route:	North Mobile Inspection Route			Date:	04/02/2026
	No actionable defects found							
Batch:	41251291 - Inspection Batch		Route:	Mobile Inspection Strategic			Date:	31/01/2026
42198137	1no pothole	31/01/2026	Outside no281	RD: CW Pothole	Internal		Committed	50190829
Batch:	41251003 - Inspection Batch		Route:	Ad hoc Route			Date:	29/01/2026
42197956	Refresh yellow box junction	29/01/2026	At junction of Manse Road	RD: Markings Refresh	Internal		Uncommitted	50190694
Batch:	41251000 - Inspection Batch		Route:	Ad hoc Route			Date:	29/01/2026
42197952	2no potholes	29/01/2026	Outside 192	RD: CW Pothole	Internal		Committed	50190690
Batch:	41249928 - Inspection Batch		Route:	Mobile Inspection Strategic			Date:	25/01/2026
	No actionable defects found							
Batch:	41249838 - Inspection Batch		Route:	Ad hoc Route			Date:	23/01/2026
42197409	old sign stump needing cut down further as it still presents a tripping hazard	23/01/2026	At the junction for Belgrave Road	RD: Unlit Sign Damaged/Missing	Internal		Committed	50190253
	Please make this safe, and cover with appropriate material- thank you							
Batch:	41249813 - Inspection Batch		Route:	Ad hoc Route			Date:	23/01/2026
42197397	1 cw pothole	23/01/2026	Outside 303	RD: CW Pothole	Internal		Committed	50190241

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South			Feature Type: Road Asset		Area: North West Locality	
Batch: 41248906 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 18/01/2026	
No actionable defects found								
Batch: 41248798 - Inspection Batch			Route: Ad hoc Route				Date: 17/01/2026	
42196768	1 number pothole	17/01/2026	Outside St Ninians Church	RD: CW Pothole	Internal		Committed	50189773
Batch: 41248259 - Inspection Batch			Route: SfP_NorthWest				Date: 14/01/2026	
42196518	1no pothole	14/01/2026	Opposite Mimis bakehouse	RD: CW Pothole	Internal		Committed	50189581
Batch: 41247796 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 11/01/2026	
42196326	1no pothole	11/01/2026	Outside no192	RD: CW Pothole	Internal		Committed	50189440
Batch: 41247160 - Inspection Batch			Route: NW_FW1_Corstorphine1				Date: 07/01/2026	
42196193	Replace 3 broken 400 x 400 perfectas Relay 8 rocking / uneven perfectas	07/01/2026	Outside 62	RD: FW Slabs Broken/Missing	Internal		Committed	50189312
42196187	Replace damaged railings	07/01/2026	Outside Napole pizzeria	RD: Railing Damage/Missing/New	Internal		Committed	50189306
Batch: 41246743 - Inspection Batch			Route: Ad hoc Route				Date: 31/12/2025	
42195976	1no pothole	31/12/2025	Outside St Ninians Church	RD: CW Pothole	Internal		Committed	50189120
Batch: 41246742 - Inspection Batch			Route: North Mobile Inspection Route				Date: 31/12/2025	
42195977	1no pothole	31/12/2025	Outside no24	RD: CW Pothole	Internal		Committed	50189121
42195975	1no pothole	31/12/2025	Outside Neilsons	RD: CW Pothole	Internal		Committed	50189119
Batch: 41246392 - Inspection Batch			Route: Ad hoc Route				Date: 29/12/2025	
42195835	1no pothole	29/12/2025	Outside no303	RD: CW Pothole	Internal		Committed	50188988
Batch: 41245735 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 22/12/2025	
No actionable defects found								
Batch: 41244508 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 15/12/2025	
42195183	Collapsed telephone box New World Telephone Company No contact details for this company	15/12/2025	On the footway outside Costa Coffee	RU: Utility Apparatus	Internal		Uncommitted	50188453
Batch: 41244275 - Inspection Batch			Route: Ad hoc Route				Date: 11/12/2025	
42195035	Double cable tv manhole on footway	11/12/2025	St John's Road outside 221 b	RU: Utility Apparatus	Internal		Uncommitted	50188320
Batch: 41243872 - Inspection Batch			Route: NW_FW1_Corstorphine1				Date: 05/12/2025	
42194795	Relay 2 rocking slabs Replace 2 broken and 5 missing slabs (400 x 400)	05/12/2025	Outside dean and caivin	RD: FW Slabs Broken/Missing	Internal		Committed	50188140
42194794	1 cw pothole	05/12/2025	Outside vantage point	RD: CW Pothole	Internal		Committed	50188139
42194789	1no pothole	05/12/2025	At the bus stop outside Greggs	RD: CW Pothole	Internal		Committed	50188080
42194787	Patch required Approx 2m x 2m	05/12/2025	Outside 303	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41243782 - Inspection Batch			Route: SfP_NorthWest				Date: 04/12/2025	
No actionable defects found								
Batch: 41243771 - Inspection Batch			Route: Ad hoc Route				Date: 04/12/2025	
42194711	1no pothole	04/12/2025	At the bus stop outside Greggs	RD: CW Pothole	Internal		No Action Required	

Effective: 26/11/2024 to 02/09/2026
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality		
Batch: 41243117 - Inspection Batch				Route: Ad hoc Route		Date: 28/11/2025		
42194242	No2 potholes	28/11/2025	Outside 192	RD: CW Pothole	Internal		Committed	50187719
Batch: 41242882 - Inspection Batch				Route: Ad hoc Route		Date: 26/11/2025		
42194025	Sunken cover	26/11/2025	Opposite the village cafe	RU: Utility Apparatus	Internal		Uncommitted	50187552
Batch: 41242880 - Inspection Batch				Route: Ad hoc Route		Date: 26/11/2025		
42194022	Potholes	26/11/2025	Outside 192-190	RD: CW Pothole	Internal		Committed	50187551
Batch: 41242879 - Inspection Batch				Route: Ad hoc Route		Date: 26/11/2025		
42194020	All markings refresh	26/11/2025	Outside corstorphine hotel	RD: Markings Refresh	Internal		Uncommitted	50187550
Batch: 41242878 - Inspection Batch				Route: Ad hoc Route		Date: 26/11/2025		
42194018	Scottish water hydrant cover sunken and causing same to surface around it	26/11/2025	Outside 263 Dunbar funeral care in bus lane	RU: Utility Apparatus	Internal		Uncommitted	50187549
Batch: 41242872 - Inspection Batch				Route: Ad hoc Route		Date: 26/11/2025		
42194014	Sunken cover in bus lane	26/11/2025	Outside 192	RU: Utility Apparatus	Internal		Uncommitted	50187546
Batch: 41242707 - Inspection Batch				Route: North Mobile Inspection Route		Date: 25/11/2025		
No actionable defects found								
Batch: 41242691 - Inspection Batch				Route: Ad hoc Route		Date: 25/11/2025		
42193903	1no pothole	25/11/2025	At the bus stop outside St Anne's Church	RD: CW Pothole	Internal		Committed	50187479
Batch: 41242275 - Inspection Batch				Route: Ad hoc Route		Date: 21/11/2025		
42193656	No 1 pothole	21/11/2025	Outside no 204 just before lights heading into town	RD: CW Pothole	Internal		Committed	50187274
Batch: 41241682 - Inspection Batch				Route: Ad hoc Route		Date: 17/11/2025		
42193396	Parking: Other - What type of sign is it? Road sign problem, type unlit Sign facing in wrong direction. (Enquiry 2030154)	17/11/2025	174 St john's road, corstorphine	NSL: Pole or and Sign Install	Internal		Committed	50187069
Batch: 41240947 - Inspection Batch				Route: SfP_NorthWest		Date: 07/11/2025		
No actionable defects found								
Batch: 41240639 - Inspection Batch				Route: NW_FW1_Corstorphine1		Date: 04/11/2025		
42192638	2 cw potholes	04/11/2025	Outside bank of Scotland & 204	RD: CW Pothole	Internal		Committed	50186463
42192640	Patch required Approx 2m x 2m	04/11/2025	Outside 303	RD: CW Cracked/Broken	Internal		No Action Required	
42192643	Relay 2 perfectas replace 2 perfectas 400 x 400	04/11/2025	Outside vets at junction with glebe road	RD: FW Slabs Broken/Missing	Internal		Committed	50186466
42192641	1 cw pothole	04/11/2025	Outside 303	RD: CW Pothole	Internal		Committed	50186464
42192630	Patch required Approx 25m x 3m	04/11/2025	Outside vantage point	RD: CW Cracked/Broken	Internal		Uncommitted	50176481
42192637	1 cw pothole	04/11/2025	Outside 192	RD: CW Pothole	Internal		Committed	50186462
42192631	Patch required Approx 4m x 2m	04/11/2025	Outside 32	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50178061

Effective: 26/11/2024 to 02/09/2026
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality		
Batch:	41240639 - Inspection Batch			Route:	NW_FW1_Corstorphine1		Date:	04/11/2025
42192642	Sunken box on footway	04/11/2025	Outside farmer autocare	RU: Utility Apparatus	Internal		Uncommitted	50186465
Batch:	41239543 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	22/10/2025
	No actionable defects found							
Batch:	41238502 - Inspection Batch			Route:	Ad hoc Route		Date:	11/10/2025
42191035	1 pothole	11/10/2025	at lamppost SBL13	RD: CW Pothole	Internal		Committed	50185491
Batch:	41237974 - Inspection Batch			Route:	SfP_NorthWest		Date:	06/10/2025
	No actionable defects found							
Batch:	41237877 - Inspection Batch			Route:	NW_FW1_Corstorphine1		Date:	03/10/2025
	No actionable defects found							
Batch:	41237150 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	22/09/2025
	No actionable defects found							
Batch:	41236989 - Inspection Batch			Route:	Ad hoc Route		Date:	19/09/2025
42190129	1 number pot at bus stop	19/09/2025	At bus stop just passed Kirk Loan	RD: CW Pothole	Internal		Committed	50184910
Batch:	41236010 - Inspection Batch			Route:	NW_FW1_Corstorphine1		Date:	04/09/2025
	No actionable defects found							
Batch:	41235621 - Inspection Batch			Route:	SfP_NorthWest		Date:	28/08/2025
	No actionable defects found							
Batch:	41235033 - Inspection Batch			Route:	Ad hoc Route		Date:	19/08/2025
42188645	Permanent repair required	19/08/2025	Outside 20-28	RD: CW Rutting	Internal		Uncommitted	50183780
Batch:	41234910 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	18/08/2025
	No actionable defects found							
Batch:	41234638 - Inspection Batch			Route:	Ad hoc Route		Date:	13/08/2025
42188385	1no pothole	13/08/2025	Outside the Bank of Scotland	RD: CW Pothole	Internal		Committed	50183560
Batch:	41234041 - Inspection Batch			Route:	NW_FW1_Corstorphine1		Date:	01/08/2025
42187984	Patch required Approx 1.5m x 1m	01/08/2025	At Kirk loan bus stop from city	RD: CW Cracked/Broken	Internal		Uncommitted	50180669
42187981	Relay 3 rocking perfectas	01/08/2025	Outside guitar guitar	RD: FW Slabs Rocking	Internal		Committed	50183301
42187982	Relay 1 rocking perfecta	01/08/2025	Outside mimi's	RD: FW Slabs Rocking	Internal		Committed	50183302
42187985	1 cw pothole	01/08/2025	At Kirk loan bus stop from city	RD: CW Pothole	Internal		Committed	50183304
Batch:	41233878 - Inspection Batch			Route:	SfP_NorthWest		Date:	30/07/2025
	No actionable defects found							
Batch:	41233303 - Inspection Batch			Route:	North Mobile Inspection Route		Date:	18/07/2025
	No actionable defects found							
Batch:	41232144 - Inspection Batch			Route:	SfP_NorthWest		Date:	02/07/2025
	No actionable defects found							

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality		
Batch: 41232101 - Inspection Batch			Route: Ad hoc Route			Date: 02/07/2025		
42186379	Permanent repair required	02/07/2025	Junction Manse Road	RD: CW Rutting	Internal		Uncommitted	50182217
Batch: 41231969 - Inspection Batch			Route: NW_FW1_Corstopphine1			Date: 30/06/2025		
42186260	Reset gully frame	30/06/2025	Junction Clermiston Road	RD: Gully Damaged/Sunken	Internal		Committed	50162475
42186264	Patch required Approx 2m x 2m	30/06/2025	Outside 303	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41231310 - Inspection Batch			Route: Ad hoc Route			Date: 18/06/2025		
42185773	C/w patch required approx 4x1m	18/06/2025	Opposite Nationwide bank	RD: CW Subsidence/Heaving	Internal		Committed	50181652
Batch: 41231211 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 17/06/2025		
Batch: 41229666 - Inspection Batch			Route: NW_FW1_Corstopphine1			Date: 30/05/2025		
42184728	2 fw potholes	30/05/2025	Outside 297	RD: FW HRA Pothole	Internal		Committed	50180666
42184731	Patch required Approx 1.5m x 1m	30/05/2025	At Kirk loan bus stop from city	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41229396 - Inspection Batch			Route: Ad hoc Route			Date: 28/05/2025		
42184454	Permanent repair required	28/05/2025	Outside 257	RD: CW Rutting	Internal		Uncommitted	50180487
Batch: 41229268 - Inspection Batch No actionable defects found			Route: SfP_NorthWest			Date: 27/05/2025		
Batch: 41228669 - Inspection Batch			Route: Ad hoc Route			Date: 20/05/2025		
42183821	Pothole on carriageway	20/05/2025	Outside 204	RD: CW Pothole	Internal		Committed	50180100
Batch: 41228668 - Inspection Batch			Route: Ad hoc Route			Date: 20/05/2025		
42183820	Pothole on carriageway	20/05/2025	Outside 303	RD: CW Pothole	Internal		Committed	50180099
Batch: 41228405 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 15/05/2025		
Batch: 41228054 - Inspection Batch			Route: Ad hoc Route			Date: 12/05/2025		
42183354	Yellow box hatching faded	12/05/2025	Junction Clermiston Road	RD: Markings Refresh	Internal		Committed	50179826
Batch: 41227268 - Inspection Batch			Route: NW_FW1_Corstopphine1			Date: 01/05/2025		
42182677	Patch required Approx 2m x 2m	01/05/2025	Outside 303	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41226841 - Inspection Batch No actionable defects found			Route: SfP_NorthWest			Date: 25/04/2025		
Batch: 41226430 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 22/04/2025		
Batch: 41225760 - Inspection Batch			Route: Ad hoc Route			Date: 10/04/2025		
42181077	Replace damaged bike rack	10/04/2025	Outside Costa coffee	RD:BikeRack Damage/Missing/N	Internal		Uncommitted	50178400

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41225099 - Inspection Batch			Route:	Ad hoc Route			Date: 03/04/2025
42180651	Reset gully frame and reinstate carriageway	03/04/2025	Outside 144	RD: CW Rutting	Internal		Uncommitted	50178142
Batch:	41225098 - Inspection Batch			Route:	Ad hoc Route			Date: 03/04/2025
42180649	Permanent repair required	03/04/2025	Outside 157	RD: CW Rutting	Internal		Uncommitted	50178140
Batch:	41224973 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 02/04/2025
42180526	Reset gully frame	02/04/2025	Junction Clermiston Road	RD: Gully Damaged/Sunken	Internal		No Action Required	
42180533	Relay 1 rocking slab	02/04/2025	Outside the torfin	RD: FW Slabs Rocking	Internal		Committed	50178066
42180528	Relay 1 rocking slab	02/04/2025	Outside dean & cauvin	RD: FW Slabs Rocking	Internal		Committed	50178065
42180522	Patch required	02/04/2025	Outside 32	RD: FW HRA Cracked/Broken	Internal		No Action Required	
	Approx 4m x 2m							
42180539	Infill missing granite at toby	02/04/2025	Outside William hill	RD: FW Grano Pothole	Internal		Committed	50178068
Batch:	41224664 - Inspection Batch			Route:	Ad hoc Route			Date: 31/03/2025
42180238	Pothole on carriageway	31/03/2025	Outside 26,24,junction Belgrave Road	RD: CW Pothole	Internal		Committed	50177881
Batch:	41224654 - Inspection Batch			Route:	Ad hoc Route			Date: 31/03/2025
42180219	Pothole on carriageway	31/03/2025	Outside 186	RD: CW Pothole	Internal		Committed	50177868
Batch:	41224652 - Inspection Batch			Route:	Ad hoc Route			Date: 31/03/2025
42180213	Pothole on carriageway	31/03/2025	Outside 267a	RD: CW Pothole	Internal		Committed	50177867
Batch:	41224492 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 30/03/2025
	No actionable defects found							
Batch:	41223810 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 22/03/2025
	No actionable defects found							
Batch:	41223723 - Inspection Batch			Route:	SfP_NorthWest			Date: 22/03/2025
	No actionable defects found							
Batch:	41223145 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 17/03/2025
	No actionable defects found							
Batch:	41222967 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 16/03/2025
	No actionable defects found							
Batch:	41221680 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 06/03/2025
42177943	1 cw pothole at crossing	06/03/2025	Outside the white lady	RD: CW Pothole	Internal		Committed	50176483
42177962	1 cw pothole	06/03/2025	Outside 83	RD: CW Pothole	Internal		Committed	50176488
42177944	1 cw pothole	06/03/2025	Outside bank of scotland	RD: CW Pothole	Internal		Committed	50176484
42177942	Reset gully frame	06/03/2025	Junction Clermiston Road	RD: Gully Damaged/Sunken	Internal		No Action Required	
42177940	Patch required	06/03/2025	Outside vantage point	RD: CW Cracked/Broken	Internal		No Action Required	
	Approx 25m x 3m							
42177941	Patch required	06/03/2025	At lp sbl13	RD: CW Cracked/Broken	Internal		Uncommitted	50176482
	Approx 5m x 1m							
42177948	Infill missing granite around box	06/03/2025	Opposite first mortgage	RD: FW Grano Open Joint	Internal		Committed	50176485

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41221480 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 05/03/2025
	No actionable defects found							
Batch:	41221475 - Inspection Batch			Route:	Ad hoc Route			Date: 05/03/2025
42177786	Yellow box faded	05/03/2025	Junction Station Road	RD: Markings Refresh	Internal		Committed	50176392
Batch:	41220769 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 26/02/2025
42177216	1no pothole	26/02/2025	Outside no303	RD: CW Pothole	Internal		Committed	50175994
42177215	1no pothole	26/02/2025	Outside McDonald's on roundabout	RD: CW Pothole	Internal		Committed	50175993
Batch:	41220630 - Inspection Batch			Route:	SfP_NorthWest			Date: 25/02/2025
	No actionable defects found							
Batch:	41220568 - Inspection Batch			Route:	Ad hoc Route			Date: 25/02/2025
42177058	1 no pothole	25/02/2025	At bus stop	RD: CW Pothole	Internal		Committed	50175883
Batch:	41219773 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 19/02/2025
	No actionable defects found							
Batch:	41219592 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 19/02/2025
	No actionable defects found							
Batch:	41219227 - Inspection Batch			Route:	Ad hoc Route			Date: 17/02/2025
42176089	7no potholes	17/02/2025	Outside Vantage Point	RD: CW Pothole	Internal		Committed	50175161
Batch:	41219058 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 13/02/2025
	No actionable defects found							
Batch:	41218945 - Inspection Batch			Route:	Ad hoc Route			Date: 13/02/2025
42175870	Pothole on carriageway	13/02/2025	Outside 186	RD: CW Pothole	Internal		Committed	50174999
Batch:	41218420 - Inspection Batch			Route:	Ad hoc Route			Date: 11/02/2025
42175677	Pothole on carriageway	11/02/2025	Outside 16	RD: CW Pothole	Internal		Committed	50174822
Batch:	41218232 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 10/02/2025
42175463	patch required around manhole	10/02/2025	Outside 83	RD: CW Cracked/Broken	Internal		Uncommitted	50174667
Batch:	41217262 - Inspection Batch			Route:	SfP_NorthWest			Date: 03/02/2025
	No actionable defects found							
Batch:	41216959 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 30/01/2025
42174494	1no pothole	30/01/2025	At the bus stop outside St Annes Church	RD: CW Pothole	Internal		Committed	50173937
Batch:	41216958 - Inspection Batch			Route:	Ad hoc Route			Date: 30/01/2025
42174493	Pothole on carriageway	30/01/2025	Outside 281	RD: CW Pothole	Internal		Committed	50173936
Batch:	41216957 - Inspection Batch			Route:	Ad hoc Route			Date: 30/01/2025
42174492	Pothole on carriageway	30/01/2025	Outside 303	RD: CW Pothole	Internal		Committed	50173935
Batch:	41215799 - Inspection Batch			Route:	Ad hoc Route			Date: 21/01/2025
42173633	Permanent repair required	21/01/2025	Outside 16	RD: CW Rutting	Internal		Uncommitted	50173310

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41215572 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 20/01/2025
	No actionable defects found							
Batch:	41215006 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 16/01/2025
	No actionable defects found							
Batch:	41214724 - Inspection Batch			Route:	Ad hoc Route			Date: 15/01/2025
42173083	Permanent repair required	15/01/2025	Outside 186	RD: Permanent Patching	Internal		Uncommitted	50172890
Batch:	41214721 - Inspection Batch			Route:	Ad hoc Route			Date: 15/01/2025
42173080	Pothole on carriageway	15/01/2025	Outside 186	RD: CW Pothole	Internal		Committed	50172889
Batch:	41214401 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 13/01/2025
	No actionable defects found							
Batch:	41212985 - Inspection Batch			Route:	Ad hoc Route			Date: 07/01/2025
42172168	Pothole on carriageway	07/01/2025	Junction Kaimes Road	RD: CW Pothole	Internal		Committed	50172209
Batch:	41212810 - Inspection Batch			Route:	Ad hoc Route			Date: 06/01/2025
42172051	Pothole on carriageway	06/01/2025	Outside 186	RD: CW Pothole	Internal		Committed	50172103
Batch:	41212809 - Inspection Batch			Route:	Ad hoc Route			Date: 06/01/2025
42172050	Pothole on carriageway	06/01/2025	Outside 190	RD: CW Pothole	Internal		Committed	50172102
Batch:	41212808 - Inspection Batch			Route:	Ad hoc Route			Date: 06/01/2025
42172049	Pothole on carriageway	06/01/2025	Outside 303	RD: CW Pothole	Internal		Committed	50172101
Batch:	41212478 - Inspection Batch			Route:	SfP_NorthWest			Date: 30/12/2024
	No actionable defects found							
Batch:	41211848 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 23/12/2024
42171771	1no pothole	23/12/2024	O/S 186	RD: CW Pothole	Internal		Committed	50171846
Batch:	41211651 - Inspection Batch			Route:	Ad hoc Route			Date: 23/12/2024
42171666	Pothole on carriageway	23/12/2024	Outside 249	RD: CW Pothole	Internal		Committed	50171760
Batch:	41211363 - Inspection Batch			Route:	NW_FW1_Corstorphine1			Date: 18/12/2024
42171454	1 fw pothole at box	18/12/2024	Outside 307	RD: FW HRA Pothole	Internal		Committed	50171594
42171462	1 fw pothole	18/12/2024	Outside dean & Cauvin	RD: FW HRA Pothole	Internal		Committed	50171598
	Infill 1 missing slab							
42171460	Relay 1 rocking slab	18/12/2024	Outside the torfin	RD: FW Slabs Rocking	Internal		Committed	50171596
42171450	Relay 1 rocking slab at box	18/12/2024	Outside mimis	RD: FW Slabs Rocking	Internal		Committed	50171593
42171448	Please reset sunken box on fw	18/12/2024	Outside farmer autocare	RU: Utility Apparatus	Internal		Uncommitted	50171591
Batch:	41211267 - Inspection Batch			Route:	Ad hoc Route			Date: 17/12/2024
42171365	Pothole on carriageway	17/12/2024	Outside St Anne's Church	RD: CW Pothole	Internal		Committed	50171560
Batch:	41210358 - Inspection Batch			Route:	Ad hoc Route			Date: 10/12/2024
42170985	Pothole on carriageway	10/12/2024	Bus stop at Kirk Loan	RD: CW Pothole	Internal		Committed	50171225

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41210327 - Inspection Batch			Route:	Ad hoc Route			Date: 10/12/2024
42170958	Pothole on carriageway	10/12/2024	Junction St Ninian's Road	RD: CW Pothole	Internal		Committed	50171203
Batch:	41210103 - Inspection Batch			Route:	Ad hoc Route			Date: 09/12/2024
42170771	Pothole on carriageway	09/12/2024	Outside 186	RD: CW Pothole	Internal		Committed	50171061
Batch:	41209817 - Inspection Batch			Route:	Ad hoc Route			Date: 06/12/2024
42170676	Patch 1	06/12/2024	Junction with St John's Gardens	RO: Permanent Patching	Internal		Committed	50170963
Batch:	41209648 - Inspection Batch			Route:	SfP_NorthWest			Date: 04/12/2024
	No actionable defects found							
Batch:	41209514 - Inspection Batch			Route:	Ad hoc Route			Date: 04/12/2024
42170353	Patch required approx 1.5x7m	04/12/2024	At the junction with St John's Gardens	RD: CW Cracked/Broken	Internal		Committed	50170742
Batch:	41209509 - Inspection Batch			Route:	Ad hoc Route			Date: 04/12/2024
42170350	Infill 1no pothole and remove excess material	04/12/2024	At St John's gardens	RD: CW Pothole	Internal		Committed	50170739
Batch:	41209028 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 28/11/2024
	No actionable defects found							

Customer Services

Enquiry No.:	34010738	Logged by:		on:	20/01/2026 10:10
Service:	Roads General	Subject:	Road Markings: Defective	Classification:	Request for service
Desc.:	Would it be possible to perform your magic on the Edinburgh council again and get the almost invisible, extremely faint Yellow Boxes reinstated at the junction of Manse road and St John's road (outside Neilsons solicitors and estate agency).				
Location:	at Manse Road	Contact:	Cllr Alan Beal		
Plot Number:	1.00	Feature Id - Location:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset
Job Number:	50190694	Defect Number:	42197956		
Enquiry No.:	34010021	Logged by:		on:	09/06/2025 09:26
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:	o/s no 14 St Johns road, please inspect for 2 large potholes.				
Location:	o/s no 14 St Johns road	Contact:			
Plot Number:	1.00	Feature Id - Location:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset
Enquiry No.:	34009922	Logged by:		on:	12/05/2025 11:30
Service:	Roads General	Subject:	Road Markings: Defective	Classification:	Request for service
Desc.:	Please inspect for yellow box juncction St John's Road on the main road through Corstorphine .				
Location:	St John's Road	Contact:	0		
Plot Number:	1.00	Feature Id - Location:	Ward 6 - From Kames Road to Drum Brae South	Feature Type:	Road Asset
Job Number:	50179826	Defect Number:	42183354		

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 31603958

Service: Roads General

Desc.: Please log on confirm for inspector to visit site at 87 Corstorphine Road and 87 Western Terrace, might be the same address, Western Terrace is a side name on Corstorphine Road

Logged by: [REDACTED]

Subject: Traffic Sign:Defective/Damaged

on: 22/01/2026 15:48

Classification: Request for service

Note to inspector:-
Please check both sides of footway for 50 m either way for sign stumps , and or any evidence of sign hit by vehicle.
See EDIR attached giving details of accident thanks.
Take a photo of any sign damage found and not location.
Accident involved a car and pedestrian, and a sign was also damaged, so there may be a damaged wall or sign stumps or some sort other evidence a road traffic accident has occurred.

There is also bus lane sign that needs turned round to face traffic , please photograph and pass to Parking Team , NSL Contracts.

Location:	Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South
Job Number: 50190253	Defect Number: 42197409
Feature Type: Road Asset	
Enquiry No.: 2207603	Logged by: Verint CRM Connector
Service: Roads General	Subject: Public Utilities: General
Desc.:	on: 02/09/2026 11:44
Classification: General Enquiry	
Location: There are two loose Scottish Water manhole covers in front of 81 and 87 St John's Road, causing serious noise nuisance and preventing/disrupting our and our neighbours' sleep. I reported this to SW in mid-June. I contacted them in late July for an update and they said that they had applied for the necessary permit to mend them, but were waiting to hear from you. Please could you update me on the position? In case helpful, the SW reference number is CAS-3232268-X859P.	Contact:
Enquiry No.: 2206977	Logged by: Verint CRM Connector
Service: Roads General	Subject: Road: Defective / Damaged
Desc.:	on: 01/09/2026 12:30
Classification: Request for service	
Location: Pothole (repair failure)	Contact:
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South
Feature Type: Road Asset	
Enquiry No.: 2205930	Logged by: [REDACTED]
Service: Roads General	Subject: Road Markings: Defective
Desc.: From: [REDACTED]	on: 30/08/2026 14:56
Date: Saturday, August 29, 2026 at 1:04:14 PM	Classification: Request for service
To: parking.contract@edinburgh.gov.uk <parking.contract@edinburgh.gov.uk>; Customer Care <customer.care@edinburgh.gov.uk>	
Subject: Disruptive loading bag on St Johns Rd opposite the coop	
Hi	
Please can the loading bay on st johns rd be removed as it causes huge tailbacks. It is often used by people to park to get a takeaway coffee at costa or nip into the coop opposite it. The traffic is hugely busy at it needs the two lanes in use. Please see photo attached showing an example photo i took whilst being a passenger	
Many thanks,	
[REDACTED]	
Location:	Contact: [REDACTED]

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2199472	Logged by: Verint CRM Connector	on: 19/08/2026 09:23
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: On pavement opposite Toby Carvery, beside building site on corner of St Jon's Road and Manse Road. Missing utility/fire hydrant cover so deep hole exposed - trip hazard particularly for young children, elderly and visually impaired	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50201472	Defect Number: 42213194	
Enquiry No.: 2195049	Logged by: Verint CRM Connector	on: 11/08/2026 19:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Rectangular deep deep depression in middle of the road which I swerve to avoid each evening. If you are facing costa Coffee at 145 St Johns Road it is to the LHS of it in the middle of the road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2193845	Logged by: Verint CRM Connector	on: 10/08/2026 09:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge hole in rust right at the bus stop. Very dangerous	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50201150	Defect Number: 42212787	
Enquiry No.: 2191379	Logged by: Verint CRM Connector	on: 05/08/2026 13:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: near the bus stop massive hole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2189274	Logged by: Verint CRM Connector	on: 01/08/2026 17:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road is crumbling and unsafe for cyclists.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2180837	Logged by: Verint CRM Connector	on: 16/07/2026 14:44
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown. Location:Pavement. Type:Foliage / Bush		
Location: Overgrown bush causing problems using pavement and obscuring line of sight leading to road crossing	Contact:	
Enquiry No.: 2180649	Logged by:	on: 16/07/2026 11:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Various potholes		
Location: o/s zoo - heading citybound	Contact:	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2177822	Logged by: Verint CRM Connector	on: 10/07/2026 17:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Every time a heavy vehicle drove over the pothole opposite my house there would be a load bang, and occasionally it would result in my house shaking. The pot hole was repaired in February this year, but within a few days it had started to sink again, and the banging returned (photo No 1). The patched area has further sunk and a hole has appeared (photo No 2 - today) The banging has got louder and my home is again shaking when heavy vehicles drive over the hole.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50199929	Defect Number: 42211132	
Enquiry No.: 2177586	Logged by: Verint CRM Connector	on: 10/07/2026 11:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Big pot hole in road that when traffic drives over it, it makes mine and my neighbours flats rattle! This pot hole has been repaired previously however the repair didn't last long and is now worse than ever causing our flats to shudder every time a vehicle passes over it! You'll be aware that St John's Road is an extremely busy road and therefore the disruption is pretty constant even throughout the night.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2174614	Logged by: Verint CRM Connector	on: 05/07/2026 17:00
Service: Roads General	Subject: Pavement: Missing Slab / Kerb	Classification: Customer Emergency
Desc.:		
Location: There is a break in the pavement and no dropped kerbs and also a damaged surface posing a trip risk and also making it difficult to get along the pavement	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2166968	Logged by: Verint CRM Connector	on: 22/06/2026 11:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole forming from previous repair	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50198948	Defect Number: 42209592	
Enquiry No.: 2166447	Logged by: Verint CRM Connector	on: 21/06/2026 08:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two small but very deep potholes on start of St John's Road outside old bank of Scotland building on lane leading into town	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50198814	Defect Number: 42209355	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2164652	Logged by: Verint CRM Connector	on: 17/06/2026 14:28
Service: Roads General	Subject: RS Pedestrian Crossing Request	Classification: General Enquiry
Desc.: Problem: Impossible to cross 10 yards of tarmac to reach the bus stop on the other side due to non-stop flow of traffic, high speed, on St John's Road. You're taking your life in your hands trying to reach the shops, the bus stop and the ice-cream parlour. Impossible for disabled to cross - no dropped kerbs on either side. .		
Location: 162, ST. JOHNS ROAD, EDINBURGH, EH12 8AZ		
Location:	Contact:	
Enquiry No.: 2160172	Logged by: Verint CRM Connector	on: 08/06/2026 23:01
Service: Roads General	Subject: RO: Drop Crossing Request	Classification: Customer Emergency
Desc.:		
Location: This area is between the Torfin and the former Thai Kitchen. There is a break in the pavement and no continuation of the pavement. [REDACTED]	Contact:	
[REDACTED] is also a gap right beside the problem kerb		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2160156	Logged by: Verint CRM Connector	on: 08/06/2026 21:52
Service: Roads General	Subject: RO: Drop Crossing Request	Classification: Request for service
Desc.: Description: At the St John's Road end of Manse Road where the proposed Northcare property is, there is a break in the pavement with no dropped kerbs.		
Reason: [REDACTED] I was forced onto the road because I couldn't continue on the pavement		
Location: At the St John's Road end of Manse Road where the proposed Northcare property is, there is a break in the pavement with no dropped kerbs.	Contact:	
Enquiry No.: 2159615	Logged by: Verint CRM Connector	on: 08/06/2026 07:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken surface having to avoid by encroaching inner lane on right hand lane heading towards Tesco - adjacent Mimi's Bakehouse 277 St John's Rd, Corstorphine, Edinburgh EH12 7XD	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2159612	Logged by: Verint CRM Connector	on: 08/06/2026 07:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on outside lane heading towards town - opposite Alex Cole-Hamilton Offices - 151St, John's Rd, Edinburgh EH12 7SL	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2159211	Logged by: Verint CRM Connector	on: 06/06/2026 20:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a pot hole in the road that affects wheelchairs,scooters and bikes.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50198152	Defect Number: 42208381	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2154291	Logged by: Verint CRM Connector	on: 28/05/2026 11:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading towards town along St Johns Road passing Belgrave Terrace on your left then as you leave the 20mph zone after a hundred yards or so, 30 zone, on the left of the two lanes there is a long section of very badly sunken / potholed tarmac causing vehicle damage for the unwary. In fact driving along the majority of Edinburgh Roads there are many more areas in need of urgent repair if this could be proactively identified.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2154282	Logged by: Verint CRM Connector	on: 28/05/2026 10:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading along St Johns Road before you reach the Zoo on the left the outside of the 2 lanes has a square manhole which has broken on the edge creating a pothole - a few hundred yards back from the zoo but due to traffic was not easy to pinpoint the exact spot - let me know if you wish a photo	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2152679	Logged by: Verint CRM Connector	on: 25/05/2026 16:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole just outside the hotel/bar	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2147872	Logged by: Verint CRM Connector	on: 15/05/2026 17:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Full lane is broken, need resurfaced with new on st johns road, near st johns terrace	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50196990	Defect Number: 42206569	
Enquiry No.: 2147719	Logged by: Verint CRM Connector	on: 15/05/2026 12:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on St Ninians church side of the road, by a drain.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50196992	Defect Number: 42206575	
Enquiry No.: 2147516	Logged by: Verint CRM Connector	on: 15/05/2026 08:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Extreme deterioration of road surface in green way lane. Multiple pot holes, causing severe risk to cyclists and likelihood of damage to vehicles.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50196920	Defect Number: 42206476	

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2137118 Logged by: [REDACTED] on: 27/04/2026 08:10
Service: Roads General Subject: Road: General Enquiry Classification: General Enquiry
Desc.: just at the junction of Victor park terr scottish water are working here and have had to close the bus stop [REDACTED] can't get to another bus stop please can someone call him back about this matter
[REDACTED] Contact:

Enquiry No.: 2136252 Logged by: Verint CRM Connector on: 24/04/2026 17:46
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Potholes when some buses pass my flat we get excessive vibrations I am afraid it will damage my walls or ceilings. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2133440 Logged by: Verint CRM Connector on: 20/04/2026 09:46
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Deepening depression at junction citybound Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2132184 Logged by: Verint CRM Connector on: 17/04/2026 08:47
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Morning Edinburgh Council. Hope you are all well. I would just like to draw your attention to poor road surface that interfaces the kerb stones next to the Kirk Loan Bus stop on St Johns Road. Yesterday, I badly turned my ankle on this interface whilst negotiating a commuter packed bus stop [REDACTED] Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2126771 Logged by: [REDACTED] on: 07/04/2026 16:49
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: From: [REDACTED]
Date: Tuesday, April 7, 2026 at 4:20:34 PM
To: Edinburgh City Council <clarence@edinburgh.gov.uk>
Subject: Problem Report: Damaged box

Location: Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Job Number: 50195375 Defect Number: 42204166

Enquiry No.: 2122556 Logged by: Verint CRM Connector on: 30/03/2026 20:24
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Sunken / broken manhole cover exiting roundabout adjacent Bank of Scotland Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2122555	Logged by: Verint CRM Connector	on: 30/03/2026 20:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole nearby Costa Coffee St Johns Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2122547	Logged by: Verint CRM Connector	on: 30/03/2026 20:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Uneven surface on Corstorphine Road opposite turn right island for Belgrave Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2122538	Logged by: Verint CRM Connector	on: 30/03/2026 19:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken gully adjacent 83 St Johns Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2122535	Logged by: Verint CRM Connector	on: 30/03/2026 19:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Right hand lane S Johns Road heading towards zoo at the traffic lights there is a pothole for past months adjacent Neilsons Estate Agents 138/142 St John's Road Edinburgh EH12 8AY	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2122529	Logged by: Verint CRM Connector	on: 30/03/2026 19:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Undulating road at bus shelter nearby Charles Wilson Buther	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50194765	Defect Number: 42203373	
Enquiry No.: 2122521	Logged by: Verint CRM Connector	on: 30/03/2026 19:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Right hand lane heading towards McDonalds sunken section of road adjacent 2 water tobys	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2119043	Logged by: Verint CRM Connector	on: 24/03/2026 14:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This pothole is near the junction of Corstorphine bank Drive and contains a drain cover in the middle of the road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2117129	Logged by: Verint CRM Connector	on: 21/03/2026 11:56
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Pavement, westbound side between bus shelter and junction with Meadowplace Road. Busy 60 metre stretch with many elderly, disabled and people with pushchairs using regularly. Uneven surface, potholes, loose stones.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50194529	Defect Number: 42202962	
Enquiry No.: 2112681	Logged by: Verint CRM Connector	on: 14/03/2026 17:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole causing drivers to swerve ,if they notice it in time Just past crossing.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2112464	Logged by: Verint CRM Connector	on: 14/03/2026 09:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: St Johns Road (between Station Road and Kaimes Road). Road surface uneven and potholed along a stretch on the northern carriageway. Drivers forced to zig zag to avoid the worst of them.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2111560	Logged by: Verint CRM Connector	on: 12/03/2026 16:44
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: On the corner of meadowplace road/ St John's Road near the pizza restaurant - and along to the shops on St John's Road the pavement is in a shocking state. I watched an elderly lady trying to negotiate this area pushing a wheelchair. I can imagine it's he same for buggies, not to mention walking. So much for putting all money into easier for wheeling in Edinburgh. Not here. It needs repaired totally	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2108585	Logged by: Verint CRM Connector	on: 08/03/2026 12:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: After turning right out of station road heading east there is a large section of road approximately 30+ metres long that is undriveable due to the unevenness of the surface. On a single decker bus it is quite unnerving but an absolute disgrace considering this is the main road into town. The section by the Murrayfield hospital is equally as bad and in face caused the disable ramp on the bus I was on to become dislodged due to the shock and vibration.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2106667	Logged by: Verint CRM Connector	on: 04/03/2026 20:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 25cm deep pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2105422	Logged by: Verint CRM Connector	on: 03/03/2026 08:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on approach to Drumbrae oundabout has been filled in badly and has reappeared within weeks.	Contact:	
Location: Easting/Northing: 319398/672941 (55.94273, -3.292031) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 303, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 7XF, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH12 8SQ (38m away)		
Enquiry No.: 2105158	Logged by: Verint CRM Connector	on: 02/03/2026 15:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2103910	Logged by: Verint CRM Connector	on: 28/02/2026 05:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Most of the surface east bound from Clermiston Road/St Johns Road junction to the Balgreen Road junction is severely deteriorated, so much so buses will signal right from stops and move into lane 2 so as to avoid driving in the bus lane. I have damaged the front lower arms on my vehicle due to the condition of the road. Sending an assessor out to report back it's an acceptable is not good enough.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2100748	Logged by: Verint CRM Connector	on: 23/02/2026 16:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road here is an absolute disgrace with potholes. Either a cars will be damaged due to the uneven road surface or a cyclist is going to be discounted due to it.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2100327

Service: Roads General

Desc.:

Location: This pot hole has been here for a few weeks and has damaged several tyres.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 23/02/2026 09:24

Classification: Request for service

Contact:

Location:
Easting/Northing: 319339/672940 (55.94271, -3.292983)
Nearest road to the pin placed on the map (automatically generated by
OpenStreetMap): St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland,
EH12 7TZ, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH12
8SH (29m away)

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2098574

Service: Roads General

Desc.: Smallish but severe pothole juust past roundabout heading east (level with island)

Location:

Logged by:

Subject: Road: Defective / Damaged

on: 19/02/2026 15:21

Classification: Request for service

Contact:

Enquiry No.: 2098549

Service: Roads General

Desc.:

Location: Sunken manhole cover in the outside lane on the out of town direction which has been like that for over 6 months.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 19/02/2026 14:59

Classification: Request for service

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2098409

Service: Roads General

Desc.:

Location: Horizontal pothole on eastbound side of St Johns Road.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 19/02/2026 12:32

Classification: Request for service

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2097928

Service: Roads General

Desc.:

Location: Numerous pot holes along this stretch of road

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 18/02/2026 15:49

Classification: Request for service

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2097702

Service: Roads General

Desc.:

Location: all along St John's Road - potholes along the side of the road on where the red sandstone buildings are - check and repair, where necessary, all potholes

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 18/02/2026 12:05

Classification: Request for service

Contact:

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2097438	Logged by: Verint CRM Connector	on: 18/02/2026 07:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: two large potholes just off the roundabout on the citybound carriageway causing an extreme hazard due to location of a busy roundabout bus stop and pedestrian crossing this needs urgent attention	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2097165	Logged by: Verint CRM Connector	on: 17/02/2026 17:14
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: east bound. pothole in the centre of the lane.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2096150	Logged by: Verint CRM Connector	on: 16/02/2026 13:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole just after roundabout in eastbound lane.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50192143	Defect Number: 42199776	
Enquiry No.: 2095876	Logged by:	on: 16/02/2026 08:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole is a crater At least 1m by 1m and 200mm deep		
Witnessed a car being grounded by it and another nearly flipping over		
Very dangerous		
Location:	Contact:	
Enquiry No.: 2094310	Logged by: Verint CRM Connector	on: 13/02/2026 10:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This pothole was 'repaired' last week, but the repair has failed and it is now deeper than before - approx 8" deep (200mm)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2093581	Logged by: Verint CRM Connector	on: 12/02/2026 13:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: masive deep pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2092471	Logged by: Verint CRM Connector	on: 11/02/2026 08:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on westbound lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50192105	Defect Number: 42199739	
Enquiry No.: 2091005	Logged by: Verint CRM Connector	on: 08/02/2026 21:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large beast of a pothole, eastbound lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2090828	Logged by: Verint CRM Connector	on: 08/02/2026 14:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a large pothole outside my house. I reported it previously under ref 101003108602 in May 2025 and it still has not been adequately resolved. It has been filled with tar at least twice now (the last time only 2 weeks ago) and it's not good enough, it needs properly fixed.	Contact:	
The vibration caused as vehicles hit the pothole is at risk of damaging my property and my car. Pictures of the pothole and pieces of tar and debris that are being thrown into my drive and onto my car are attached.		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2090469	Logged by: Verint CRM Connector	on: 07/02/2026 15:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on outside lane before lines going west. Incredibly large and deep. Measures 38.7cm deep and 86.3cm wide. Very very dangerous.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2087711	Logged by: Verint CRM Connector	on: 03/02/2026 07:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 16a St John's Road there are numerous potholes along this stretch of road which are a hazard	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2082685	Logged by: Verint CRM Connector	on: 25/01/2026 17:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive category 1 pothole on main road just past the bus stop towards drumbrae roundabout.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2080154	Logged by: Verint CRM Connector	on: 20/01/2026 22:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 2 x large potholes on boundary of bus lane and east bound carriageway. Degrading fast due to heavy traffic on arterial route. Next to the newly painted repaired ironwork.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50190690	Defect Number: 42197952	
Enquiry No.: 2078614	Logged by: Verint CRM Connector	on: 18/01/2026 15:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: City bound outside lane at the traffic lights. Deep depression in the surface.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2075932	Logged by: Verint CRM Connector	on: 14/01/2026 09:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole has just been repaired but has disintegrated already.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50189773	Defect Number: 42196768	
Enquiry No.: 2071294	Logged by:	on: 06/01/2026 19:16
Service: Roads General	Subject: Fence: Damaged / Defective	Classification: Request for service
Desc.: Citizen GrimRealist Snagging, Esq. @CitizenSnagging Mentioned @edinhel 11 minutes ago		
See this evening that someone's trashed a couple of panels of pedestrian railings on southeast quadrant of Drumbrae South roundabout EH12. There is also what looks like black plastic debris. Needs securing & tidying up?		
Location: on southeast quadrant of Drumbrae South roundabout EH12	Contact:	
Enquiry No.: 2066091	Logged by: Verint CRM Connector	on: 30/12/2025 09:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: As well as this pothole there are also a couple of issues with the road at kerbside on same side of road towards St Ninian's Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50189120	Defect Number: 42195976	
Enquiry No.: 2062468	Logged by: Verint CRM Connector	on: 23/12/2025 04:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Big hole - tarmac has lifted looks like a large wave	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50188988	Defect Number: 42195835	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2060452	Logged by: Verint CRM Connector	on: 18/12/2025 11:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken area of road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2053285	Logged by: Verint CRM Connector	on: 04/12/2025 10:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Significant sunken / depression section of road at lights in eastbound carriageway. Dangerous for cyclists.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2052656	Logged by: Verint CRM Connector	on: 03/12/2025 08:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole outside 303	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2051916	Logged by:	on: 01/12/2025 17:02
Service: Roads General	Subject: Public Utilities: General	Classification: Request for service
Desc.: @edinhelp Rocking / subsiding hatches in pavement on St John's Road EH12 7UU today near to Wong's Chinese restaurant at number 221 ...		
Location:	Contact:	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2048992

Service: Roads General

Desc.: Decay aroun iron works

Report ID: 8464470

Logged by:

Subject: Street Furniture: Defective

on: 26/11/2025 09:14

Classification: Request for service

Category: Roads/highways

Decay

Location:

Easting/Northing: 319541/672984 (55.94314, -3.289766)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): WT Dunbar & Sons, 263, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 7XF, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH12 7XD (29m away)

Location: Decay aroun iron works

Report ID: 8464470

Contact:

Category: Roads/highways

Decay

Location:

Easting/Northing: 319541/672984 (55.94314, -3.289766)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): WT Dunbar & Sons, 263, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 7XF, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH12 7XD (29m away)

Plot Number: 1.00

Job Number: 50187549

Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South

Defect Number: 42194018

Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2048978

Service: Roads General

Desc.: Sunken iron work

Report ID: 8464464

Logged by: [REDACTED]

Subject: Street Furniture: Defective

on: 26/11/2025 09:08

Classification: Request for service

Category: Roads/highways

Decay

Location:

Easting/Northing: 319660/672980 (55.943125, -3.287856)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): The Village Café, 235, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 7XA, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH12 7XA (18m away)

Location: Sunken iron work

Report ID: 8464464

Contact:

Category: Roads/highways

Decay

Location:

Easting/Northing: 319660/672980 (55.943125, -3.287856)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): The Village Café, 235, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 7XA, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH12 7XA (18m away)

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South

Feature Type: Road Asset

Job Number: 50187552

Defect Number: 42194025

Enquiry No.: 2048511

Service: Roads General

Desc.: please see document attached. the yellow marker shows where problem is

Location: please see document attached. the yellow marker shows where problem is

Logged by: [REDACTED]

Subject: Road: Defective / Damaged

on: 25/11/2025 11:42

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South

Feature Type: Road Asset

Job Number: 50187719

Defect Number: 42194242

Enquiry No.: 2048492

Service: Roads General

Desc.: Sunken manhole cover

Location:

Logged by: [REDACTED]

Subject: Covers: Damaged / Defective

on: 25/11/2025 11:26

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South

Feature Type: Road Asset

Job Number: 50187546

Defect Number: 42194014

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 2048485	Logged by: [REDACTED]	on: 25/11/2025 11:21
Service: Roads General	Subject: Road Markings: Defective	Classification: Request for service
Desc.: Cross hatching markings invisible		
Location:	Contact: Anon	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50187550	Defect Number: 42194020	
Enquiry No.: 2048480	Logged by: [REDACTED]	on: 25/11/2025 11:16
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole on bus lane		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50187551	Defect Number: 42194022	
Enquiry No.: 2048351	Logged by: Verint CRM Connector	on: 25/11/2025 07:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot hole.Report ID: 8460632Category: Potholes	Contact:	
PotholeLocation:Easting/Northing: 320536/672842 (55.942028, -3.273796)Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): St Anne's Church, St John's Road, Corstorphine, City of Edinburgh, Alba / Scotland, EH12 6NU, United KingdomNearest postcode to the pin placed on the map (automatically generated): EH12 6NU (49m away)		
Enquiry No.: 2047184	Logged by: Verint CRM Connector	on: 22/11/2025 12:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Really big pothole on road in bus lane on the eastbound side. Watched a cyclist almost come off when he hit it. It is near the bus stop outside St Anne's church.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50187479	Defect Number: 42193903	
Enquiry No.: 2045681	Logged by: Verint CRM Connector	on: 19/11/2025 15:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken area in road at the traffic lights	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2045592	Logged by: [REDACTED]	on: 19/11/2025 13:30
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole		
Location: just after roundabout	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50187274	Defect Number: 42193656	

Effective: 26/11/2024 to 02/09/2026
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Customer Services

Enquiry No.: 2040215 Logged by: Verint CRM Connector on: 09/11/2025 08:57
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: There is a pot hole in the middle of the pedestrian crossing outside 40-42 Saint Johns Road. Every time a bus or heavy truck passes over the pothole the entire building shakes and shudders. The pot hole is getting bigger as time goes on and the road surface is breaking up. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2038824 Logged by: Verint CRM Connector on: 06/11/2025 09:14
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: There's a 50 metre stretch of road, eastbound, outside numbers 24 to 20 St John's Road. It's been deteriorating for the past five years. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2038519 Logged by: Verint CRM Connector on: 05/11/2025 14:55
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: This bus shelter road heading west from the city is a mess. It's like every 6 months it needs repairing and going on for several years. I was soaked when a lorry went through it with several other elderly people too Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2031815 Logged by: Verint CRM Connector on: 22/10/2025 12:17
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Multiple sunken areas and areas of broken / breaking surfacing. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset

Enquiry No.: 2031688 Logged by: [REDACTED] on: 22/10/2025 09:10
 Service: Roads General Subject: Street Furniture: Defective Classification: Request for service

Desc.: Please see attached
 Location: Contact:

Enquiry No.: 2025902 Logged by: Verint CRM Connector on: 09/10/2025 11:58
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: On St John's road, opposite the entrance of St. John's terrace, the road surfaces is broken over a large stretch of the road. As a result a large number of deep dents and holes (some 10cm deep) have occurred. These are particular problematic as they are on the stretch (previously) marked for cycling. [REDACTED] Contact:

Plot Number: 1.00 Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Feature Type: Road Asset
 Job Number: 50185491 Defect Number: 42191035

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2024681	Logged by: Verint CRM Connector	on: 07/10/2025 03:47
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Drum brae south bus stop for going towards the airport/ away from the city centre has glass shards and is currently broken	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2019317	Logged by: Verint CRM Connector	on: 25/09/2025 15:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The bus stop outside Charlie Wilson's also has a huge pothole in the road. Someone is going to be injured.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 2016158	Logged by: Verint CRM Connector	on: 18/09/2025 18:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole at Kirk Loan bus stop	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50184910	Defect Number: 42190129	
Enquiry No.: 2011085	Logged by: Verint CRM Connector	on: 08/09/2025 19:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken part of road on east bound carriageway, near to centre.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1994090	Logged by: Verint CRM Connector	on: 11/08/2025 13:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: A8 East bound into Edinburgh City centre, between properties 20 & 28 corstorphine road. The road is in very poor condition pot hole and very lumpy undulating road condition! Also the footpath east bound as well is in very poor undulated condition and needs repairing. Take a look!	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50183780	Defect Number: 42188645	
Enquiry No.: 1993794	Logged by: Verint CRM Connector	on: 10/08/2025 22:53
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit St Johns RC Church White direction sign has been turned and facing in wrong direction. Needs turned back.		
Location: St Johns RC Church White direction sign has been turned and facing in wrong direction. Needs turned back.	Contact:	
Enquiry No.: 1987241	Logged by: Verint CRM Connector	on: 29/07/2025 20:31
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Outside Costa on St Johns Road , bike stand has been struck and is unusable	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1971547	Logged by: Verint CRM Connector	on: 01/07/2025 10:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is hole or a dip right on the center of the junction . It is right on the white Stop line . The road has dipped	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50182217	Defect Number: 42186379	
Enquiry No.: 1966839	Logged by:	on: 23/06/2025 10:23
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Tree branch obstructing entrance to property		
Location: o/s no 184	Contact:	
Enquiry No.: 1965290	Logged by:	on: 18/06/2025 10:21
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: Called to report barrier left behind after roadworks		
Location: 245 St Johns Road	Contact:	
Enquiry No.: 1965075	Logged by: Verint CRM Connector	on: 17/06/2025 19:47
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: From the eastern edge outside of 297 St John's Road past 299 along to 309, then round the corner to southern edge outside of 3 Meadow Place Road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1955820	Logged by:	on: 30/05/2025 08:29
Service: Roads General	Subject: Roadworks: General Enquiry	Classification: General Enquiry
Desc.: Case Details		
Case RefQNE0ANC0-101003122725 [QNE0ANC0]		
ClassificationFeedback >> Compliment, suggestion or complaint >> Make a compliment, suggestion or complaint		
Associated with22, CORSTORPHINE BANK DRIVE, CORSTORPHINE, EDINBURGH, EDINBURGH, EH12 8RS		
TitleUnnecessary narrowing of road de toon, St John's Road; poor management of associated roadworks including closure of Templeland Road.		
What kind of feedback would you like to provide? complaint		
What area does your complaint relate to ? road_travel_parking Short description of complaint : Unnecessary narrowing of road de toon, St John's Road; poor management of associated roadworks including closure of Templeland Road.		
Please provide the details of the complaint : It appears corstorphine is subjected to more unnecessary road narringing, namely St John's Riad, near Featherhall Avenue. The consultation held as part of the wider (unwarranted) LTN, aka ETRO22, would have told planners this was not wanted- I specifically made retry to this section in my correspondence. Despite this, someone has seen fit to create a pinch point in this very area permanent. Someone had presumably agreed to it and funded it. All entirely inappropriate and unnecessary. Why are the residents being subjected to such egregious mischief? Who will take responsibility for it and how can it be restored? As I have said in consultation (is it possible we to see that this action was actively desired?), Corstorphine deserves better. We certainly can't take much more ineptitude		
How would you like us to deal with this? : I look forward to hearing your response. Please put me in touch with some who can actually help		
Location: St Johns Road	Contact:	

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1954204	Logged by: Verint CRM Connector	on: 27/05/2025 16:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes and Broken Surface please find the attached	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1954202	Logged by: Verint CRM Connector	on: 27/05/2025 16:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes and Broken Surface please find the attached	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1954198	Logged by: Verint CRM Connector	on: 27/05/2025 16:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes and Broken Surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50180487	Defect Number: 42184454	
Enquiry No.: 1950461	Logged by: Verint CRM Connector	on: 20/05/2025 00:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a large pothole in the bus lane heading towards drumbrae roundabout. It has gotten so bad, that when buses and lorries hit it, it causes my property (303 St John's Road) to shake. I am concerned that if left untreated it will cause some structural damage over time.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50180099	Defect Number: 42183820	
Enquiry No.: 1942271	Logged by: [REDACTED]	on: 02/05/2025 11:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Large Pothole on road		
Location: in line with BT Fibre Cabinet	Contact:	
Enquiry No.: 1937795	Logged by: Verint CRM Connector	on: 23/04/2025 21:54
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: What type of sign is it? Road sign problem, type unlit Pole with no sign on it. This is near to Ladbrokees on St Johns Road. Has been missing since at least 2018. Can pole be removed if not required.		
Location: Pole near ladbrokees/Sally Beauty is missing a sign. Missing since at least 2018. If no longer required can it be removed.	Contact:	
Enquiry No.: 1931005	Logged by: Verint CRM Connector	on: 09/04/2025 12:30
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Bike stand rail is leaning over outside Costa's	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50178400	Defect Number: 42181077	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1926754 Service: Roads General Desc.: Location: This is a bit of a rough location as it is difficult when driving to pinpoint exactly where the pothole is, as there are so many. I see there are two others marked in the area which may correspond to the one I hit.			Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 01/04/2025 12:04 Classification: Request for service Contact:		
Plot Number: 1.00 Job Number: 50178140			Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Defect Number: 42180649 Feature Type: Road Asset		
Enquiry No.: 1925933 Service: Roads General Desc.: Location: pothole eastbound carriageway			Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 30/03/2025 21:57 Classification: Request for service Contact:		
Plot Number: 1.00 Job Number: 50178142			Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Defect Number: 42180651 Feature Type: Road Asset		
Enquiry No.: 1925865 Service: Roads General Desc.: Location: Very deep (25cm+) pothole in left hand lane of carriageway			Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 30/03/2025 19:05 Classification: Request for service Contact:		
Enquiry No.: 1924765 Service: Roads General Desc.: Problem: Overgrown. Location: Pavement. Type: Foliage / Bush Location: The hedge bordering the Bank of Scotland is thorny and overhangs the pavement. I am a wheelchair user and the hedge is at my head height and I have to swerve to avoid it hitting me in the face.			Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect on: 27/03/2025 20:03 Classification: Request for service Contact:		
Enquiry No.: 1922837 Service: Roads General Desc.: Location: deep pothol			Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 24/03/2025 13:07 Classification: Request for service Contact:		
Plot Number: 1.00 Job Number: 50177867			Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Defect Number: 42180213 Feature Type: Road Asset		
Enquiry No.: 1921287 Service: Roads General Desc.: Location: various potholes along this section of road			Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 20/03/2025 19:38 Classification: Request for service Contact:		
Plot Number: 1.00 Job Number: 50177881			Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South Defect Number: 42180238 Feature Type: Road Asset		

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1913300	Logged by: Verint CRM Connector	on: 05/03/2025 04:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Long section of road in inside of eastbound carriageway badly breaking up / sunken and dangerous for cycling	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1911327	Logged by: Verint CRM Connector	on: 28/02/2025 16:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The yellow box junction on St John's Road, Edinburgh at the junction with Station Road, Edinburgh has completely faded. This is causing issues for vehicles trying exit and enter Station Road, Edinburgh. Could the yellow box junction please be repainted. Your reporting system does not allow photographs to be attached!!!	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50176392	Defect Number: 42177786	
Enquiry No.: 1909175	Logged by: Verint CRM Connector	on: 25/02/2025 09:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: large pothole forming on the carriageway outside the shops -may cause vehicle damage.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1904793	Logged by: Verint CRM Connector	on: 17/02/2025 11:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: heading east, it is just before the pedestrian lights at the Centurion pub	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1904298	Logged by: Verint CRM Connector	on: 16/02/2025 13:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very large & deep pothole in middle of East bound carriageway o/s no 138 st johns road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1903721	Logged by: Verint CRM Connector	on: 14/02/2025 14:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sizeable pothole covering both lanes and within crossing area	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1903602	Logged by: Verint CRM Connector	on: 14/02/2025 12:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There are two sunken drain covers, one after another, opposite Royal bank of Scotland and opposite the Village Cafe, Eastbound half of the main road. On the furthest west drain cover the steel rim seems to more exposed and causing a problem. I went over this one Thursday 13th February, approx 19.35 hrs and now have a damaged wheel and tyre for which there will be a damage claim submitted, either direct or through my insurers	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1902600	Logged by: Verint CRM Connector	on: 12/02/2025 13:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on eastbound side of road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50174999	Defect Number: 42175870	
Enquiry No.: 1900696	Logged by: Verint CRM Connector	on: 08/02/2025 10:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole in centre of road. Cars swerving to avoid it	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50174822	Defect Number: 42175677	
Enquiry No.: 1898859	Logged by: Verint CRM Connector	on: 05/02/2025 07:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken manhole outside Mimi's	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1890298	Logged by: Verint CRM Connector	on: 21/01/2025 14:27
Service: Roads General	Subject: Public Utilities: General	Classification: Request for service
Desc.:		
Location: SCOTTISH WATER REPAIR COMPLETED DAYS AGO AND NOT BACKFILLED, TEMP LIGHTS CAUSING HUGE TAILBACKS	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1889488	Logged by: Verint CRM Connector	on: 20/01/2025 10:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole in middle of road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50173310	Defect Number: 42173633	

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1878569	Logged by: Verint CRM Connector	on: 03/01/2025 11:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot-hole on St John's Road just West of Featherhall Avenue Eastbound	Contact:	
I have invoices for 2 separate occasions with this same pot-hole on 15/10/24 and 01/01/25. Another driver was in Farmer Autocare due to same pot-hole and is also reporting.		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1878394	Logged by: Verint CRM Connector	on: 02/01/2025 22:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: St Johns Rd at junction of Templeland Road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1878148	Logged by: Verint CRM Connector	on: 02/01/2025 14:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1878139	Logged by: Verint CRM Connector	on: 02/01/2025 14:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Severe deep hole 12" deep by approx 18" wide, potential to lead to fatality.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1878101	Logged by: Verint CRM Connector	on: 02/01/2025 13:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: mega pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1878000	Logged by: Verint CRM Connector	on: 02/01/2025 11:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a deep pothole somewhere between WT Dunbar and Magnet on St Johns Road going eastbound towards town. I hit it in the dark last night taking my son to the bus stop and overnight my tire has since burst.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1877103	Logged by: Verint CRM Connector	on: 30/12/2024 19:02
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The whole pavement from Napoli around to Tanz shop is very uneven,unsafe for elderly and infirm.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1874176	Logged by: Verint CRM Connector	on: 22/12/2024 10:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The pothole is in the road, in front of 'Salon 13' .	Contact:	
The area around the drain has previously been patched but is once again crumbling.		
The lid of the drain would appear to be loose as it rattles when driven over by traffic.		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50171760	Defect Number: 42171666	
Enquiry No.: 1871790	Logged by: Verint CRM Connector	on: 16/12/2024 13:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Drove here; can't point to the exact location, but it's on St John's Road and near the	Contact:	
bottom of Corstorphine Bank Drive, in the eastbound lane. Dangerously deep!		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1869436	Logged by: Verint CRM Connector	on: 10/12/2024 12:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Beside the pedestrian crossing - very large, deep pothole.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1869304	Logged by: Verint CRM Connector	on: 10/12/2024 09:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: If you are driving on St John's road towards drumbrae roundabout, the traffic light	Contact:	
system & road where you can turn right up Belgrave terrace needs repainted. There		
are no white lines on the road to indicate the lane cars are to be in. When it's rush		
hour, cars go into the right lane to turn right but when traffic light allows for those in		
left hand lane to go forward, vehicles on the right lane will also go forward. It's an		
accident waiting to happen and a lot of frustration / horns being used.		
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868930	Logged by: Verint CRM Connector	on: 09/12/2024 12:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868800	Logged by:	on: 09/12/2024 10:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Potholes, Heading towards city. 20 Yards back from Neilson Agents. Deep pot holes that popped callers tyre		
Location: St John's Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026

Service: Roads General

Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1868779	Logged by: Verint CRM Connector	on: 09/12/2024 10:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The issue is on the road opposite Neilson solicitors,heading into Edinburgh consists of 2 pot holes with a trench in between.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868666	Logged by: Verint CRM Connector	on: 09/12/2024 07:39
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just after Drumbrae roundabout heading towards zoo/city centre. I think on pavement side of the road. Hit a pothole which seriously damaged my husbands front left tyre. Happened on 8 December about 18.00.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868479	Logged by: Verint CRM Connector	on: 08/12/2024 12:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The pothole is on St Johns Road, heading into Edinburgh, just before Templeland Road, see photograph. Its partially obliterated the "S" of Slow in the road markings. The hole is approx 5" to 6" deep.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868432	Logged by: Verint CRM Connector	on: 08/12/2024 09:39
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Bus stop outside no.53 St Johns Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Enquiry No.: 1868397	Logged by: Verint CRM Connector	on: 07/12/2024 21:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: A large hole 2ftx3ft 6 inch deep at the lights next to fetherhall in the middle of the road back from the centurion bar when I hit the hole I thought it would have broken the suspension. It jerked my wifes back	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset
Job Number: 50171061	Defect Number: 42170771	
Enquiry No.: 1868048	Logged by: Verint CRM Connector	on: 06/12/2024 14:22
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Increasingly large amount of tar hill, from ineffective attempt to fill pothole, on pavement and kerb, creating tripping hazard, also tar blocking drain.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality	
50116529	Road Markings: Defective - request to have yellow box repainted (Enquiry 34005539)refresh yellow junction box (RD: Markings Refresh)	St John's Road junction St Ninians Road	RD: Cat 4 - Programmed	Job Complete	14/07/2022	30/11/2025	Act. ROAD/82097233
50155031	Permanent repair required to footway (75.0*2.5) (RD: FW HRA Depression/Sunken)	From 297-307	RD: Cat 3 - 60 Day	Job Committed	07/03/2024	30/05/2024	Est. ROAD/82088866
50155032	Refresh carriageway markings (RD: Markings Refresh)	Junction Clermiston Road	RD: Cat 4 - Programmed	Job Complete	07/03/2024	27/08/2026	Act. ROAD/82109264
50162475	Reset gully frame (RD: Gully Damaged/Sunken)	Junction Clermiston Road	RD: Cat 3 - 60 Day	Job Complete	17/06/2024	03/11/2025	Act. ROAD/82093867
50169911	Patch required Approx 5m x 1m (RD: CW Cracked/Broken)	At junction with St John's gardens	RD: Cat 3 - 60 Day	Job Complete	18/11/2024	11/12/2024	Act. ROAD/82098504
50170739	Infill 1no pothole and remove excess material (RD: CW Pothole)	At St John's gardens	RD: Cat 2 - 5 Day	Job Complete	04/12/2024	08/12/2024	Act. ROAD/82099069
50170742	Patch required approx 1.5x7m (RD: CW Cracked/Broken)	At the junction with St John's Gardens	RD: Cat 3 - 60 Day	Job Complete	04/12/2024	09/12/2024	Act. ROAD/82099072
50170963	Patch 1 (RO: Permanent Patching)	Junction with St John's Gardens	RO: Programmed Works	Job Committed	06/12/2024	06/12/2025	Est. ROAD/82099241
50171061	Pothole on carriageway (RD: CW Pothole)	Outside 186	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/12/2024	09/12/2024	Act. ROAD/82099314
50171203	Pothole on carriageway (RD: CW Pothole)	Junction St Ninian's Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/12/2024	10/12/2024	Act. ROAD/82099429
50171225	Pothole on carriageway (RD: CW Pothole)	Bus stop at Kirk Loan	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/12/2024	10/12/2024	Act. ROAD/82099442
50171560	Pothole on carriageway (RD: CW Pothole)	Outside St Anne's Church	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/12/2024	18/12/2024	Act. ROAD/82099738
50171593	Relay 1 rocking slab at box (RD: FW Slabs Rocking)	Outside mimis	RD: Cat 3 - 60 Day	Job Complete	18/12/2024	19/12/2024	Act. ROAD/82099770
50171594	1 fw pothole at box (RD: FW HRA Pothole)	Outside 307	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2024	18/12/2024	Act. ROAD/82099771
50171596	Relay 1 rocking slab (RD: FW Slabs Rocking)	Outside the torfin	RD: Cat 3 - 60 Day	Job Complete	18/12/2024	19/12/2024	Act. ROAD/82099773
50171598	1 fw pothole Infill 1 missing slab (RD: FW HRA Pothole)	Outside dean & Cauvin	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2024	18/12/2024	Act. ROAD/82099775
50171760	Pothole on carriageway (RD: CW Pothole)	Outside 249	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/12/2024	24/12/2024	Act. ROAD/82099868
50171846	1no pothole (RD: CW Pothole)	O/S 186	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/12/2024	27/12/2024	Act. ROAD/82099921
50172101	Pothole on carriageway (RD: CW Pothole)	Outside 303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2025	06/01/2025	Act. ROAD/82100139

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality	
50172102	Pothole on carriageway (RD: CW Outside 190 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2025	06/01/2025	Act. ROAD/82100140
50172103	Pothole on carriageway (RD: CW Outside 186 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2025	06/01/2025	Act. ROAD/82100141
50172209	Pothole on carriageway (RD: CW Junction Kaimes Road Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2025	08/01/2025	Act. ROAD/82100232
50172889	Pothole on carriageway (RD: CW Outside 186 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/01/2025	16/01/2025	Act. ROAD/82100794
50173935	Pothole on carriageway (RD: CW Outside 303 Pothole)		RG: Gully - Standard Priority	RD: Made Safe Job Complete	30/01/2025	31/01/2025	Act. ROAD/82101527
50173936	Pothole on carriageway (RD: CW Outside 281 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/01/2025	31/01/2025	Act. ROAD/82101528
50173937	1no pothole (RD: CW Pothole)	At the bus stop outside St Annes Church	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2025	31/01/2025	Act. ROAD/82101529
50174822	Pothole on carriageway (RD: CW Outside 16 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/02/2025	11/02/2025	Act. ROAD/82102232
50174999	Pothole on carriageway (RD: CW Outside 186 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/02/2025	17/02/2025	Act. ROAD/82102424
50175161	7no potholes (RD: CW Pothole)	Outside Vantage Point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2025	18/02/2025	Act. ROAD/82102560
50175883	1 no pothole (RD: CW Pothole)	At bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2025	26/02/2025	Act. ROAD/82103164
50175993	1no pothole (RD: CW Pothole)	Outside McDonald's on roundabout	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/02/2025	27/02/2025	Act. ROAD/82103257
50175994	1no pothole (RD: CW Pothole)	Outside no303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/02/2025	27/02/2025	Act. ROAD/82103258
50176392	Yellow box faded (RD: Markings Refresh)	Junction Station Road	RD: Cat 4 - Programmed	Job Complete	05/03/2025	30/11/2025	Act. ROAD/82109267
50176483	1 cw pothole at crossing (RD: CW Pothole)	Outside the white lady	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2025	07/03/2025	Act. ROAD/82103649
50176484	1 cw pothole (RD: CW Pothole)	Outside bank of scotland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2025	07/03/2025	Act. ROAD/82103651
50176485	Infill missing granite around box (RD: FW Grano Open Joint)	Opposite first mortgage	RD: Cat 4 - Programmed	Job Complete	06/03/2025	26/09/2025	Act. ROAD/82109234
50176488	1 cw pothole (RD: CW Pothole)	Outside 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2025	07/03/2025	Act. ROAD/82103656
50177867	Pothole on carriageway (RD: CW Outside 267a Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2025	01/04/2025	Act. ROAD/82104630
50177868	Pothole on carriageway (RD: CW Outside 186 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/03/2025	31/03/2025	Act. ROAD/82104631
50177881	Pothole on carriageway (RD: CW Outside 26,24,junction Belgrave Pothole)	Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2025	01/04/2025	Act. ROAD/82104639
50178065	Relay 1 rocking slab (RD: FW Slabs Rocking)	Outside dean & cauvin	RD: Cat 3 - 60 Day	Job Complete	02/04/2025	03/04/2025	Act. ROAD/82104771

Effective: 26/11/2024 to 02/09/2026
 Service: Roads General
 Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset		Area: North West Locality		
50178066	Relay 1 rocking slab (RD: FW Slabs Rocking)	Outside the torfin	RD: Cat 3 - 60 Day	Job Complete	02/04/2025	07/04/2025	Act. ROAD/82104772
50178068	Infill missing granite at toby (RD: FW Grano Pothole)	Outside William hill	RD: Cat 3 - 60 Day	Job Complete	02/04/2025	03/04/2025	Act. ROAD/82104773
50179393	Patch required Approx 2m x 2m (RD: CW Cracked/Broken)	Outside 303	RD: Cat 4 - Programmed	Job Committed	01/05/2025		ROAD/82113077
50179826	Yellow box hatching faded (RD: Markings Refresh)	Junction Clermiston Road	RD: Cat 4 - Programmed	Gully: Investigation Required	12/05/2025		ROAD/82109268
50180099	Pothole on carriageway (RD: CW Pothole)	Outside 303	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2025	21/05/2025	Act. ROAD/82106154
50180100	Pothole on carriageway (RD: CW Pothole)	Outside 204	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2025	21/05/2025	Act. ROAD/82106155
50180666	2 fw potholes (RD: FW HRA Pothole)	Outside 297	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/05/2025	02/06/2025	Act. ROAD/82106535
50181652	C/w patch required approx 4x1m (RD: CW Subsidence/Heaving)	Opposite Nationwide bank	RD: Cat 4 - Programmed	Job Committed	18/06/2025		ROAD/82107117
50183301	Relay 3 rocking perfectas (RD: FW Slabs Rocking)	Outside guitar guitar	RD: Cat 3 - 60 Day	Job Complete	01/08/2025	21/08/2025	Act. ROAD/82108176
50183302	Relay 1 rocking perfecta (RD: FW Slabs Rocking)	Outside mimi's	RD: Cat 3 - 60 Day	Job Complete	01/08/2025	19/08/2025	Act. ROAD/82108177
50183304	1 cw pothole (RD: CW Pothole)	At Kirk loan bus stop from city	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/08/2025	04/08/2025	Act. ROAD/82108179
50183560	1no pothole (RD: CW Pothole)	Outside the Bank of Scotland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/08/2025	13/08/2025	Act. ROAD/82108328
50184910	1 number pot at bus stop (RD: CW Pothole)	At bus stop just passed Kirk Loan	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/09/2025	20/09/2025	Act. ROAD/82109132
50185491	1 pothole (RD: CW Pothole)	at lamppost SBL13	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/10/2025	13/10/2025	Act. ROAD/82109595
50186462	1 cw pothole (RD: CW Pothole)	Outside 192	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/11/2025	05/11/2025	Act. ROAD/82110176
50186463	2 cw potholes (RD: CW Pothole)	Outside bank of Scotland & 204	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/11/2025	05/11/2025	Act. ROAD/82110177
50186464	1 cw pothole (RD: CW Pothole)	Outside 303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/11/2025	05/11/2025	Act. ROAD/82110178
50186466	Relay 2 perfectas replace 2 perfectas 400 x 400 (RD: FW Slabs Broken/Missing)	Outside vets at junction with glebe road	RD: Cat 3 - 60 Day	Job Complete	04/11/2025	10/11/2025	Act. ROAD/82110179
50187069	Parking: Other - What type of sign is it? Road sign problem, type unlit Sign facing in wrong direction. (Enquiry 2030154) (NSL: Pole or and Sign Install)	174 St john's road, corstorphine	Parking Operations	NSL Job Complete	17/11/2025	13/01/2026	Act. NSL/40036
50187274	No 1 pothole (RD: CW Pothole)	Outside no 204 just before lights heading into town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/11/2025	24/11/2025	Act. ROAD/82110735

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset		Area: North West Locality		
50187479	1no pothole (RD: CW Pothole)	At the bus stop outside St Anne's Church	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/11/2025	26/11/2025	Act. ROAD/82110884
50187551	Potholes (RD: CW Pothole)	Outside 192-190	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/11/2025	03/12/2025	Act. ROAD/82110932
50187719	No2 potholes (RD: CW Pothole)	Outside 192	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2025	03/12/2025	Act. ROAD/82111060
50188080	1no pothole (RD: CW Pothole)	At the bus stop outside Greggs	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/12/2025	09/12/2025	Act. ROAD/82111342
50188139	1 cw pothole (RD: CW Pothole)	Outside vantage point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/12/2025	09/12/2025	Act. ROAD/82111388
50188140	Relay 2 rocking slabs Replace 2 broken and 5 missing slabs (400 x 400) (RD: FW Slabs Broken/Missing)	Outside dean and cauvin	RD: Cat 3 - 60 Day	Job Complete	05/12/2025	23/12/2025	Act. ROAD/82111389
50188988	1no pothole (RD: CW Pothole)	Outside no303	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/12/2025	30/12/2025	Act. ROAD/82112066
50189119	1no pothole (RD: CW Pothole)	Outside Neilsons	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/12/2025	06/01/2026	Act. ROAD/82112178
50189120	1no pothole (RD: CW Pothole)	Outside St Ninians Church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/12/2025	06/01/2026	Act. ROAD/82112179
50189121	1no pothole (RD: CW Pothole)	Outside no24	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/12/2025	06/01/2026	Act. ROAD/82112180
50189306	Replace damaged railings (RD: Railing Damage/Missing/New)	Outside Napole pizzeria	RD: Cat 2 - 5 Day	Job Complete	07/01/2026	20/01/2026	Act. ROAD/82112328
50189312	Replace 3 broken 400 x 400 perfectas Relay 8 rocking / uneven perfectas (RD: FW Slabs Broken/Missing)	Outside 62	RD: Cat 3 - 60 Day	Job Complete	07/01/2026	04/02/2026	Act. ROAD/82112334
50189440	1no pothole (RD: CW Pothole)	Outside no192	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2026	12/01/2026	Act. ROAD/82112445
50189581	1no pothole (RD: CW Pothole)	Opposite Mimis bakehouse	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/01/2026	14/01/2026	Act. ROAD/82112553
50189773	1 number pothole (RD: CW Pothole)	Outside St Ninians Church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	22/01/2026	Act. ROAD/82112702
50190241	1 cw pothole (RD: CW Pothole)	Outside 303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/01/2026	26/01/2026	Act. ROAD/82113073
50190253	old sign stump needing cut down further as it still presents a tripping hazard Please make this safe, and cover with appropriate material- thank you (RD: Unlit Sign Damaged/Missing)	At the junction for Belgrave Road	RD: Cat 3 - 60 Day	Job Complete	23/01/2026	12/02/2026	Act. ROAD/82113087

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South		Feature Type: Road Asset		Area: North West Locality	
50190690	2no potholes (RD: CW Pothole)	Outside 192	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/01/2026	03/02/2026	Act. ROAD/82113433
50190829	1no pothole (RD: CW Pothole)	Outside no281	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2026	03/02/2026	Act. ROAD/82113545
50191295	1no pothole (RD: CW Pothole)	Outside no303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/02/2026	09/02/2026	Act. ROAD/82113939
50191299	1no pothole (RD: CW Pothole)	Outside the old Bank of Scotland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2026	12/02/2026	Act. ROAD/82113943
50191300	2no potholes (RD: CW Pothole)	Outside no24	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2026	09/02/2026	Act. ROAD/82113944
50191301	2no potholes (RD: CW Pothole)	Opposite no79	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2026	09/02/2026	Act. ROAD/82113945
50191784	1 cw pothole (RD: CW Pothole)	Outside 303	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	13/02/2026	13/02/2026	Act. ROAD/82114333
50191865	2no potholes (RD: CW Pothole)	Near the junction with Corstorphine Bank Drive	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	17/02/2026	Act. ROAD/82114404
50191866	1no pothole (RD: CW Pothole)	Outside no192	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	17/02/2026	Act. ROAD/82114405
50191867	1no pothole (RD: CW Pothole)	At the corner of St Ninian's Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	17/02/2026	Act. ROAD/82114406
50191868	1no pothole (RD: CW Pothole)	Opposite no73	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	17/02/2026	Act. ROAD/82114407
50191870	1no pothole (RD: CW Pothole)	At the bus stop outside St Anne Church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	16/02/2026	Act. ROAD/82114408
50192105	1no pothole (RD: CW Pothole)	pothole on westbound lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2026	18/02/2026	Act. ROAD/82114615
50192143	2no potholes (RD: CW Pothole)	just after roundabout in eastbound lane.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2026	02/03/2026	Act. ROAD/82114649
50192533	2no Cw potholes (RD: CW Pothole)	Outside no26	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2026	02/03/2026	Act. ROAD/82115002
50192534	1no Cw pothole (RD: CW Pothole)	Opposite no85	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2026	23/02/2026	Act. ROAD/82115003
50193369	Relay 1 rocking & 2 sunken slabs (RD: FW Slabs Rocking)	Outside pizza hut	RD: Cat 3 - 60 Day	Job Complete	05/03/2026	18/03/2026	Act. ROAD/82115654
50193370	1 pothole (RD: CW Pothole)	Outside 303	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/03/2026	06/03/2026	Act. ROAD/82115655
50194898	1 pothole (RD: CW Pothole)	Outside 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116856
50194903	5 potholes (RD: FW HRA Pothole)	Outside 299	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116858
50194904	1 pothole (RD: CW Pothole)	Outside 190a	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116859
50196920	1 number pothole (RD: CW Pothole)	Outside St Anne's church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2026	15/05/2026	Act. ROAD/82118436

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 6 - From Kames Road to Drum Brae South	Feature Type: Road Asset		Area: North West Locality		
50196990	1 number pothole (RD: CW Pothole)	Opposite number 85 eastbound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/05/2026	19/05/2026	Act. ROAD/82118485
50196992	1 number pothole (RD: CW Pothole)	Outside St Ninians church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/05/2026	19/05/2026	Act. ROAD/82118487
50197599	1 number pothole (RD: CW Pothole)	At junction of Kames Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/05/2026	01/06/2026	Act. ROAD/82118977
50197803	1 pothole (RD: FW HRA Pothole)	Outside 297	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/06/2026	04/06/2026	Act. ROAD/82119126
50198152	1 number pothole (RD: CW Pothole)	Outside number 305 on crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/06/2026	08/06/2026	Act. ROAD/82119370
50198814	1 number pothole (RD: CW Pothole)	At entrance to old Bank Of Scotland heading into town	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/06/2026	22/06/2026	Act. ROAD/82119922
50198948	1 number pothole (RD: CW Pothole)	Outside number 192	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2026	24/06/2026	Act. ROAD/82120016
50199609	1 pothole (RD: FW HRA Pothole)	Outside 32	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120604
50199612	Replace 1 broken perfecta Replace 1 missing perfecta Relay 1 rocking perfecta (RD: FW Slabs Broken/Missing)	Outside the white lady	RD: Cat 3 - 60 Day	Job Complete	07/07/2026	04/08/2026	Act. ROAD/82120607
50199616	Relay 1 rocking slab (RD: FW Slabs Rocking)	Outside Dunbar funeral care	RD: Cat 3 - 60 Day	Job Complete	07/07/2026	31/07/2026	Act. ROAD/82120611
50199620	Relay 6 rocking & uneven perfectas (RD: FW Slabs Rocking)	Outside pizza hut	RD: Cat 3 - 60 Day	Job Complete	07/07/2026	31/07/2026	Act. ROAD/82120615
50199623	1 pothole (RD: CW Pothole)	Outside 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120618
50199929	1 number pothole (RD: CW Pothole)	Opposite number 73	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/07/2026	16/07/2026	Act. ROAD/82120853
50200833	1 number pothole (RD: CW Pothole)	At lamppost SBL13	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/08/2026	04/08/2026	Act. ROAD/82121515
50200835	2number potholes (RD: CW Pothole)	Opposite number 87	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/08/2026	04/08/2026	Act. ROAD/82121516
50200992	1 pothole (RD: CW Pothole)	Outside guitar guitar	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2026	05/08/2026	Act. ROAD/82121679
50201091	1 number pothole (RD: CW Pothole)	At exit of roundabout heading towards city	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/08/2026	07/08/2026	Act. ROAD/82121763
50201150	1 number pothole (RD: CW Pothole)	At bus stop opposite Nationwide Bank	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/08/2026	11/08/2026	Act. ROAD/82121811
50201975	Remove old pole stump and make safe with tar (RD: Other Defect Type)	Outside 63	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2026	11/09/2026	Act. ROAD/82122447
50201977	1 pothole (RD: CW Pothole)	Outside old bank of Scotland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2026	09/09/2026	Act. ROAD/82122449

Effective: 26/11/2024 to 02/09/2026
Service: Roads General
Site: St John's Road (7903285)

Asset Number: 1.00 to 1.00
Display Action Officer: No