

Effective: 05/01/2025 to 05/01/2026

Service: Roads General

Site: Frogston Road East (7900684)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Frogston Road East (7900684)	Locality: Mortonhall, Edinburgh, City of Edinburgh	Area: South East Locality
------------------------------------	--	---------------------------

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch:	41245512 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/12/2025
	No actionable defects found							
Batch:	41242344 - Inspection Batch			Route: Ad hoc Route				Date: 24/11/2025
42193707	No 1 pothole	24/11/2025	Frogston Rd East westbound near junction with Mortonhall Park avenue just before bustop	RD: CW Pothole	Internal		Committed	50187311
Batch:	41241622 - Inspection Batch			Route: South Mobile Inspection Route				Date: 17/11/2025
	No actionable defects found							
Batch:	41241570 - Inspection Batch			Route: Ad hoc Route				Date: 17/11/2025
42193364	No 1 pothole	17/11/2025	At bustop heading west opposite lampost FFU21	RD: CW Pothole	Internal		Committed	50187037
Batch:	41238993 - Inspection Batch			Route: South Mobile Inspection Route				Date: 16/10/2025
	No actionable defects found							
Batch:	41236589 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/09/2025
	No actionable defects found							
Batch:	41235830 - Inspection Batch			Route: SE_CF1_Frogston1				Date: 02/09/2025
42189407	Patch required Approx 5m x 1m	02/09/2025	Approx 30m east of Ip ffv56	RD: CW Cracked/Broken	Internal		Uncommitted	50165543
Batch:	41235475 - Inspection Batch			Route: Ad hoc Route				Date: 27/08/2025
42189108	No 1 pothole	27/08/2025	West bound lane on the bend in road nxt to black n white road sign passed the entrance to the gym ...physique body shop	RD: CW Pothole	Internal		Committed	50184088
Batch:	41234455 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/08/2025
	No actionable defects found							
Batch:	41232791 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/07/2025
	No actionable defects found							
Batch:	41230185 - Inspection Batch			Route: South Mobile Inspection Route				Date: 05/06/2025
	No actionable defects found							
Batch:	41227661 - Inspection Batch			Route: South Mobile Inspection Route				Date: 06/05/2025
	No actionable defects found							
Batch:	41225807 - Inspection Batch			Route: South Mobile Inspection Route				Date: 10/04/2025
	No actionable defects found							
Batch:	41222750 - Inspection Batch			Route: South Mobile Inspection Route				Date: 14/03/2025
	No actionable defects found							

Effective: 05/01/2025 to 05/01/2026

Service: Roads General

Site: Frogston Road East (7900684)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41219412 - Inspection Batch			Route: Ad hoc Route				Date: 18/02/2025	
42176242	2 no potholes	18/02/2025	Bustop opposite mortonhall park avenue junction	RD: CW Pothole	Internal		Committed	50175277
Batch: 41218616 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/02/2025	
No actionable defects found								
Batch: 41213492 - Inspection Batch			Route: South Mobile Inspection Route				Date: 09/01/2025	
42172518	1no pothole	09/01/2025	At the bus stop just past Mortonhall Park Avenue	RD: CW Pothole	Internal		Committed	50172474

Customer Services

Enquiry No.: 2062522		Logged by: Verint CRM Connector		on: 23/12/2025 09:26	
Service: Roads General		Subject: Pavement: Damaged / Defective		Classification: Request for service	
Desc.:					
Location: Hoke in the pavement .. currently filled with water			Contact:		
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Enquiry No.: 2047550		Logged by: Verint CRM Connector		on: 23/11/2025 15:32	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: Pothole Frogston Rd East westbound near junction with Mortonhall Park Avenue			Contact:		
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Job Number: 50187311		Defect Number: 42193707			
Enquiry No.: 2043688		Logged by: Verint CRM Connector		on: 15/11/2025 16:59	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: There is a pothole next to the south side of the kerb			Contact:		
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Job Number: 50187037		Defect Number: 42193364			
Enquiry No.: 2009643		Logged by: Verint CRM Connector		on: 05/09/2025 12:54	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: Manholes collapsing Report ID: 8123960 Category: Potholes This obvious defect is not being addressed. Despite months of work on this junction, here we are again - already collapsing into disrepair. Manholes collapsing doubtless due to the tofu used in the original resurfacing (or dressing is it called now? Probably appropriate since the work has the traffic resilience of blue cheese). Location: Easting/Northing: 327377/668065 (55.900202, -3.163009) Nearest road to the pin placed on the map			Contact:		

Effective: 05/01/2025 to 05/01/2026
Service: Roads General
Site: Frogston Road East (7900684)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2003232 Logged by: Verint CRM Connector on: 26/08/2025 00:36
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Several potholes on the content outside physiques gym, west bound. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50184088 Defect Number: 42189108

Enquiry No.: 1982580 Logged by: Verint CRM Connector on: 21/07/2025 15:11
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: At Tree on the corner of path next to [REDACTED] Frogston Rd East is a problem - tree is too big and obscures light to both [REDACTED] Frogston Rd East and [REDACTED] Mortonhall Lower part of tree is sprouting branches blocking path and pavement on Frogston Rd East, next to bus stop - it is also beginning to attract rubbish dumping... This tree is not part of [REDACTED] Frogston Rd East, although apparently some neighbours think it is! Contact:

Enquiry No.: 1980552 Logged by: Verint CRM Connector on: 17/07/2025 16:44
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: Tree branches overhanging pavement almost opposite Broomhill Road. You have to duck under branches overhanging pavement almost opposite. Contact:

Enquiry No.: 1954934 Logged by: Verint CRM Connector on: 28/05/2025 18:05
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: This free is overgrown. The trunk has thick shoots heavily covered in leaves which encroached the public pathway into Mortonhall estate. The shoots are a danger at children's eye level. The branches hang over my gate which is on the opposite side of the pathway. It's roots have damaged my driveway. It's leaves like up on the path [REDACTED] Contact:

Enquiry No.: 1939173 Logged by: Verint CRM Connector on: 26/04/2025 20:09
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Have had several near misses when sitting in the eastbound filter lane whilst waiting to turn right into Greenwell Wynd. Traffic travelling west from Kaimes Crossroads frequently cuts corner and strays into filter lane. Apart from that, the filter lane is not properly marked as a right turn. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Effective: 05/01/2025 to 05/01/2026

Service: Roads General

Site: Frogston Road East (7900684)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1903994

Service: Roads General

Desc.:

Location: Large pothole before bus shelter and smaller one after

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 15/02/2025 12:38

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50175277

Feature Id - Location: Whole Street

Defect Number: 42176242

Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50172474	1no pothole (RD: CW Pothole)	At the bus stop just past Mortonhall Park Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2025	16/01/2025	Act. ROAD/82100446
50175277	2 no potholes (RD: CW Pothole)	Bustop opposite mortonhall park avenue junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2025	19/02/2025	Act. ROAD/82102646
50184088	No 1 pothole (RD: CW Pothole)	West bound lane on the bend in road nxt to black n white road sign passed the entrance to the gym ...physique body shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/08/2025	27/08/2025	Act. ROAD/82108624
50187037	No 1 pothole (RD: CW Pothole)	At bustop heading west opposite lampost FFU21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2025	19/11/2025	Act. ROAD/82110553
50187311	No 1 pothole (RD: CW Pothole)	Frogston Rd East westbound near junction with Mortonhall Park avenue just before bustop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/11/2025	24/11/2025	Act. ROAD/82110762