

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Lanark Road West (7906119)

Locality: Currie, Edinburgh, City of Edinburgh

Area: South West Locality

Customer Services

Enquiry No.: 34010942 **Logged by:** [REDACTED] **on:** 01/05/2026 10:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: 440 lanark road west, please inspect damaged road surface o/s property.
Location: 440 lanark road west **Contact:**

Enquiry No.: 2194108 **Logged by:** Verint CRM Connector **on:** 10/08/2026 13:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface has large ridge next to bus stop shelter **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2180772 **Logged by:** Verint CRM Connector **on:** 16/07/2026 13:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drain collapsing in road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2175764 **Logged by:** Verint CRM Connector **on:** 07/07/2026 15:15
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location: Cycleway.
Type: Foliage / Bush
Location: Butterbur is taking over half of the Water of Leith walkway on the section between Woodhall Mill Rd and the Currie Kirkgate **Contact:**

Enquiry No.: 2167046 **Logged by:** Verint CRM Connector **on:** 22/06/2026 12:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the entrance to the bowling club **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50198881 **Defect Number:** 42209487

Enquiry No.: 2155466 **Logged by:** Verint CRM Connector **on:** 30/05/2026 17:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2153607 **Logged by:** Verint CRM Connector **on:** 27/05/2026 10:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes uneven surface here just before crossing island heading East bound into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50197613 **Defect Number:** 42207476

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2150503 Service: Roads General Desc.: Location: uneven road surface potholes all over the road around here	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 21/05/2026 09:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2149531 Service: Roads General Desc.: Location: road has loads of potholes near left hand curb heading west bound	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/05/2026 16:01 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2149471 Service: Roads General Desc.: Location: Pothole at bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/05/2026 15:03 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50197106	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42206718	Feature Type: Road Asset
Enquiry No.: 2145900 Service: Roads General Desc.: Location: pothole forming here west bound near centre line	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/05/2026 11:25 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50196746	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42206181	Feature Type: Road Asset
Enquiry No.: 2145899 Service: Roads General Desc.: Location: pothole here heading east bound near centre line off road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/05/2026 11:23 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50196745	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42206180	Feature Type: Road Asset
Enquiry No.: 2138770 Service: Roads General Desc.: Location: pothole here near the curb heading west bound	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 29/04/2026 14:42 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50196123	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42205256	Feature Type: Road Asset
Enquiry No.: 2137929 Service: Roads General Desc.: Location: pothole here near middle line heading east bound	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/04/2026 10:06 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2137382 **Logged by:** [REDACTED] **on:** 27/04/2026 12:50
Service: Roads General **Subject:** Street Furniture: Defective **Classification:** Request for service
Desc.: i could not find an attribute to match the enquiry...sorry i could not access the original ref number and have therefore set up a new request which dates back to april 2024. please see document attached
Location: i could not find an attribute to match the enquiry...sorry i could not access the original ref number and have therefore set up a new request which dates back to april 2024. please see document attached **Contact:**

Enquiry No.: 2136337 **Logged by:** Verint CRM Connector **on:** 24/04/2026 22:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2135508 **Logged by:** Verint CRM Connector **on:** 23/04/2026 13:15
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: I tripped and fell badly on the uneven, broken up pavement on Lanark Road West walking east between Bryce Road and the Nether Currie bus stop. I fell forward and bashed my head and fractured my hand. The pavements all over Currie are in a shocking, dangerous state. [REDACTED] **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2135364 **Logged by:** Verint CRM Connector **on:** 23/04/2026 10:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here heading west bound around ironwork near left hand edge off road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50195968 **Defect Number:** 42204994

Enquiry No.: 2134158 **Logged by:** Verint CRM Connector **on:** 21/04/2026 10:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here near the centre white line heading west bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2133376 **Logged by:** [REDACTED] **on:** 20/04/2026 08:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Deep pothole. Difficult to avoid and getting larger
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50195957 **Defect Number:** 42204967

Enquiry No.: 2130541 **Logged by:** Verint CRM Connector **on:** 14/04/2026 14:50
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: CATV manhole cover sitting up causing a trip hazard **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2129503 **Logged by:** Verint CRM Connector **on:** 12/04/2026 19:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a pothole approximately 3ft long on the road on the left side of the road (heading east) - opposite 301 Lanark rd West. Cyclists have to swerve into the middle of the carriageway to avoid it. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2128430 **Logged by:** Verint CRM Connector **on:** 10/04/2026 11:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: I have attached photos for your information, the holes are next to traffic lights, they are horrendous & shocking, I can not believe how this is not picked up sooner many thanks **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2128245 **Logged by:** Verint CRM Connector **on:** 10/04/2026 00:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole, size or a 6x3 snooker table, can't miss it **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2125270 **Logged by:** Verint CRM Connector **on:** 04/04/2026 12:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole, on Lanark Road West just after Dolphin Avenue heading into town. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2124533 **Logged by:** Verint CRM Connector **on:** 02/04/2026 18:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface crumbling at traffic light junction. On the left side heading towards town. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2122153 **Logged by:** Verint CRM Connector **on:** 30/03/2026 12:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2122046 **Logged by:** Verint CRM Connector **on:** 30/03/2026 10:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here heading west bound near middle white line **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2121572 **Logged by:** Verint CRM Connector **on:** 29/03/2026 12:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Many crater potholes all around the bus stop area. Can't take photos due to driving **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2121510 **Logged by:** Verint CRM Connector **on:** 29/03/2026 09:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: You cant miss this one, its huge. I have no photos cause im driving **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2119291 **Logged by:** Verint CRM Connector **on:** 24/03/2026 20:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On road opposite 215 Rive House, Lanark Road West, Currie EH14 5NT. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2119286 **Logged by:** Verint CRM Connector **on:** 24/03/2026 20:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The T junction adjacent Riccarton Inn 198 Lanark Road West, Edinburgh EH14 5NX **Contact:**
- defects circled red

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2119278 **Logged by:** Verint CRM Connector **on:** 24/03/2026 19:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: See ref Your reference number is: 102000226457 **Contact:**

The repair is unsatisfactory as the surface is crumbling with potholes per new images.
Large area adjacent William Purves 348 Lanark Road West, Edinburgh, EH14 5RR.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2118753 **Logged by:** Verint CRM Connector **on:** 24/03/2026 09:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole around here near curb heading west bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2118685 **Logged by:** Verint CRM Connector **on:** 24/03/2026 08:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here heading west bound near middle of the whole road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2118562 **Logged by:** Verint CRM Connector **on:** 23/03/2026 20:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Beside flats **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2117025 **Logged by:** Verint CRM Connector **on:** 21/03/2026 08:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole on lanark road west. On left hand side if you are driving into Edinburgh. At a very awkward spot as parked cars make it very difficult to avoid **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2116449 **Logged by:** [REDACTED] **on:** 20/03/2026 08:33
Service: Roads General **Subject:** Road: General Enquiry **Classification:** General Enquiry
Desc.: Wires sticking out of pothole. This has been going on for years. The council fill it in with substandard material, then when it rains the pothole appears again. Can you not fix it properly.

Once again they're are two big potholes with cables sticking out. This is right next to the Water of Leith Visitors Centre
Location: **Contact:**

Enquiry No.: 2116220 **Logged by:** Verint CRM Connector **on:** 19/03/2026 17:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The repair to the already existing potholes is completely unacceptable and back to the exact same state as previous. **Contact:**

This is causing damage to cars pulling into the parking spaces as well as cars driving on the mail road.

This need rectified immediately and to a high standard.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50194226 **Defect Number:** 42202544

Enquiry No.: 2115543 **Logged by:** Verint CRM Connector **on:** 18/03/2026 19:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole on the road eastbound. Further huge potholes going westbound between 375 Lanark Road West and Walkmill Loan. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2115227 **Logged by:** Verint CRM Connector **on:** 18/03/2026 13:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole, been there for at least a fortnight, cars driving on wrong side of road to avoid, accident waiting to happen. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2115199 Logged by: Verint CRM Connector on: 18/03/2026 12:55
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: pothole here heading westbound Contact:

Plot Number: 1.00 Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Feature Type: Road Asset

Enquiry No.: 2114896 Logged by: Verint CRM Connector on: 18/03/2026 08:04
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Currie - adjacent William Purves
348 Lanark Road West
Edinburgh EH14 5RR
Larrge section of road rutted / pot holes at the bus stop next to Kip McGrath /
William Purves since August 2025 or earlier.

This is a dangerous hazard for unsuspecting motor cyclists / cyclists and cars
grounding when accessing the off street parking in front of William Purves.

Plot Number: 1.00 Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Feature Type: Road Asset

Enquiry No.: 2114308 Logged by: Verint CRM Connector on: 17/03/2026 10:49
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: pothole here in line with the bus stop Contact:

Plot Number: 1.00 Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Feature Type: Road Asset

Enquiry No.: 2113315 Logged by: Verint CRM Connector on: 16/03/2026 09:10
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Several holes at this difficult junction Contact:

Location:
Easting/Northing: 319179/668249 (55.900543, -3.294141)
Nearest road to the pin placed on the map (automatically generated by
OpenStreetMap): 26, Lanark Road West, Blinkbonny, Currie, City of Edinburgh, Alba
/ Scotland, EH14 5JX, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH14
5EU (69m away)

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2113310 **Logged by:** Verint CRM Connector **on:** 16/03/2026 09:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The hole is on fairly large and can be seen after passing dolphin avenue passing the park next t to the Pentlands medical practice. It will cause significant damage to cars if not treated. **Contact:**

Location:
Easting/Northing: 317726/667511 (55.89367, -3.31715)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 298, Lanark Road West, Currie, City of Edinburgh, Alba / Scotland, EH14 5RS, United Kingdom
Nearest postcode to the pin placed on the map (automatically generat

Enquiry No.: 2113299 **Logged by:** [REDACTED] **on:** 16/03/2026 08:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Couple of large spreading holes
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50193964 **Defect Number:** 42202168

Enquiry No.: 2113009 **Logged by:** Verint CRM Connector **on:** 15/03/2026 16:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Various really deep potholes. Please resurface as when cars come round the corner they dont know they are there. Theres a bus stop just up. A car could loose control due to the potholes and hit school kids. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2113004 **Logged by:** Verint CRM Connector **on:** 15/03/2026 16:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Shark fin type ridge formed in road. Its very dangerous. If a car drives over it there could be damage to a tyre leading to loss of control of vehicle and pedestrian severe injury/death. Resurface this piece of road please its dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2112883 **Logged by:** Verint CRM Connector **on:** 15/03/2026 12:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole at least a meter long needs sorted asap due to parked cars on other side of the road causing the traffic to build up and cars unable to avoid the ginormous hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2112833 Service: Roads General Desc.: Location: Large pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/03/2026 10:28 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2112770 Service: Roads General Desc.: Location: Large pothole on the road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/03/2026 21:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2112565 Service: Roads General Desc.: Location: Potholes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/03/2026 12:26 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2112533 Service: Roads General Desc.: Location: Massive crater on road been there for weeks . Edinburghs roads are an absolute embarrassment	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/03/2026 11:35 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2112254 Service: Roads General Desc.: Location: Terrible pothole beside bus stop.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/03/2026 16:37 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2111552 Service: Roads General Desc.: Problem: Causing Obstruction. Location:Footpath. Type:Foliage / Bush Location: Struggling to get my wheelchair between the hedge and bus stop without snagging my clothes	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 12/03/2026 16:36 Classification: Request for service Contact:

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2111287 **Logged by:** Verint CRM Connector **on:** 12/03/2026 12:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: As the roads bends on the Edinburgh bound lane there is a substantial pothole about 1/1.5m long and 0.5 wide 10 to 15 cm deep. Right outside 298 LRW Drivers see it at the last minute pull out to avoid it causing other traffic in the other direction to move
Its a busy road
School kids walk along
Traffic rarely drops below 30 mph
cars park on other side squeezing the road space
Water is sprayed up and over the wall
It's deep and will damage your suspension
Cyclists will see it late

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2109696 **Logged by:** Verint CRM Connector **on:** 10/03/2026 09:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Eastbound by the bus stop. Multiple potholes and deteriorating road surface.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2109694 **Logged by:** Verint CRM Connector **on:** 10/03/2026 09:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: In the eastbound lane.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2108454 **Logged by:** Verint CRM Connector **on:** 08/03/2026 07:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in centre line of road. Previous fixed Sep 25 but has returned.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50193509 **Defect Number:** 42201539

Enquiry No.: 2106441 **Logged by:** Verint CRM Connector **on:** 04/03/2026 13:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Two massive pot holes right outside William Purves Funeral Directors, 348 Lanark Road West, Currie, one of the holes is a crater, really deep and dangerous

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2106053 **Logged by:** Verint CRM Connector **on:** 04/03/2026 00:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There's a pothole on the road

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2105887 **Logged by:** Verint CRM Connector **on:** 03/03/2026 16:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: This is roughly a 5ft long pot hole that has already been reported a few times in the last few weeks and has been repaired twice but due to this being a busy road and needs repaired again. Exposed cables as well
Location: Outside NO 9 Lanard RD West (Currie side) just as you come out of Juniper Green **Contact:**

Enquiry No.: 2104266 **Logged by:** Verint CRM Connector **on:** 01/03/2026 07:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are 4 substantial pot holes that have now created 1 large pot hole. **Contact:**
Multiple cars park at the funeral directors every day & residents park their cars there at night.

Pulling into these spaces is now damaging the suspension on my car because of how bad these holes are.

They need immediately repaired, not just filled.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2104009 **Logged by:** Verint CRM Connector **on:** 28/02/2026 10:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Three deep potholes at bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2104007 **Logged by:** Verint CRM Connector **on:** 28/02/2026 10:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface breaking up. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2103027 **Logged by:** Verint CRM Connector **on:** 26/02/2026 16:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes just past Bus stop outside William Purves Funeral Directore **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2101464 **Logged by:** Verint CRM Connector **on:** 24/02/2026 16:04
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:

Location: The water stopcock for 98 Lanark Road West is situated on the opposite side of the road in the gutter/pavement edge outside my driveway at 99 LR West. It was painted blue last year and for sometime has been dangerous for tyre damage of vehicles accessing the driveway of number 99. No.98 is being renovated and workmen have been using the stopcock recently. It now represents a serious threat to tyres when accessing my driveway. I am in my 80s and have had a stroke so a photo could be tricky.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50192693 **Defect Number:** 42200438

Enquiry No.: 2100244 **Logged by:** Verint CRM Connector **on:** 23/02/2026 07:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2099930 **Logged by:** Verint CRM Connector **on:** 22/02/2026 13:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2099921 **Logged by:** Verint CRM Connector **on:** 22/02/2026 12:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Opposite No 351, at bus stop into city centre, 3 potholes in line. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2099776 **Logged by:** Verint CRM Connector **on:** 21/02/2026 21:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Approx location: <https://maps.app.goo.gl/6tPtQ7GPFVcCCjA79>
55.8909769, -3.3267961 **Contact:**

Significant flooding in roadway heading west, vehicles need to cross into opposite side of road, deep pothole is also throwing significant water into oncoming traffic.

Enquiry No.: 2099763 **Logged by:** Verint CRM Connector **on:** 21/02/2026 21:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: potholes and crumbling surface around lights **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2099716 **Logged by:** Verint CRM Connector **on:** 21/02/2026 17:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Flooding across carriageway at dip in the road. Never seen flooding as bad there. **Contact:**
Also a pothole at this location near centre of road. Must be gully blocked

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2099018 **Logged by:** Verint CRM Connector **on:** 20/02/2026 11:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes on road adjacent to pedestrian island **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2098671 **Logged by:** Verint CRM Connector **on:** 19/02/2026 17:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken/settled utilities transverse crossing over Balerno bound carriageway and **Contact:**
maybe city bound carriageway as well. Noticeable bump when you cross

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50192373 **Defect Number:** 42200023

Enquiry No.: 2097441 **Logged by:** Verint CRM Connector **on:** 18/02/2026 08:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Just by the bus stop citybound where the road is breaking up from the channel with **Contact:**
potholes formed.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2097158 **Logged by:** Verint CRM Connector **on:** 17/02/2026 17:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Lanark Road West on the East bound carriageway covering 30m up to the traffic **Contact:**
lights at junction with Blinkbonny Road.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2095394 **Logged by:** Verint CRM Connector **on:** 15/02/2026 10:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2095307 **Logged by:** Verint CRM Connector **on:** 14/02/2026 23:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50192045 **Defect Number:** 42199673

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2095306 **Logged by:** Verint CRM Connector **on:** 14/02/2026 23:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: HUGE POTHOLE AFFECTING TRAFFIC AND PEDESTRIANS **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2095111 **Logged by:** Verint CRM Connector **on:** 14/02/2026 15:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Near the flats **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2095106 **Logged by:** Verint CRM Connector **on:** 14/02/2026 15:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094941 **Logged by:** Verint CRM Connector **on:** 14/02/2026 10:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The whole road is a disgrace. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094860 **Logged by:** Verint CRM Connector **on:** 13/02/2026 22:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2ft wide pothole on east bound carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094840 **Logged by:** Verint CRM Connector **on:** 13/02/2026 21:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094839 **Logged by:** Verint CRM Connector **on:** 13/02/2026 21:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2094617 **Logged by:** Verint CRM Connector **on:** 13/02/2026 15:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is massive pothole on Lanark Road West between Dolphin Avenue and Currie Community Centre. Its going to cause some damage to cars and then lots of compensation claims to the council if not sorted. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094451 **Logged by:** Verint CRM Connector **on:** 13/02/2026 12:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here heading westbound near the middle centre white dotted line **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094299 **Logged by:** Verint CRM Connector **on:** 13/02/2026 10:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: massive piece of road broken up and disappered leaving large pothole now here near curb heading into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2094161 **Logged by:** Verint CRM Connector **on:** 13/02/2026 07:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large water filled pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2093951 **Logged by:** Verint CRM Connector **on:** 12/02/2026 18:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Opposite Currie Community Centre by bus stop and also one by traffic lights before this
Stood at bus stop and got covered in water several times by passing cars as there was no where to go to avoid the pot holes whilst waiting for the bus. The main one covers almost three quarters of the width of the road travelling towards Balerno. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50191754 **Defect Number:** 42199321

Enquiry No.: 2092964 **Logged by:** Verint CRM Connector **on:** 11/02/2026 16:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole at the junction of Lanark Road West and Dolphin Avenue, Currie **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2092791 Service: Roads General Desc.: Location: pothole here heading out of town near the bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/02/2026 14:12 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191652	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42199180	Feature Type: Road Asset
Enquiry No.: 2092225 Service: Roads General Desc.: Location: Pothole on west bound road surface	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/02/2026 17:48 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191579	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42199103	Feature Type: Road Asset
Enquiry No.: 2091817 Service: Roads General Desc.: Pothole Report ID: 8869125 Category: Potholes Pothole Location: Easting/Northing: 317720/667513 (55.893685, -3.317243) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 298, Lanark Road West, Currie, City of Edinburgh, Alba / Scotland, EH14 5RS, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH14 5RT (36m away) Location: Pothole Report ID: 8869125 Category: Potholes Pothole Location: Easting/Northing: 317720/667513 (55.893685, -3.317243) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 298, Lanark Road West, Currie, City of Edinburgh, Alba / Scotland, EH14 5RS, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH14 5RT (36m away)	Logged by:  Subject: Road: Defective / Damaged	on: 10/02/2026 09:31 Classification: Request for service Contact:
Enquiry No.: 2090959 Service: Roads General Desc.: Location: Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 08/02/2026 18:54 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset
Enquiry No.: 2090879 Service: Roads General Desc.: Location: Huge hole in road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 08/02/2026 16:18 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409	Feature Type: Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2090670 **Logged by:** Verint CRM Connector **on:** 08/02/2026 10:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Humongous hole on the left hand side of the road close to the kerb, major issue has cars driving on this side of the road have to place themselves closer to the kerb to allow traffic to pass on the other side of the road due to parked cars **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2090447 **Logged by:** Verint CRM Connector **on:** 07/02/2026 14:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole developing **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2090445 **Logged by:** Verint CRM Connector **on:** 07/02/2026 14:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface breaking up potholes developing **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2090042 **Logged by:** Verint CRM Connector **on:** 06/02/2026 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole in nearside channel - growing daily and is full depth of wearing course of asphalt - approx 800x400mm **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2089295 **Logged by:** Verint CRM Connector **on:** 05/02/2026 12:35
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: I am writing to report a serious concern regarding several trees located at neighbours property which I believe present a danger to public safety and my property.

Over recent years, these trees have caused ongoing problems, including falling branches and debris. As a result, I am increasingly concerned that without intervention, there will be serious injury as branches are falling where my grandchildren play, with one branch falling last week onto the decking measuring over 10feet. **Contact:**

Enquiry No.: 2088550 **Logged by:** Verint CRM Connector **on:** 04/02/2026 11:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: potholes and various breakup parts of the road here near the curb heading west bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2086922 **Logged by:** Verint CRM Connector **on:** 01/02/2026 18:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Significant depression in road surface prior to traffic lights. Same area as previous repair with lighter coloured surface. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2086915 **Logged by:** Verint CRM Connector **on:** 01/02/2026 17:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in middle of road as you pull out of Riccarton Main Road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50190934 **Defect Number:** 42198248

Enquiry No.: 2086393 **Logged by:** Verint CRM Connector **on:** 31/01/2026 13:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: It is just at the entrance to dolphin avenue towards the high school, it is on Lanark road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2085423 **Logged by:** Verint CRM Connector **on:** 29/01/2026 16:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2085086 **Logged by:** Verint CRM Connector **on:** 29/01/2026 10:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: massive pot hole here heading east bound needs fixed asap as someone is going to get hurt either going into it or avoiding it **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2085073 **Logged by:** Verint CRM Connector **on:** 29/01/2026 10:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole on Lanark Road West A70 by the junction for Dolphin Avenue **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2085026 **Logged by:** Verint CRM Connector **on:** 29/01/2026 09:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50190638 **Defect Number:** 42210516

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2085018
Service: Roads General
Desc.:
Location: The huge pothole you cant miss

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 29/01/2026 09:45
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2084816
Service: Roads General
Desc.:
Location: Hole in road between Stewart road and dolphin avenue. Near kerb. Eastbound side. Near to simply wellness massage therapists. Irreparable damage done to one of my tyres. Was unable to take a photo due to heavy rush hour traffic

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 28/01/2026 20:25
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2084776
Service: Roads General
Desc.:
Location: If heading into town, there is a pothole near 366 Lanark Road West.

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 28/01/2026 18:54
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2083303
Service: Roads General
Desc.:
Location: Pothole

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 26/01/2026 15:51
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2083205
Service: Roads General
Desc.:
Location: Called to report that both sides of the road is distorted, which is a safety hazard to cyclists. after Dolphin avenue to Pentland View Court

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 26/01/2026 14:26
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50190445 **Defect Number:** 42197618

Enquiry No.: 2080980
Service: Roads General
Desc.:
Location: Road surface breaking up

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 22/01/2026 09:52
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2079933
Service: Roads General
Desc.:
Location: Multiple potholes along the lanark road that need sorted out.

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 20/01/2026 15:16
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2079112 **Logged by:** [REDACTED] **on:** 19/01/2026 13:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Potholes on road with exposed wires showing underneath
Location: o/s no 9 by disabled parking bay **Contact:**

Enquiry No.: 2077109 **Logged by:** Verint CRM Connector **on:** 15/01/2026 16:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At bus stop area road is now badly deformed due on bus stop area on carriageway heading into Edinburgh **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50189721 **Defect Number:** 42196712

Enquiry No.: 2076831 **Logged by:** Verint CRM Connector **on:** 15/01/2026 11:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here near curb **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2076755 **Logged by:** Verint CRM Connector **on:** 15/01/2026 10:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here near curb **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50189712 **Defect Number:** 42196701

Enquiry No.: 2075616 **Logged by:** Verint CRM Connector **on:** 13/01/2026 16:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: potholes here heading into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50189579 **Defect Number:** 42196516

Enquiry No.: 2074693 **Logged by:** Verint CRM Connector **on:** 12/01/2026 12:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2070418 **Logged by:** Verint CRM Connector **on:** 05/01/2026 20:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: That section of road between 36 Lanark Road West and the traffic lights at the junction with Blinkbonny Road. The condition of the surface is deteriorating and the tyre noise from all vehicle types is becoming deafening. A full resurface is long overdue. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2069787 Service: Roads General Desc.: Location: pothole here heading out of town	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/01/2026 12:47 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50188793	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42195637	Feature Type: Road Asset
Enquiry No.: 2062064 Service: Roads General Desc.: Location: pothole here on road heading into town near middle painted white dotted line	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/12/2025 09:49 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50188792	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42195636	Feature Type: Road Asset
Enquiry No.: 2062057 Service: Roads General Desc.: Location: pothole around here heading into town near the centre of the whole road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/12/2025 09:36 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50188792	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42195636	Feature Type: Road Asset
Enquiry No.: 2061238 Service: Roads General Desc.: Location: pothole along here heading west near curb	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/12/2025 15:40 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50188792	Feature Id - Location: Ward 2 - From Lanark Road west to east side of No.409 Defect Number: 42195636	Feature Type: Road Asset
Enquiry No.: 2054597 Service: Roads General Desc.: Location: Small but deep Report ID: 8510221 Category: Potholes Hole at corner of previous fix Location: Easting/Northing: 317297/667294 (55.891651, -3.323936) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 399, Lanark Road West, Currie, City of Edinburgh, Alba / Scotland, EH14 5RS, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH14 5SL (10m away)	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 08/12/2025 08:03 Classification: Request for service Contact:

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2050914 **Logged by:** Verint CRM Connector **on:** 29/11/2025 12:58
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: On the pavement outside 376 Lanark Road West, Currie mud coming from vehicle driving in and out muddy driveway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2050238 **Logged by:** Verint CRM Connector **on:** 28/11/2025 09:06
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Footpath.
Type:Foliage / Bush
Location: Large tree about to fall onto public footpath **Contact:**

Enquiry No.: 2047730 **Logged by:** Verint CRM Connector **on:** 24/11/2025 08:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Small but deep holes
Report ID: 8453615 **Contact:**

Category: Potholes

Two holes one o each side of the carriage way. Holes are small but deep and can't be avoided without going onto the other side of the road

Location:
Easting/Northing: 318299/667806 (55.896421, -3.308068)Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Hope Scott Garage, 170, Lanark Road West, Blinkbonny, Currie, City of Edinburgh, Alba / Scotland, EH14 5NY, United KingdomNearest postcode to the

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50187403 **Defect Number:** 42193808

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2043595 **Logged by:** Verint CRM Connector **on:** 15/11/2025 13:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Pothole, foot/half foot deep. Wires showing. Caused damage to tires
Report ID: 8420819

Contact:

Category: Potholes

Has caused damage to my car. Wires showing, foot/half foot deep

Location:

Easting/Northing: 322083/670710 (55.923132, -3.248415)

Nearest road to the pin placed on the map (automatically generated by
OpenStreetMap): Lanark Road, Longstone, City of Edinburgh, Alba / Scotland, EH14
1TH, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH14
1TH (45m awa

Enquiry No.: 2040053 **Logged by:** Verint CRM Connector **on:** 08/11/2025 13:37
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: The cement holding the bus shelter supports in place outside Domino's in Pentland
View Shopping Centre has cracked and the shelter is moving when high winds blow.
There is a danger of it collapsing and injuring someone unless the cement is
repaired.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2023899 **Logged by:** Verint CRM Connector **on:** 05/10/2025 15:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Pothole

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2021518 **Logged by:** Verint CRM Connector **on:** 30/09/2025 14:31
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: The bt chamber is significantly higher than the surrounding pavement. This caused
my father to fall badly and cut his knee and put a hole in his trousers. He has been
in pain for a week or so now

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2021052 **Logged by:** [REDACTED] **on:** 29/09/2025 16:52
Service: Roads General **Subject:** Street Furniture: Defective **Classification:** Request for service
Desc.: From: [REDACTED]
Date: Saturday, September 27, 2025 at 6:53:21 PM
To: Customer Care <customer.care@edinburgh.gov.uk>
Subject: Lanark Road Railings

Hi,
Can I report damage to railings. These are on Lanark Road West in Edinburgh. Nearest address is 529 Lanark Road, Juniper Green EH14 5DE.
Thanks,
[REDACTED]
Sent from Outlook for iOS

Location: **Contact:**

Enquiry No.: 2016022 **Logged by:** Verint CRM Connector **on:** 18/09/2025 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This is just before the bus stop heading toward Edinburgh called Dolphin Avenue. **Contact:**
The tarmac has sunk and risen leaving a ridge parallel to the kerb. This ridge is approx 7cm in height and can't be seen when riding in the dark. As you can imagine this is normally hit end on but is also dangerous to anyone trying to go obliquely over the ridge. It is also a potential trip hazard to pedestrians. Please do not delete before talking with Cllr Jenkinson.

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2009097 **Logged by:** [REDACTED] **on:** 04/09/2025 14:54
Service: Roads General **Subject:** Road Safety: General Enquiry **Classification:** General Enquiry
Desc.: Urgent sorry caller very worried as linked to an ice cream van the pavement is being dug up, there is no traffic management in place and it looks as though people carrying out work are not using the correct professional tools
Location: front of 376 - 378 **Contact:**

Enquiry No.: 2008326 **Logged by:** Verint CRM Connector **on:** 03/09/2025 13:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Job Number: 50184426 **Defect Number:** 42189508

Enquiry No.: 2002955 **Logged by:** Verint CRM Connector **on:** 25/08/2025 15:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: another pothole here heading west bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 2002953 **Logged by:** Verint CRM Connector **on:** 25/08/2025 15:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole here heading west bound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2001722 **Logged by:** Verint CRM Connector **on:** 23/08/2025 08:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Hedge overgrown and growing into bus shelter at Nether Currie (city) stop **Contact:**

Enquiry No.: 1999084 **Logged by:** Verint CRM Connector **on:** 19/08/2025 08:45
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush
Location: **Contact:**

Enquiry No.: 1995891 **Logged by:** Verint CRM Connector **on:** 14/08/2025 10:34
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: pothole around iron work heading west bound near curb **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset

Enquiry No.: 1995236 **Logged by:** Verint CRM Connector **on:** 13/08/2025 10:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole as you enter car park from main road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 2 - From Lanark Road west to east side of No.409 **Feature Type:** Road Asset
Job Number: 50183618 **Defect Number:** 42210520

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 2 - From Lanark Road west to east side of No.409		Feature Type: Road Asset		Area: South West Locality	
50184426	Pothole (RD: CW Pothole)	Outside William purvis funeral directors	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/09/2025	04/09/2025	Act. ROAD/82108815
50187403	Potholes on both lanes (RD: CW Pothole)	Between riccarton and Kirkgate junctions	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/11/2025	26/11/2025	Act. ROAD/82110841
50188792	Pothole (RD: CW Pothole)	Near the bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/12/2025	29/12/2025	Act. ROAD/82111895
50188793	Pothole (RD: CW Pothole)	At the junction with riccarton mains road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/12/2025	29/12/2025	Act. ROAD/82111896
50189086	Potholes (RD: CW Pothole)	At bus stop west bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/12/2025	31/12/2025	Act. ROAD/82112148
50189579	Pothole in old track (RD: CW Pothole)	Opposite 403	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/01/2026	14/01/2026	Act. ROAD/82112551
50189712	Potholes (RD: CW Pothole)	Opposite 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2026	16/01/2026	Act. ROAD/82112661
50189735	1no Fw pothole (RD: FW HRA Pothole)	No126	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2026	19/01/2026	Act. ROAD/82112674

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 2 - From Lanark Road west to east side of No.409		Feature Type: Road Asset		Area: South West Locality	
50189991	Pothole (RD: CW Pothole)	Opposite 16	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/01/2026	22/01/2026	Act. ROAD/82112878
50190316	1no cw pothole (RD: CW Pothole)	Outside no374	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/01/2026	26/01/2026	Act. ROAD/82113141
50190445	Pothole (RD: CW Pothole)	Opposite currie community centre in bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/01/2026	28/01/2026	Act. ROAD/82113250
50190517	Pothole (RD: CW Pothole)	At bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2026	30/01/2026	Act. ROAD/82113304
50190519	Pothole (RD: CW Pothole)	Opposite 386	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2026	30/01/2026	Act. ROAD/82113305
50190520	Pothole (take away broken up tar) (RD: CW Pothole)	Outside 374	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/01/2026	29/01/2026	Act. ROAD/82113306
50190934	Potholes (RD: CW Pothole)	At the junction with Riccarton Main Road.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2026	03/02/2026	Act. ROAD/82113633
50190935	Pothole (RD: CW Pothole)	Near junction of Riccarton Main Road.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2026	03/02/2026	Act. ROAD/82113634
50190953	Pothole at ironwork (RD: CW Pothole)	Opposite 70	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2026	03/02/2026	Act. ROAD/82113647
50191579	Potholes (RD: CW Pothole)	west bound at disabled bay	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	16/02/2026	Act. ROAD/82114173
50191652	Pothole (RD: CW Pothole)	Opposite 204 near the bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/02/2026	12/02/2026	Act. ROAD/82114233
50191754	Pothole (RD: CW Pothole)	Opposite currie community centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2026	19/02/2026	Act. ROAD/82114316
50191779	Enquiry 2057949 - loose sign west of jnc Stewart Road needs resecured. Also syl skm signage opposite jnc Stewart Road needs replaced. (NSL: Pole or and Sign Install)	Near junction of Stewart Road	Parking Operations	NSL Job Complete	13/02/2026	30/03/2026	Act. NSL/40119
50192045	Pothole (RD: CW Pothole)	Opposite 386	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2026	19/02/2026	Act. ROAD/82114561
50192051	Potholes (RD: CW Pothole)	Outside William purges funeral	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2026	05/03/2026	Act. ROAD/82114566
50192060	Pothole (RD: CW Pothole)	Outside 141	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2026	19/02/2026	Act. ROAD/82114575
50192368	Pothole (RD: CW Pothole)	Outside 115 at junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/02/2026	25/02/2026	Act. ROAD/82114860
50192373	Potholes (RD: CW Pothole)	Outside 225 to bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	22/03/2026	Act. ROAD/82114863
50192624	Potholes (RD: CW Pothole)	From riccarton junction to Near Easter currie court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2026	26/02/2026	Act. ROAD/82115075
50193069	Potholes (RD: CW Pothole)	At bus stop opposite scorned carpark	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2026	03/03/2026	Act. ROAD/82115449

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 2 - From Lanark Road west to east side of No.409		Feature Type: Road Asset		Area: South West Locality	
50193508	Potholes (RD: CW Pothole)	Opposite 204	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2026	22/03/2026	Act. ROAD/82115786
50193509	Pothole (RD: CW Pothole)	Middle of junction with riccarton mains	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2026	22/03/2026	Act. ROAD/82115787
50193964	Potholes (RD: CW Pothole)	Outside 112 at road island	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2026	22/03/2026	Act. ROAD/82116151
50194226	Potholes (RD: CW Pothole)	Outside William purves funeral at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/03/2026	22/03/2026	Act. ROAD/82116349
50194227	Potholes west bound lane (RD: CW Pothole)	Opposite community centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/03/2026	22/03/2026	Act. ROAD/82116350
50194228	Potholes (RD: CW Pothole)	West bound lane from 143 to 149	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/03/2026	22/03/2026	Act. ROAD/82116351
50194229	Pothole (RD: CW Pothole)	West bound outside 7b disabled bay	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/03/2026	22/03/2026	Act. ROAD/82116352
50194718	Pothole(loose pieces of tar to be lifted) (RD: CW Pothole)	Outside 372	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/03/2026	31/03/2026	Act. ROAD/82116702
50194783	Pothole (RD: CW Pothole)	Outside 398 east bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2026	02/04/2026	Act. ROAD/82116751
50194979	Pothole (RD: CW Pothole)	Outside 368	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/04/2026	08/04/2026	Act. ROAD/82116919
50195081	Pothole (RD: CW Pothole)	Outside 113 west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2026	11/04/2026	Act. ROAD/82117016
50195957	Pothole (RD: CW Pothole)	Outside 398	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/04/2026	29/04/2026	Act. ROAD/82117709
50195968	Potholes (RD: CW Pothole)	Outside 7a	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/04/2026	28/04/2026	Act. ROAD/82117716
50196123	Pothole (RD: CW Pothole)	Outside no 1 west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/04/2026	01/05/2026	Act. ROAD/82117815
50196273	Hra overlay patch needed (RD: CW Pothole)	Outside 300	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/05/2026	06/05/2026	Act. ROAD/82117961
50196378	Parking: Other - Enquiry 2128818 - previously sent job not completed. Reattach sign to pole. (NSL: Pole or and Sign Install)	Sign is located at top of stewart rd-left side entering from lanark road west heading to balerno..rattles constantly	Parking Operations	NSL Job Complete	06/05/2026	02/07/2026	Act. NSL/40183
50196456	Potholes in need of hra overlay (RD: CW Pothole)	Outside riccarton inn both lanes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/05/2026	08/05/2026	Act. ROAD/82118090
50196745	Pothole (RD: CW Pothole)	On cross track	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2026	14/05/2026	Act. ROAD/82118321
50196746	Potholes (RD: CW Pothole)	Outside 399 west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2026	14/05/2026	Act. ROAD/82118322
50196747	Potholes (RD: CW Pothole)	Opposite 386 west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2026	14/05/2026	Act. ROAD/82118323
50196751	Potholes east bound lane (RD: CW Pothole)	Outside 28 before and after traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2026	14/05/2026	Act. ROAD/82118326

Site History Report

Effective: 13/08/2025 to 13/08/2026
Service: Roads General
Site: Lanark Road West (7906119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 2 - From Lanark Road west to east side of No.409		Feature Type: Road Asset		Area: South West Locality	
50196830	Parking: Disabled Bay refresh (Enquiry 34010945) (NSL: Marking Refresh Defect)	9 Lanark Road West	Parking Operations	NSL Job Complete	13/05/2026	27/05/2026	Act. NSL/40194
50197106	Pothole (RD: CW Pothole)	Outside William purvis funeral at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2026	21/05/2026	Act. ROAD/82118563
50197184	Pothole west bound lane (RD: CW Pothole)	Outside 155 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/05/2026	21/05/2026	Act. ROAD/82118645
50198093	Parking: Other - Gavin Graham requesting refresh of private car park including missing syl on junction entry. (NSL: Marking Refresh Defect)	Pentland view car park	Parking Operations	NSL Job Complete	05/06/2026	26/06/2026	Act. NSL/40218
50198881	Pothole (RD: CW Pothole)	Junction entrance leading to the bowling club	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/06/2026	23/06/2026	Act. ROAD/82119963
50199576	Pothole (RD: CW Pothole)	Opposite 360	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120579
50199577	Pothole (RD: CW Pothole)	Opposite 356	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120580
50199580	Pothole (RD: CW Pothole)	Adjacent to bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120582
50199581	Pothole (RD: CW Pothole)	At crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120583
50199583	Pothole (RD: CW Pothole)	Adjacent to community centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120585
50199588	Pothole with with ha (RD: FW HRA Pothole)	Outside domino's at slab area	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120588
50199591	Pothole (RD: CW Pothole)	At crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120590
50199598	Pothole (RD: CW Pothole)	Adjacent to Bruce road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120595
50199599	Pothole with with ha (RD: FW HRA Pothole)	Outside 112	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120596
50199607	Open joint (RD: CW Open Joint)	Outside 50	RD: Cat 3 - 60 Day	Job Committed	07/07/2026	29/09/2026	Est. ROAD/82120602
50199610	Pothole (RD: CW Pothole)	At traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/07/2026	08/07/2026	Act. ROAD/82120605