

Site History Report

Effective: 22/06/2024 to 22/06/2025			Asset Number: 1.00 to 1.00		
Display Action Officer: No			Site: Saughton Road (7903233)		

Site: Saughton Road (7903233)		Locality: Saughton, Edinburgh, City of Edinburgh		Area: South West Locality	
-------------------------------	--	--	--	---------------------------	--

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Link road outside No.8 joining main section of Saughto			Feature Type: Road Asset		Area: South West Locality	
Batch: 41220564 - Inspection Batch			Route: SW_CF1_SaughtonRd1				Date: 25/02/2025	
42177040	Cracked broken cw	25/02/2025	Section of cw	RD: CW Cracked/Broken	Internal		Uncommitted	50153578
42177042	Cracked broken cw	25/02/2025	At junction	RD: CW Cracked/Broken	Internal		No Action Required	
42177041	Refresh residue	25/02/2025	At junction	RD: CW Loss of Skid Resistance	Internal		No Action Required	
42177039	Refresh markings	25/02/2025	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50098459
Batch: 41219027 - Inspection Batch			Route: Ad hoc Route				Date: 13/02/2025	
42175994	2 potholes	13/02/2025	At the junction of Saughton road	RD: CW Pothole	Internal		Committed	50175072

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 7 - Link road outside No.8 joining main section of Saughto			Feature Type: Road Asset		Area: South West Locality
50175072	2 potholes (RD: CW Pothole)	At the junction of Saughton road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	14/02/2025	Act. ROAD/82102480