Site History Report

Effective: 01/06/2023 to 09/10/2026
Service: Roads General
Site: Saughton Mains Avenue (7903222)
Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Saughton Mains Avenue (7903222) **Locality:** Saughton, Edinburgh, City of Edinburgh **Area:** South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	**Asset - Locn.:** Whole Street			**Feature Type:** Road Asset			**Area:** South West Locality	
Batch: 41260473 - Inspection Batch				**Route:** Ad hoc Route				**Date:** 09/04/2026
42203847	Pothole	09/04/2026	Outside 29	RD: CW Pothole	Internal		Committed	50195114
Batch: 41253558 - Inspection Batch				**Route:** SW_CF2_SaughtonCentral1				**Date:** 14/02/2026
No actionable defects found								
Batch: 41236065 - Inspection Batch				**Route:** Ad hoc Route				**Date:** 05/09/2025
42189658	Damaged manhole cover	05/09/2025	Outside 35 on footway	RU: Utility Apparatus	Internal		Uncommitted	50184533
Batch: 41219280 - Inspection Batch				**Route:** SW_CF2_SaughtonCentral1				**Date:** 17/02/2025
42176153	All markings refresh	17/02/2025	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50096688
42176150	Broken cw surface	17/02/2025	Near number 29	RD: CW Cracked/Broken	Internal		Uncommitted	50096692
42176151	Broken cw surface	17/02/2025	Near junction with saughton mains garden	RD: CW Cracked/Broken	Internal		Uncommitted	50096690
42176149	Pothole	17/02/2025	At speed bump at lamppost 09	RD: CW Pothole	Internal		Committed	50175187
Batch: 41182591 - Inspection Batch				**Route:** SW_CF2_SaughtonCentral1				**Date:** 15/02/2024
42147811	Broken cw surface	15/02/2024	Near number 29	RD: CW Cracked/Broken	Internal		No Action Required	
42147820	All markings refresh	15/02/2024	Entire cw including all junctions	RD: Markings Refresh	Internal		No Action Required	
42147812	Broken cw surface	15/02/2024	Near junction with saughton mains garden	RD: CW Cracked/Broken	Internal		No Action Required	

Customer Services

Enquiry No.: 34011009 **Logged by:** [redacted] **on:** 12/06/2026 14:28
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.:
Location: No 34 **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2186746 **Logged by:** Verint CRM Connector **on:** 28/07/2026 08:16
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: I reported this yesterday and I got a reply this morning stating a road inspector has visited the issue….. I don’t understand how this makes sense for an overgrown tree in the back garden which can’t be seen by road and is growing into our garden which again can’t be seen by road? Thanks **Contact:**

Site History Report

Effective: 01/06/2023 to 09/10/2026
Service: Roads General
Site: Saughton Mains Avenue (7903222)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2186550 **Logged by:** Verint CRM Connector **on:** 27/07/2026 16:48
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Tree in back garden of [redacted] Saughton Mains Avenue (empty property) is over growing into our garden [redacted] and parts keep breaking off into iur garden where our kids are playing and this is unsafe **Contact:**

Enquiry No.: 2161295 **Logged by:** Verint CRM Connector **on:** 10/06/2026 20:09
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: No [redacted] and [redacted] Saughton mains avenue have not trimmed the hedge back and it has taken over the pavement causing buggies and pedestrians to walk on grass verge **Contact:**

Enquiry No.: 2142192 **Logged by:** Verint CRM Connector **on:** 05/05/2026 12:49
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Very large overgrown tree overhanging rear garden at [redacted] saughton mains drive and over [redacted] saughton mains drive.. and pushing on telegraph pole wires. comes over from another council neighbours garden . **Contact:**

Also large white blossom tree in same garden. the white stuff goes everywhere all over the garden and also over another private owned neighbours garden. Creating a large mess and sticky residue.
Request to be removed if possible. not protected area/tree and getting far to large for the location.

Enquiry No.: 2009646 **Logged by:** Verint CRM Connector **on:** 05/09/2025 12:55
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Missing cover **Contact:**
Report ID: 8124167

Category: Pavements/footpaths

Cover missing, dangerous hole in ground

Location:
Easting/Northing: 320867/671546 (55.930443, -3.268111)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Saughton Mains Avenue, Stenhouse, Stenhouse, Saughton Mains and Whitson, City of Edinburgh, Alba / Scotland, EH11 3PL, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH11 3QF (31m away)

Site History Report

Effective: 01/06/2023 to 09/10/2026
Service: Roads General
Site: Saughton Mains Avenue (7903222)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1987413 **Logged by:** Verint CRM Connector **on:** 30/07/2025 09:49
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: Neighbour not cutting the hedge, it is so overgrown now you can't see the garden gate. **Contact:**

Enquiry No.: 1963640 **Logged by:** Verint CRM Connector **on:** 14/06/2025 18:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Trees on verge are very overgrown, actually can't remember them EVER having been cut back... obscuring light into my elderly [redacted] home, making house very dark/dim, has to put light on early even on lighter days **Contact:**

Enquiry No.: 1962252 **Logged by:** Verint CRM Connector **on:** 12/06/2025 11:11
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Ref 101003155823. This is not a road problem! As stated this is 2 lge overgrown trees which need trimmed.They block light in my dads house & they are hanging into his property. **Contact:**

Enquiry No.: 1961926 **Logged by:** Verint CRM Connector **on:** 11/06/2025 18:49
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: There is 2 lge overgrown trees outside my [redacted] house which are blocking natural light making inside his house dark but are also overhanging [redacted] hedge.Please can you see about getting these trimmed? As my [redacted] is housebound any contact is through me @ this email or [redacted]
Regards
[redacted] **Contact:**

Enquiry No.: 1891365 **Logged by:** Verint CRM Connector **on:** 23/01/2025 12:41
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Hedge outside [redacted] Saughton Mains |Gardens is causing an obstruction for wheelchair access and normal pedestrians. **Contact:**

Site History Report

Effective: 01/06/2023 to 09/10/2026
Service: Roads General
Site: Saughton Mains Avenue (7903222)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1855596 **Logged by:** Verint CRM Connector **on:** 07/11/2024 13:13
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Boundary hedge outside of Saughton Mains Avenue and Saughton Mains Avenue are seriously overgrown which is forcing pedestrians to have to enter the road way in order to pass. **Contact:**

Enquiry No.: 1808793 **Logged by:** Verint CRM Connector **on:** 31/07/2024 17:06
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Most of the property boundary hedges are massively overgrown and take up most, if not all of the footpath. This has forced my family to have to walk on the main road as there is not enough room to follow the footpath. **Contact:**

Enquiry No.: 1644392 **Logged by:** Verint CRM Connector **on:** 14/11/2023 20:10
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Tree on grass verge outside Saughton Mains Avenue, EH11 3QB **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion		Works Order
Asset: 1.00	**Asset - Locn.:** Whole Street		**Feature Type:** Road Asset		**Area:** South West Locality			
50175187	Pothole (RD: CW Pothole)	At speed bump at lamppost 09	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2025	18/02/2025	Act.	ROAD/82102583
50195114	Pothole (RD: CW Pothole)	Outside 29	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2026	13/04/2026	Act.	ROAD/82117044